Asbestos in Grounds, Asbestos Management Plan, Lake Heights Public School, Lake Heights, NSW

March 2013

NSW Public Works

PARSONS BRINCKERHOFF

Parsons Brinckerhoff Australia Pty Limited ABN 80 078 004 798

Level 27, Ernst & Young Centre 680 George Street Sydney NSW 2000 GPO Box 5394 Sydney NSW 2001

Australia

Telephone +61 2 9272 5100 Facsimile +61 2 9272 5101

Email <u>sydney@pb.com.au</u>

Certified to ISO 9001, ISO 14001, AS/NZS 4801 A GRI Rating: Sustainability Report 2011



© Parsons Brinckerhoff Australia Pty Limited (PB) [2013].

Copyright in the drawings, information and data recorded in this document (the information) is the property of PB. This document and the information are solely for the use of the authorised recipient and this document may not be used, copied or reproduced in whole or part for any purpose other than that for which it was supplied by PB. PB makes no representation, undertakes no duty and accepts no responsibility to any third party who may use or rely upon this document or the information.

Author:		Warre	n La
Signed:	Mull		
Reviewer:	10 M/11	John	Batty
Signed:	Och Mall		
Approved by:		Jason I	North
Signed:		A STATE OF THE STA	





Contents

			Page Number
1.	Intro	oduction	1
	1.1 1.2 1.3	Document Review Background Asbestos removal/clean-up works	1 1 1
2.	Asbe	estos materials	3
	2.1 2.2	Asbestos zone locations Risk management	3 3
3.	Asbe	estos register (Grounds)	4
4.	Asbe	estos zone routine management	7
	4.1 4.2 4.3	Inspections Maintenance Checklist	7 7 7
5.	Asbe	estos zone maintenance works management	9
	5.1 5.2	General Sub-soil areas within school grounds	9
6.	Pern	nit for work	11
7.	Legi	slative requirements	13
8.	Safe	work procedures for asbestos work	15

List of Tables

Table 3-1 Asbestos Register – Asbestos zones only for Lake Heights Public School

List of Figures

Site layout plans

Appendices

Appendix A Grounds management checklist



1. Introduction

1.1 Document Review

No Activity and/or no Re-occurrence of ACM in grounds on this site since October 2012, as such the following is recommended:

This document is to be reviewed and updated

- when works occur on site
- when works occur on site which may cause grounds disturbance
- when any ACM in grounds is reported
- every second year, if no activity.
- until ten years of inactivity, when document review and update will occur every five years

1.2 Background

In May 2010, fibrous cement fragments were identified on the ground surfaces of the northern and southern playing fields, at Lake Heights Public School, located on Northcliffe Drive, Lake Heights NSW 2502.

In order to manage the risk of exposure to asbestos, any fibrous cement fragments are to be removed from the ground surfaces (Refer to Section 1.3). The areas where fibrous cement fragments have been identified within the fill material (and further in-situ asbestos fragments may be present) have been designated as "asbestos zones".

In the previous ground inspection report, reference 2116799B/LT_2157/TR/fr dated 18 May 2010, it was proposed that regular monitoring should be undertaken in the following asbestos zones:

- Area A Bike rack area to the north of Block D
- Area B Playground seating area situated to the north of the playground equipment.
- Area C Playground area running along the eastern perimeter of the school
- Area D Out of bounds area to the south of Block B and to the west of Block A.

This report outlines the plan for management of the identified asbestos impacted areas (zones), and should be read in conjunction with the existing Department of Education and Communities (DEC) Asbestos Management Plan for all other identified asbestos materials within the school.

1.3 Asbestos removal/clean-up works

The asbestos removal/ clean up works completed in May 2010 comprised:



• the removal, clean-up and disposal of the visible fragments of fibrous cement on the ground surface. Removal was limited to the accessible surface areas only.

The remediated areas are shown in Figure 1.





2. Asbestos materials

2.1 Asbestos zone locations

Asbestos cement fragments may be present as a component of buried fill within the asbestos zone areas. Refer to Figure 1 site plan. A hygienist should be engaged to determine whether the asbestos within the Asbestos Zones is considered *non friable* or *friable* in accordance with the NSW WorkCover Authority 'Working with Asbestos, 2008'. This contains safety guidelines and requirements for work involving asbestos.

2.2 Risk management

The in-situ asbestos within the asbestos zones can be classified as low risk provided that the following measures are undertaken:

- The control measures installed are fully maintained.
- The in-situ asbestos remains undisturbed.
- An asbestos management plan remains in effect.
- Any works undertaken on or near the asbestos zones are to be under the control of a permit to work where the contractor has acknowledged the presence of asbestos and has prepared a safe work method statement(s) to ensure that asbestos is not disturbed and therefore airborne asbestos fibres are not generated.



3. Asbestos register (Grounds)

Table 3-1 outlines the findings of the inspection of the grounds indicating the areas requiring management.

Table 3-1 Asbestos Register – Asbestos zones only for Lake Heights Public School

Event	Location	Description of Material	Extent	Condition	Risk Status	Control Priority	Control Recommendation/Comments
School o	Grounds* Bike rack area to the north of Block D	Possible buried asbestos cement fragments	Throughout – below ground surface	Unknown	Low	Low	Inspect frequently for signs of surface wear and possible fragments at surface. Provide repair to surface coverage using re-turfing, paving and/or mulched garden beds as appropriate. Do not disturb soil surface. Inspect every three months for signs of surface wear and possible fragments at
	Playground seating		Surideo				surface. The initial inspections should be carried out by a Department of Commerce representative. Inspect frequently for signs of surface wear and possible fragments at surface. Provide
В	area situated to the north of the playground equipment.	Possible buried asbestos cement fragments	Throughout – below ground surface	Unknown	Low	Low	repair to surface coverage using re-turfing, paving and/or mulched garden beds as appropriate. Do not disturb soil surface. Inspect every three months for signs of surface wear and possible fragments at surface. The initial inspections should be carried out by a Department of Commerce representative.
С	Playground area running along the eastern perimeter of the school	Possible buried asbestos cement fragments	Throughout – below ground surface	Unknown	Low	Low	Inspect frequently for signs of surface wear and possible fragments at surface. Provide repair to surface coverage using re-turfing, paving and/or mulched garden beds as appropriate. Do not disturb soil surface. Inspect every three months for signs of surface wear and possible fragments at surface. The initial inspections should be

PARSONS BRINCKERHOFF 2171479A PR_6945 Page 4



Event	Location	Description of Material	Extent	Condition	Risk Status	Control Priority	Control Recommendation/Comments
							carried out by a Department of Commerce representative.
D	Out of bounds area to the south of Block B and to the west of Block A.	Possible buried asbestos cement fragments	Throughout – below ground surface	Unknown	Low	Low	Inspect frequently for signs of surface wear and possible fragments at surface. Provide repair to surface coverage using re-turfing, paving and/or mulched garden beds as appropriate. Do not disturb soil surface. Inspect every three months for signs of surface wear and possible fragments at surface. The initial inspections should be carried out by a Department of Commerce representative.

^{*}Refer to Figure 1 for detail of area locations

Risk assessment factors

Low risk: Asbestos materials that pose a low health risk to personnel, employees and the general public provided they remain undisturbed.

Medium risk: Asbestos materials that pose a moderate risk to people in the area – there is a medium potential for the material to release asbestos fibres, if disturbed.

High risk: Asbestos materials that pose a high health risk to personnel or the public in the area of the material – there is a high potential for the material to release asbestos fibres, if disturbed.







4. Asbestos zone routine management

4.1 Inspections by local staff

In order to monitor the effectiveness of the on-site asbestos zone management, it is essential that the affected areas are regularly inspected. Visual inspections of the asbestos remedial measures should be carried out to ensure that they are maintained adequately. Such inspections should occur on the following occasions:

- at three monthly intervals (e.g. a walkover of remediated areas to ensure that applications of mulch and turf, etc. have been maintained)
- after a period of prolonged heavy rain (e.g. a walkover of remediated areas to ensure that applications of mulch and turf, etc. have not been disturbed by heavy rain)
- whenever damage or disturbance has been reported (e.g. a walkover of remediated areas to ensure that applications of mulch and turf, etc. have not been disturbed by events such as vehicle movements).
- whenever works are about to commence that may cause grounds disturbance

Should areas be identified where encapsulating measures appear to be damaged or are no longer effective, these areas should be re-covered immediately. Some remedial measures such as the installation of layers of mulch and top soil will require ongoing maintenance to ensure that a sufficient barrier layer is in place.

4.2 Maintenance

All remediation measures carried out in the affected areas must be maintained as per their original application. In particular:

- All surface cover/treatments within the asbestos zones must be fully maintained at all times. For example, mulch levels should remain as per their original application, turf should be maintained to ensure full coverage and any other measures should be maintained in a good condition.
- All hard standing surfaces must be maintained and re-instated should any works that disturb them be carried out.
- If any portion of an affected area is found to be damaged (i.e. the surface cover has been damaged so that it has resulted or may result in the soil becoming exposed), the DEC local Asset Management Unit (AMU) should be contacted immediately.

4.3 Checklist

A checklist of site management requirements is presented in Appendix A of this document. This checklist should be used whenever walkover inspections are carried



out and where maintenance issues have been raised. The checklist is specific to the requirements of the grounds at the Lake Heights Public School and sets out the frequency of inspections required. It is recommended that a hard copy of the checklist retained by the school and field copies are taken on-site when required.





5. Asbestos zone maintenance works management

5.1 General

An Asbestos Management Plan (AMP) has been implemented for all NSW state schools and educational facilities. The plan includes procedures for managing friable asbestos and working on asbestos. A generic permit to work template will also be included in the management plan which will be able to be used where any work is required that may disturb asbestos materials within an asbestos zone.

5.2 Sub-soil areas within school grounds

- Any contractor, maintenance person; all Department of Commerce, Department of Education & Communities personnel or other authorised persons must acknowledge the presence of buried asbestos cement materials within these areas. A copy of the asbestos register must be made available to any such person prior to commencing work.
- Any contractor, maintenance person; all Department of Commerce, Department of Education & Communities or other authorised person who may potentially disturb the soil surface must complete a permit to work or similar form that ensures that any work will not disturb the buried asbestos.
- If work is to be carried out in grounds that will disturb or potentially disturb the buried asbestos, the contractor, maintenance person; all Department of Commerce, Department of Education & Communities personnel or other authorised person must engage a licensed asbestos removal contractor with a friable asbestos licence to undertake the work. The licensed contractor should prepare a safe work method statement detailing procedures that ensure that personnel working in the asbestos zones and any other persons within the school will not be exposed to asbestos fibres. The work area must be completely enclosed and work undertaken out of school hours.
- Work in progress asbestos air monitoring should be carried out during any work that disturbs or could potentially disturb the buried asbestos and/or the soil surface. Air-monitoring should be in accordance with the National Occupational Health & Safety Commission's Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC: 3003 (2005)] and be conducted by National Association of testing Authorities (NATA) accredited personnel operating from a NATA registered laboratory.
- All asbestos management measures originally installed must be re-instated at the completion of work and prior to the removal of the work area enclosure.







6. Permit for work

Any contractor who proposes to work in any of the asbestos zones where asbestos may be disturbed or the ground surface may be broken must complete a permit to work form.

Before a permit to work is issued, individuals will be required to read and understand the AMP, as well as copies of the relevant asbestos registers. Individuals must be aware of their legal obligations in relation to health and safety as specified in the Work Health and Safety Act 2011 and the Work Health and Safety Regulation 2011.

Permits to work are designed to ensure appropriate work practices are employed in the vicinity of asbestos-containing materials/products. The permit to work will document what asbestos is to be removed, encapsulated or otherwise protected, prior to the contracted maintenance or building works proceeding. The permit to work will also indicate whether other requirements, such as the use of personal protective equipment (PPE), the installation of barricading and/or airborne fibre monitoring, are necessary.

When the work is completed, or the permit to work expires (whichever occurs first), the permit shall be signed and returned to the DEC Facility Manager for cancellation after that Manager has checked a safe situation exists.

The DEC local AMU shall be advised immediately of any incidents of non-compliance with the AMP.

In accordance with the interpretation of the NSW WorkCover Authority published in 'Working with Asbestos,' Guide 2008, a licenced asbestos assessor should be engaged to determine whether the buried asbestos is considered *non-friable* or *friable*. Therefore, any fibrous cement materials or other suspected asbestos-containing materials excavated should be inspected by a hygienist to determine if it's friable. This means that any such asbestos should be worked on only by contractors with an appropriate asbestos licence and a project specific permit issued by WorkCover NSW (in addition to the permit to work, mentioned above).







7. Legislative requirements

The following legislative requirements will apply to asbestos zone maintenance works:

- All asbestos removal and disposal work shall be carried out in accordance with the requirements of the WorkCover NSW Guidelines for Licensed Asbestos Removal Contractors
- The asbestos contractor shall notify WorkCover NSW of the proposed work at least 5 days prior to the commencement of any work in accordance with NSW Occupational Health and Safety Regulation 2011. However this time period may be waived in the case for DEC properties
- All work shall be carried out in strict accordance with the NSW Work Health and Safety Act 2011, the NSW Work Health and Safety Regulation 2011, How to Safely Remove Asbestos – Code of Practice 2011, and the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC 3003 (2005)].









8. Safe work procedures for asbestos work


The following safe work procedures will apply for asbestos work:

- The removal contractor must develop a site-specific asbestos removal plan before commencing the asbestos work. Such a plan must be prepared in accordance with Section 3 of the Work Safe Australia- How to safely remove asbestos: Code of Practice 2011.
- Only personnel who have been trained in work procedures for the safe removal of asbestos shall work on asbestos.
- A trained, experienced operator must remain on duty outside the removal area and/or enclosure (if installed) at all times that asbestos removal is in progress. Curricula vitae for all persons undertaking asbestos removal works must be submitted to the Principal prior to the commencement of work on the sites.
- Removal of asbestos must generally be carried out by wet removal techniques. That is, as the asbestos material becomes accessible during the removal process, it shall be thoroughly wetted down. Care must be exercised to prevent excessive use of water. The contractor will be held responsible for any water damage.
- Decontamination facilities and procedures shall be undertaken to the complete satisfaction of a hygienist.
- Any signage existing prior to removal must be re-affixed to any new or existing assembly.
- The contractor must ensure that persons in the work area(s) are not exposed to fibre levels greater than those stated in the National Exposure Standard for the type of asbestos being removed.

Figures

Site layout plans

4011 — Lake Heights Public School Site Plan (12744)



Appendix A

Grounds management checklist

Lake Heights School grounds asbestos management checklist – Routine three monthly inspections

Table 1 Routine monthly inspection checklist

		Three monthly inspections	Initial inspection		Subsequent three-monthly inspections			
Area	Location description		Date:	Date:	Date:	Date:	Date:	
Α	Bike rack area to the north of Block D	Surface cover adequate (Y/N)						
		Suspected asbestos materials visible (Y/N)						
В	Playground seating area situated to the	Surface cover adequate (Y/N)						
	north of the playground equipment.	Suspected asbestos materials visible (Y/N)						
С	Playground area running along the eastern perimeter of the school	Surface cover adequate (Y/N)						
		Suspected asbestos materials visible (Y/N)						
D	Out of bounds area to the south of Block B and to the west of Block A	Surface cover adequate (Y/N)						
		Suspected asbestos materials visible (Y/N)						

Lake Heights Public School grounds asbestos management checklist – Incident inspections (e.g. after heavy rain or disturbance)

Table 2 Incident inspection checklist

		Three monthly inspections	Initial inspection		Subsequent three-monthly inspections			
Area	Location description		Date:	Date:	Date:	Date:	Date:	
A	Bike rack area to the north of Block D	Surface cover adequate (Y/N)						
		Suspected asbestos materials visible (Y/N)						
В	Playground seating area situated to the	Surface cover adequate (Y/N)						
	north of the playground equipment.	Suspected asbestos materials visible (Y/N)						
С	Playground area running along the eastern perimeter of the school	Surface cover adequate (Y/N)						
		Suspected asbestos materials visible (Y/N)						
D	Out of bounds area to the south of Block B and to the west of Block A	Surface cover adequate (Y/N)						
		Suspected asbestos materials visible (Y/N)						