


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Anna Bay Public School (1040)
Region : Hunter/Central Coast
State Electorate : Port Stephens
Local Government Area : Port Stephens

Initial Survey : Noel Arnold & Associates : 20 - May - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Staff Facilities - 1983 - Brick/Veneer (Brick/Veneer)**Exterior**

Wall Cladding	Flat AC Sheeting	40m2	East, West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior**B00A - R0001 - Movement**

Wall Cladding	Flat AC Sheeting 1040/B00A/R0006/Wall Linings Internal/S7					No Asbestos Detected
In-fill-panel	Flat AC Sheeting 1040/B00A/R0001/In-fill-panel/S9					No Asbestos Detected

B00A - R0002 - Clerical Office/Workroom

No Asbestos

B00A - R0003 - Disabled Toilet

No Asbestos

B00A - R0004 - Movement

No Asbestos

B00A - R0005 - Staff Room

No Asbestos

B00A - R0006 - Movement

Wall Cladding	Flat AC Sheeting 1040/B00A/R0006/Wall Linings Internal/S7					No Asbestos Detected
---------------	--	--	--	--	--	-----------------------------

B00A - R0007 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting 1040/B00A/R0007/Wall Linings Internal/S8					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 1040/B00A/R0007/Wall Linings Internal/S8					No Asbestos Detected

B00A - R0008 - Cleaning Distributed Store

No Asbestos

B00A - R0009 - Security Store

No Asbestos

B00A - R0010 - Principal

No Asbestos

B00A - R0011 - Entry Vestibule

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Movement

No Asbestos

B00B - R0002 - Practical Activities - 1hb

No Asbestos

B00B - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0008 - Practical Activities - 1hb

No Asbestos

B00B - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities/Staff Facilities - 1984 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00C - R0003 - Movement

No Asbestos

B00C - R0004 - Canteen Office/Store

No Asbestos

B00C - R0005 - Staff Toilet

No Asbestos

B00C - R0006 - Canteen Office/Store

No Asbestos

B00C - R0007 - Canteen

No Asbestos

B00C - R0008 - Canteen Covered Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Building Services - 1984 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Cleaning Supplies

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1984 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	80m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00E - R0001 - Home Base Store

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1040/B00E/R0003/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

B00E - R0002 - Home Base

Wall Linings Internal	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1040/B00E/R0002/Wall Linings Internal/S2					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1040/B00E/R0003/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting	2m	South, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	1040/B00F/R0005/In-fill-panel/S3					Chrysotile (white asbestos)

B00E - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1040/B00E/R0003/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting	3m	West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1040/B00E/R0003/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

B00E - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1040/B00E/R0003/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning/Administration - 1961 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	80m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00F - R0001 - Withdrawal Space - 1hb

Wall Linings Internal	Flat AC Sheeting	5m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	1040/B00E/R0002/Wall Linings Internal/S2			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1040/B00E/R0003/Ceiling Structures/Linings/S1			Chrysotile (white asbestos)		

B00F - R0002 - Interview

No Asbestos

B00F - R0003 - General Storeroom

No Asbestos

B00F - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	59m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1040/B00E/R0003/Ceiling Structures/Linings/S1			Chrysotile (white asbestos)		

B00F - R0005 - Home Base

In-fill-panel	Flat AC Sheeting	2m	North, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1040/B00F/R0005/In-fill-panel/S3			Chrysotile (white asbestos)		

B00F - R0006 - Home Base

In-fill-panel	Flat AC Sheeting	2m	North, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1040/B00F/R0005/In-fill-panel/S3			Chrysotile (white asbestos)		

B00F - R0007 - Craft Store

No Asbestos

B00F - R0008 - Disabled Toilet

No Asbestos

B00F - R0009 - Practical Activities - 1hb

No Asbestos

B00F - R0010 - Home Base

In-fill-panel	Flat AC Sheeting	2m	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1040/B00F/R0005/In-fill-panel/S3			Chrysotile (white asbestos)		



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Administration/Communal Facilities - 1983 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Sports Store

No Asbestos

B00G - R0002 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Building Services - 1984 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Building Services - 1984 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B001 - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Pupil Facilities - 1984 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	30m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	--------------	--------------------	---------	--------------------

Assumed Asbestos

Ceiling Voids	Requires Inspection					
---------------	---------------------	--	--	--	--	--

Underfloor Voids	Requires Inspection					
------------------	---------------------	--	--	--	--	--

Interior

B00J - R0001 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	---------------------	------	------------	--------------------	---------	--------------------

1040/B00J/R0001/Partition Walls (Cubicles)/S5

Chrysotile (white asbestos)

Ceiling Structures/Linings	Flat AC Sheeting					
----------------------------	------------------	--	--	--	--	--

1040/B00J/R0002/Ceiling Structures/Linings/S4

No Asbestos Detected

B00J - R0002 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
----------------------------	------------------	--	--	--	--	--

1040/B00J/R0002/Ceiling Structures/Linings/S4

No Asbestos Detected

B00J - R0003 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	---------------------	------	------------	--------------------	---------	--------------------

1040/B00J/R0001/Partition Walls (Cubicles)/S5

Chrysotile (white asbestos)

Ceiling Structures/Linings	Flat AC Sheeting					
----------------------------	------------------	--	--	--	--	--

1040/B00J/R0002/Ceiling Structures/Linings/S4

No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00K - R0001 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0002 - Practical Activities - 1hb

No Asbestos

B00K - R0003 - Movement

No Asbestos

B00K - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0007 - Practical Activities - 1hb

No Asbestos

B00K - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Library/Pupil Facilities - 1981 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00L - R0001 - Movement

No Asbestos

B00L - R0002 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1040/B00J/R0001/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)	

B00L - R0003 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1040/B00J/R0001/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)	

B00L - R0004 - Reading Area

No Asbestos

B00L - R0005 - Seminar/Study

No Asbestos

B00L - R0006 - Library Office/Workroom

No Asbestos

B00L - R0007 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1040/B00L/R0007/Wall Linings Internal/S6					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00M - R0001 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00M - R0002 - Home Base Store

No Asbestos

B00M - R0003 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00M - R0004 - No Access

No Asbestos

B00M - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00M - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00M - R0007 - Home Base Store

No Asbestos

B00M - R0008 - Practical Activities - 1hb

No Asbestos

B00M - R0009 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00N - R0001 - Movement

No Asbestos

B00N - R0002 - Practical Activities - 1hb

No Asbestos

B00N - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00N - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00N - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00N - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00N - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00N - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B000 - Administration - 2005 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B000 - R0001 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0002 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0003 - Sick Bay

No Asbestos

B000 - R0004 - Disabled Shower/Toilet

No Asbestos

B000 - R0005 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0006 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0007 - Security Store

No Asbestos

B000 - R0008 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0009 - Cleaning Distributed Store

No Asbestos

B000 - R0010 - Main Switch Board

No Asbestos

B000 - R0011 - Staff Toilet

No Asbestos

B000 - R0012 - Staff Toilet

No Asbestos

B000 - R0013 - Staff Toilet

No Asbestos

B000 - R0014 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0015 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0016 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0017 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0018 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B000 - R0019 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00P - Communal Facilities - 2005 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00P - R0001 - Disabled Shower/Toilet**

No Asbestos

B00P - R0002 - Toilets - Girls

No Asbestos

B00P - R0003 - Movement

No Asbestos

B00P - R0004 - Chair Store

No Asbestos

B00P - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00P - R0006 - Movement

No Asbestos

B00P - R0007 - Raised Platform

No Asbestos

B00P - R0008 - Movement

No Asbestos

B00P - R0009 - Performance Store

No Asbestos

B00P - R0010 - Cleaning Distributed Store

No Asbestos

B00P - R0011 - Cleaning Supplies

No Asbestos

B00P - R0012 - Movement

No Asbestos

B00P - R0013 - P.E. Store

No Asbestos

B00P - R0014 - Communications Cupboard

No Asbestos

B00P - R0015 - Toilets - Boys

No Asbestos

B00P - R0016 - Sports Store

No Asbestos

B00P - R0017 - Movement

No Asbestos

B00P - R0018 - Covered Outdoor Learning Area

No Asbestos

B00P - R0019 - Movement

No Asbestos

B00P - R0020 - Communal Space

No Asbestos

B00P - R0021 - Movement

No Asbestos

B00P - R9001 - Garden Store

No Asbestos

B00P - R9002 - General Assistant/Bulk Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Library/Staff Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00Q - R0001 - External Movement

No Asbestos

B00Q - R0002 - Toilet - Lobby

No Asbestos

B00Q - R0003 - Cleaning Distributed Store

No Asbestos

B00Q - R0004 - Staff Toilet

No Asbestos

B00Q - R0005 - Main Switch Board

No Asbestos

B00Q - R0006 - Reading Area

No Asbestos

B00Q - R0007 - K.L.A. Store

No Asbestos

B00Q - R0008 - Communications Room

No Asbestos

B00Q - R0009 - Library Office/Workroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00R - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00R - R0001 - External Movement

No Asbestos

B00R - R0002 - Practical Activities - 1hb

No Asbestos

B00R - R0003 - Home Base

No Asbestos

B00R - R0004 - Home Base Store

No Asbestos

B00R - R0005 - Withdrawal Space - 2hb

No Asbestos

B00R - R0006 - Practical Activities - 1hb

No Asbestos

B00R - R0007 - Home Base

No Asbestos

B00R - R0008 - Home Base Store

No Asbestos

B00R - R0009 - Practical Activities - 1hb

No Asbestos

B00R - R0010 - Home Base

No Asbestos

B00R - R0011 - Home Base Store

No Asbestos

B00R - R0012 - Withdrawal Space - 2hb

No Asbestos

B00R - R0013 - Practical Activities - 1hb

No Asbestos

B00R - R0014 - Home Base

No Asbestos

B00R - R0015 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00S - Building Services - 2000 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00S - R0001 - No Access

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 601 - D13234 - Learning Unit - Standard/Withdrawal : Placement Date - 5/11/1999

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 601 - D14108 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 842 - D15566 - Country Toilet - Relta - Boys/Girls : Placement Date - 6/02/2009

Exterior

No Asbestos Found.

Interior

R1 - Toilets-Girls

No Asbestos Found.

R2 - Staff Toilet

No Asbestos Found.

R3 - Toilets-Boys

No Asbestos Found.

R4 - Staff Toilet

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017