

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Annandale North Public School (1042)  
**Region :** Sydney  
**State Electorate :** Balmain  
**Local Government Area :** Leichhardt

**Initial Survey :** Noel Arnold & Associates : 10 - Mar - 2008  
**Reviewed By :** Parsons Brinckerhoff : 14 - Feb - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Administration - 1974 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Infil panel below window	Flat AC Sheeting	40m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	1042/B00A/R1018/Infil panels below window/S10					<b>Chrysotile (white asbestos)</b>

**Interior**

**B00A - R0001 - Principal (12.57 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	1042/B00A/R0028/Ceiling Structures/Linings/S6					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00A - R0002 - General Storeroom (2.49 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	1042/B00A/R0028/Ceiling Structures/Linings/S6					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1042/B00B/R0011/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>

**B00A - R0003 - Movement (2.27 m2)**

No Asbestos

**B00A - R0004 - Entry Vestibule (23.26 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	1042/B00A/R0028/Ceiling Structures/Linings/S6					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Floor Coverings Res/Textile	Vinyl Tiles	24m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1042/B00B/R0011/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>

**B00A - R0005 - Clerical Office (10.61 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	1042/B00A/R0028/Ceiling Structures/Linings/S6					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00A - R0006 - Clerical Office/Workroom (10.26 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	1042/B00A/R0028/Ceiling Structures/Linings/S6					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00A - R0007 - Staff Toilet (5.44 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	1042/B00A/R0028/Ceiling Structures/Linings/S6					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00A - R0008 - Staff Toilet (3.34 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	1042/B00A/R0028/Ceiling Structures/Linings/S6					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00A - R0009 - Security Store (10.26 m2)**

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	1042/B00A/R0028/Ceiling Structures/Linings/S6					
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Floor Coverings Res/Textile	Vinyl Tiles	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1042/B00B/R0011/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>

**B00A - R0010 - General Storeroom (10.68 m2)**

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	1042/B00A/R0010/Wall Linings Internal/S8					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0011 - General Storeroom (1.6 m2)</b>						
No Asbestos						
<b>B00A - R0012 - Duplicating Workroom (19.99 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	1042/B00A/R0028/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1042/B00B/R0011/Floor Coverings Res/Textile/S3					Chrysotile (white asbestos)
<b>B00A - R0013 - Cleaning Distributed Store (1.75 m2)</b>						
No Asbestos						
<b>B00A - R0014 - Deputy Principal (13.89 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	1042/B00A/R0028/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0015 - Deputy Principal (12.68 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	1042/B00A/R0028/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0016 - Main Switch Board (2.55 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	1042/B00A/R0028/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1042/B00B/R0011/Floor Coverings Res/Textile/S3					Chrysotile (white asbestos)
<b>B00A - R0017 - Distribution Board (0.79 m2)</b>						
No Asbestos						
					Note: No inspection of live electrical installation.	
<b>B00A - R0018 - Movement (13.42 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	1042/B00A/R0028/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1042/B00B/R0011/Floor Coverings Res/Textile/S3					Chrysotile (white asbestos)
<b>B00A - R0019 - General Storeroom (7.77 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	1042/B00A/R0028/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1042/B00B/R0011/Floor Coverings Res/Textile/S3					Chrysotile (white asbestos)
<b>B00A - R0020 - No Access (3.7 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	1042/B00A/R0028/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1042/B00B/R0011/Floor Coverings Res/Textile/S3					Chrysotile (white asbestos)
<b>B00A - R0021 - Home Base Store (4.12 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	1042/B00A/R0028/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00A - R0024 - Toilets - Boys/Girls (3.46 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Vermiculite 1042/B00A/R0028/Ceiling Structures/Linings/S6					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00A - R0025 - Home Base Store (3.13 m2)</b>						
Ceiling Structures/Linings	Vermiculite 1042/B00A/R0028/Ceiling Structures/Linings/S6					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 1042/B00B/R0011/Floor Coverings Res/Textile/S3	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R0026 - Personal Effects Storage (6.49 m2)</b>						
Ceiling Structures/Linings	Vermiculite 1042/B00A/R0028/Ceiling Structures/Linings/S6					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 1042/B00B/R0011/Floor Coverings Res/Textile/S3	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R0027 - Toilets - Girls (28 m2)</b>						
Ceiling Structures/Linings	Vermiculite 1042/B00A/R0028/Ceiling Structures/Linings/S6					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Partition Walls (Cubicles)	Compressed AC Sheet 1042/B00A/R0029/Partition Walls (Cubicles)/S7	10m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R0028 - Cleaning Distributed Store (6.58 m2)</b>						
Cistern	Compressed AC Sheet 1042/B00A/R0028/Cistern/S5	2Unit(s)	East facing	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
Ceiling Structures/Linings	Vermiculite 1042/B00A/R0028/Ceiling Structures/Linings/S6					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
<b>B00A - R0029 - Toilets - Boys (31.11 m2)</b>						
Ceiling Structures/Linings	Vermiculite 1042/B00A/R0028/Ceiling Structures/Linings/S6					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Partition Walls (Cubicles)	Compressed AC Sheet 1042/B00A/R0029/Partition Walls (Cubicles)/S7	6m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R0030 - Movement (109.16 m2)</b>						
Infill panel below window	Flat AC Sheeting 1042/B00A/R0010/Wall Linings Internal/S8					No Asbestos Detected
<b>B00A - R0031 - General Storeroom (2.05 m2)</b>						
No Asbestos						
<b>B00A - R0032 - Plant (3.52 m2)</b>						
Cistern	Compressed AC Sheet 1042/B00A/R0028/Cistern/S5	8Unit(s)	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B00A - R0033 - Stairs (4.42 m2)</b>						
No Asbestos						
<b>B00A - R0034 - Access Shower/Toilet/Change (12.18 m2)</b>						
No Asbestos						
<b>B00A - R0035 - Home Base (58.31 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0036 - Home Base (54.98 m2)</b>						
No Asbestos						
<b>B00A - R0037 - Home Base (58.23 m2)</b>						
No Asbestos						
<b>B00A - R1001 - Home Base (56.56 m2)</b>						
No Asbestos						
<b>B00A - R1002 - Home Base Store (6.6 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00B/R0011/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1003 - Personal Effects Storage (14.06 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00B/R0011/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1004 - Home Base (57.42 m2)</b>						
No Asbestos						
<b>B00A - R1005 - Home Base Store (6.6 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00B/R0011/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1006 - Personal Effects Storage (8.2 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00B/R0011/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1007 - Home Base Store (7.91 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00B/R0011/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1008 - Home Base (56.96 m2)</b>						
No Asbestos						
<b>B00A - R1009 - Home Base (56.96 m2)</b>						
No Asbestos						
<b>B00A - R1010 - Home Base Store (6.68 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00B/R0011/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1011 - Personal Effects Storage (14.18 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00B/R0011/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1012 - Home Base Store (6.68 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00B/R0011/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1013 - Home Base (62.73 m2)</b>						
No Asbestos						
<b>B00A - R1014 - Toilets - Boys (18.85 m2)</b>						
No Asbestos						
<b>B00A - R1015 - Cleaning Distributed Store (3.2 m2)</b>						
No Asbestos						
<b>B00A - R1016 - General Storeroom (14.77 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00B/R0011/Floor Coverings Res/Textile/S3					<b>Chrysotile (white asbestos)</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R1017 - Toilets - Girls (17.89 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00A/R0029/Partition Walls (Cubicles)/S7					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1018 - Movement (127.62 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	128m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00A/R1018/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos)</b>	
Infil panels below window	Flat AC Sheeting	22m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00A/R1018/Infil panels below window/S10					<b>Chrysotile (white asbestos)</b>	
Wall Linings Internal	Flat AC Sheeting	15m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00A/R1018/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1019 - General Storeroom (6.5 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00A/R1018/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos)</b>	
Wall Linings Internal	Flat AC Sheeting	15m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00A/R1018/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1020 - Stairs (6.13 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00A/R1018/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning/Pupil Facilities - 1974 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	80m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1042/B00B/Eaves Linings/S1					<b>Chrysotile (white asbestos)</b>

**Interior****B00B - R0017 - External Movement (28.33 m2)**

No Asbestos

**B00B - R0018 - Practical Activities/Movement - 1hb (13.08 m2)**

No Asbestos

**B00B - R0019 - Home Base Store (3.92 m2)**

No Asbestos

**B00B - R0020 - Home Base (55.59 m2)**

No Asbestos

**B00B - R0021 - Movement (32.24 m2)**

No Asbestos

**B00B - R0022 - Staff Toilet (2.13 m2)**

No Asbestos

**B00B - R0023 - Canteen Office/Store (10.1 m2)**

No Asbestos

**B00B - R0024 - Canteen (30.38 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning/Library - 1907 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00C - M0001 - Movement (4.03 m2)**

No Asbestos

**B00C - M0002 - Movement (13.54 m2)**

No Asbestos

**B00C - M0003 - Sports Store (10.13 m2)**

No Asbestos

**B00C - M0004 - Staff Toilet (1.78 m2)**

No Asbestos

**B00C - M0005 - Staff Toilet (1.78 m2)**

No Asbestos

**B00C - R0001 - Home Base (47.66 m2)**

No Asbestos

**B00C - R0002 - Home Base (47.43 m2)**

No Asbestos

**B00C - R0003 - Home Base (47.13 m2)**

No Asbestos

**B00C - R0004 - Home Base (46.92 m2)**

No Asbestos

**B00C - R0005 - Uniform Shop (19.81 m2)**

No Asbestos

**B00C - R0006 - General Storeroom (7.59 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00C/R0015/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>	

**B00C - R0007 - Cleaning Supplies (4.14 m2)**

No Asbestos

**B00C - R0008 - Staff Room (51 m2)**

No Asbestos

**B00C - R0009 - General Storeroom (10.18 m2)**

No Asbestos

**B00C - R0010 - Movement (6.66 m2)**

No Asbestos

**B00C - R0011 - Cleaning Distributed Store (4.72 m2)**

No Asbestos

**B00C - R0012 - Home Base (50.82 m2)**

No Asbestos

**B00C - R0013 - Plant (19.63 m2)**

No Asbestos

**B00C - R0015 - General Storeroom (8.5 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00C/R0015/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>	

**B00C - R0016 - Movement (98.62 m2)**



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	80m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00C/R0015/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)	
<b>B00C - R0017 - Staff Toilet (1.74 m2)</b>						
Cistern	Compressed AC Sheet	1Unit(s)	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00A/R0028/Cistern/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)	
<b>B00C - R0018 - Staff Toilet (1.74 m2)</b>						
Cistern	Compressed AC Sheet	1Unit(s)	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00A/R0028/Cistern/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)	
<b>B00C - R0019 - Stairs (3.44 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00C/R0015/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)	
<b>B00C - R0020 - Stairs (3.82 m2)</b>						
No Asbestos						
<b>B00C - R0021 - Movement (4.11 m2)</b>						
No Asbestos						
<b>B00C - R0022 - Plant (19.61 m2)</b>						
No Asbestos						
<b>B00C - R1001 - Reading Area (96.87 m2)</b>						
No Asbestos						
<b>B00C - R1002 - Library Office/Workroom (17.8 m2)</b>						
No Asbestos						
<b>B00C - R1003 - Reading Area (17.85 m2)</b>						
No Asbestos						
<b>B00C - R1004 - Plant (11.36 m2)</b>						
No Asbestos						
<b>B00C - R1005 - Home Base (47.4 m2)</b>						
No Asbestos						
<b>B00C - R1006 - Home Base (47.21 m2)</b>						
No Asbestos						
<b>B00C - R1007 - General Storeroom (19.84 m2)</b>						
No Asbestos						
<b>B00C - R1008 - General Storeroom (8.12 m2)</b>						
No Asbestos						
<b>B00C - R1009 - Movement (1.13 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00C/R0015/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)	
<b>B00C - R1010 - Home Base (50.63 m2)</b>						
No Asbestos						
<b>B00C - R1011 - Home Base (50.75 m2)</b>						
No Asbestos						
<b>B00C - R1012 - Movement (74.1 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	75m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00C/R1012/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall lining of Sink	Compressed AC Sheet	1m2	West facing, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00A/R0029/Partition Walls (Cubicles)/S7					<b>Chrysotile (white asbestos)</b>	
<b>B00C - R1013 - Stairs (3.76 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00C/R0015/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>	
<b>B00C - R1014 - Stairs (2.41 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00C/R0015/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>	
<b>B00C - R1015 - Stairs (5.37 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1042/B00C/R0015/Floor Coverings Res/Textile/S11					<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Communal Facilities/General Learning - 2012 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00D - R0001 - External Movement (111.26 m2)**

No Asbestos

**B00D - R0002 - External Movement (86.4 m2)**

No Asbestos

**B00D - R0003 - Special Programs Room (31.55 m2)**

No Asbestos

**B00D - R0004 - Special Programs Room (31.6 m2)**

No Asbestos

**B00D - R0005 - Main Switch Board (5.02 m2)**

No Asbestos

**B00D - R0006 - Access Shower/Toilet/Change (4.51 m2)**

No Asbestos

**B00D - R0007 - Toilet - Lobby (2.39 m2)**

No Asbestos

**B00D - R0008 - Toilets - Boys (20.88 m2)**

No Asbestos

**B00D - R0009 - Toilet - Lobby (2.19 m2)**

No Asbestos

**B00D - R0010 - Toilets - Girls (26.29 m2)**

No Asbestos

**B00D - R0011 - Cleaning Distributed Store (4.51 m2)**

No Asbestos

**B00D - R0012 - General Storeroom (0.34 m2)**

No Asbestos

**B00D - R0013 - Movement (8 m2)**

No Asbestos

**B00D - R0014 - P.E. Store (17.27 m2)**

No Asbestos

**B00D - R0015 - Communal/Performance Store (15.89 m2)**

No Asbestos

**B00D - R0016 - Hall Chair Store (9.78 m2)**

No Asbestos

**B00D - R0017 - Movement (7.01 m2)**

No Asbestos

**B00D - R0018 - Communal Space (280.03 m2)**

No Asbestos

**B00D - R0019 - No Access (1.97 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017