

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Appin Public School (1045)
Region : South Western Sydney
State Electorate : Wollondilly
Local Government Area : Wollondilly

Initial Survey : Noel Arnold & Associates : 23 - Apr - 2008
Reviewed By : Parsons Brinckerhoff : 28 - Dec - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1950 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1045/B00A/Eaves Linings/S1				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00A - R0001 - Staff Toilet

No Asbestos

B00A - R0002 - Sick Bay

No Asbestos

B00A - R0003 - Clerical Office/Workroom

No Asbestos

B00A - R0004 - Principal

No Asbestos

B00A - R0005 - General Storeroom

No Asbestos

B00A - R0006 - Entry Vestibule

No Asbestos

B00A - R0007 - Staff Room

No Asbestos

B00A - R0008 - Staff Kitchen

No Asbestos

B00A - R0009 - General Storeroom

No Asbestos

B00A - R0011 - Cleaning Distributed Store

No Asbestos

B00A - R0012 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting					
	1045/B00A/R0012/Wall Linings Internal/S3					No Asbestos Detected

B00A - R0013 - Staff Shower/Change

No Asbestos

B00A - R0014 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1045/B00A/R0014/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1962 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting 1045/B00B/Eaves Linings/S5	20m2	South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting 1045/B00B/Gable Verge Lining/S17	12m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
In-fill-panel	Compressed AC Sheet 1045/B00B/In-fill-panel/S9	28m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting 1045/B00B/In-fill-panel/S11					No Asbestos Detected
Underfloor Voids	Flat AC Sheeting 1045/B00B/Underfloor Voids/S19	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5) Chrysotile (white asbestos)
Ceiling Void	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 1045/B00B/Eaves Linings/S14	24m2	South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Gable Ends	Flat AC Sheeting 1045/B00B/Gable Ends/S18					No Asbestos Detected

Interior**B00B - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 1045/B00B/R0001/Ceiling Structures/Linings/S6	75m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting 1045/B00B/In-fill-panel/S7	4m2	North, East, West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00B - R0002 - Personal Effects Storage

No Asbestos

B00B - R0003 - General Storeroom

No Asbestos

B00B - R0004 - Toilets - Boys/Girls

Wall Linings Internal	Flat AC Sheeting 1045/B00B/R0004/Wall Linings Internal/S8	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------	--	-----	------------	--------------------	---------	--

B00B - R0005 - Home Base

No Asbestos

B00B - R0006 - Home Base

No Asbestos

B00B - R0007 - Home Base

No Asbestos

B00B - R9001 - General Storeroom

No Asbestos

B00B - R9002 - General Storeroom

No Asbestos

B00B - R9003 - Sports Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Building Services - 1928 - Timber (Timber)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00C - R0001 - General Storeroom

Electrical Backing Board	Resinous Board	1Unit	East, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
1045/B00C/R0001/Electrical Backing Board/S24					Chrysotile (white asbestos)	

B00C - R0002 - General Storeroom

Chalk Board	Flat AC Sheeting	3m2	Middle portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
1045/B00C/R0001/Chalk Board/S4					Chrysotile (white asbestos)	

Chalk Board	Flat AC Sheeting	3m2	Infill to Fireplace	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
1045/B00C/R0002/Chalk Board/S23					Chrysotile (white asbestos)	

B00C - R0003 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting 1045/B00D/Eaves Linings/S15					No Asbestos Detected
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00D - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 1045/B00D/R0001/Ceiling Structures/Linings/S20					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00D - R0002 - Practical Activities - 1hb

No Asbestos

B00D - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

B00D - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

B00D - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 1045/B00D/R0007/Ceiling Structures/Linings/S21					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00D - R0006 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

B00D - R0007 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 1045/B00D/R0007/Ceiling Structures/Linings/S21					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00D - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

B00D - R0009 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

B00D - R0010 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1965 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1045/B00E/Eaves Linings/S10			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior

B00E - R0001 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet					No Asbestos Detected
	1045/B00E/R0001/Partition Walls (Cubicles)/S12					
Ceiling Structures/Linings	Flat AC Sheeting	31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1045/B00E/R0001/Ceiling Structures/Linings/S13			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0002 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1045/B00E/R0003/Ceiling Structures/Linings/S22			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

B00E - R0003 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1045/B00E/R0003/Ceiling Structures/Linings/S22			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

B00E - R0004 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet					No Asbestos Detected
	1045/B00E/R0001/Partition Walls (Cubicles)/S12					
Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1045/B00E/R0001/Ceiling Structures/Linings/S13			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0005 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1950 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00F - R0001 - Drinking Facilities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Staff Facilities/Building Services - 1867 - Sandstone (Sandstone)

Exterior

Eaves Linings	Flat AC Sheeting 1045/B00G/Eaves Linings/S16					No Asbestos Detected
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00G - R0001 - Staff Kitchen

No Asbestos

B00G - R0002 - Laundry - Type 2

No Asbestos

B00G - R0003 - Staff Toilet

No Asbestos

B00G - R0004 - Movement

No Asbestos

B00G - R0005 - Music Store

No Asbestos

B00G - R0006 - Security Store

No Asbestos

B00G - R0007 - Security Store

No Asbestos

B00G - R0008 - Security Store

No Asbestos

B00G - R0009 - Security Store

No Asbestos

B00G - R0010 - Hall Chair Store

No Asbestos

B00G - R0012 - Movement

Electrical Backing Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
1045/B00G/R0012/Electrical Backing Board/S25					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00L - R0001 - Practical Activities - 1hb

No Asbestos

B00L - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0003 - Home Base Store

No Asbestos

B00L - R0004 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0005 - Practical Activities - 1hb

No Asbestos

B00L - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0007 - Home Base Store

No Asbestos

B00L - R0008 - Practical Activities - 1hb

No Asbestos

B00L - R0009 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0010 - Home Base Store

No Asbestos

B00L - R0011 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0012 - Practical Activities - 1hb

No Asbestos

B00L - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0014 - Home Base Store

No Asbestos

B00L - R0015 - Movement

No Asbestos

B00L - R0016 - Movement

No Asbestos

B00L - R0017 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0018 - Movement

No Asbestos

B00L - R0019 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Library - 2003 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00M - R0001 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00M - R0002 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00M - R0003 - Communications Room

No Asbestos

B00M - R0004 - No Access

No Asbestos

B00M - R0005 - Communications Cupboard

No Asbestos

B00M - R0006 - Staff Toilet

No Asbestos

B00M - R0007 - Cleaning Supplies

No Asbestos

B00M - R0008 - Movement

No Asbestos

B00M - R0009 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00P - R0001 - Communal Space

No Asbestos

B00P - R0002 - Raised Platform

No Asbestos

B00P - R0003 - Chair Storeroom

No Asbestos

B00P - R0004 - P.E. Store

No Asbestos

B00P - R0005 - P.E. Store

No Asbestos

B00P - R0006 - Toilet - Lobby

No Asbestos

B00P - R0007 - Toilets - Girls

No Asbestos

B00P - R0008 - Sound Cupboard

No Asbestos

B00P - R0009 - Toilet - Lobby

No Asbestos

B00P - R0010 - Toilets - Boys

No Asbestos

B00P - R0011 - Cleaning Distributed Store

No Asbestos

B00P - R0012 - Other

No Asbestos

B00P - R0013 - Main Switch Board

No Asbestos

B00P - R0014 - Access Shower/Toilet/Change

No Asbestos

B00P - R0015 - Covered Outdoor Learning Area

No Asbestos

B00P - R0016 - Movement

No Asbestos

B00P - R0017 - Ramp

No Asbestos

B00P - R0018 - Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 810 - D13877 - FSU/Shelter/Stores : Placement Date - 20/05/2004

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Canteen

No Asbestos Found.

R2 - Covered Area

No Asbestos Found.

R3 - Store

No Asbestos Found.

R4 - Sports Store

No Asbestos Found.

R5 - Garden Store

No Asbestos Found.

R6 - Change Room

No Asbestos Found.

R7 - Store

No Asbestos Found.

NS 101 - D15685 - Learning Unit - Double Primary/PAA : Placement Date - 11/11/2014

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Home Base

No Asbestos Found.

R3 - Entry

No Asbestos Found.

R4 - Practical Activity Area

No Asbestos Found.

R5 - Home Base Store

No Asbestos Found.

R6 - Practical Activity Area

No Asbestos Found.

R7 - Entry

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017