


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Ashbury Public School (1064)
Region : Sydney
State Electorate : Summer Hill
Local Government Area : Canterbury

Initial Survey : Noel Arnold & Associates : 11 - Mar - 2008
Reviewed By : AECOM : 29 - Oct - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Tiered Learning - 1928 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00A - R0001 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R0001/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)	

B00A - R0002 - Cleaning Distributed Store

No Asbestos

B00A - R0003 - Disabled Shower/Toilet

Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
1064/B00A/R1020/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)	

B00A - R0005 - Movement

No Asbestos

B00A - R0006 - Home Base

Chalk Board	Compressed AC Sheet	6m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R0011/Chalk Board/S3					Chrysotile (white asbestos)	

Ceiling Structures/Linings	Flat AC Sheeting	10m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R0001/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)	

B00A - R0007 - Home Base

No Asbestos

B00A - R0008 - Home Base

No Asbestos

B00A - R0009 - Home Base

Chalk Board	Compressed AC Sheet	6m2	East facing, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R0011/Chalk Board/S3					Chrysotile (white asbestos)	

B00A - R0010 - Home Base

No Asbestos

B00A - R0011 - Home Base

Chalk Board	Compressed AC Sheet	6m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R0011/Chalk Board/S3					Chrysotile (white asbestos)	

Ceiling Structures/Linings	Flat AC Sheeting	10m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R0001/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)	

B00A - R0012 - Movement

No Asbestos

B00A - R0013 - External Movement

Gable End	Flat AC Sheeting	2m2	Central, Western Side of Block A	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R0013/Gable End/S8					Chrysotile (white asbestos)	

Ceiling Structures/Linings	Flat AC Sheeting	8m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R0001/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)	

B00A - R0014 - External Movement

No Asbestos

B00A - R0015 - Cleaning Distributed Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0016 - Movement						
No Asbestos						
B00A - R0017 - Security Store						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
1064/B00A/R1020/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)	
B00A - R0018 - Withdrawal Space - 1hb						
No Asbestos						
B00A - R0019 - Special Programs Room						
No Asbestos						
B00A - R0020 - Communal Space						
No Asbestos						
B00A - R0021 - Practical Activities - 1hb						
Floor Coverings Res/Textile	Vinyl Tiles	31m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
1064/B00A/R1020/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)	
B00A - R0022 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R0022/Ceiling Structures/Linings/S13					Chrysotile (white asbestos)	
B00A - R0023 - Distribution Board						
Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R0023/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)	
B00A - R0024 - Special Programs Room						
No Asbestos						
B00A - R0025 - Cleaning Distributed Store						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
1064/B00A/R1020/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)	
B00A - R0026 - Movement						
No Asbestos						
B00A - R0027 - Stairs						
No Asbestos						
B00A - R0028 - Stairs						
No Asbestos						
B00A - R0029 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	12.5m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R0001/Ceiling Structures/Linings/S12					Chrysotile (white asbestos)	
B00A - R0030 - External Movement						
Ceiling Structures/Linings	No Asbestos Found					
B00A - R1001 - Movement						
No Asbestos						
B00A - R1002 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R1002/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)	
B00A - R1003 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	22m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R1002/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)	
B00A - R1004 - Craft Store						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00A/R1002/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00A/R1004/Floor Coverings Res/Textile/S7				Chrysotile (white asbestos)	
B00A - R1005 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00A/R1002/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
B00A - R1006 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	49m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00A/R1002/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
B00A - R1007 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00A/R1002/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
B00A - R1008 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00A/R1002/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
B00A - R1009 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00A/R1002/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
B00A - R1010 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00A/R1002/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
B00A - R1011 - Toilets - Girls						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00A/R1002/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
B00A - R1012 - Toilets - Boys						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00A/R1002/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
B00A - R1013 - Cleaning Distributed Store						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00A/R1002/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00A/R1020/Floor Coverings Res/Textile/S6				Chrysotile (white asbestos)	
B00A - R1014 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	35m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00A/R1002/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
B00A - R1015 - Personal Effects Storage						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00A/R1002/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
B00A - R1016 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00A/R1002/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)	
B00A - R1017 - Security Store						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R1018 - Special Programs Room						
Ceiling Structures/Linings	Flat AC Sheeting	31m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R1002/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)	
B00A - R1019 - Communal Space						
Ceiling Structures/Linings	Flat AC Sheeting	89m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R1002/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)	
B00A - R1020 - Practical Activities - 1hb						
Ceiling Structures/Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R1002/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles	30m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
1064/B00A/R1020/Floor Coverings Res/Textile/S6					Chrysotile (white asbestos)	
B00A - R1021 - Staff Room Annexe						
Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R1002/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)	
B00A - R1022 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R0022/Ceiling Structures/Linings/S13					Chrysotile (white asbestos)	
B00A - R1023 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R0022/Ceiling Structures/Linings/S13					Chrysotile (white asbestos)	
B00A - Room+1 - AR1022						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R1002/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)	
B00A - Room+2 - AR1023						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00A/R1002/Ceiling Structures/Linings/S15					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration/Communal Facilities - 1977 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	65m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00B/Room+1/Ceiling Structures/Linings/S9				Chrysotile (white asbestos)	
Underfloor Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00B - R0010 - Canteen

No Asbestos

B00B - R0015 - External Movement

No Asbestos

B00B - R0017 - External Movement

No Asbestos

B00B - R0018 - Stairs

No Asbestos

B00B - R0019 - Hall Chair Store

No Asbestos

B00B - R0021 - Canteen Office/Store

No Asbestos

B00B - R0022 - Toilets - Girls

No Asbestos

B00B - R0023 - Toilet - Lobby

No Asbestos

B00B - R0024 - Toilets - Boys

No Asbestos

B00B - R0025 - Sound Cupboard

No Asbestos

B00B - R0026 - General Storeroom

No Asbestos

B00B - R0027 - Cleaning Distributed Store

No Asbestos

B00B - R0028 - Communal Space

No Asbestos

B00B - R0029 - Movement

No Asbestos

B00B - R0030 - Raised Platform

No Asbestos

B00B - R0031 - Hall Chair Store

No Asbestos

B00B - R0032 - Communal/Performance Store

No Asbestos

B00B - R0033 - Main Switch Board

Air Conditioning Unit	Flat AC Sheeting					
	1064/B00B/R0033/Air Conditioning Unit/S14				No Asbestos Detected	

B00B - R0034 - Canteen Office/Store

No Asbestos

B00B - R1002 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00B/R1012/Floor Coverings Res/Textile/S10				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
B00B - R1003 - Staff Toilet						
Partition Walls (Cubicles)	Compressed AC Sheet	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00B/R0005/Partition Walls (Cubicles)/S4				Chrysotile (white asbestos)		
B00B - R1004 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00B/R1012/Floor Coverings Res/Textile/S10				Chrysotile (white asbestos)		
B00B - R1005 - Deputy Principal						
Floor Coverings Res/Textile	Vinyl Tiles	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00B/R1012/Floor Coverings Res/Textile/S10				Chrysotile (white asbestos)		
B00B - R1006 - Sick Bay						
Floor Coverings Res/Textile	Vinyl Tiles	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00B/R1012/Floor Coverings Res/Textile/S10				Chrysotile (white asbestos)		
B00B - R1007 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00B/R1012/Floor Coverings Res/Textile/S10				Chrysotile (white asbestos)		
B00B - R1008 - Staff Room Annexe						
Floor Coverings Res/Textile	Vinyl Tiles	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00B/R1012/Floor Coverings Res/Textile/S10				Chrysotile (white asbestos)		
B00B - R1009 - Principal						
No Asbestos						
B00B - R1010 - Clerical Office/Workroom						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00B/R1012/Floor Coverings Res/Textile/S10				Chrysotile (white asbestos)		
B00B - R1011 - Clerical Office/Workroom						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00B/R1012/Floor Coverings Res/Textile/S10				Chrysotile (white asbestos)		
B00B - R1012 - Entry Vestibule						
Floor Coverings Res/Textile	Vinyl Tiles	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00B/R1012/Floor Coverings Res/Textile/S10				Chrysotile (white asbestos)		
B00B - R1013 - Duplicating Workroom						
Floor Coverings Res/Textile	Vinyl Tiles	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00B/R1012/Floor Coverings Res/Textile/S10				Chrysotile (white asbestos)		
B00B - R1014 - Cleaning Distributed Store						
Floor Coverings Res/Textile	Vinyl Tiles	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00B/R1012/Floor Coverings Res/Textile/S10				Chrysotile (white asbestos)		
B00B - R1015 - Staff Toilet						
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00B/R0005/Partition Walls (Cubicles)/S4				Chrysotile (white asbestos)		
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00B/R1012/Floor Coverings Res/Textile/S10				Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Vinyl Tiles	NA	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00B/R1012/Floor Coverings Res/Textile/S10				Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Vinyl Tiles	NA	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00B/R0005/Partition Walls (Cubicles)/S4				Chrysotile (white asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R1017 - Movement						
No Asbestos						
B00B - R1018 - Movement						
No Asbestos						
B00B - R1019 - Stairs						
No Asbestos						
B00B - R1020 - Staff Room						
No Asbestos						
B00B - R1021 - Staff Kitchen						
No Asbestos						
B00B - Room+1 - AR1017						
Ceiling Structures/Linings	Flat AC Sheeting	75m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00B/Room+1/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	1064/B00B/Room+1/Wall Linings Internal/S11					
B00B - Room+2 - BR1018						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00B/Room+1/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	1064/B00B/Room+1/Wall Linings Internal/S11					
B00B - Room+3 - BR1019						
Ceiling Structures/Linings	Flat AC Sheeting	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00B/Room+1/Ceiling Structures/Linings/S9					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	1064/B00B/Room+1/Wall Linings Internal/S11					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Library - 1978 - Concrete (Concrete)

Exterior

AC Pipe	Fibre Cement Pipe	1m	South-west Penetrating Roof Slab	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Could not access with standard						
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00C - R0001 - Reading Area

No Asbestos

B00C - R0002 - Toilets - Girls

No Asbestos

B00C - R0003 - Cleaning Distributed Store

No Asbestos

B00C - R0004 - Entry Vestibule

No Asbestos

B00C - R0005 - Toilets - Boys

No Asbestos

B00C - R0006 - Distribution Board

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00D/R0001/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	

B00C - R0007 - Communications Room

Floor Coverings Res/Textile	Vinyl Tiles	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00C/R0007/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	

B00C - R0008 - Library Office/Workroom

Floor Coverings Res/Textile	Vinyl Tiles	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00C/R0007/Floor Coverings Res/Textile/S5					Chrysotile (white asbestos)	

B00C - R0009 - Seminar/Study

No Asbestos

B00C - R0010 - K.L.A. Store

No Asbestos

B00C - R0011 - Library Office/Workroom

No Asbestos

B00C - R0012 - External Movement

No Asbestos

B00C - R0013 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1928 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00D - R0001 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00D/R0001/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet					
1064/B00D/R0002/Partition Walls (Cubicles)/S1					No Asbestos Detected	

B00D - R0002 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1064/B00D/R0001/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet					
1064/B00D/R0002/Partition Walls (Cubicles)/S1					No Asbestos Detected	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1977 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00E - R0001 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00D/R0001/Ceiling Structures/Linings/S16				Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet					
	1064/B00D/R0002/Partition Walls (Cubicles)/S1				No Asbestos Detected	

B00E - R0002 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00D/R0001/Ceiling Structures/Linings/S16				Chrysotile (white asbestos)	
Partition Walls (Cubicles)	Compressed AC Sheet					
	1064/B00D/R0002/Partition Walls (Cubicles)/S1				No Asbestos Detected	

B00E - R0003 - P.E. Store

Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1064/B00D/R0001/Ceiling Structures/Linings/S16				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00G - R0001 - Home Base

No Asbestos

B00G - R0002 - Home Base Store

No Asbestos

B00G - R0003 - Practical Activities - 1hb

No Asbestos

B00G - R0004 - Withdrawal Space - 2hb

No Asbestos

B00G - R0005 - Home Base

No Asbestos

B00G - R0006 - Home Base Store

No Asbestos

B00G - R0007 - Practical Activities - 1hb

No Asbestos

B00G - R0008 - Garden Store

No Asbestos

B00G - R0009 - General Assistant/Bulk Store

No Asbestos

B00G - R0010 - Sports Store

No Asbestos

B00G - R0011 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 603 - D12952 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 9/12/2004

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017