


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Auburn West Public School (1075)  
**Region :** South Western Sydney  
**State Electorate :** Auburn  
**Local Government Area :** Auburn

**Initial Survey :** Noel Arnold & Associates : 13 - Mar - 2008  
**Reviewed By :** Parsons Brinckerhoff : 03 - Jan - 2017



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Administration/Library - 1934 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	--------------	--------------------	---------	--------------------

**Assumed Asbestos - Not accessible due to height >6**

Ceiling Void	No Asbestos Found					
--------------	-------------------	--	--	--	--	--

Underfloor Voids	No Asbestos Found					
------------------	-------------------	--	--	--	--	--

**Interior**

**B00B - R0002 - Main Switch Board**

No Asbestos

**B00B - R0003 - Entry Vestibule**

No Asbestos

**B00B - R0005 - Movement**

No Asbestos

**B00B - R0006 - Movement**

No Asbestos

**B00B - R0009 - Entry Vestibule**

No Asbestos

**B00B - R0010 - General Storeroom**

No Asbestos

**B00B - R0016 - Interview**

No Asbestos

**B00B - R0017 - Cleaning Distributed Store**

No Asbestos

**B00B - R0018 - Entry Vestibule**

No Asbestos

**B00B - R0019 - Movement**

No Asbestos

**B00B - R0020 - Duplicating Workroom**

No Asbestos

**B00B - R0021 - Security Store**

No Asbestos

**B00B - R0022 - Access Shower/Toilet**

No Asbestos

**B00B - R0023 - Sick Bay**

No Asbestos

**B00B - R0024 - Security Store**

No Asbestos

**B00B - R0025 - Security Store**

No Asbestos

**B00B - R0026 - Staff Toilet**

No Asbestos

**B00B - R0027 - Staff Toilet**

No Asbestos

**B00B - R0028 - Staff Toilet**

No Asbestos

**B00B - R0029 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0030 - Security Store**

No Asbestos

**B00B - R0031 - Deputy Principal**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
	<b>B00B - R0032 - Deputy Principal</b>					
No Asbestos						
	<b>B00B - R0033 - Principal</b>					
No Asbestos						
	<b>B00B - R0034 - Clerical Office</b>					
No Asbestos						
	<b>B00B - R0035 - Clerical Office</b>					
No Asbestos						
	<b>B00B - R0036 - Movement</b>					
No Asbestos						
	<b>B00B - R0037 - Staff Room</b>					
No Asbestos						
	<b>B00B - R0038 - Movement</b>					
No Asbestos						
	<b>B00B - R0039 - Stairs</b>					
No Asbestos						
	<b>B00B - R0040 - Staff Room Annexe</b>					
No Asbestos						
	<b>B00B - R1001 - K.L.A. Store</b>					
No Asbestos						
	<b>B00B - R1005 - Special Programs Room</b>					
No Asbestos						
	<b>B00B - R1010 - Special Programs Store</b>					
No Asbestos						
	<b>B00B - R1011 - Distribution Board</b>					Note: No inspection of live electrical installation.
No Asbestos						
	<b>B00B - R1012 - Stairs</b>					
No Asbestos						
	<b>B00B - R1013 - Movement</b>					
No Asbestos						
	<b>B00B - R1015 - Library Office/Workroom</b>					
No Asbestos						
	<b>B00B - R1016 - Communications Room</b>					
No Asbestos						
	<b>B00B - R1017 - Staff Toilet</b>					
No Asbestos						
	<b>B00B - R1018 - Cleaning Distributed Store</b>					
No Asbestos						
	<b>B00B - R1019 - Distribution Board</b>					Note: No inspection of live electrical installation.
No Asbestos						
	<b>B00B - R1020 - Special Programs Room</b>					
No Asbestos						
	<b>B00B - R1021 - Reading Area</b>					
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - General Learning - 2002 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00L - R0001 - Toilets - Girls**

No Asbestos

**B00L - R0002 - Toilets - Boys**

No Asbestos

**B00L - R0003 - Laundry - Type 2**

No Asbestos

**B00L - R0004 - Access Shower/Toilet - Type 2**

No Asbestos

**B00L - R0005 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00L - R0006 - Practical Activities - 1hb**

No Asbestos

**B00L - R0007 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00L - R0008 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00L - R0009 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00L - R0010 - Practical Activities - 1hb**

No Asbestos

**B00L - R0011 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00L - R0012 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00L - R0013 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00L - R0014 - Practical Activities - 1hb**

No Asbestos

**B00L - R0015 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00L - R0016 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00L - R0017 - Practical Activities - 1hb**

No Asbestos

**B00L - R0018 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00L - R0019 - Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00L - R0020 - Distribution Board</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00L - R0021 - Stairs</b>						
No Asbestos						
<b>B00L - R0022 - No Access</b>						
No Asbestos						
<b>B00L - R0023 - No Access</b>						
No Asbestos						
<b>B00L - R0024 - Stairs</b>						
No Asbestos						
<b>B00L - R0025 - Movement</b>						
No Asbestos						
<b>B00L - R1001 - Special Programs Room</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00L - R1002 - Special Programs Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00L - R1003 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00L - R1004 - Disabled Toilet</b>						
No Asbestos						
<b>B00L - R1005 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00L - R1006 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00L - R1007 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00L - R1008 - Withdrawal Space - 2hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00L - R1009 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00L - R1010 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00L - R1011 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00L - R1012 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00L - R1013 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00L - R1014 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00L - R1015 - Withdrawal Space - 2hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00L - R1016 - Home Base</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00L - R1017 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00L - R1018 - Practical Activities - 1hb**

No Asbestos

**B00L - R1019 - Movement**

No Asbestos

**B00L - R1020 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00L - R1021 - No Access**

No Asbestos

**B00L - R1022 - Stairs**

No Asbestos

**B00L - R1023 - Stairs**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00M - R0001 - Movement**

No Asbestos

**B00M - R0002 - Practical Activities - 1hb**

No Asbestos

**B00M - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00M - R0004 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00M - R0005 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00M - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00M - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00M - R0008 - Practical Activities - 1hb**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00N - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00N - R0001 - Movement**

No Asbestos

**B00N - R0002 - Practical Activities - 1hb**

No Asbestos

**B00N - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00N - R0004 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00N - R0005 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00N - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00N - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00N - R0008 - Practical Activities - 1hb**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B000 - General Learning - 2004 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B000 - R0001 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B000 - R0002 - Practical Activities - 1hb**

No Asbestos

**B000 - R0003 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B000 - R0004 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B000 - R0005 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B000 - R0006 - Practical Activities - 1hb**

No Asbestos

**B000 - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B000 - R0008 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B000 - R0009 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B000 - R0010 - Practical Activities - 1hb**

No Asbestos

**B000 - R0011 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B000 - R0012 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B000 - R0013 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B000 - R0014 - Practical Activities - 1hb**

No Asbestos

**B000 - R0015 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B000 - R0016 - Movement**

No Asbestos

**B000 - R1001 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B000 - R1002 - Practical Activities - 1hb**

No Asbestos

**B000 - R1003 - Home Base**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B000 - R1004 - Withdrawal Space - 2hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B000 - R1005 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B000 - R1006 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B000 - R1007 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B000 - R1008 - Distribution Board</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B000 - R1009 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B000 - R1010 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B000 - R1011 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B000 - R1012 - Withdrawal Space - 2hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B000 - R1013 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B000 - R1014 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B000 - R1015 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B000 - R1016 - Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00P - Communal Facilities - 2004 - Brick/Veneer (Brick/Veneer)****Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

**Interior****B00P - R0001 - Access Shower/Toilet**

No Asbestos

**B00P - R0002 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00P - R0003 - Cleaning Distributed Store**

No Asbestos

**B00P - R0004 - Communications Cupboard**

No Asbestos

**B00P - R0005 - Toilets - Girls**

No Asbestos

**B00P - R0006 - Garden Store**

No Asbestos

**B00P - R0007 - Hall Chair Store**

No Asbestos

**B00P - R0008 - Movement**

No Asbestos

**B00P - R0009 - Raised Platform**

No Asbestos

**B00P - R0010 - Movement**

No Asbestos

**B00P - R0011 - Communal/Performance Store**

No Asbestos

**B00P - R0012 - Cleaning Supplies**

No Asbestos

**B00P - R0013 - General Assistant/Bulk Store**

No Asbestos

**B00P - R0014 - P.E. Store**

No Asbestos

**B00P - R0015 - Sports Store**

No Asbestos

**B00P - R0016 - Toilets - Boys**

No Asbestos

**B00P - R0017 - Communal Space**

No Asbestos

**B00P - R0018 - Canteen**

No Asbestos

**B00P - R0019 - Canteen Office/Store**

No Asbestos

**B00P - R0020 - Toilets - Girls**

No Asbestos

**B00P - R0021 - Kiln Room**

No Asbestos

**B00P - R0022 - Toilets - Boys**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00P - R0023 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00Q - Other - 2007 - Steel (Steel)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00Q - R0001 - Community Clinic**

No Asbestos

**B00Q - R0002 - Community Clinic**

No Asbestos

**B00Q - R0003 - Community Clinic**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00T - General Learning - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00T - R0001 - Practical Activities**

No Asbestos

**B00T - R0002 - Home Base**

No Asbestos

**B00T - R0003 - Home Base Store**

No Asbestos

**B00T - R0004 - Withdrawal Space - 1hb**

No Asbestos

**B00T - R0005 - Practical Activities**

No Asbestos

**B00T - R0006 - Home Base**

No Asbestos

**B00T - R0007 - Home Base Store**

No Asbestos

**B00T - R0008 - Withdrawal Space - 1hb**

No Asbestos

**B00T - R0009 - Practical Activities**

No Asbestos

**B00T - R0010 - Home Base**

No Asbestos

**B00T - R0011 - Communications Cupboard**

No Asbestos

**B00T - R0012 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00T - R0013 - External Movement**

No Asbestos

**B00T - R0014 - External Stairs**

No Asbestos

**B00T - R1001 - Home Base**

No Asbestos

**B00T - R1002 - Home Base Store**

No Asbestos

**B00T - R1003 - Withdrawal Space - 1hb**

No Asbestos

**B00T - R1004 - Practical Activities**

No Asbestos

**B00T - R1005 - Home Base**

No Asbestos

**B00T - R1006 - Home Base Store**

No Asbestos

**B00T - R1007 - Withdrawal Space - 1hb**

No Asbestos

**B00T - R1008 - Practical Activities**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00T - R1009 - Home Base</b>						
No Asbestos						
<b>B00T - R1010 - Home Base Store</b>						
No Asbestos						
<b>B00T - R1011 - Practical Activities</b>						
No Asbestos						
<b>B00T - R1012 - External Movement</b>						
No Asbestos						
<b>B00T - R1013 - External Stairs</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00U - Special Purpose/General Learning - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00U - R0001 - External Movement**

No Asbestos

**B00U - R0002 - Special Programs Room - Type 2**

No Asbestos

**B00U - R0003 - Special Programs Store**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 603 - D10083 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 1/10/2003**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D10634 - Learning Unit - Standard With P.A.A. : Placement Date - 16/02/2008**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D11765 - Learning Unit - Standard With P.A.A. : Placement Date - 11/03/2008**

**Exterior**

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

**Interior**

**R1 - Learning space/withdrawal/entry**

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

**R2 - Home Base Store**

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

**OS 602 - D12252 - Learning Unit - Standard With P.A.A. : Placement Date - 16/02/2008**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 603 - D12317 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 28/03/2013**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 603 - D12728 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 7/10/2003**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 603 - D12861 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 8/10/2003**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 603 - D12863 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 9/10/2003**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 603 - D12904 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 3/10/2003**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 750 - D14057 - Learning Unit - ESL : Placement Date - 30/06/1995**

**Exterior**

Eave Lining	Flat AC Sheet	Assumed Asbestos	5.76 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Esl</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
<b>OS 603 - D14662 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 30/09/2003</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 603 - D15871 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 7/10/2003</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 750 - D17731 - Learning Unit - ESL : Placement Date - 14/12/2013</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Esl</b>						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017