

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Albert Park Public School (4177)
Region : North Coast
State Electorate : Lismore
Local Government Area : Lismore

Initial Survey : Noel Arnold & Associates : 11 - Jun - 2008
Reviewed By : Parsons Brinckerhoff : 08 - Oct - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Administration/General Learning - 1942 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting 4177/B00A/Eaves Linings/S6					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00A - R0001 - Interview**

No Asbestos

B00A - R0002 - Movement

No Asbestos

B00A - R0003 - Security Store

No Asbestos

B00A - R0004 - Principal

No Asbestos

B00A - R0006 - Sick Bay

No Asbestos

B00A - R0007 - Staff Room

No Asbestos

B00A - R0008 - Clerical Office

No Asbestos

B00A - R0009 - Entry Vestibule

No Asbestos

B00A - R0010 - Communications Room

No Asbestos

B00A - R0013 - Movement

No Asbestos

B00A - R0014 - Home Base

No Asbestos

B00A - R0015 - Practical Activities - 1hb

No Asbestos

B00A - R0016 - Withdrawal Space - 1hb

No Asbestos

B00A - R0017 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0018 - Cleaning Distributed Store

No Asbestos

B00A - R0019 - Home Base

No Asbestos

B00A - R0020 - Practical Activities - 1hb

No Asbestos

B00A - R0021 - External Movement

No Asbestos

B00A - R0023 - Practical Activities - 1hb

No Asbestos

B00A - R0024 - Withdrawal Space - 1hb

No Asbestos

B00A - R0027 - General Storeroom

No Asbestos

B00A - R0028 - External Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
No Asbestos						
B00A - R0029 - Home Base						
No Asbestos						
B00A - R0030 - Toilet - Lobby						
No Asbestos						
B00A - R0031 - Staff Toilet						
No Asbestos						
B00A - R0032 - Staff Shower/Change						
No Asbestos						
B00A - R0033 - Communal Space						
No Asbestos						
B00A - R9001 - Movement						
No Asbestos						
B00A - R9002 - Other-Not Used						
Ceiling Structures/Linings	Flat AC Sheeting	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4177/B00A/R9002/Ceiling Structures/Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R9003 - Raised Platform						
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4177/B00A/R9003/Ceiling Structures/Linings/S11				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R9004 - General Storeroom						
No Asbestos						
B00A - R9005 - Main Switch Board						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4177/B00A/R9005/Ceiling Structures/Linings/S12				Chrysotile (white asbestos)		
Electrical Mounting Board	Resinous Board	2m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
4177/B00A/R9005/Electrical Mounting Board/S13				Chrysotile (white asbestos)		
B00A - R9006 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	78m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4177/B00A/R9006/Ceiling Structures/Linings/S14				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R9007 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles	1m2	East	Minimal Damage (2)	Medium (2)	Medium Priority (4-5)
4177/B00A/R9007/Floor Coverings Res/Textile/S16				Chrysotile (white asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4177/B00A/R9007/Ceiling Structures/Linings/S15				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R9008 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4177/B00A/R9008/Ceiling Structures/Linings/S17				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00A - R9009 - Canteen						
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4177/B00A/R9009/Ceiling Structures/Linings/S18				Chrysotile (white asbestos) , Amosite (brown asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Music - 1964 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	4m2	North and South	Minimal Damage (2)	Medium (2)	Medium Priority (4-5)
	4177/B00B/Gable Verge Lining/S8			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Eaves Linings	Flat AC Sheeting	10m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
	4177/B00B/Eaves Linings/S7			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior

B00B - R0001 - Home Base Store

No Asbestos

B00B - R0002 - Home Base

No Asbestos

B00B - R0003 - Withdrawal Space - 1hb

Floor Coverings Res/Textile	Vinyl Tiles					
	4177/B00B/R0003/Floor Coverings Res/Textile/S1				No Asbestos Detected	

B00B - R0004 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4177/B00B/R0004/Ceiling Structures/Linings/S19			Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Pupil Facilities - 1942 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	150m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4177/B00C/Eaves Linings/S9				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior

B00C - R0001 - No Access

Floor Coverings Res/Textile	Vinyl Tiles					
	4177/B00C/R0005/Floor Coverings Res/Textile/S2				No Asbestos Detected	

B00C - R0002 - Staff Room Annexe

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4177/B00C/R0002/Ceiling Structures/Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00C - R0003 - Movement

Floor Coverings Res/Textile	Vinyl Tiles					
	4177/B00C/R0005/Floor Coverings Res/Textile/S2				No Asbestos Detected	
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4177/B00C/R0003/Ceiling Structures/Linings/S21				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00C - R0004 - Duplicating Workroom

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4177/B00C/R0004/Ceiling Structures/Linings/S22				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00C - R0005 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles					
	4177/B00C/R0005/Floor Coverings Res/Textile/S2				No Asbestos Detected	
Ceiling Structures/Linings	Flat AC Sheeting	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4177/B00C/R0005/Ceiling Structures/Linings/S23				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00C - R0006 - Home Base

No Asbestos

B00C - R0007 - Home Base

No Asbestos

B00C - R0008 - Home Base

No Asbestos

B00C - R0009 - Movement

Floor Coverings Res/Textile	Vinyl Tiles					
	4177/B00C/R0005/Floor Coverings Res/Textile/S2				No Asbestos Detected	

B00C - R0010 - Withdrawal Space - 1hb

No Asbestos

B00C - R0011 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Tiles					
	4177/B00C/R0005/Floor Coverings Res/Textile/S2				No Asbestos Detected	

B00C - R0012 - Withdrawal Space - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0013 - Practical Activities - 1hb						
Floor Coverings Res/Textile	Vinyl Tiles					
	4177/B00C/R0005/Floor Coverings Res/Textile/S2					No Asbestos Detected
Ceiling Structures/Linings	No Asbestos Found					
Ceiling Structures/Linings	No Asbestos Found					
Ceiling Structures/Linings	No Asbestos Found					
B00C - R0014 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles					
	4177/B00C/R0005/Floor Coverings Res/Textile/S2					No Asbestos Detected
B00C - R0015 - Home Base						
No Asbestos						
B00C - R0016 - Home Base Store						
No Asbestos						
B00C - R0017 - Toilets - Boys/Girls						
No Asbestos						
B00C - R0018 - Staff Toilet						
No Asbestos						
B00C - R9001 - Cleaning Distributed Store						
No Asbestos						
B00C - R9002 - Sports Store						
No Asbestos						
B00C - R9003 - Staff Shower/Change						
No Asbestos						
B00C - R9004 - Staff Shower/Change						
No Asbestos						
B00C - R9005 - Movement						
No Asbestos						
B00C - R9006 - Garden Store						
No Asbestos						
B00C - R9007 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1942 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00D - R0001 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4177/B00D/R0007/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)	

B00D - R0002 - Toilets - Girls

No Asbestos

B00D - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4177/B00D/R0003/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	

B00D - R0004 - Staff Toilet

No Asbestos

B00D - R0005 - Staff Toilet

No Asbestos

B00D - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0007 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4177/B00D/R0007/Partition Walls (Cubicles)/S4					Chrysotile (white asbestos)	

B00D - R0008 - External Movement

No Asbestos

B00D - R0009 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Building Services - 1994 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00E - R0001 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	4177/B00E/R0001/Ceiling Structures/Linings/S24					
Floor Coverings Res/Textile	Vinyl Tiles	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4177/B00E/R0001/Floor Coverings Res/Textile/S25					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Library - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00F - R0001 - Reading Area

No Asbestos

B00F - R0002 - Communications Room

No Asbestos

B00F - R0003 - K.L.A. Store

No Asbestos

B00F - R0004 - Library Office/Workroom

No Asbestos

B00F - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017