


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Ashcroft Public School (4344)
Region : South Western Sydney
State Electorate : Liverpool
Local Government Area : Liverpool

Initial Survey : Noel Arnold & Associates : 06 - May - 2008
Reviewed By : Greencap-NAA : 29 - May - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1962 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00C/Gable Verge Lining/S22				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Eaves Linings	Flat AC Sheeting	80m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00A/Eaves Linings/S21				Chrysotile (white asbestos)		
Ceiling Voids	No Asbestos Found					

Interior

B00A - R0001 - Clerical Office

Floor Coverings Res/Textile	Vinyl Sheet					No Asbestos Detected
4344/B00A/R0001/Floor Coverings Res/Textile/S20						

B00A - R0002 - Clerical Office

Floor Coverings Res/Textile	Vinyl Sheet					No Asbestos Detected
4344/B00A/R0001/Floor Coverings Res/Textile/S20						

B00A - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00A/R0003/Ceiling Structures/Linings/S19				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
In-fill-panel	Flat AC Sheeting	1m	East, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00B/R0006/In-fill-panel/S4				Chrysotile (white asbestos)		

B00A - R0004 - Entry Vestibule

No Asbestos

B00A - R0005 - Principal

Floor Coverings Res/Textile	Vinyl Sheet					No Asbestos Detected
4344/B00A/R0001/Floor Coverings Res/Textile/S20						

B00A - R0006 - Movement

Floor Coverings Res/Textile	Vinyl Tiles	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00A/R0006/Floor Coverings Res/Textile/S15				Chrysotile (white asbestos)		

B00A - R0007 - Staff Toilet

No Asbestos

B00A - R0008 - General Storeroom

No Asbestos

B00A - R0009 - General Storeroom

No Asbestos

B00A - R0010 - Plant

No Asbestos

B00A - R0011 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00A/R0006/Floor Coverings Res/Textile/S15				Chrysotile (white asbestos)		

B00A - R0012 - General Storeroom

Non Accessible

B00A - R0013 - Staff Room Annexe

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00A/R0006/Floor Coverings Res/Textile/S15				Chrysotile (white asbestos)		

B00A - R0014 - Main Switch Board

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting	3m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00A/R0014/Wall Linings Internal/S16					Chrysotile (white asbestos)	
B00A - R0015 - General Storeroom						
No Asbestos						
B00A - R0016 - Home Base						
No Asbestos						
B00A - R0017 - Home Base Store						
No Asbestos						
B00A - R0018 - General Storeroom						
No Asbestos						
B00A - R0019 - Movement						
No Asbestos						
B00A - R0020 - General Storeroom						
No Asbestos						
B00A - R0021 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00A/R0003/Ceiling Structures/Linings/S19					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
In-fill-panel	Flat AC Sheeting	1m	West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00B/R0006/In-fill-panel/S4					Chrysotile (white asbestos)	
B00A - R0022 - General Storeroom						
No Asbestos						
B00A - R0023 - General Storeroom						
No Asbestos						
B00A - R0024 - Duplicating Workroom						
No Asbestos						
B00A - R0025 - Staff Room Annexe						
No Asbestos						
B00A - R0026 - Home Base						
No Asbestos						
B00A - R0027 - Other-Vacant						
No Asbestos						
B00A - R0028 - Other-Vacant						
No Asbestos						
B00A - R0029 - Movement						
No Asbestos						
B00A - R0030 - Other-Vacant						
No Asbestos						
B00A - R0031 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00A/R0003/Ceiling Structures/Linings/S19					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
In-fill-panel	Flat AC Sheeting	1m	West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00B/R0006/In-fill-panel/S4					Chrysotile (white asbestos)	
B00A - R0032 - Other-Vacant						
No Asbestos						
B00A - R0033 - Home Base						
No Asbestos						
B00A - R0034 - General Storeroom						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration/General Learning - 1962 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00C/Gable Verge Lining/S22				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Eaves Linings	Flat AC Sheeting	60m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00A/Eaves Linings/S21				Chrysotile (white asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris	150m2	Variable positions	Minimal Damage (2)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Area inaccessible Bolted access door						
Underfloor Voids	Packing	150m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Area inaccessible Bolted access door						

Interior

B00B - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00B/R0001/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)		

B00B - R0002 - Staff Room Annexe

Floor Coverings Res/Textile	Vinyl Tiles	31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00B/R0002/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		

B00B - R0003 - Staff Toilet

Floor Coverings Res/Textile	Vinyl Tiles	2m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00B/R0002/Floor Coverings Res/Textile/S2				Chrysotile (white asbestos)		

B00B - R0004 - Staff Shower/Change

Wall Linings Internal	Flat AC Sheeting	12m2	Throughout, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00B/R0004/Wall Linings Internal/S1				Chrysotile (white asbestos)		

B00B - R0005 - Movement

No Asbestos

B00B - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00B/R0001/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)		
In-fill-panel	Flat AC Sheeting	1m	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00B/R0006/In-fill-panel/S4				Chrysotile (white asbestos)		

B00B - R0007 - Staff Room

No Asbestos

B00B - R0008 - General Storeroom

No Asbestos

B00B - R0009 - Cleaning Distributed Store

No Asbestos

B00B - R0010 - Movement

No Asbestos

B00B - R0011 - General Storeroom

No Asbestos

B00B - R0012 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00B/R0001/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
In-fill-panel	Flat AC Sheeting	1m	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00B/R0006/In-fill-panel/S4					Chrysotile (white asbestos)	
B00B - R0013 - General Storeroom						
No Asbestos						
B00B - R0014 - General Storeroom						
No Asbestos						
B00B - R0015 - Communal Space						
No Asbestos						
B00B - R0016 - Raised Platform						
No Asbestos						
B00B - R0017 - General Storeroom						
No Asbestos						
B00B - R0018 - General Storeroom						
No Asbestos						
B00B - R0019 - Movement						
No Asbestos						
B00B - R0020 - General Storeroom						
No Asbestos						
B00B - R0021 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00B/R0001/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
In-fill-panel	Flat AC Sheeting	1m	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00B/R0006/In-fill-panel/S4					Chrysotile (white asbestos)	
B00B - R0022 - General Storeroom						
No Asbestos						
B00B - R0023 - General Storeroom						
No Asbestos						
B00B - R0024 - Home Base						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1962 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)	
	4344/B00C/Gable Verge Lining/S22			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)			
Eaves Linings	Flat AC Sheeting	60m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)	
	4344/B00A/Eaves Linings/S21			Chrysotile (white asbestos)			
Ceiling Voids	No Asbestos Found						
Underfloor Voids	Packing					No Asbestos Detected	
	4344/B00C/Underfloor Voids/S23						

Interior

B00C - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00B/R0001/Ceiling Structures/Linings/S3			Chrysotile (white asbestos)		
In-fill-panel	Flat AC Sheeting	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00B/R0006/In-fill-panel/S4			Chrysotile (white asbestos)		

B00C - R0002 - Cleaning Distributed Store

No Asbestos

B00C - R0003 - No Access

No Asbestos

B00C - R0004 - No Access

No Asbestos

B00C - R0005 - Movement

No Asbestos

B00C - R0006 - Home Base

No Asbestos

B00C - R0007 - Home Base Store

No Asbestos

B00C - R0008 - Personal Effects Storage

No Asbestos

B00C - R0009 - Movement

No Asbestos

B00C - R0010 - Home Base Store

No Asbestos

B00C - R0011 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00B/R0001/Ceiling Structures/Linings/S3			Chrysotile (white asbestos)		
In-fill-panel	Flat AC Sheeting	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00B/R0006/In-fill-panel/S4			Chrysotile (white asbestos)		

B00C - R0012 - Home Base Store

No Asbestos

B00C - R0013 - Home Base Store

No Asbestos

B00C - R0014 - Home Base

No Asbestos

B00C - R0015 - Home Base

No Asbestos

B00C - R0016 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00C - R0017 - Personal Effects Storage

No Asbestos

B00C - R0018 - Movement

No Asbestos

B00C - R0019 - Home Base Store

No Asbestos

B00C - R0020 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	------------	--------------------	---------	--------------------

4344/B00B/R0001/Ceiling Structures/Linings/S3 **Chrysotile (white asbestos)**

In-fill-panel	Flat AC Sheeting	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	----	----------------------	--------------------	---------	--------------------

4344/B00B/R0006/In-fill-panel/S4 **Chrysotile (white asbestos)**

B00C - R0021 - Home Base Store

No Asbestos

B00C - R0022 - Home Base Store

No Asbestos

B00C - R0023 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1962 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00C/Gable Verge Lining/S22			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Eaves Linings	Flat AC Sheeting	60m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00A/Eaves Linings/S21			Chrysotile (white asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Packing	150m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00D/R0015/In-fill-panel/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior

B00D - R0001 - Home Base

No Asbestos

B00D - R0002 - Home Base Store

No Asbestos

B00D - R0003 - Personal Effects Storage

No Asbestos

B00D - R0004 - Movement

No Asbestos

B00D - R0005 - Home Base Store

No Asbestos

B00D - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00A/R0003/Ceiling Structures/Linings/S19			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
In-fill-panel	Flat AC Sheeting	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00D/R0015/In-fill-panel/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0007 - Home Base Store

No Asbestos

B00D - R0008 - Home Base Store

No Asbestos

B00D - R0009 - Home Base

No Asbestos

B00D - R0010 - Home Base

No Asbestos

B00D - R0011 - Home Base Store

No Asbestos

B00D - R0012 - Personal Effects Storage

No Asbestos

B00D - R0013 - Movement

No Asbestos

B00D - R0014 - Home Base Store

No Asbestos

B00D - R0015 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00A/R0003/Ceiling Structures/Linings/S19			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
In-fill-panel	Flat AC Sheeting 4344/B00D/R0015/In-fill-panel/S5	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0016 - Home Base Store

No Asbestos

B00D - R0017 - Home Base Store

No Asbestos

B00D - R0018 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Library - 1962 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids	Non Accessible Area - Extreme Access Issue - Access Restriction <0.5m height, width & length.					
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00C/Gable Verge Lining/S22			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Eaves Linings	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00A/Eaves Linings/S21			Chrysotile (white asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Height Restriction - Extreme Access Issue - Access Restriction <0.5m height, width & length.					

Interior

B00F - R0001 - K.L.A. Store

No Asbestos

B00F - R0002 - K.L.A. Store

No Asbestos

B00F - R0003 - K.L.A. Store

No Asbestos

B00F - R0004 - Movement

No Asbestos

B00F - R0005 - Seminar/Study

No Asbestos

B00F - R0006 - Movement

No Asbestos

B00F - R0007 - Movement


No Asbestos

B00F - R0008 - Reading Area

No Asbestos

B00F - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00B/R0001/Ceiling Structures/Linings/S3			Chrysotile (white asbestos)		
In-fill-panel	Flat AC Sheeting	1m	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00B/R0006/In-fill-panel/S4			Chrysotile (white asbestos)		



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1965 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00G - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4344/B00G/R0001/Ceiling Structures/Linings/S25					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00G - R0002 - Home Base

No Asbestos

B00G - R0003 - Home Base

No Asbestos

B00G - R0004 - General Storeroom

Wall Linings Internal	Flat AC Sheeting	12m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00G/R0004/Wall Linings Internal/S6					Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1965 - Timber (Timber)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00H - R0001 - General Storeroom

No Asbestos

B00H - R0002 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles	10m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00H/R0002/Floor Coverings Res/Textile/S8					Chrysotile (white asbestos)	
Bench Top	Compressed AC Sheet	3m2	East	Good Condition (1)	Medium (2)	Low Priority (2-3)
4344/B00H/R0002/Bench Top/S26					Chrysotile (white asbestos)	

B00H - R0003 - Home Base

No Asbestos

B00H - R0004 - Home Base Store

Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00H/R0004/Wall Linings Internal/S7					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	4344/B00G/R0001/Ceiling Structures/Linings/S25			No Asbestos Detected	

B00H - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	4344/B00G/R0001/Ceiling Structures/Linings/S25			No Asbestos Detected	
----------------------------	------------------	--	--	--	-----------------------------	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Pupil Facilities - 1964 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof Non Accessible Area
- Area inaccessible

Underfloor Voids - Slab on Ground

Interior

B001 - R0001 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
4344/B001/R0001/Ceiling Structures/Linings/S18						

B001 - R0002 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
4344/B001/R0001/Ceiling Structures/Linings/S18						

B001 - R0003 - Canteen

Ceiling Structures/Linings	Flat AC Sheeting	32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
4344/B001/R0001/Ceiling Structures/Linings/S18						

B001 - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos)	
4344/B001/R0001/Ceiling Structures/Linings/S18						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Administration - 1962 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00C/Gable Verge Lining/S22				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Eaves Linings	Flat AC Sheeting	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00A/Eaves Linings/S21				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00J - R0001 - Home Base

No Asbestos

B00J - R0002 - Other - Regional Use

Floor Coverings Res/Textile	Vinyl Sheet					
	4344/B00J/R0025/Floor Coverings Res/Textile/S28				No Asbestos Detected	

B00J - R0003 - Other - Regional Use

Floor Coverings Res/Textile	Vinyl Sheet					
	4344/B00J/R0025/Floor Coverings Res/Textile/S28				No Asbestos Detected	

B00J - R0004 - Movement

Floor Coverings Res/Textile	Vinyl Sheet					
	4344/B00J/R0025/Floor Coverings Res/Textile/S28				No Asbestos Detected	

B00J - R0005 - Other - Regional Use

No Asbestos

B00J - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00J/R0023/Ceiling Structures/Linings/S13				Chrysotile (white asbestos) , Amosite (brown asbestos)	

In-fill-panel	Flat AC Sheeting	1m	West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00B/R0006/In-fill-panel/S4				Chrysotile (white asbestos)	

B00J - R0007 - Other - Regional Use

No Asbestos

B00J - R0008 - Other - Regional Use

Floor Coverings Res/Textile	Vinyl Sheet					
	4344/B00J/R0025/Floor Coverings Res/Textile/S28				No Asbestos Detected	

B00J - R0009 - General Storeroom

Floor Coverings Res/Textile	Vinyl Sheet					
	4344/B00J/R0025/Floor Coverings Res/Textile/S28				No Asbestos Detected	

B00J - R0010 - Home Base

No Asbestos

B00J - R0011 - Home Base

No Asbestos

B00J - R0012 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00K/R0016/Floor Coverings Res/Textile/S11				Chrysotile (white asbestos)	

B00J - R0013 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00K/R0016/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)	
B00J - R0014 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00K/R0016/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)	
B00J - R0015 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00J/R0023/Ceiling Structures/Linings/S13				Chrysotile (white asbestos) , Amosite (brown asbestos)		
In-fill-panel	Flat AC Sheeting	1m	West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00B/R0006/In-fill-panel/S4					Chrysotile (white asbestos)	
B00J - R0016 - Cleaning Distributed Store						
Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00K/R0016/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)	
B00J - R0017 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00K/R0016/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)	
B00J - R0018 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00K/R0016/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)	
B00J - R0019 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00K/R0016/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)	
B00J - R0020 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00J/R0023/Ceiling Structures/Linings/S13				Chrysotile (white asbestos) , Amosite (brown asbestos)		
In-fill-panel	Flat AC Sheeting	1m	West, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00B/R0006/In-fill-panel/S4					Chrysotile (white asbestos)	
B00J - R0021 - Staff Toilet						
Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00K/R0016/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00J/R0021/Wall Linings Internal/S14					Chrysotile (white asbestos)	
B00J - R0022 - Interview						
No Asbestos						
B00J - R0023 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00J/R0023/Ceiling Structures/Linings/S13				Chrysotile (white asbestos) , Amosite (brown asbestos)		
In-fill-panel	Flat AC Sheeting	1m	East, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00B/R0006/In-fill-panel/S4					Chrysotile (white asbestos)	
B00J - R0024 - Sports Store						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Sink Splash Back	Fibre Cement Casting (Monocrete) 4344/B00J/R0024/Sink Splash Back/S27	2m2	North	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
B00J - R0025 - Staff Room Annexe						
Sink Splash Back	Fibre Cement Casting (Monocrete) 4344/B00J/R0024/Sink Splash Back/S27	3m2	East	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Sheet 4344/B00J/R0025/Floor Coverings Res/Textile/S28					No Asbestos Detected
B00J - R0026 - General Storeroom						
No Asbestos						
B00J - R0027 - No Access						
No Asbestos						
B00J - R0028 - No Access						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 1962 - Brick/Veneer (Brick/Veneer)**Exterior**

Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00C/Gable Verge Lining/S22			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Eaves Linings	Flat AC Sheeting	60m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00A/Eaves Linings/S21			Chrysotile (white asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00K - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00K/R0019/Ceiling Structures/Linings/S10			Chrysotile (white asbestos)		
In-fill-panel	Flat AC Sheeting	1m	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00B/R0006/In-fill-panel/S4			Chrysotile (white asbestos)		

B00K - R0002 - Toilets - Boys/Girls

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00K/R0019/Ceiling Structures/Linings/S10			Chrysotile (white asbestos)		

B00K - R0003 - Movement

No Asbestos

B00K - R0004 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00K/R0016/Floor Coverings Res/Textile/S11			Chrysotile (white asbestos)		

B00K - R0005 - Home Base

No Asbestos

B00K - R0006 - Home Base

No Asbestos

B00K - R0007 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00K/R0016/Floor Coverings Res/Textile/S11			Chrysotile (white asbestos)		

B00K - R0008 - Movement

No Asbestos

B00K - R0009 - Cleaning Distributed Store

No Asbestos

B00K - R0010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00K/R0019/Ceiling Structures/Linings/S10			Chrysotile (white asbestos)		
In-fill-panel	Flat AC Sheeting	1m	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00B/R0006/In-fill-panel/S4			Chrysotile (white asbestos)		

B00K - R0011 - General Storeroom

No Asbestos

B00K - R0012 - Personal Effects Storage

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00K/R0016/Floor Coverings Res/Textile/S11			Chrysotile (white asbestos)		

B00K - R0013 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00K/R0016/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)	
B00K - R0014 - Home Base						
No Asbestos						
B00K - R0015 - Home Base						
No Asbestos						
B00K - R0016 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00K/R0016/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)	
B00K - R0017 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00K/R0016/Floor Coverings Res/Textile/S11					Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting					
4344/B00K/R0017/Wall Linings Internal/S12					No Asbestos Detected	
B00K - R0018 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00K/R0019/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)	
In-fill-panel	Flat AC Sheeting	1m	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00B/R0006/In-fill-panel/S4					Chrysotile (white asbestos)	
B00K - R0019 - Toilets - Boys/Girls						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4344/B00K/R0019/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)	
B00K - R0020 - Outdoor Learning Area						
No Asbestos						
B00K - R0021 - Outdoor Learning Area						
No Asbestos						
B00K - R0022 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning - 1962 - Brick/Veneer (Brick/Veneer)

Exterior

Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00C/Gable Verge Lining/S22			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Eaves Linings	Flat AC Sheeting	60m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00A/Eaves Linings/S21			Chrysotile (white asbestos)		
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00L - R0001 - Home Base

No Asbestos

B00L - R0002 - Home Base Store

No Asbestos

B00L - R0003 - Personal Effects Storage

No Asbestos

B00L - R0004 - Movement

No Asbestos

B00L - R0005 - General Storeroom

No Asbestos

B00L - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00A/R0003/Ceiling Structures/Linings/S19			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
In-fill-panel	Flat AC Sheeting	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00B/R0006/In-fill-panel/S4			Chrysotile (white asbestos)		

B00L - R0007 - Other-Vacant

No Asbestos

B00L - R0008 - Home Base Store

No Asbestos

B00L - R0009 - Home Base

No Asbestos

B00L - R0010 - Home Base

No Asbestos

B00L - R0011 - Home Base Store

No Asbestos

B00L - R0012 - Personal Effects Storage

No Asbestos

B00L - R0013 - Movement

No Asbestos

B00L - R0014 - General Storeroom

No Asbestos

B00L - R0015 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00A/R0003/Ceiling Structures/Linings/S19			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
In-fill-panel	Flat AC Sheeting	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00B/R0006/In-fill-panel/S4			Chrysotile (white asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00L - R0016 - Cleaning Distributed Store						
No Asbestos						
B00L - R0017 - Home Base Store						
No Asbestos						
B00L - R0018 - Home Base						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Other - 1965 - Timber (Timber)

Exterior

Underfloor Voids	No Asbestos Found					
Ceiling Voids	Non Accessible Area - Area inaccessible					

Interior

B00M - R0001 - Other

Ceiling Structures/Linings	Flat AC Sheeting 4344/B00M/R0001/Ceiling Structures/Linings/S9					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00M - R0002 - Other

No Asbestos						
-------------	--	--	--	--	--	--

B00M - R0003 - Other

No Asbestos						
-------------	--	--	--	--	--	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Pupil Facilities/Building Services - 1962 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00A/Eaves Linings/S21					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00N - R0001 - Drinking Facilities

No Asbestos

B00N - R0002 - Toilets - Boys

No Asbestos

B00N - R0003 - Cleaning Supplies

No Asbestos

B00N - R0004 - Cleaning Supplies

No Asbestos

B00N - R0005 - No Access

No Asbestos

B00N - R0006 - General Storeroom

No Asbestos

B00N - R0007 - Toilets - Girls

No Asbestos

B00N - R0008 - Drinking Facilities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Pupil Facilities - 1962 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	10m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00A/Eaves Linings/S21				Chrysotile (white asbestos)	
Underfloor Voids	Non Accessible Area - Area inaccessible					
Ceiling Voids	No Asbestos Found					

Interior

B000 - R0001 - Handwashing Facilities

No Asbestos

B000 - R0002 - Toilets - Boys

No Asbestos

B000 - R0003 - Drinking Facilities

No Asbestos

B000 - R0004 - Toilets - Girls

No Asbestos

B000 - R0005 - Handwashing Facilities

No Asbestos

B000 - R0006 - Movement

No Asbestos

B000 - R0007 - Cleaning Distributed Store

Stored Sheet	Flat AC Sheeting	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	4344/B00O/R0007/Stored Sheet/S24				Chrysotile (white asbestos)	

B000 - R0008 - Cleaning Distributed Store

No Asbestos

B000 - R0009 - General Storeroom

No Asbestos

B000 - R0010 - Garden Store

No Asbestos

B000 - R0011 - No Access

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Pre-School Facilities - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00P - R0001 - Movement

No Asbestos

B00P - R0002 - Entry Vestibule

No Asbestos

B00P - R0003 - Security Store

No Asbestos

B00P - R0004 - General Storeroom - Pre

No Asbestos

B00P - R0005 - Home Base - Pre

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00P - R0006 - Practical Activities - Pre

No Asbestos

B00P - R0007 - Toilets - Boys/Girls - Pre

No Asbestos

B00P - R0008 - Laundry - Pre

No Asbestos

B00P - R0009 - Access Shower/Toilet - Type 2

No Asbestos

B00P - R0010 - Cleaning Distributed Store

No Asbestos

B00P - R0011 - Kitchen - Pre

No Asbestos

B00P - R0012 - Clerical Office - Pre

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00P - R0013 - Clerical Office - Pre

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00P - R0014 - General Storeroom - Pre

No Asbestos

B00P - R0015 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids	Non Accessible Area - Area inaccessible
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible

Interior

B00Q - R0001 - Communal Space

No Asbestos

B00Q - R0002 - Raised Platform

No Asbestos

B00Q - R0003 - Chair Storeroom

No Asbestos

B00Q - R0004 - Communal/Performance Store

No Asbestos

B00Q - R0005 - P.E. Store

No Asbestos

B00Q - R0006 - Toilet - Lobby

No Asbestos

B00Q - R0007 - Toilets - Girls

No Asbestos

B00Q - R0008 - Sound Cupboard

No Asbestos

B00Q - R0009 - Toilet - Lobby

No Asbestos

B00Q - R0010 - Toilets - Boys

No Asbestos

B00Q - R0011 - Cleaning Distributed Store

No Asbestos

B00Q - R0012 - Plant

No Asbestos

B00Q - R0013 - Main Switch Board

No Asbestos

B00Q - R0014 - Access Shower/Toilet

No Asbestos

B00Q - R0015 - Covered Outdoor Learning Area

No Asbestos

B00Q - R0016 - Movement

No Asbestos

B00Q - R0017 - Movement

No Asbestos

B00Q - R0018 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017