


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Aldavilla Public School (4601)  
**Region :** North Coast  
**State Electorate :** Oxley  
**Local Government Area :** Kempsey

**Initial Survey :** Noel Arnold & Associates : 01 - May - 2008  
**Reviewed By :** Parsons Brinckerhoff : 29 - Aug - 2016



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - Administration - 1992 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

**Interior**

**B001 - R0002 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0003 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0004 - Principal**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0005 - Duplicating Workroom**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0006 - Interview**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0009 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0010 - Cleaning Supplies**

No Asbestos

**B001 - R0011 - Sick Bay**

No Asbestos

**B001 - R0013 - Staff Toilet**

No Asbestos

**B001 - R0014 - Distribution Board**

Note: No inspection of live electrical installation.

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0015 - Security Store**

No Asbestos

**B001 - R0017 - Staff Room Annexe**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0018 - External Movement**

No Asbestos

**B001 - R0019 - External Movement**

No Asbestos

**B001 - R0020 - Staff Room**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B001 - R0021 - Staff Kitchen**

No Asbestos

**B001 - R0022 - Toilet - Lobby**

No Asbestos

**B001 - R0023 - Staff Toilet**

No Asbestos

**B001 - R0024 - Staff Toilet**

No Asbestos

**B001 - R0025 - Staff Toilet**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

**B001 - R0026 - Movement**

No Asbestos

**B001 - R0027 - Staff Toilet**

No Asbestos

**B001 - R0028 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B001 - R0029 - Clerical Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B002 - Pupil Facilities - 1992 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior**

**B002 - R0001 - Canteen**

No Asbestos

**B002 - R0002 - Canteen Office/Store**

No Asbestos

**B002 - R0003 - Disabled Toilet**

No Asbestos

**B002 - R0004 - General Storeroom**

No Asbestos

**B002 - R0005 - Main Switch Board**

No Asbestos

**B002 - R0006 - Cleaning Supplies**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B003 - Library - 1992 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B003 - R0001 - Library Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B003 - R0002 - Communications Room**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B003 - R0003 - Special Programs Room**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B003 - R0004 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B003 - R0005 - Security Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B003 - R0006 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B004 - General Learning - 1992 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior****B004 - R0001 - General Assistant/Bulk Store**

No Asbestos

**B004 - R0002 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B004 - R0003 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B004 - R0004 - Practical Activities - 1hb**

No Asbestos

**B004 - R0005 - General Storeroom**

No Asbestos

**B004 - R0006 - Practical Activities - 1hb**

No Asbestos

**B004 - R0007 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B004 - R0008 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B004 - R0009 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B004 - R0010 - Cleaning Supplies**

No Asbestos

**B004 - R0011 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B004 - R0012 - Practical Activities - 1hb**

No Asbestos

**B004 - R0013 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B004 - R0014 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B004 - R0015 - Practical Activities - 1hb**

No Asbestos

**B004 - R0016 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B004 - R0017 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B004 - R0018 - Toilets - Boys**

No Asbestos

**B004 - R0019 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B005 - General Learning - 1992 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B005 - R0001 - Toilets - Girls**

No Asbestos

**B005 - R0002 - P.E. Store**

No Asbestos

**B005 - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B005 - R0004 - Special Programs Room**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B005 - R0005 - Practical Activities - 1hb**

No Asbestos

**B005 - R0006 - Practical Activities - 1hb**

No Asbestos

**B005 - R0007 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B005 - R0008 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B005 - R0009 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B005 - R0010 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B005 - R0011 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B005 - R0012 - Practical Activities - 1hb**

No Asbestos

**B005 - R0013 - Kiln Room**

No Asbestos

**B005 - R0014 - Practical Activities - 1hb**

No Asbestos

**B005 - R0015 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B005 - R0016 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B005 - R0017 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B005 - R0018 - Cleaning Supplies**

No Asbestos

**B005 - R0019 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B005 - R0020 - Practical Activities - 1hb**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B005 - R0021 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B005 - R0022 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B005 - R0023 - Practical Activities - 1hb**

No Asbestos

**B005 - R0024 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B005 - R0025 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B005 - R0026 - Toilets - Girls**

No Asbestos

**B005 - R0027 - Toilets - Boys**

No Asbestos

**B005 - R0028 - External Movement**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B006 - Communal Facilities - 1992 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B006 - R0001 - External Movement**

No Asbestos

**B006 - R0002 - No Access**

No Asbestos

**B006 - R0003 - Toilets - Boys/Girls**

No Asbestos

**B006 - R0004 - Cleaning Supplies**

No Asbestos

**B006 - R0005 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B006 - R0006 - Personal Effects Storage**

No Asbestos

**B006 - R0007 - Movement**

No Asbestos

**B006 - R0008 - Staff Kitchen**

No Asbestos

**B006 - R0009 - Communal Space**

No Asbestos

**B006 - R0010 - General Storeroom**

No Asbestos

**B006 - R0011 - Raised Platform**

No Asbestos

**B006 - R0012 - General Storeroom**

No Asbestos

**B006 - R0013 - External Movement**

No Asbestos

**B006 - R0015 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B007 - General Learning/Building Services - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B007 - R0001 - External Movement**

No Asbestos

**B007 - R0002 - No Access**

No Asbestos

**B007 - R0003 - General Assistant/Bulk Store**

No Asbestos

**B007 - R0004 - Sports Store**

No Asbestos

**B007 - R0005 - Practical Activities/Movement - 1hb**

No Asbestos

**B007 - R0006 - Home Base Store**

No Asbestos

**B007 - R0007 - Home Base**

No Asbestos

**B007 - R0008 - Withdrawal Space - 2hb**

No Asbestos

**B007 - R0009 - Home Base**

No Asbestos

**B007 - R0010 - Home Base Store**

No Asbestos

**B007 - R0011 - Practical Activities/Movement - 1hb**

No Asbestos

**B007 - R0012 - No Access**

No Asbestos

**B007 - R0013 - No Access**

No Asbestos

**B007 - R0014 - Special Programs Store**

No Asbestos

**B007 - R0015 - Movement**

No Asbestos

**B007 - R0016 - Special Programs Room**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B008 - Building Services - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B008 - R0001 - Sports Store**

No Asbestos

**B008 - R0002 - General Assistant/Bulk Store**

No Asbestos

**B008 - R0003 - No Access**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B009 - Railway Carriage - 1950 - Steel (Steel)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B009 - R0001 - General Storeroom**

No Asbestos

**B009 - R0002 - Movement**

No Asbestos

**B009 - R0003 - Kitchen - Pre**

No Asbestos

**B009 - R0004 - Movement**

No Asbestos

**B009 - R0005 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
4601/B009/R0005/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>	

**B009 - R0006 - External Movement**

No Asbestos

**B009 - R0007 - Movement**

Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
4601/B009/R0005/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>	

**B009 - R0008 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
4601/B009/R0005/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>	

**B009 - R0009 - General Storeroom**

No Asbestos

**B009 - R0010 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 602 - D13543 - Learning Unit - Standard With P.A.A. : Placement Date - 30/11/2015**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017