



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/Staff Facilities - 2006 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior**

**B00A - R0001 - Entry Vestibule**

No Asbestos

**B00A - R0002 - Staff Kitchen**

No Asbestos

**B00A - R0003 - Sick Bay**

No Asbestos

**B00A - R0004 - Disabled Shower/Toilet**

No Asbestos

**B00A - R0005 - Deputy Principal**

No Asbestos

**B00A - R0006 - Interview**

No Asbestos

**B00A - R0007 - Deputy Principal**

No Asbestos

**B00A - R0008 - Staff Room**

No Asbestos

**B00A - R0009 - Staff Room Annexe**

No Asbestos

**B00A - R0010 - Movement**

No Asbestos

**B00A - R0011 - Staff Toilet**

No Asbestos

**B00A - R0012 - Staff Toilet**

No Asbestos

**B00A - R0013 - Staff Toilet**

No Asbestos

**B00A - R0014 - Cleaning Distributed Store**

No Asbestos

**B00A - R0015 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0016 - Security Store**

No Asbestos

**B00A - R0017 - Principal**

No Asbestos

**B00A - R0018 - Clerical Office**

No Asbestos

**B00A - R0019 - Clerical Office/Workroom**

No Asbestos

**B00A - R0020 - External Movement**

No Asbestos

**B00A - R0021 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Communal Facilities/Pupil Facilities - 2006 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior**

**B00B - R0001 - Communal Space**

No Asbestos

**B00B - R0002 - Raised Platform**

No Asbestos

**B00B - R0003 - Main Switch Board**

No Asbestos

**B00B - R0004 - Communal/Performance Store**

No Asbestos

**B00B - R0005 - P.E. Store**

No Asbestos

**B00B - R0006 - Hall Chair Store**

No Asbestos

**B00B - R0007 - Movement**

No Asbestos

**B00B - R0008 - Toilets - Boys**

No Asbestos

**B00B - R0009 - Movement**

No Asbestos

**B00B - R0010 - Disabled Shower/Toilet**

No Asbestos

**B00B - R0011 - Other**

No Asbestos

**B00B - R0012 - Toilets - Girls**

No Asbestos

**B00B - R0013 - Canteen**

No Asbestos

**B00B - R0014 - Canteen Office/Store**

No Asbestos

**B00B - R0015 - Cleaning Supplies**

No Asbestos

**B00B - R0016 - Garden Store**

No Asbestos

**B00B - R0017 - General Assistant/Bulk Store**

No Asbestos

**B00B - R0018 - Sports Store**

No Asbestos

**B00B - R0019 - General Storeroom**

No Asbestos

**B00B - R0021 - Covered Outdoor Learning Area**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00D - Library/General Learning - 2006 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior**

**B00D - R0001 - Cleaning Distributed Store**

No Asbestos

**B00D - R0002 - Staff Toilet**

No Asbestos

**B00D - R0003 - K.L.A. Store**

No Asbestos

**B00D - R0004 - Communications Room**

No Asbestos

**B00D - R0005 - Library Office/Workroom**

No Asbestos

**B00D - R0006 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0007 - Reading Area**

No Asbestos

**B00D - R0008 - Special Programs Store**

No Asbestos

**B00D - R0009 - Staff Room Annexe**

No Asbestos

**B00D - R0010 - Home Base Store**

No Asbestos

**B00D - R0011 - Practical Activities - 1hb**

No Asbestos

**B00D - R0012 - Home Base**

No Asbestos

**B00D - R0013 - Withdrawal Space - 2hb**

No Asbestos

**B00D - R0014 - Practical Activities - 1hb**

No Asbestos

**B00D - R0015 - Home Base Store**

No Asbestos

**B00D - R0016 - Home Base**

No Asbestos

**B00D - R0017 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0019 - External Movement**

No Asbestos

**B00D - R0020 - Home Base Store**

No Asbestos

**B00D - R0021 - Home Base**

No Asbestos

**B00D - R0022 - Practical Activities - 1hb**

No Asbestos

**B00D - R0023 - Withdrawal Space - 2hb**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00D - R0024 - Home Base</b>						
No Asbestos						
<b>B00D - R0025 - Home Base Store</b>						
No Asbestos						
<b>B00D - R0026 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00D - R0027 - Plant</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00E - General Learning/Pupil Facilities - 2006 - Brick/Veneer (Brick/Veneer)**

**Exterior**

No Asbestos

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

**Interior**

**B00E - R0001 - External Movement**

No Asbestos

**B00E - R0008 - Home Base Store**

No Asbestos

**B00E - R0009 - Practical Activities - 1hb**

No Asbestos

**B00E - R0010 - Home Base**

No Asbestos

**B00E - R0011 - Withdrawal Space - 2hb**

No Asbestos

**B00E - R0012 - Home Base**

No Asbestos

**B00E - R0013 - Practical Activities - 1hb**

No Asbestos

**B00E - R0014 - Home Base Store**

No Asbestos

**B00E - R0015 - Home Base Store**

No Asbestos

**B00E - R0016 - Practical Activities - 1hb**

No Asbestos

**B00E - R0017 - Home Base**

No Asbestos

**B00E - R0018 - Withdrawal Space - 2hb**

No Asbestos

**B00E - R0019 - Home Base**

No Asbestos

**B00E - R0020 - Practical Activities - 1hb**

No Asbestos

**B00E - R0021 - Home Base Store**

No Asbestos

**B00E - R0023 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0024 - Toilets - Girls**

No Asbestos

**B00E - R0025 - Toilets - Boys**

No Asbestos

**B00E - R0026 - Cleaning Distributed Store**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning/Pupil Facilities - 2006 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00F - R0001 - Home Base**

No Asbestos

**B00F - R0002 - Home Base Store**

No Asbestos

**B00F - R0003 - Practical Activities - 1hb**

No Asbestos

**B00F - R0004 - Withdrawal Space - 2hb**

No Asbestos

**B00F - R0005 - Home Base**

No Asbestos

**B00F - R0006 - Practical Activities - 1hb**

No Asbestos

**B00F - R0007 - Home Base Store**

No Asbestos

**B00F - R0008 - Home Base Store**

No Asbestos

**B00F - R0009 - Practical Activities - 1hb**

No Asbestos

**B00F - R0010 - Home Base**

No Asbestos

**B00F - R0011 - Withdrawal Space - 2hb**

No Asbestos

**B00F - R0012 - Home Base**

No Asbestos

**B00F - R0013 - Practical Activities - 1hb**

No Asbestos

**B00F - R0014 - Home Base Store**

No Asbestos

**B00F - R0015 - Home Base Store**

No Asbestos

**B00F - R0016 - Practical Activities - 1hb**

No Asbestos

**B00F - R0017 - Home Base**

No Asbestos

**B00F - R0018 - Withdrawal Space - 2hb**

No Asbestos

**B00F - R0019 - Home Base**

No Asbestos

**B00F - R0020 - Practical Activities - 1hb**

No Asbestos

**B00F - R0021 - Home Base Store**

No Asbestos

**B00F - R0022 - Distribution Board**

No Asbestos

Note: No inspection of live electrical installation.

**B00F - R0023 - Distribution Board**

No Asbestos

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

**B00F - R0024 - Disabled Shower/Toilet**

No Asbestos

**B00F - R0026 - Other**

No Asbestos

**B00F - R0027 - Toilets - Girls**

No Asbestos

**B00F - R0028 - Toilets - Boys**

No Asbestos

**B00F - R0029 - Kiln Room**

No Asbestos

**B00F - R0030 - External Movement**

No Asbestos

**B00F - R0031 - Special Programs Room**

No Asbestos

**B00F - R0032 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning/Special Learn - 2014 - Steel (Steel)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00G - R0001 - Home Base - Bd/Cd/Ed**

No Asbestos

**B00G - R0002 - Home Base - Bd/Cd/Ed**

No Asbestos

**B00G - R0003 - Special Programs Room**

No Asbestos

**B00G - R0004 - Home Base - Bd/Cd/Ed**

No Asbestos

**B00G - R0005 - Teachers Aide Special Ed**

No Asbestos

**B00G - R0006 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 521 - D10140 - Staff Study : Placement Date - 2/01/2014**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Staff Room**

No Asbestos Found.

**R2 - Staff Toilet**

No Asbestos Found.

**R3 - Staff Toilet**

No Asbestos Found.

**R4 - Lobby**

No Asbestos Found.

**OS 602 - D10407 - Learning Unit - Standard With P.A.A. : Placement Date - 11/01/2011**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D10461 - Learning Unit - Standard With P.A.A. : Placement Date - 6/01/2012**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D10811 - Learning Unit - Standard With P.A.A. : Placement Date - 11/01/2011**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D13592 - Learning Unit - Standard With P.A.A. : Placement Date - 11/01/2011**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D13688 - Learning Unit - Standard With P.A.A. : Placement Date - 4/02/2014</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D13801 - Learning Unit - Standard With P.A.A. : Placement Date - 30/11/2012</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 603 - D13813 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 19/09/2008</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D13922 - Learning Unit - Standard With P.A.A. : Placement Date - 5/03/2009</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 603 - D14020 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 29/01/2008</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D14271 - Learning Unit - Standard With P.A.A. : Placement Date - 9/01/2009</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 603 - D17660 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 26/02/2008</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**There are no asbestos related file attachment(s) for this school.**

2017