

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Australia Street Infants School (5104)
Region : Sydney
State Electorate : Newtown
Local Government Area : Marrickville

Initial Survey : Noel Arnold & Associates : 10 - Mar - 2008
Reviewed By : AECOM : 26 - May - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Library/Administration - 1889 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	Non Accessible Area - Height Restriction - Access to ceiling void is greater than 5m.
Eaves Linings	No Asbestos Found
Underfloor Voids	Non Accessible Area - Area inaccessible

Interior**B00A - R0001 - Staff Kitchen**

No Asbestos

B00A - R0002 - Principal

No Asbestos

B00A - R0003 - Clerical Office

No Asbestos

B00A - R0004 - Movement

No Asbestos

B00A - R0005 - Staff Room

No Asbestos

B00A - R0006 - Home Base

No Asbestos

B00A - R0007 - Cleaning Distributed Store

No Asbestos

B00A - R0008 - Movement

No Asbestos

B00A - R0009 - Home Base

No Asbestos

B00A - R0010 - Movement

Floor Coverings Res/Textile	Vinyl Tiles					
	5104/B00A/R0010/Floor Coverings Res/Textile/S4					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5104/B00A/R0017/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00A - R0011 - Movement

No Asbestos

B00A - R0012 - Movement

No Asbestos

B00A - R0013 - Handwashing Facilities

No Asbestos

B00A - R0014 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet					
	5104/B00A/R0014/Partition Walls (Cubicles)/S1					No Asbestos Detected

B00A - R0015 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet					
	5104/B00A/R0014/Partition Walls (Cubicles)/S1					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5104/B00A/R0017/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00A - R0016 - Cleaning Distributed Store

No Asbestos

B00A - R0017 - Duplicating Workroom

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
5104/B00A/R0017/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	
B00A - R0018 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
5104/B00A/R0017/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	
B00A - R0019 - Clerical Office/Workroom						
No Asbestos						
B00A - R0020 - Stairs						
No Asbestos						
B00A - R0021 - Stairs						
No Asbestos						
B00A - R1001 - Home Base						
No Asbestos						
B00A - R1002 - Movement						
No Asbestos						
B00A - R1003 - Library Office/Workroom						
No Asbestos						
B00A - R1004 - K.L.A. Store						
No Asbestos						
B00A - R1005 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	47m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
					Assumed Asbestos - Height Restriction - Too high to	
B00A - R1006 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
					Assumed Asbestos - Height Restriction - Too high to	
B00A - R1007 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
					Assumed Asbestos - - Too high to sample < 5metres.	
B00A - R1008 - Withdrawal Space - 1hb						
No Asbestos						
B00A - R1009 - Movement						
No Asbestos						
B00A - R1010 - Stairs						
No Asbestos						
B00A - R1011 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Pre-School Facilities - 1889 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible
Underfloor Voids	No Asbestos Found

Interior**B00B - R0003 - P.E. Store**

No Asbestos

B00B - R0004 - Movement

No Asbestos

B00B - R0005 - General Storeroom

No Asbestos

B00B - R0006 - Home Base Store

No Asbestos

B00B - R0007 - Withdrawal Space - 1hb

No Asbestos

B00B - R0008 - Clerical Office

No Asbestos

B00B - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

5104/B00B/R0037/Ceiling Structures/Linings/S2

Chrysotile (white asbestos)**B00B - R0010 - Movement**

No Asbestos

B00B - R0011 - Home Base - Pre

No Asbestos

B00B - R0012 - Practical Activities - Pre

No Asbestos

B00B - R0013 - Staff Toilet

No Asbestos

B00B - R0014 - Staff Kitchen

No Asbestos

B00B - R0015 - General Storeroom

No Asbestos

B00B - R0016 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	--------------	--------------------	---------	--------------------

5104/B00B/R0016/Ceiling Structures/Linings/S6

Chrysotile (white asbestos)**B00B - R0017 - Toilets - Boys/Girls**

No Asbestos

B00B - R0018 - General Storeroom

No Asbestos

B00B - R0019 - Distribution Board

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

5104/B00B/R0019/Ceiling Structures/Linings/S7

Chrysotile (white asbestos)**B00B - R0020 - Staff Kitchen**

No Asbestos

B00B - R0021 - Withdrawal - Pre

No Asbestos

B00B - R0022 - Clerical Office/Workroom

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00B - R0023 - Movement

No Asbestos

B00B - R0024 - Clerical Office

No Asbestos

B00B - R0025 - Staff Room Annexe

No Asbestos

B00B - R0026 - Movement

No Asbestos

B00B - R0027 - Movement

No Asbestos

B00B - R0028 - General Storeroom

No Asbestos

B00B - R0029 - Entry Vestibule

No Asbestos

B00B - R0030 - Security Store

No Asbestos

B00B - R0031 - Laundry - Pre

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

Assumed Asbestos - Height Restriction - too high could**B00B - R0032 - Staff Toilet**

No Asbestos

B00B - R0033 - Outdoor Learning Area

Ceiling Structures/Linings	Flat AC Sheeting	10m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	-------------	--------------------	---------	--------------------

5104/B00B/R0037/Ceiling Structures/Linings/S2

Chrysotile (white asbestos)**B00B - R0034 - General Storeroom**

No Asbestos

B00B - R0035 - Movement

No Asbestos

B00B - R0036 - Laundry - Pre

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-----	--------------	--------------------	---------	--------------------

5104/B00B/R0036/Ceiling Structures/Linings/S8

Chrysotile (white asbestos)**B00B - R0037 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	--------------	--------------------	---------	--------------------

5104/B00B/R0037/Ceiling Structures/Linings/S2

Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Communal Facilities - 1889 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					
Gable Ends	Flat AC Sheeting	3m2	Upper portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	5104/B00D/Gable Ends/S10			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior**B00D - R0001 - P.E. Store**

Floor Coverings Res/Textile	Vinyl Tiles					
	5104/B00D/R0001/Floor Coverings Res/Textile/S3			No Asbestos Detected		

B00D - R0002 - P.E. Store

Floor Coverings Res/Textile	Vinyl Tiles					
	5104/B00D/R0001/Floor Coverings Res/Textile/S3			No Asbestos Detected		

B00D - R0003 - Raised Platform

No Asbestos

B00D - R0004 - Staff Toilet

No Asbestos

B00D - R0005 - Communal Space

No Asbestos

B00D - R0006 - Staff Toilet

No Asbestos

B00D - R0007 - Movement

No Asbestos

B00D - R0008 - Movement

Electrical Backing Board	Flat AC Sheeting	2m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
	5104/B00D/R0008/Electrical Backing Board/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	5104/B00D/R0008/Electrical Backing Board/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1970 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00E - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Building Services - 1889 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00F - R0001 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Library - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

No Asbestos

Interior

B00G - R0001 - Reading Area

No Asbestos

B00G - R0002 - Library Office/Workroom

No Asbestos

B00G - R0003 - K.L.A. Store

No Asbestos

B00G - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

5104_ASB_010313_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017