


# Asbestos Register

(Hazardous Materials and Risk Assessment)



**School :** Arndell School (5538)  
**Region :** Northern Sydney  
**State Electorate :** Ryde  
**Local Government Area :** Ryde

**Initial Survey :** Noel Arnold & Associates : 14 - Jan - 2010  
**Reviewed By :** Parsons Brinckerhoff : 03 - May - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B038 - Administration/Other-Community Use - 1959 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	200m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5538/B039/Eaves Linings/S7					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B038 - R0001 - Other-Community Use (24.13 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B038 - R0002 - Other-Community Use (8.58 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B038 - R0003 - Other-Community Use (11.3 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B038 - R0004 - Other-Community Use (3.89 m2)**

No Asbestos

**B038 - R0005 - Other-Community Use (24.3 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B038 - R0006 - Other-Community Use (12.14 m2)**

Decorative Coating	Vermiculite					<b>Limited Samples Taken</b>
	5538/B038/R0006/Decorative Coating/S10					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B038 - R0007 - Other-Community Use (13.22 m2)**

Floor Coverings Res/Textile	Vinyl Sheeting (Under Carpet)					<b>No Asbestos Detected</b>
	5538/B038/R0007/Floor Coverings Res/Textile/S14					

**B038 - R0008 - Other-Community Use (11.86 m2)**

No Asbestos

**B038 - R0009 - Other-Community Use (13.57 m2)**

No Asbestos

**B038 - R0010 - Other-Community Use (15.99 m2)**

No Asbestos

**B038 - R0011 - Other-Community Use (4.16 m2)**

No Asbestos

**B038 - R0012 - Other-Community Use (3.85 m2)**

No Asbestos

**B038 - R0013 - Other-Community Use (4.23 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5538/B038/R1012/Partition Walls (Cubicles)/S6					<b>Chrysotile (white asbestos)</b>

**B038 - R0014 - Other-Community Use (4.27 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	1m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5538/B038/R1012/Partition Walls (Cubicles)/S6					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B038 - R0015 - Other-Community Use (13.97 m2)</b>						
No Asbestos						
<b>B038 - R0016 - Movement (1.59 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Poor Condition - Extensive Damage (4)	Medium (2)	High Priority (6-8)
5538/B038/R0016/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos)</b>	
<b>B038 - R0017 - Principal (21.38 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B038 - R0018 - Clerical Office (10.87 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B038 - R0019 - Other-Community Use (9.5 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B038 - R0020 - Other-Community Use (11.62 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B038 - R0021 - Movement (81.5 m2)</b>						
No Asbestos						
<b>B038 - R0022 - Other-Community Use (13.73 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
5538/B038/R1013/Floor Coverings Res/Textile/S8					<b>No Asbestos Detected</b>	
<b>B038 - R1001 - Other-Community Use (23.66 m2)</b>						
Decorative Coating	Vermiculite					
5538/B038/R0006/Decorative Coating/S10					<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B038 - R1002 - Other-Community Use (10.2 m2)</b>						
No Asbestos						
<b>B038 - R1003 - Other-Community Use (11.5 m2)</b>						
No Asbestos						
<b>B038 - R1004 - Other-Community Use (25.53 m2)</b>						
No Asbestos						
<b>B038 - R1005 - Other-Community Use (12.41 m2)</b>						
No Asbestos						
<b>B038 - R1006 - Other-Community Use (13.64 m2)</b>						
No Asbestos						
<b>B038 - R1007 - Other-Community Use (12.37 m2)</b>						
No Asbestos						
<b>B038 - R1008 - Other-Community Use (14.76 m2)</b>						
No Asbestos						
<b>B038 - R1009 - Other-Community Use (15.96 m2)</b>						
No Asbestos						
<b>B038 - R1010 - Other-Community Use (4.27 m2)</b>						
No Asbestos						
<b>B038 - R1011 - Other-Community Use (24.4 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5538/B038/R1012/Partition Walls (Cubicles)/S6					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5538/B038/R1011/Ceiling Structures/Linings/S11					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B038 - R1012 - Other-Community Use (22.99 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5538/B038/R1012/Partition Walls (Cubicles)/S6					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5538/B038/R1011/Ceiling Structures/Linings/S11					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B038 - R1013 - Other-Community Use (7 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	5538/B038/R1013/Floor Coverings Res/Textile/S8					<b>No Asbestos Detected</b>
<b>B038 - R1014 - Other-Community Use (63.97 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Limited Samples Taken</b>
	<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>					
Floor Coverings Res/Textile	Vinyl Tiles					
	5538/B039/R0006/Floor Coverings Res/Textile/S4					<b>No Asbestos Detected</b>
<b>B038 - R1015 - Other-Community Use (68.68 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	5538/B039/R0022/Floor Coverings Res/Textile/S5					<b>No Asbestos Detected</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### B039 - General Learning/Pupil Facilities - 1959 - Brick/Block (Brick/Block)

#### Exterior

Eaves Linings	Flat AC Sheeting	125m2	Upper & Lower South and East sections	Good Condition (1)	Low (1)	Low Priority (2-3)
	5538/B039/Eaves Linings/S7					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

#### Interior

##### B039 - R0001 - External Movement (127.68 m2)

No Asbestos

##### B039 - R0002 - Withdrawal Space - 1hb (3.56 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

##### B039 - R0003 - Home Base (26.39 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

##### B039 - R0004 - Home Base Store (3.06 m2)

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	5538/B039/R0005/Floor Coverings Res/Textile/S3					

##### B039 - R0005 - Practical Activities - 1hb (9.17 m2)

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	5538/B039/R0005/Floor Coverings Res/Textile/S3					
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

##### B039 - R0006 - Special Programs Room (11.42 m2)

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	5538/B039/R0006/Floor Coverings Res/Textile/S4					

##### B039 - R0007 - Craft Store (4.59 m2)

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	5538/B039/R0006/Floor Coverings Res/Textile/S4					

##### B039 - R0008 - Special Programs Room (25.8 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

##### B039 - R0009 - Kiln Room (5.15 m2)

No Asbestos

##### B039 - R0010 - Staff Shower/Change (4.2 m2)

No Asbestos

##### B039 - R0011 - Interview (8.69 m2)

No Asbestos

##### B039 - R0012 - Materials Store (4.9 m2)

No Asbestos

##### B039 - R0013 - Main Switch Board (3.91 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Debris	AC Fragments/Debris	1m2	South	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
5538/B039/R0013/Debris/S12					Chrysotile (white asbestos)	
<b>B039 - R0014 - Materials Technology L.S. (38.06 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
5538/B039/R0037/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B039 - R0015 - Raised Platform (12.56 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
5538/B039/R0037/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B039 - R0016 - Communal Space (88.09 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
5538/B039/R0037/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B039 - R0017 - General Learning Space (15.18 m2)</b>						
No Asbestos						
<b>B039 - R0019 - Sports Store (5.95 m2)</b>						
No Asbestos						
<b>B039 - R0020 - Sports Store (5.95 m2)</b>						
No Asbestos						
<b>B039 - R0021 - General Learning Space (8.38 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
5538/B039/R0037/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B039 - R0023 - Cleaning Distributed Store (4 m2)</b>						
No Asbestos						
<b>B039 - R0024 - Toilets - Boys/Girls (2.81 m2)</b>						
No Asbestos						
<b>B039 - R0025 - Toilets - Boys/Girls (2.76 m2)</b>						
No Asbestos						
<b>B039 - R0026 - Toilets - Boys/Girls (2.69 m2)</b>						
No Asbestos						
<b>B039 - R0027 - Toilets - Boys/Girls (2.86 m2)</b>						
No Asbestos						
<b>B039 - R0028 - External Movement (113.95 m2)</b>						
No Asbestos						
<b>B039 - R0029 - Home Base Store (3.06 m2)</b>						
No Asbestos						
<b>B039 - R0030 - Practical Activities - 1hb (8.53 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
5538/B039/R0037/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B039 - R0031 - Home Base (25.92 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
5538/B039/R0037/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
<b>B039 - R0032 - Withdrawal Space - 1hb (3.54 m2)</b>						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
5538/B039/R0037/Ceiling Structures/Linings/S2					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B039 - R0033 - Home Base Store (2.95 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
5538/B039/R0037/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B039 - R0034 - Practical Activities - 1hb (8.32 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
5538/B039/R0037/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Vermiculite					
5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Limited Samples Taken</b>	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B039 - R0035 - Home Base (25.57 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Limited Samples Taken</b>	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B039 - R0036 - Withdrawal Space - 1hb (3.56 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Limited Samples Taken</b>	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B039 - R0037 - Practical Activities - 1hb (8.74 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
5538/B039/R0037/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Vermiculite					
5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Limited Samples Taken</b>	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B039 - R0038 - Home Base Store (3.02 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
5538/B039/R0037/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B039 - R0039 - Home Base (25.58 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Limited Samples Taken</b>	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B039 - R0040 - Withdrawal Space - 1hb (3.56 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
5538/B039/R0037/Ceiling Structures/Linings/S2					<b>Limited Samples Taken</b>	
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B039 - R0041 - Special Programs Room (16.91 m2)</b>						
No Asbestos						
<b>B039 - R0042 - General Assistant/Bulk Store (8.5 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
5538/B039/R0042/Floor Coverings Res/Textile/S13					<b>No Asbestos Detected</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B083 - Pupil Facilities - 1959 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B083 - R0001 - General Assistant/Bulk Store (4.9 m2)**

No Asbestos

**B083 - R0003 - Toilet - P (5.34 m2)**

No Asbestos

**B083 - R0004 - Other (4.54 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017