


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Anson Street School (5625)
Region : Western NSW
State Electorate : Orange
Local Government Area : Orange

Initial Survey : Noel Arnold & Associates : 21 - May - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1988 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0002 - Home Base Store

No Asbestos

B00A - R0003 - Plant

No Asbestos

B00A - R0004 - Disabled Shower/Toilet

No Asbestos

B00A - R0005 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0006 - Movement

No Asbestos

B00A - R0007 - Practical Activities - 1hb

No Asbestos

B00A - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0009 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0010 - Toilets - Boys/Girls

No Asbestos

B00A - R0011 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0013 - Craft Store

No Asbestos

B00A - R0014 - Materials Workshop - Type 3

No Asbestos

B00A - R0015 - Hydrotherapy - Pool

No Asbestos

B00A - R0016 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0017 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0018 - No Access

No Asbestos

B00A - R0019 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0020 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0021 - General Storeroom						
No Asbestos						
B00A - R0022 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R0023 - Movement						
No Asbestos						
B00A - R0024 - Home Base						
No Asbestos						
B00A - R0025 - Withdrawal Space - 1hb						
No Asbestos						
B00A - R0026 - Home Base Store						
No Asbestos						
B00A - R0027 - Toilets - Boys/Girls						
No Asbestos						
B00A - R0028 - Movement						
No Asbestos						
B00A - R0029 - Plant						
No Asbestos						
B00A - R0030 - Laundry						
No Asbestos						
B00A - R0031 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0032 - Toilets - Boys/Girls						
No Asbestos						
B00A - R0033 - Home Base Store						
No Asbestos						
B00A - R0034 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0035 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0036 - Home Base Store						
No Asbestos						
B00A - R0037 - Toilets - Boys						
No Asbestos						
B00A - R0038 - Movement						
No Asbestos						
B00A - R0039 - Staff Room Annexe						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0040 - Plant						
No Asbestos						
B00A - R0041 - Toilets - Boys/Girls						
No Asbestos						
B00A - R0042 - Home Base Store						
No Asbestos						
B00A - R0043 - Home Base						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0044 - Withdrawal Space - 1hb						
No Asbestos						
B00A - R0045 - Cleaning Supplies						
No Asbestos						
B00A - R0046 - Practical Activities - 1hb						
No Asbestos						
B00A - R0047 - General Storeroom						
No Asbestos						
B00A - R0048 - Entry Vestibule						
No Asbestos						
B00A - R0049 - External Movement						
No Asbestos						
B00A - R0050 - Covered Vehicle Area/Porte Cochere						
No Asbestos						
B00A - R0051 - Wheelchair Store						
No Asbestos						
B00A - R0052 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0053 - Interview						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0054 - Interview						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0055 - Disabled Toilet						
No Asbestos						
B00A - R0056 - Distribution Board						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0057 - Deputy Principal						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0058 - No Access						
No Asbestos						
B00A - R0059 - No Access						
No Asbestos						
B00A - R0060 - Canteen						
No Asbestos						
B00A - R0061 - Movement						
No Asbestos						
B00A - R0062 - Entry Vestibule						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0063 - Clerical Office						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0064 - Principal						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0065 - Security Store						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0066 - General Storeroom						

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0067 - Staff Toilet						
No Asbestos						
B00A - R0068 - Staff Room Annexe						
No Asbestos						
B00A - R0069 - Duplicating Workroom						
No Asbestos						
B00A - R0070 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0071 - Movement						
No Asbestos						
B00A - R0077 - Communal Space						
No Asbestos						
B00A - R0078 - Hall Chair Store						
No Asbestos						
B00A - R0079 - Plant						
No Asbestos						
B00A - R0080 - Toilets - Girls						
No Asbestos						
B00A - R0081 - Toilets - Boys						
No Asbestos						
B00A - R0082 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R0083 - Plant						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0084 - Staff Toilet						
No Asbestos						
B00A - R0085 - Staff Toilet						
No Asbestos						
B00A - R0086 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0087 - Staff Shower/Change						
No Asbestos						
B00A - R0088 - Main Switch Board						
No Asbestos						
B00A - R0089 - Staff Room						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0090 - Staff Room Annexe						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0091 - Staff Room						
No Asbestos						
B00A - R0092 - Toilets - Boys/Girls						
No Asbestos						
B00A - R0093 - Plant						
No Asbestos						
B00A - R0094 - Home Base Store						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0095 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0096 - External Movement						
No Asbestos						
B00A - R0097 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0098 - Practical Activities - 2hb						
No Asbestos						
B00A - R0099 - Pantry						
No Asbestos						
B00A - R0100 - Laundry						
No Asbestos						
B00A - R0101 - External Movement						
No Asbestos						
B00A - R0102 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R0103 - External Movement						
No Asbestos						
B00A - R0104 - No Access						
No Asbestos						
B00A - R0105 - Laundry						
No Asbestos						
B00A - R0106 - Other						
No Asbestos						
B00A - R0107 - Practical Activities - 1hb						
No Asbestos						
B00A - R0108 - Plant						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Other - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - General Storeroom

No Asbestos

B00B - R0002 - General Assistant/Bulk Store

No Asbestos

B00B - R0003 - Garden Store

No Asbestos

B00B - R0004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Other - 2010 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Personal Effects Storage

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 2013 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00D - R0001 - Home Base - M**

No Asbestos

B00D - R0002 - Withdrawal - M

No Asbestos

B00D - R0003 - Home Base Store - M

No Asbestos

B00D - R0004 - Practical Activities - M - 2hb

No Asbestos

B00D - R0005 - Access Shower/Toilet/Change

No Asbestos

B00D - R0006 - Laundry - P

No Asbestos

B00D - R0007 - Access Shower/Toilet - Type 2

No Asbestos

B00D - R0008 - Movement

No Asbestos

B00D - R0009 - Cleaning Distributed Store

No Asbestos

B00D - R0010 - Home Base - M

No Asbestos

B00D - R0011 - Withdrawal - M

No Asbestos

B00D - R0012 - Home Base Store - M

No Asbestos

B00D - R0013 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0014 - External Movement

No Asbestos

B00D - R0015 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 2013 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00E - R0001 - Home Base - M**

No Asbestos

B00E - R0002 - Withdrawal - M

No Asbestos

B00E - R0003 - Home Base Store - M

No Asbestos

B00E - R0004 - Practical Activities - M - 2hb

No Asbestos

B00E - R0005 - Access Shower/Toilet/Change

No Asbestos

B00E - R0006 - Laundry - P

No Asbestos

B00E - R0007 - Access Shower/Toilet - Type 2

No Asbestos

B00E - R0008 - Movement

No Asbestos

B00E - R0009 - Home Base - M

No Asbestos

B00E - R0010 - Withdrawal - M

No Asbestos

B00E - R0011 - Home Base Store - M

No Asbestos

B00E - R0012 - External Movement

No Asbestos

B00E - R0013 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Other - 2009 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - M0001 - General Storeroom

No Asbestos

B00F - R0001 - General Assistant/Bulk Store

No Asbestos

B00F - R0002 - General Storeroom

No Asbestos

B00F - R0003 - General Assistant/Bulk Store

No Asbestos

B00F - R0004 - Staff Toilet

No Asbestos

B00F - R0005 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Building Services - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Garden Store Room

No Asbestos

B00G - R0002 - Shelter

No Asbestos

B00G - R0003 - Shelter

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00H - General Learning - 2009 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00H - R0001 - External Movement**

No Asbestos

B00H - R0002 - General Learning Space

No Asbestos

B00H - R0003 - Kitchen - Type 1

No Asbestos

B00H - R0004 - General Storeroom

No Asbestos

B00H - R0005 - General Learning Space

No Asbestos

B00H - R0006 - General Storeroom

No Asbestos

B00H - R0007 - Staff Kitchen

No Asbestos

B00H - R0008 - Access Staff Shower/Toilet

No Asbestos

B00H - R0009 - Staff Study

No Asbestos

B00H - R0010 - Toilets - Girls

No Asbestos

B00H - R0011 - Toilets - Boys

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - General Learning - 2009 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B001 - R0001 - External Movement

No Asbestos

B001 - R0002 - General Learning Space

No Asbestos

B001 - R0003 - General Storeroom

No Asbestos

B001 - R0004 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Administration - 1988 - Fibre Clad Shed (Fibre Clad Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00J - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 1988 - Fibre Clad Shed (Fibre Clad Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00K - R0001 - Practical Activities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Other - 1988 - Fibre Clad Shed (Fibre Clad Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00L - R0001 - Plant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Other - 2009 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00M - R0001 - Home Base

No Asbestos

B00M - R0002 - Kitchen - Pre

No Asbestos

B00M - R0003 - Toilets - Girls/Disabled Cubicle

No Asbestos

B00M - R0004 - External Movement

No Asbestos

B00M - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Other - 2009 - Greenhouse (Greenhouse)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00N - R0001 - Other

No Asbestos

B00N - R0002 - Other

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 603 - D10819 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 12/04/2011

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 601 - D13762 - Learning Unit - Standard/Withdrawal : Placement Date - 22/09/2003

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

OS 844 - D13911 - Country Toilet - Reltc - Boys/Girls : Placement Date - 15/01/2009

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	2.88 m2

Interior

R1 - Staff Toilet

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	9 m2

R2 - Staff Toilet

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	9 m2

OS 601 - D13969 - Learning Unit - Standard/Withdrawal : Placement Date - 22/11/2003

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 601 - D14026 - Learning Unit - Standard/Withdrawal : Placement Date - 6/01/2006						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017