


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Auburn Public School (7403)
Region : South Western Sydney
State Electorate : Auburn
Local Government Area : Auburn

Initial Survey : Noel Arnold & Associates : 21 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 28 - Aug - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1920 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00A - R0001 - Movement

No Asbestos

B00A - R0002 - Movement

No Asbestos

B00A - R0003 - Home Base

No Asbestos

B00A - R0004 - Security Store

No Asbestos

B00A - R0005 - General Storeroom

No Asbestos

B00A - R0006 - Home Base

No Asbestos

B00A - R0007 - Home Base

No Asbestos

B00A - R0008 - Home Base

No Asbestos

B00A - R0009 - Home Base

No Asbestos

B00A - R0011 - Movement

No Asbestos

B00A - R0012 - Movement

No Asbestos

B00A - R0013 - Staff Toilet

No Asbestos

B00A - R0014 - Sick Bay

No Asbestos

B00A - R0015 - Movement

No Asbestos

B00A - R0016 - Cleaning Distributed Store

No Asbestos

B00A - R0017 - Entry Vestibule

No Asbestos

B00A - R0018 - Clerical Office/Workroom

No Asbestos

B00A - R0019 - Deputy Principal

No Asbestos

B00A - R0020 - General Storeroom

No Asbestos

B00A - R0021 - Movement

No Asbestos

B00A - R0022 - Stairs

No Asbestos

B00A - R0023 - Stairs

No Asbestos

B00A - R0024 - Staff Room

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
						No Asbestos
	B00A - R0025 - Staff Kitchen					No Asbestos
	B00A - R1001 - Movement					No Asbestos
	B00A - R1002 - Home Base					No Asbestos
	B00A - R1003 - Home Base					No Asbestos
	B00A - R1004 - Home Base					No Asbestos
	B00A - R1005 - Special Programs Room					No Asbestos
	B00A - R1006 - Home Base					No Asbestos
	B00A - R1007 - Movement					No Asbestos
	B00A - R1008 - General Storeroom					No Asbestos
	B00A - R1009 - General Storeroom					No Asbestos
	B00A - R1010 - Communal Space					No Asbestos
	B00A - R1011 - Raised Platform					No Asbestos
	B00A - R1012 - Personal Effects Storage					No Asbestos
	B00A - R1013 - Movement					No Asbestos
	B00A - R1014 - Stairs					No Asbestos
	B00A - R1015 - Stairs					No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Pupil Facilities/General Learning - 1886 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting					
	7403/B00B/Underfloor Voids - Packing to Floor Joists/S19					No Asbestos Detected

Interior

B00B - R0001 - Home Base

Chalk Board	Flat AC Sheeting	1m2	East facing, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	7403/B00B/R0008/Chalk Board/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00B - R0002 - Home Base

Chalk Board	Flat AC Sheeting	1m2	North facing, West facing, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	7403/B00B/R0008/Chalk Board/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00B - R0003 - Toilets - Boys/Girls

No Asbestos

B00B - R0004 - Practical Activities - 1hb

No Asbestos

B00B - R0005 - Interview

No Asbestos

B00B - R0006 - Movement

No Asbestos

B00B - R0007 - Movement

No Asbestos

B00B - R0008 - Communal Space

Chalk Board	Flat AC Sheeting	8m2	All surfaces, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	7403/B00B/R0008/Chalk Board/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00B - R0009 - Personal Effects Storage

No Asbestos

B00B - R0010 - General Storeroom

No Asbestos

B00B - R0011 - Home Base

No Asbestos

B00B - R0012 - Practical Activities - 1hb

No Asbestos

B00B - R0013 - General Storeroom

No Asbestos

B00B - R0014 - Movement

No Asbestos

B00B - R0015 - General Storeroom

No Asbestos

B00B - R0016 - Practical Activities - 1hb

No Asbestos

B00B - R0017 - Home Base

No Asbestos

B00B - R0018 - Movement

No Asbestos

B00B - R0019 - Garden Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00B - R0020 - Movement						
No Asbestos						
B00B - R0021 - General Storeroom						
No Asbestos						
B00B - R0022 - Stairs						
No Asbestos						
B00B - R0023 - Stairs						
No Asbestos						
B00B - R1001 - Movement						
No Asbestos						
B00B - R1002 - Store						
No Asbestos						
B00B - R1003 - Home Base						
Chalk Board	Flat AC Sheeting	8m2	East facing, West facing, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	7403/B00B/R0008/Chalk Board/S15				Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00B - R1004 - Home Base						
Chalk Board	Flat AC Sheeting	12m2	All surfaces, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	7403/B00B/R0008/Chalk Board/S15				Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00B - R1005 - Practical Activities - 1hb						
No Asbestos						
B00B - R1006 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities/Pre-School Facilities - 1886 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00C - R0001 - Canteen Office/Store

No Asbestos

B00C - R0002 - Canteen

No Asbestos

B00C - R0003 - Movement

No Asbestos

B00C - R0004 - Movement

No Asbestos

B00C - R0005 - General Storeroom - Pre

Floor Coverings Res/Textile	Vinyl Tiles	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
7403/B00C/R0005/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	

B00C - R0006 - Special Programs Room

No Asbestos

B00C - R0007 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1913 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00F - R0001 - K.L.A. Store

Chalk Board	Flat AC Sheeting	8m2	West facing, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	7403/B00F/R0001/Chalk Board/S16					Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1996 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00G - R0001 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 7403/B00G/R0001/Partition Walls (Cubicles)/S3					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 7403/B00G/R0001/Wall Linings Internal/S4					No Asbestos Detected

B00G - R0002 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 7403/B00G/R0001/Partition Walls (Cubicles)/S3					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 7403/B00G/R0001/Wall Linings Internal/S4					No Asbestos Detected

B00G - R0004 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities - 1950 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids Non Accessible Area
- No Manhole to access Ceiling Void

Underfloor Voids - Slab on Ground No Asbestos Found

Interior

B00H - R0001 - Movement

No Asbestos

B00H - R0002 - Toilets - Boys

Ceiling Structures/Linings Flat AC Sheeting
7403/B00H/R0002/Ceiling Structures/Linings/S5 **No Asbestos Detected**

Partition Walls (Cubicles) Compressed AC Sheet
7403/B00H/R0002/Partition Walls (Cubicles)/S6 **No Asbestos Detected**

B00H - R0003 - Toilets - Girls

Ceiling Structures/Linings Flat AC Sheeting
7403/B00H/R0002/Ceiling Structures/Linings/S5 **No Asbestos Detected**

Partition Walls (Cubicles) Compressed AC Sheet
7403/B00H/R0002/Partition Walls (Cubicles)/S6 **No Asbestos Detected**

B00H - R0005 - Movement

No Asbestos

B00H - R0006 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - General Learning/Pupil Facilities - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B001 - R0001 - Covered Outdoor Learning Area

No Asbestos

B001 - R0002 - Movement

No Asbestos

B001 - R0003 - Canteen

No Asbestos

B001 - R0004 - Practical Activities - 1hb

No Asbestos

B001 - R0005 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0007 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0008 - Practical Activities - 1hb

No Asbestos

B001 - R0009 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0010 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Administration/General Learning - 1915 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	3m2	North facing, East facing, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	7403/B00J/Eaves Linings/S8					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting					
	7403/B00J/Underfloor Voids - Packing to Floor Joists/S20					No Asbestos Detected

Interior

B00J - R0001 - Entry Vestibule

No Asbestos

B00J - R0003 - Movement

No Asbestos

B00J - R0004 - Deputy Principal

No Asbestos

B00J - R0005 - Principal

No Asbestos

B00J - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0007 - Deputy Principal

No Asbestos

B00J - R0008 - Clerical Office

No Asbestos

B00J - R0009 - Clerical Office/Workroom

No Asbestos

B00J - R0010 - Security Store

No Asbestos

B00J - R0011 - Movement

No Asbestos

B00J - R0012 - Sick Bay

No Asbestos

B00J - R0013 - Sick Bay - Shower/Toilet

Wall Linings Internal Flat AC Sheeting
7403/B00J/R0013/Wall Linings Internal/S1

No Asbestos Detected

B00J - R0014 - Staff Room Annexe

No Asbestos

B00J - R0016 - Movement

No Asbestos

B00J - R0017 - Staff Toilet

Wall Linings Internal Flat AC Sheeting
7403/B00J/R0017/Wall Linings Internal/S2

No Asbestos Detected

B00J - R0018 - Staff Toilet

Wall Linings Internal Flat AC Sheeting
7403/B00J/R0017/Wall Linings Internal/S2

No Asbestos Detected

B00J - R0019 - Cleaning Distributed Store

No Asbestos

B00J - R0020 - General Storeroom

No Asbestos

B00J - R0021 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00J - R0022 - Movement						
No Asbestos						
B00J - R0023 - Disabled Toilet						
No Asbestos						
B00J - R0024 - Movement						
No Asbestos						
B00J - R0025 - Interview						
No Asbestos						
B00J - R0026 - General Storeroom						
No Asbestos						
B00J - R0027 - Movement						
No Asbestos						
B00J - R0028 - Movement						
No Asbestos						
B00J - R0029 - Cleaning Distributed Store						
No Asbestos						
B00J - R0030 - Stairs						
No Asbestos						
B00J - R0031 - Stairs						
No Asbestos						
B00J - R0032 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	7403/B00J/R0032/Ceiling Structures/Linings/S7					No Asbestos Detected
B00J - R0033 - Staff Room						
No Asbestos						
B00J - R0034 - Staff Kitchen						
No Asbestos						
B00J - R0035 - Movement						
No Asbestos						
B00J - R1001 - Movement						
Floor Coverings Res/Textile	Vinyl Sheet					
	7403/B00J/R1001/Floor Coverings Res/Textile/S22					No Asbestos Detected
B00J - R1002 - Home Base						
No Asbestos						
B00J - R1003 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	74m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	7403/B00J/R1004/Floor Coverings Res/Textile/S21					Chrysotile (white asbestos)
B00J - R1004 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	49m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	7403/B00J/R1004/Floor Coverings Res/Textile/S21					Chrysotile (white asbestos)
B00J - R1005 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	4m2	South	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	7403/B00J/R1004/Floor Coverings Res/Textile/S21					Chrysotile (white asbestos)
B00J - R1006 - General Storeroom						
No Asbestos						
B00J - R1007 - Practical Activities - 1hb						
No Asbestos						
B00J - R1008 - Withdrawal Space - 1hb						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 7403/B00J/R1004/Floor Coverings Res/Textile/S21	23m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
B00J - R1009 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 7403/B00J/R1004/Floor Coverings Res/Textile/S21	50m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
B00J - R1010 - Home Base						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 7403/B00J/R1004/Floor Coverings Res/Textile/S21	49m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
B00J - R1011 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 7403/B00J/R1004/Floor Coverings Res/Textile/S21	10m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
B00J - R1012 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 7403/B00J/R1004/Floor Coverings Res/Textile/S21	4m2	South	Minimal Damage (2)	Low (1)	Low Priority (2-3)
B00J - R1013 - Stairs						
No Asbestos						
B00J - R1014 - Stairs						
No Asbestos						
B00J - R9001 - General Storeroom						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Shed - 1921 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	No Asbestos Found					
Barge Board	Flat AC Sheeting					
	7403/B00K/Barge Board/S23					No Asbestos Detected

Interior

B00K - R0001 - Garden Store

Ceiling Structures/Linings	Flat AC Sheeting	26m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	7403/B00K/R0002/Ceiling Structures/Linings/S14					Chrysotile (white asbestos)

B00K - R0002 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting	32m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	7403/B00K/R0002/Ceiling Structures/Linings/S14					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning - 1996 - Brick/Block (Brick/Block)

Exterior

Window Infill Panels	Flat AC Sheeting 7403/B00L/Infill Panels/S13					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 7403/B00L/Gable Ends/S18					No Asbestos Detected
Gable Ends	Flat AC Sheeting 7403/B00L/Gable Ends/S18					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00L - R0001 - Movement

No Asbestos

B00L - R0002 - Practical Activities - 1hb

No Asbestos

B00L - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0006 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0007 - Practical Activities - 1hb

No Asbestos

B00L - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0009 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0010 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0011 - Movement

No Asbestos

B00L - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0013 - Practical Activities - 1hb

No Asbestos

B00L - R0014 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0015 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0016 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R0017 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00L - R0018 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00L - R0019 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00L - R0020 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00L - R0021 - Movement						
No Asbestos						
B00L - R0022 - Stairs						
No Asbestos						
B00L - R0023 - Stairs						
No Asbestos						
B00L - R0024 - Movement						
No Asbestos						
B00L - R1001 - Movement						
Wall Linings Internal	Flat AC Sheeting		7403/B00L/R1001/Wall Linings Internal/S12			No Asbestos Detected
B00L - R1002 - Practical Activities - 1hb						
No Asbestos						
B00L - R1003 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00L - R1004 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00L - R1005 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00L - R1006 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00L - R1007 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00L - R1008 - Practical Activities - 1hb						
No Asbestos						
B00L - R1009 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00L - R1010 - Practical Activities - 1hb						
No Asbestos						
B00L - R1011 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00L - R1012 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00L - R1013 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00L - R1014 - Home Base						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R1015 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00L - R1016 - Practical Activities - 1hb

No Asbestos

B00L - R1017 - Stairs

No Asbestos

B00L - R1018 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Tiered Learning - 1996 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00M - R0001 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00M - R0002 - Movement

No Asbestos

B00M - R0003 - Kiln Room

Wall Linings Internal	Flat AC Sheeting 7403/B00M/R0004/Wall Linings Internal/S10	No Asbestos Detected
-----------------------	---	-----------------------------

B00M - R0004 - No Access

Wall Linings Internal	Flat AC Sheeting 7403/B00M/R0004/Wall Linings Internal/S10	No Asbestos Detected
-----------------------	---	-----------------------------

B00M - R0005 - Cleaning Distributed Store

Wall Linings Internal	Flat AC Sheeting 7403/B00M/R0005/Wall Linings Internal/S11	No Asbestos Detected
-----------------------	---	-----------------------------

B00M - R0006 - Plant

Wall Linings Internal	Flat AC Sheeting 7403/B00M/R0005/Wall Linings Internal/S11	No Asbestos Detected
-----------------------	---	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Library - 1996 - Brick/Veneer (Brick/Veneer)

Exterior

Window Infill Panels	Flat AC Sheeting 7403/B00N/Infill Panels/S9					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00N - R0001 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

B00N - R0002 - Reading Area

Window Infill Panels	Flat AC Sheeting 7403/B00N/Infill Panels/S9					No Asbestos Detected
----------------------	--	--	--	--	--	-----------------------------

B00N - R0003 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00N - R0004 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Other-Community Use - 1923 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B000 - R0001 - General Storeroom

No Asbestos

B000 - R0002 - Movement

No Asbestos

B000 - R0003 - General Storeroom

No Asbestos

B000 - R0004 - Community Clinic

No Asbestos

B000 - R0005 - Community Clinic

No Asbestos

B000 - R0006 - Movement

No Asbestos

B000 - R0007 - Toilets - Boys/Girls

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Communal Facilities - 1997 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00P - R0001 - Canteen

No Asbestos

B00P - R0002 - Canteen Office/Store

No Asbestos

B00P - R0003 - Plant

No Asbestos

B00P - R0004 - Cleaning Supplies

No Asbestos

B00P - R0005 - Interview

No Asbestos

B00P - R0006 - Hall Chair Store

No Asbestos

B00P - R0007 - P.E. Store

No Asbestos

B00P - R0008 - Toilets - Girls

No Asbestos

B00P - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00P - R0010 - Communal Space

No Asbestos

B00P - R0011 - Shower/Change

No Asbestos

B00P - R0012 - Toilets - Boys

No Asbestos

B00P - R0013 - Sports Store

No Asbestos

B00P - R0014 - Garden Store

No Asbestos

B00P - R0015 - General Assistant/Bulk Store

No Asbestos

B00P - R0016 - Disabled Toilet

No Asbestos

B00P - R0017 - Cleaning Distributed Store

No Asbestos

B00P - R0018 - Raised Platform

No Asbestos

B00P - R0019 - Movement

No Asbestos

B00P - R0020 - Movement

No Asbestos

B00P - R0021 - Movement

No Asbestos

B00P - R0023 - Movement

No Asbestos

B00P - R0024 - Covered Outdoor Learning Area

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00Q - R0001 - Movement

No Asbestos

B00Q - R0002 - Practical Activities - 1hb

No Asbestos

B00Q - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00Q - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00Q - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00Q - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00Q - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00Q - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00R - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00R - R0001 - Movement

No Asbestos

B00R - R0002 - Practical Activities - 1hb

No Asbestos

B00R - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00R - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00R - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00R - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00R - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00R - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00S - Pupil Facilities - 2009 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00S - R0001 - External Movement

No Asbestos

B00S - R0002 - Cleaning Distributed Store

No Asbestos

B00S - R0003 - Handwashing Facilities

No Asbestos

B00S - R0004 - Toilets - Boys

No Asbestos

B00S - R0005 - Disabled Shower/Toilet

No Asbestos

B00S - R0006 - Handwashing Facilities

No Asbestos

B00S - R0007 - Toilets - Girls

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00T - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00T - R0001 - External Movement

No Asbestos

B00T - R0002 - Practical Activities/Movement - 1hb

No Asbestos

B00T - R0003 - Withdrawal Space - 1hb

No Asbestos

B00T - R0004 - Home Base Store

No Asbestos

B00T - R0005 - Home Base

No Asbestos

B00T - R0006 - Special Programs Room

No Asbestos

B00T - R0007 - Special Programs Store

No Asbestos

B00T - R0008 - Movement

No Asbestos

B00T - R0009 - No Access

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 751 - D11812 - Learning Unit - ESL : Placement Date - 22/02/2006

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		11.52 m2

Interior

R1 - Es1

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		36 m2

R2 - Es1

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		36 m2

OS 601 - D13736 - Learning Unit - Standard/Withdrawal : Placement Date - 12/01/2001

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos		10 m2
---------	---------------	------------------	--	-------

OS 601 - D14038 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos		10 m2
---------	---------------	------------------	--	-------

OS 750 - D14044 - Learning Unit - ESL : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		5.76 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Interior

R1 - Esl

End wall panel	Flat AC Sheet	Assumed Asbestos				50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017