


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Albury High School (8101)  
**Region :** Riverina  
**State Electorate :** Albury  
**Local Government Area :** Albury

**Initial Survey :** Noel Arnold & Associates : 14 - May - 2008  
**Reviewed By :** AECOM : 29 - Oct - 2014



2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

### B00A - Administration/General Learning - 1926 - Brick/Veneer (Brick/Veneer)

#### Exterior

|                  |  |
|------------------|--|
| Ceiling Voids    | Non Accessible Area<br>- Area inaccessible - Generally fixed ceilings and slab to lower level and 4-5m height. Generally fixed ceilings to upper level and 4-6m in height. Some areas inaccessible due recent fire and building re-construction works. |
| Underfloor Voids | No Asbestos Found  |

#### Interior

##### B00A - R0001 - Movement (3.04 m2)

No Asbestos

##### B00A - R0002 - General Learning Space (60.01 m2)

No Asbestos

##### B00A - R0003 - Principal Office (27.98 m2)

No Asbestos

##### B00A - R0004 - Principal Office (26.45 m2)

No Asbestos

##### B00A - R0008 - Administration - Clerical (26.15 m2)

No Asbestos

##### B00A - R0009 - Movement (39.64 m2)

No Asbestos

##### B00A - R0010 - Movement (257.11 m2)

No Asbestos

##### B00A - R0011 - Deputy Principal Office (10.33 m2)

No Asbestos

##### B00A - R0012 - Deputy Principal Office (16.14 m2)

No Asbestos

##### B00A - R0013 - General Storeroom (7.4 m2)

No Asbestos

##### B00A - R0014 - Leading Teacher (8.61 m2)

No Asbestos

##### B00A - R0015 - Duplicating Workroom (33.15 m2)

No Asbestos

##### B00A - R0016 - General Learning Space (55.16 m2)

No Asbestos

##### B00A - R0017 - Senior Study (60.09 m2)

No Asbestos

##### B00A - R0018 - Movement (2.99 m2)

No Asbestos

##### B00A - R0019 - Movement (2.99 m2)

No Asbestos

##### B00A - R0020 - Cleaning Store - Distributed (5.13 m2)

No Asbestos

##### B00A - R0021 - Staff Study (10.68 m2)

No Asbestos

##### B00A - R0022 - Pupil Entry (10.3 m2)

No Asbestos

##### B00A - R0024 - Commonroom (79.01 m2)

No Asbestos

| Product  | Material Description | Extent                           | Location Reference                                     | Material Condition | Risk Status                        | Control Priority   |
|--|----------------------|----------------------------------|--|--------------------|------------------------------------|--------------------|
| Sample No  |                      |                                  |  |                    | Test Result                        |                    |
| <b>B00A - R0025 - Clinic - Girls (14.78 m2)</b>              |                      |                                  |  |                    |                                    |                    |
| No Asbestos  |                      |                                  |  |                    |                                    |                    |
| <b>B00A - R0026 - Clinic - Boys (14.87 m2)</b>               |                      |                                  |  |                    |                                    |                    |
| No Asbestos  |                      |                                  |  |                    |                                    |                    |
| <b>B00A - R0027 - General Storeroom (10.7 m2)</b>            |                      |                                  |  |                    |                                    |                    |
| No Asbestos  |                      |                                  |  |                    |                                    |                    |
| <b>B00A - R0028 - Interview/Office - Type 1 (10.77 m2)</b>   |                      |                                  |  |                    |                                    |                    |
| No Asbestos  |                      |                                  |  |                    |                                    |                    |
| <b>B00A - R0029 - Staff Study (12.62 m2)</b>                 |                      |                                  |  |                    |                                    |                    |
| Floor Coverings Res/Textile                                  | Vinyl Tiles          | 7m2                              | East facing  | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00A/R0023/Floor Coverings Res/Textile/S2               |                      |                                  |  |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00A - R0030 - Office/Store (6.34 m2)</b>                 |                      |                                  |  |                    |                                    |                    |
| No Asbestos  |                      |                                  |  |                    |                                    |                    |
| <b>B00A - R0031 - Staff - Toilet (23.7 m2)</b>               |                      |                                  |  |                    |                                    |                    |
| Floor Coverings Res/Textile                                  | Vinyl Tiles          | 11m2                             | East facing  | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00A/R0023/Floor Coverings Res/Textile/S2               |                      |                                  |  |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00A - R0032 - General Storeroom (3.66 m2)</b>            |                      |                                  |  |                    |                                    |                    |
| No Asbestos  |                      |                                  |  |                    |                                    |                    |
| <b>B00A - R0033 - Cleaning Store - Distributed (3.18 m2)</b> |                      |                                  |  |                    |                                    |                    |
| No Asbestos  |                      |                                  |  |                    |                                    |                    |
| <b>B00A - R0034 - Staff Study (10.69 m2)</b>                 |                      |                                  |  |                    |                                    |                    |
| No Asbestos  |                      |                                  |  |                    |                                    |                    |
| <b>B00A - R0035 - General Storeroom (5.04 m2)</b>            |                      |                                  |  |                    |                                    |                    |
| No Asbestos  |                      |                                  |  |                    |                                    |                    |
| <b>B00A - R0036 - Movement (2.99 m2)</b>                     |                      |                                  |  |                    |                                    |                    |
| No Asbestos  |                      |                                  |  |                    |                                    |                    |
| <b>B00A - R0037 - Stairs (9.68 m2)</b>                       |                      |                                  |  |                    |                                    |                    |
| No Asbestos  |                      |                                  |  |                    |                                    |                    |
| <b>B00A - R0038 - Stairs (9.58 m2)</b>                       |                      |                                  |  |                    |                                    |                    |
| No Asbestos  |                      |                                  |  |                    |                                    |                    |
| <b>B00A - R0039 - Toilet - Lobby (16.66 m2)</b>              |                      |                                  |  |                    |                                    |                    |
| Floor Coverings Res/Textile                                  | Vinyl Tiles          | 8m2                              | Portion of floor                                       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00A/R0039/Floor Coverings Res/Textile/S28              |                      |                                  |  |                    | <b>Chrysotile (white asbestos)</b> |                    |
| Bituminous adhesive to floor                                 | Bituminous adhesive  | 16.67m2                          | Throughout room (below vinyl floor tiles and sheeting) | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00A/R0039/Bituminous adhesive to floor/S31             |                      |                                  |  |                    | <b>Chrysotile (white asbestos)</b> |                    |
| Window putty   | Mastic               | 8101/B00A/R0039/Window putty/S32 |  |                    | <b>No Asbestos Detected</b>        |                    |
| <b>B00A - R0040 - Staff - Toilet (5.85 m2)</b>               |                      |                                  |  |                    |                                    |                    |
| Bituminous adhesive to floor                                 | Bituminous adhesive  | 5.86m2                           | Throughout (below vinyl floor sheeting)                | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00A/R0039/Bituminous adhesive to floor/S31             |                      |                                  |  |                    | <b>Chrysotile (white asbestos)</b> |                    |
| Window putty   | Mastic               | 8101/B00A/R0039/Window putty/S32 |  |                    | <b>No Asbestos Detected</b>        |                    |
| <b>B00A - R0041 - Administration - Clerical (47.73 m2)</b>   |                      |                                  |  |                    |                                    |                    |
| No Asbestos  |                      |                                  |  |                    |                                    |                    |
| <b>B00A - R1001 - General Learning Space (61.37 m2)</b>      |                      |                                  |  |                    |                                    |                    |

| Product  | Material Description | Extent | Location Reference                 | Material Condition | Risk Status | Control Priority            |
|--|----------------------|--------|------------------------------------|--------------------|-------------|-----------------------------|
| Sample No  |                      |        |                                    |                    | Test Result |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |
| <b>B00A - R1002 - General Storeroom (17.36 m2)</b>         |                      |        |                                    |                    |             |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |
| <b>B00A - R1003 - General Learning Space (56.57 m2)</b>    |                      |        |                                    |                    |             |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |
| <b>B00A - R1006 - Staff Study (81.22 m2)</b>               |                      |        |                                    |                    |             |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |
| <b>B00A - R1007 - General Learning Space (52.72 m2)</b>    |                      |        |                                    |                    |             |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |
| <b>B00A - R1008 - General Learning Space (57.11 m2)</b>    |                      |        |                                    |                    |             |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |
| <b>B00A - R1009 - General Learning Space (61.21 m2)</b>    |                      |        |                                    |                    |             |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |
| <b>B00A - R1010 - Movement (157.19 m2)</b>                 |                      |        |                                    |                    |             |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |
| <b>B00A - R1011 - Staff Study (11.19 m2)</b>               |                      |        |                                    |                    |             |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |
| <b>B00A - R1012 - General Storeroom (2.78 m2)</b>          |                      |        |                                    |                    |             |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |
| <b>B00A - R1013 - Pupil Entry (4.63 m2)</b>                |                      |        |                                    |                    |             |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |
| <b>B00A - R1014 - General Storeroom (2.93 m2)</b>          |                      |        |                                    |                    |             |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |
| <b>B00A - R1015 - Movement (250.01 m2)</b>                 |                      |        |                                    |                    |             |                             |
| Floor Coverings Res/Textile                                | Vinyl Sheet          |        |                                    |                    |             |                             |
|  |                      |        | 8101/B00A/R1019/Floor coverings/S1 |                    |             | <b>No Asbestos Detected</b> |
| <b>B00A - R1016 - Interview/Office - Type 1 (11.58 m2)</b> |                      |        |                                    |                    |             |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |
| <b>B00A - R1017 - Staff Study (11.53 m2)</b>               |                      |        |                                    |                    |             |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |
| <b>B00A - R1018 - General Storeroom (8.81 m2)</b>          |                      |        |                                    |                    |             |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |
| <b>B00A - R1019 - Movement (32.48 m2)</b>                  |                      |        |                                    |                    |             |                             |
| Floor Coverings Res/Textile                                | Vinyl Sheet          |        |                                    |                    |             |                             |
|  |                      |        | 8101/B00A/R1019/Floor coverings/S1 |                    |             | <b>No Asbestos Detected</b> |
| <b>B00A - R1020 - General Storeroom (36.93 m2)</b>         |                      |        |                                    |                    |             |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |
| <b>B00A - R1021 - Stairs (10.77 m2)</b>                    |                      |        |                                    |                    |             |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |
| <b>B00A - R1022 - Stairs (10.77 m2)</b>                    |                      |        |                                    |                    |             |                             |
| No Asbestos  |                      |        |                                    |                    |             |                             |

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00B - Various - 1979 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Slab on Ground

Ceiling Voids Non Accessible Area  
- Area inaccessible - lower level is generally vermiculite/slab.  
Upper level is generally fixed raked ceilings.

**Interior****B00B - M2001 - No Access (70.16 m2)**

Loose insulation material Encapsulated Insulation material within unit  
8101/B00B/M2001/Loose insulation material/S33 **No Asbestos Detected**

**B00B - M2002 - Careers Advisers Office (38.71 m2)**

No Asbestos

**B00B - M2003 - Main Area (68.74 m2)**

No Asbestos

**B00B - M2004 - No Access (25.53 m2)**

No Asbestos

**B00B - M2005 - General Storeroom (14.87 m2)**

No Asbestos

**B00B - M2006 - No Access (25.51 m2)**

Loose insulation material Encapsulated Insulation material within unit  
8101/B00B/M2001/Loose insulation material/S33 **No Asbestos Detected**

**B00B - M2007 - Stairs (3.27 m2)**

No Asbestos

**B00B - M2008 - Stairs (3.24 m2)**

No Asbestos

**B00B - R0001 - General Storeroom (8.1 m2)**

No Asbestos

**B00B - R0002 - Movement (30.91 m2)**

No Asbestos

**B00B - R0003 - General Storeroom (23.5 m2)**

Floor Coverings Vinyl Tiles 24m2 All surfaces Good Condition (1) Low (1) Low Priority (2-3)  
Res/Textile  
8101/B00B/R1004/Floor Coverings Res/Textile/S4 **Chrysotile (white asbestos)**

**B00B - R0004 - Computer Learning Space (56.12 m2)**

Ceiling Structures/Linings Vermiculite  
8101/B00B/R2007/Ceiling Structures/Linings/S3 **Limited Samples Taken**  
**Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works**

Floor Coverings Vinyl Tiles 57m2 All surfaces Good Condition (1) Low (1) Low Priority (2-3)  
Res/Textile  
8101/B00B/R1004/Floor Coverings Res/Textile/S4 **Chrysotile (white asbestos)**

**B00B - R0005 - General Storeroom (5.16 m2)**

Floor Coverings Vinyl Tiles 6m2 All surfaces Good Condition (1) Low (1) Low Priority (2-3)  
Res/Textile  
8101/B00B/R1004/Floor Coverings Res/Textile/S4 **Chrysotile (white asbestos)**

**B00B - R0006 - Computer Learning Space (61.83 m2)**

Ceiling Structures/Linings Vermiculite  
8101/B00B/R2007/Ceiling Structures/Linings/S3 **Limited Samples Taken**  
**Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works**

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status                        | Control Priority   |
|---|----------------------|--------|--------------------|--------------------|------------------------------------|--------------------|
| Sample No   |                      |        |                    |                    | Test Result                        |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 62m2   | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R0007 - General Storeroom (6.64 m2)</b>   |                      |        |                    |                    |                                    |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 7m2    | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R0008 - Computer Learning Space (57.11 m2)</b>  |                      |        |                    |                    |                                    |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |                                    |                    |
| 8101/B00B/R2007/Ceiling Structures/Linings/S3   |                      |        |                    |                    | <b>Limited Samples Taken</b>       |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                    |                    |                                    |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 5m2    | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R0009 - General Storeroom (5.06 m2)</b>   |                      |        |                    |                    |                                    |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 6m2    | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R0011 - Materials Store (7.93 m2)</b>   |                      |        |                    |                    |                                    |                    |
| No Asbestos   |                      |        |                    |                    |                                    |                    |
| <b>B00B - R0012 - Plant (11.49 m2)</b>  |                      |        |                    |                    |                                    |                    |
| Flue  | Fibre Cement Pipe    | 15m    | South facing       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R0012/Flue/S6   |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R0013 - Garden Store Room (5.55 m2)</b>   |                      |        |                    |                    |                                    |                    |
| No Asbestos   |                      |        |                    |                    |                                    |                    |
| <b>B00B - R0014 - General Learning Space (61.9 m2)</b>  |                      |        |                    |                    |                                    |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |                                    |                    |
| 8101/B00B/R2007/Ceiling Structures/Linings/S3   |                      |        |                    |                    | <b>Limited Samples Taken</b>       |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                    |                    |                                    |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 62m2   | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R0015 - General Storeroom (6.4 m2)</b>  |                      |        |                    |                    |                                    |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 7m2    | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R0016 - General Learning Space (61.82 m2)</b>   |                      |        |                    |                    |                                    |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |                                    |                    |
| 8101/B00B/R2007/Ceiling Structures/Linings/S3   |                      |        |                    |                    | <b>Limited Samples Taken</b>       |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                    |                    |                                    |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 62m2   | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R0017 - General Storeroom (6.55 m2)</b>   |                      |        |                    |                    |                                    |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 7m2    | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R0018 - General Learning Space (57.52 m2)</b>   |                      |        |                    |                    |                                    |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |                                    |                    |
| 8101/B00B/R2007/Ceiling Structures/Linings/S3   |                      |        |                    |                    | <b>Limited Samples Taken</b>       |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                    |                    |                                    |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 58m2   | All surfaces       | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R0019 - General Storeroom (5.02 m2)</b>   |                      |        |                    |                    |                                    |                    |

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status  | Control Priority   |
|---|----------------------|--------|--------------------|--------------------|--|--------------------|
| Sample No   |                      |        |                    |                    | Test Result  |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 6m2    | All surfaces       | Good Condition (1) | Low (1)  | Low Priority (2-3) |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>                   |                    |
| <b>B00B - R0020 - Movement (55.27 m2)</b>   |                      |        |                    |                    |  |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 56m2   | All surfaces       | Good Condition (1) | Low (1)  | Low Priority (2-3) |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>                   |                    |
| <b>B00B - R0021 - Stairs (8.2 m2)</b>   |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00B - R0022 - Stairs (8.2 m2)</b>   |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00B - R0023 - Lift (2.24 m2)</b>  |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00B - R0024 - Movement (29.3 m2)</b>  |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00B - R1001 - Laboratory L.S. (91.14 m2)</b>  |                      |        |                    |                    |  |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 92m2   | All surfaces       | Good Condition (1) | Low (1)  | Low Priority (2-3) |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>                   |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |  |                    |
| 8101/B00B/R2007/Ceiling Structures/Linings/S3   |                      |        |                    |                    | <b>Limited Samples Taken</b>                         |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                    |                    |  |                    |
| <b>B00B - R1002 - Movement (25.06 m2)</b>   |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00B - R1003 - Laboratory L.S. (83.81 m2)</b>  |                      |        |                    |                    |  |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |  |                    |
| 8101/B00B/R2007/Ceiling Structures/Linings/S3   |                      |        |                    |                    | <b>Limited Samples Taken</b>                         |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                    |                    |  |                    |
| <b>B00B - R1007 - Laboratory L.S. (82.47 m2)</b>  |                      |        |                    |                    |  |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |  |                    |
| 8101/B00B/R2007/Ceiling Structures/Linings/S3   |                      |        |                    |                    | <b>Limited Samples Taken</b>                         |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                    |                    |  |                    |
| <b>B00B - R1008 - Movement (59 m2)</b>  |                      |        |                    |                    |  |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 60m2   | All surfaces       | Good Condition (1) | Low (1)  | Low Priority (2-3) |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>                   |                    |
| <b>B00B - R1010 - Distribution Board Cupboard (0.45 m2)</b>   |                      |        |                    |                    |  |                    |
|   |                      |        |                    |                    | Note: No inspection of live electrical installation. |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00B - R1011 - Laboratory L.S. (91.14 m2)</b>  |                      |        |                    |                    |  |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |  |                    |
| 8101/B00B/R2007/Ceiling Structures/Linings/S3   |                      |        |                    |                    | <b>Limited Samples Taken</b>                         |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                    |                    |  |                    |
| <b>B00B - R1012 - Chemical Store (12.71 m2)</b>   |                      |        |                    |                    |  |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |  |                    |
| 8101/B00B/R2007/Ceiling Structures/Linings/S3   |                      |        |                    |                    | <b>Limited Samples Taken</b>                         |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                    |                    |  |                    |
| <b>B00B - R1013 - Chemical Store (3.2 m2)</b>   |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00B - R1014 - Preparation (31.54 m2)</b>  |                      |        |                    |                    |  |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |  |                    |
| 8101/B00B/R2007/Ceiling Structures/Linings/S3   |                      |        |                    |                    | <b>Limited Samples Taken</b>                         |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                    |                    |  |                    |
| <b>B00B - R1015 - Stairs (17.05 m2)</b>   |                      |        |                    |                    |  |                    |

| Product   | Material Description | Extent | Location Reference         | Material Condition | Risk Status                        | Control Priority   |
|---|----------------------|--------|----------------------------|--------------------|------------------------------------|--------------------|
| Sample No   |                      |        |                            |                    | Test Result                        |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 18m2   | All surfaces               | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                            |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R1016 - Stairs (17 m2)</b>  |                      |        |                            |                    |                                    |                    |
| No Asbestos   |                      |        |                            |                    |                                    |                    |
| <b>B00B - R1017 - Movement (20.94 m2)</b>   |                      |        |                            |                    |                                    |                    |
| No Asbestos   |                      |        |                            |                    |                                    |                    |
| <b>B00B - R1018 - Preparation - Science (44.38 m2)</b>  |                      |        |                            |                    |                                    |                    |
| Window putty  | Mastic               | 2Unit  | Throughout                 | Minimal Damage (2) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R1018/Window putty/S34  |                      |        |                            |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R2001 - General Storeroom (12.92 m2)</b>  |                      |        |                            |                    |                                    |                    |
| Eaves Lining  | Compressed AC Sheet  | 2m2    | North facing, South facing | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R2007/Internal Eave/S4  |                      |        |                            |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R2002 - Workroom (17.72 m2)</b>   |                      |        |                            |                    |                                    |                    |
| No Asbestos   |                      |        |                            |                    |                                    |                    |
| <b>B00B - R2003 - Staff - Toilet (3.16 m2)</b>  |                      |        |                            |                    |                                    |                    |
| No Asbestos   |                      |        |                            |                    |                                    |                    |
| <b>B00B - R2004 - Movement (26.55 m2)</b>   |                      |        |                            |                    |                                    |                    |
| No Asbestos   |                      |        |                            |                    |                                    |                    |
| <b>B00B - R2005 - Toilets-Boys (3.04 m2)</b>  |                      |        |                            |                    |                                    |                    |
| No Asbestos   |                      |        |                            |                    |                                    |                    |
| <b>B00B - R2006 - General Learning Space (72.08 m2)</b>   |                      |        |                            |                    |                                    |                    |
| Eaves Lining  | Compressed AC Sheet  | 2m2    | North facing, South facing | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R2007/Internal Eave/S4  |                      |        |                            |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R2007 - Main Area (325.64 m2)</b>   |                      |        |                            |                    |                                    |                    |
| Eaves Lining  | Compressed AC Sheet  | 20m2   | North facing, South facing | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R2007/Internal Eave/S5  |                      |        |                            |                    | <b>Chrysotile (white asbestos)</b> |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                            |                    |                                    |                    |
| 8101/B00B/R2007/Ceiling Structures/Linings/S3   |                      |        |                            |                    | <b>Limited Samples Taken</b>       |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                            |                    |                                    |                    |
| <b>B00B - R2008 - Study Space (13.11 m2)</b>  |                      |        |                            |                    |                                    |                    |
| Eaves Lining  | Compressed AC Sheet  | 2m2    | North facing, South facing | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R2007/Internal Eave/S4  |                      |        |                            |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R2009 - Study Space (11.61 m2)</b>  |                      |        |                            |                    |                                    |                    |
| No Asbestos   |                      |        |                            |                    |                                    |                    |
| <b>B00B - R2010 - No Access (7.62 m2)</b>   |                      |        |                            |                    |                                    |                    |
| No Asbestos   |                      |        |                            |                    |                                    |                    |
| <b>B00B - R2011 - No Access (4.9 m2)</b>  |                      |        |                            |                    |                                    |                    |
| No Asbestos   |                      |        |                            |                    |                                    |                    |
| <b>B00B - R2012 - Cleaning Store - Distributed (0.36 m2)</b>  |                      |        |                            |                    |                                    |                    |
| No Asbestos   |                      |        |                            |                    |                                    |                    |
| <b>B00B - R2013 - Movement (4.29 m2)</b>  |                      |        |                            |                    |                                    |                    |
| No Asbestos   |                      |        |                            |                    |                                    |                    |
| <b>B00B - R2014 - Movement (0.24 m2)</b>  |                      |        |                            |                    |                                    |                    |
| No Asbestos   |                      |        |                            |                    |                                    |                    |
| <b>B00B - R2016 - Study Space (11.7 m2)</b>   |                      |        |                            |                    |                                    |                    |
| No Asbestos   |                      |        |                            |                    |                                    |                    |



| Product  | Material Description | Extent | Location Reference         | Material Condition | Risk Status                        | Control Priority   |
|--|----------------------|--------|----------------------------|--------------------|------------------------------------|--------------------|
| Sample No  |                      |        |                            |                    | Test Result                        |                    |
| <b>B00B - R2017 - Study Space (13.11 m2)</b>           |                      |        |                            |                    |                                    |                    |
| Eaves Lining   | Compressed AC Sheet  | 2m2    | North facing, South facing | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R2007/Internal Eave/S4                       |                      |        |                            |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R2018 - Audio Visual Workroom (28.58 m2)</b> |                      |        |                            |                    |                                    |                    |
| Eaves Lining   | Compressed AC Sheet  | 2m2    | North facing, South facing | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R2007/Internal Eave/S4                       |                      |        |                            |                    | <b>Chrysotile (white asbestos)</b> |                    |
| <b>B00B - R2019 - Librarian (11.33 m2)</b>             |                      |        |                            |                    |                                    |                    |
| No Asbestos  |                      |        |                            |                    |                                    |                    |
| <b>B00B - R2020 - Stairs (17.05 m2)</b>                |                      |        |                            |                    |                                    |                    |
| No Asbestos  |                      |        |                            |                    |                                    |                    |
| <b>B00B - R2021 - Stairs (17 m2)</b>                   |                      |        |                            |                    |                                    |                    |
| No Asbestos  |                      |        |                            |                    |                                    |                    |
| <b>B00B - R2022 - Stairs (0.71 m2)</b>                 |                      |        |                            |                    |                                    |                    |
| No Asbestos  |                      |        |                            |                    |                                    |                    |
| <b>B00B - R2023 - Stairs (0.78 m2)</b>                 |                      |        |                            |                    |                                    |                    |
| No Asbestos  |                      |        |                            |                    |                                    |                    |
| <b>B00B - R2024 - Movement (30.77 m2)</b>              |                      |        |                            |                    |                                    |                    |
| Ceiling Structures/Linings                             | Flat AC Sheeting     |        |                            |                    |                                    |                    |
| 8101/B00B/R2024/Ceiling Structures/Linings/S35         |                      |        |                            |                    | <b>No Asbestos Detected</b>        |                    |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00C - Technological & Applied Studies - 1979 - Brick/Block (Brick/Block)****Exterior**

|                                   |   |  |  |  |  |                             |
|-----------------------------------|---|--|--|--|--|-----------------------------|
| Awnings                           | Flat AC Sheeting<br>8101/B00C/Awnings/S13   |  |  |  |  | <b>No Asbestos Detected</b> |
| Underfloor Voids - Slab on Ground |   |  |  |  |  |                             |
| Ceiling Voids                     | Non Accessible Area<br>- Area inaccessible - Lower level fixed ceilings/slab. Upper level fixed raked ceilings. |  |  |  |  |                             |

**Interior****B00C - R0001 - Materials Technology L.S. (82.76 m2)**

|   |  |  |  |  |  |                              |
|---|--|--|--|--|--|------------------------------|
| Ceiling Structures/Linings  | Vermiculite<br>8101/B00C/R2006/Ceiling Structures/Linings/S8 |  |  |  |  | <b>Limited Samples Taken</b> |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |  |  |  |  |  |                              |

**B00C - R0002 - Movement (2.35 m2)**

No Asbestos

**B00C - R0003 - Distribution Board Cupboard (0.74 m2)**

Note: No inspection of live electrical installation.

|  |                                 |       |              |                    |         |                                    |
|--|---------------------------------|-------|--------------|--------------------|---------|------------------------------------|
| Door Lining  | Flat AC Sheeting                | 6m2   | North facing | Good Condition (1) | Low (1) | Low Priority (2-3)                 |
|  | 8101/B00C/R0003/Door Lining/S10 |       |              |                    |         | <b>Chrysotile (white asbestos)</b> |
| Electrical Mounting Board                                  | Resinous Board                  | 1Unit | West facing  | Good Condition (1) | Low (1) | Low Priority (2-3)                 |
| <b>Assumed Asbestos - Electrical Hazard - board marked</b> |                                 |       |              |                    |         |                                    |

**B00C - R0004 - Cleaning Store - Distributed (4.1 m2)**

No Asbestos

**B00C - R0005 - Staff - Toilet (20.39 m2)**

|   |  |  |  |  |  |                              |
|---|--|--|--|--|--|------------------------------|
| Ceiling Structures/Linings  | Vermiculite<br>8101/B00C/R2006/Ceiling Structures/Linings/S8 |  |  |  |  | <b>Limited Samples Taken</b> |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |  |  |  |  |  |                              |

**B00C - R0006 - Staff Study (19.27 m2)**

|   |  |  |  |  |  |                              |
|---|--|--|--|--|--|------------------------------|
| Ceiling Structures/Linings  | Vermiculite<br>8101/B00C/R2006/Ceiling Structures/Linings/S8 |  |  |  |  | <b>Limited Samples Taken</b> |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |  |  |  |  |  |                              |

**B00C - R0007 - Art Learning Space (63.86 m2)**

|   |  |      |              |                    |         |                                    |
|---|--|------|--------------|--------------------|---------|------------------------------------|
| Ceiling Structures/Linings  | Vermiculite<br>8101/B00C/R2006/Ceiling Structures/Linings/S8 |      |              |                    |         | <b>Limited Samples Taken</b>       |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |  |      |              |                    |         |                                    |
| Floor Coverings Res/Textile   | Vinyl Tiles  | 64m2 | All surfaces | Good Condition (1) | Low (1) | Low Priority (2-3)                 |
|   | 8101/B00B/R1004/Floor Coverings Res/Textile/S4               |      |              |                    |         | <b>Chrysotile (white asbestos)</b> |

**B00C - R0008 - Kiln Space (14.51 m2)**

|   |  |      |              |                    |         |                                    |
|---|--|------|--------------|--------------------|---------|------------------------------------|
| Ceiling Structures/Linings  | Vermiculite<br>8101/B00C/R2006/Ceiling Structures/Linings/S8 |      |              |                    |         | <b>Limited Samples Taken</b>       |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |  |      |              |                    |         |                                    |
| Floor Coverings Res/Textile   | Vinyl Tiles  | 15m2 | All surfaces | Good Condition (1) | Low (1) | Low Priority (2-3)                 |
|   | 8101/B00B/R1004/Floor Coverings Res/Textile/S4               |      |              |                    |         | <b>Chrysotile (white asbestos)</b> |

**B00C - R0009 - Resources Store (8.06 m2)**

|   |  |     |              |                    |         |                                    |
|---|--|-----|--------------|--------------------|---------|------------------------------------|
| Ceiling Structures/Linings  | Vermiculite<br>8101/B00C/R2006/Ceiling Structures/Linings/S8 |     |              |                    |         | <b>Limited Samples Taken</b>       |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |  |     |              |                    |         |                                    |
| Floor Coverings Res/Textile   | Vinyl Tiles  | 9m2 | All surfaces | Good Condition (1) | Low (1) | Low Priority (2-3)                 |
|   | 8101/B00B/R1004/Floor Coverings Res/Textile/S4               |     |              |                    |         | <b>Chrysotile (white asbestos)</b> |

| Product   | Material Description                           | Extent  | Location Reference | Material Condition | Risk Status | Control Priority            |
|---|--|---------|--------------------|--------------------|-------------|-----------------------------|
| Sample No   |  |         |                    |                    | Test Result |                             |
| <b>B00C - R0011 - Movement (22.27 m2)</b>   |  |         |                    |                    |             |                             |
| No Asbestos   |  |         |                    |                    |             |                             |
| <b>B00C - R0012 - General Storeroom (8.36 m2)</b>   |  |         |                    |                    |             |                             |
| No Asbestos   |  |         |                    |                    |             |                             |
| <b>B00C - R0015 - General Storeroom (10.92 m2)</b>  |  |         |                    |                    |             |                             |
| Ceiling Structures/Linings  | Vermiculite                                    |         |                    |                    |             |                             |
|   | 8101/B00C/R2006/Ceiling Structures/Linings/S8  |         |                    |                    |             | Limited Samples Taken       |
| <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |  |         |                    |                    |             |                             |
| <b>B00C - R0016 - Materials Store (21.14 m2)</b>  |  |         |                    |                    |             |                             |
| Ceiling Structures/Linings  | Vermiculite                                    |         |                    |                    |             |                             |
|   | 8101/B00C/R2006/Ceiling Structures/Linings/S8  |         |                    |                    |             | Limited Samples Taken       |
| <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |  |         |                    |                    |             |                             |
| <b>B00C - R0017 - Movement (53.54 m2)</b>   |  |         |                    |                    |             |                             |
| Ceiling Structures/Linings  | Vermiculite                                    |         |                    |                    |             |                             |
|   | 8101/B00C/R2006/Ceiling Structures/Linings/S8  |         |                    |                    |             | Limited Samples Taken       |
| <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |  |         |                    |                    |             |                             |
| Floor Coverings Res/Textile   | Vinyl Tiles                                    | 54m2    | All surfaces       | Good Condition (1) | Low (1)     | Low Priority (2-3)          |
|   | 8101/B00B/R1004/Floor Coverings Res/Textile/S4 |         |                    |                    |             | Chrysotile (white asbestos) |
| <b>B00C - R0018 - Stairs (8.51 m2)</b>  |  |         |                    |                    |             |                             |
| No Asbestos   |  |         |                    |                    |             |                             |
| <b>B00C - R0019 - Kiln Space (3.82 m2)</b>  |  |         |                    |                    |             |                             |
| Ceiling Structures/Linings  | Flat AC Sheeting                               |         |                    |                    |             |                             |
|   | 8101/B00C/R0019/Ceiling Structures/Linings/S36 |         |                    |                    |             | No Asbestos Detected        |
| <b>B00C - R0020 - Dust Extraction Space (11.71 m2)</b>  |  |         |                    |                    |             |                             |
| Wall Linings Internal   | Flat AC Sheeting                               |         |                    |                    |             |                             |
|   | 8101/B00C/R0020/Wall Linings Internal/S40      |         |                    |                    |             | No Asbestos Detected        |
| Ceiling Structures/Linings  | Flat AC Sheeting                               | 11.72m2 | Throughout         | Good Condition (1) | Low (1)     | Low Priority (2-3)          |
| <i>Assumed Asbestos - Area inaccessible - height</i>  |  |         |                    |                    |             |                             |
| <b>B00C - R0021 - Movement (4.64 m2)</b>  |  |         |                    |                    |             |                             |
| No Asbestos   |  |         |                    |                    |             |                             |
| <b>B00C - R0022 - Staff - Toilet (10.59 m2)</b>   |  |         |                    |                    |             |                             |
| Partition Walls (Cubicles)  | Compressed AC Sheet                            | 3m2     | Throughout         | Good Condition (1) | Low (1)     | Low Priority (2-3)          |
|   | 8101/B00C/R0022/Partition Walls (Cubicles)/S37 |         |                    |                    |             | Chrysotile (white asbestos) |
| <b>B00C - R0023 - Staff - Toilet (5.56 m2)</b>  |  |         |                    |                    |             |                             |
| Partition Walls (Cubicles)  | Compressed AC Sheet                            | 5m2     | Throughout         | Good Condition (1) | Low (1)     | Low Priority (2-3)          |
|   | 8101/B00C/R0022/Partition Walls (Cubicles)/S37 |         |                    |                    |             | Chrysotile (white asbestos) |
| Wall Linings Internal   | Flat AC Sheeting                               |         |                    |                    |             |                             |
|   | 8101/B00C/R0023/Wall Linings Internal/S38      |         |                    |                    |             | No Asbestos Detected        |
| <b>B00C - R0024 - Materials Technology L.S. (82.57 m2)</b>  |  |         |                    |                    |             |                             |
| Ceiling Structures/Linings  | Vermiculite                                    |         |                    |                    |             |                             |
|   | 8101/B00C/R2006/Ceiling Structures/Linings/S8  |         |                    |                    |             | Limited Samples Taken       |
| <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |  |         |                    |                    |             |                             |
| <b>B00C - R1001 - Materials Technology L.S. (82.66 m2)</b>  |  |         |                    |                    |             |                             |
| Ceiling Structures/Linings  | Vermiculite                                    |         |                    |                    |             |                             |
|   | 8101/B00C/R2006/Ceiling Structures/Linings/S8  |         |                    |                    |             | Limited Samples Taken       |
| <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |  |         |                    |                    |             |                             |
| <b>B00C - R1002 - Movement (2.51 m2)</b>  |  |         |                    |                    |             |                             |
| No Asbestos   |  |         |                    |                    |             |                             |
| <b>B00C - R1003 - Movement (52 m2)</b>  |  |         |                    |                    |             |                             |

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status   | Control Priority             |
|---|----------------------|--------|--------------------|--------------------|---|------------------------------|
| Sample No   |                      |        |                    |                    | Test Result   |                              |
| No Asbestos   |                      |        |                    |                    |   |                              |
| <b>B00C - R1004 - Distribution Board Cupboard (0.75 m2)</b> <span style="float: right;">Note: No inspection of live electrical installation.</span> |                      |        |                    |                    |   |                              |
| Door Lining   | Flat AC Sheeting     | 6m2    | North facing       | Good Condition (1) | Low (1)   | Low Priority (2-3)           |
| 8101/B00C/R0003/Door Lining/S10   |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>  |                              |
| <b>B00C - R1005 - Cleaning Store - Distributed (4.1 m2)</b>   |                      |        |                    |                    |   |                              |
| No Asbestos   |                      |        |                    |                    |   |                              |
| <b>B00C - R1006 - Darkroom Space (21.26 m2)</b>   |                      |        |                    |                    |   |                              |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |   | <b>Limited Samples Taken</b> |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8   |                      |        |                    |                    | <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                              |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 22m2   | All surfaces       | Good Condition (1) | Low (1)   | Low Priority (2-3)           |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>  |                              |
| <b>B00C - R1007 - Design L.S. (59.48 m2)</b>  |                      |        |                    |                    |   |                              |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |   | <b>Limited Samples Taken</b> |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8   |                      |        |                    |                    | <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                              |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 60m2   | All surfaces       | Good Condition (1) | Low (1)   | Low Priority (2-3)           |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>  |                              |
| <b>B00C - R1008 - General Storeroom (13.46 m2)</b>  |                      |        |                    |                    |   |                              |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 14m2   | All surfaces       | Good Condition (1) | Low (1)   | Low Priority (2-3)           |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>  |                              |
| <b>B00C - R1009 - Design L.S. (55.03 m2)</b>  |                      |        |                    |                    |   |                              |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |   | <b>Limited Samples Taken</b> |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8   |                      |        |                    |                    | <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                              |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 56m2   | All surfaces       | Good Condition (1) | Low (1)   | Low Priority (2-3)           |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>  |                              |
| <b>B00C - R1010 - Movement (19.23 m2)</b>   |                      |        |                    |                    |   |                              |
| No Asbestos   |                      |        |                    |                    |   |                              |
| <b>B00C - R1011 - Materials Technology L.S. (82.58 m2)</b>  |                      |        |                    |                    |   |                              |
| No Asbestos   |                      |        |                    |                    |   |                              |
| <b>B00C - R1012 - General Storeroom (10.82 m2)</b>  |                      |        |                    |                    |   |                              |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |   | <b>Limited Samples Taken</b> |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8   |                      |        |                    |                    | <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                              |
| <b>B00C - R1013 - General Storeroom (6.99 m2)</b>   |                      |        |                    |                    |   |                              |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |   | <b>Limited Samples Taken</b> |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8   |                      |        |                    |                    | <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                              |
| <b>B00C - R1014 - Materials Store (13.97 m2)</b>  |                      |        |                    |                    |   |                              |
| No Asbestos   |                      |        |                    |                    |   |                              |
| <b>B00C - R1015 - Stairs (17.81 m2)</b>   |                      |        |                    |                    |   |                              |
| No Asbestos   |                      |        |                    |                    |   |                              |
| <b>B00C - R2001 - Staff Study (33.55 m2)</b>  |                      |        |                    |                    |   |                              |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |   | <b>Limited Samples Taken</b> |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8   |                      |        |                    |                    | <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                              |

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status  | Control Priority   |
|---|----------------------|--------|--------------------|--------------------|--|--------------------|
| Sample No   |                      |        |                    |                    | Test Result  |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 34m2   | All surfaces       | Good Condition (1) | Low (1)  | Low Priority (2-3) |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>                   |                    |
| <b>B00C - R2002 - Movement (2.45 m2)</b>  |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00C - R2003 - Distribution Board Cupboard (0.9 m2)</b>  |                      |        |                    |                    | Note: No inspection of live electrical installation. |                    |
| Door Lining   | Flat AC Sheeting     | 6m2    | North facing       | Good Condition (1) | Low (1)  | Low Priority (2-3) |
| 8101/B00C/R0003/Door Lining/S10   |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>                   |                    |
| <b>B00C - R2004 - Cleaning Store - Distributed (4.06 m2)</b>  |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00C - R2005 - Plant (10.03 m2)</b>  |                      |        |                    |                    |  |                    |
| Electrical Mounting Board   | Resinous Board       | 1Unit  | South facing       | Good Condition (1) | Low (1)  | Low Priority (2-3) |
| <b>Assumed Asbestos - Electrical Hazard</b>   |                      |        |                    |                    |  |                    |
| <b>B00C - R2006 - Leading Teacher (16.8 m2)</b>   |                      |        |                    |                    |  |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |  |                    |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8   |                      |        |                    |                    | <b>Limited Samples Taken</b>                         |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                    |                    |  |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 17m2   | All surfaces       | Good Condition (1) | Low (1)  | Low Priority (2-3) |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>                   |                    |
| <b>B00C - R2007 - Study Space (13.91 m2)</b>  |                      |        |                    |                    |  |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |  |                    |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8   |                      |        |                    |                    | <b>Limited Samples Taken</b>                         |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                    |                    |  |                    |
| <b>B00C - R2008 - Study Space (12.62 m2)</b>  |                      |        |                    |                    |  |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |  |                    |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8   |                      |        |                    |                    | <b>Limited Samples Taken</b>                         |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                    |                    |  |                    |
| <b>B00C - R2009 - General Learning Space (69.51 m2)</b>   |                      |        |                    |                    |  |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |  |                    |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8   |                      |        |                    |                    | <b>Limited Samples Taken</b>                         |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                    |                    |  |                    |
| <b>B00C - R2010 - Staff Study (13.98 m2)</b>  |                      |        |                    |                    |  |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |  |                    |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8   |                      |        |                    |                    | <b>Limited Samples Taken</b>                         |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                    |                    |  |                    |
| <b>B00C - R2011 - General Storeroom (12.66 m2)</b>  |                      |        |                    |                    |  |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |  |                    |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8   |                      |        |                    |                    | <b>Limited Samples Taken</b>                         |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                    |                    |  |                    |
| <b>B00C - R2012 - Movement (21.4 m2)</b>  |                      |        |                    |                    |  |                    |
| In-fill-panel   | Flat AC Sheeting     |        |                    |                    |  |                    |
| 8101/B00C/R2012/Infill Panel/S9   |                      |        |                    |                    | <b>No Asbestos Detected</b>                          |                    |
| <b>B00C - R2013 - Movement (58.21 m2)</b>   |                      |        |                    |                    |  |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 59m2   | All surfaces       | Good Condition (1) | Low (1)  | Low Priority (2-3) |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>                   |                    |
| <b>B00C - R2014 - General Storeroom (16.63 m2)</b>  |                      |        |                    |                    |  |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |  |                    |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8   |                      |        |                    |                    | <b>Limited Samples Taken</b>                         |                    |
| <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                      |        |                    |                    |  |                    |

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status   | Control Priority             |
|---|----------------------|--------|--------------------|--------------------|---|------------------------------|
| Sample No   |                      |        |                    |                    | Test Result   |                              |
| Floor Coverings Res/Textile                         | Vinyl Tiles          | 17m2   | All surfaces       | Good Condition (1) | Low (1)   | Low Priority (2-3)           |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4      |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>  |                              |
| <b>B00C - R2015 - Art Learning Space (68.33 m2)</b> |                      |        |                    |                    |   |                              |
| Ceiling Structures/Linings                          | Vermiculite          |        |                    |                    |   | <b>Limited Samples Taken</b> |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8       |                      |        |                    |                    | <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                              |
| Floor Coverings Res/Textile                         | Vinyl Tiles          | 68m2   | All surfaces       | Good Condition (1) | Low (1)   | Low Priority (2-3)           |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4      |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>  |                              |
| <b>B00C - R2016 - Art Learning Space (68.87 m2)</b> |                      |        |                    |                    |   |                              |
| Ceiling Structures/Linings                          | Vermiculite          |        |                    |                    |   | <b>Limited Samples Taken</b> |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8       |                      |        |                    |                    | <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                              |
| Floor Coverings Res/Textile                         | Vinyl Tiles          | 69m2   | All surfaces       | Good Condition (1) | Low (1)   | Low Priority (2-3)           |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4      |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>  |                              |
| <b>B00C - R2017 - General Storeroom (16.44 m2)</b>  |                      |        |                    |                    |   |                              |
| Ceiling Structures/Linings                          | Vermiculite          |        |                    |                    |   | <b>Limited Samples Taken</b> |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8       |                      |        |                    |                    | <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |                              |
| Floor Coverings Res/Textile                         | Vinyl Tiles          | 17m2   | All surfaces       | Good Condition (1) | Low (1)   | Low Priority (2-3)           |
| 8101/B00B/R1004/Floor Coverings Res/Textile/S4      |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>  |                              |
| <b>B00C - R2018 - Stairs (17.81 m2)</b>             |                      |        |                    |                    |   |                              |
| No Asbestos   |                      |        |                    |                    |   |                              |

2017



| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status  | Control Priority   |
|---|----------------------|--------|--------------------|--------------------|--|--------------------|
| Sample No   |                      |        |                    |                    | Test Result  |                    |
| Ceiling Structures/Linings  | Vermiculite          | 59m2   | All surfaces       | Good Condition (1) | Low (1)  | Low Priority (2-3) |
| 8101/B00D/R0003/Floor Coverings Res/Textile/S18   |                      |        |                    |                    | <b>No Asbestos Detected - Note 1</b>                 |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |  |                    |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8   |                      |        |                    |                    | <b>Limited Samples Taken</b>                         |                    |
| <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |                      |        |                    |                    |  |                    |
| <b>B00D - R0006 - Chemical Store (42.86 m2)</b>   |                      |        |                    |                    |  |                    |
| Window putty  | Mastic               | 2Unit  | Throughout         | Minimal Damage (2) | Low (1)  | Low Priority (2-3) |
| 8101/B00D/R0006/Window putty/S39  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>                   |                    |
| <b>B00D - R0007 - General Storeroom (21.79 m2)</b>  |                      |        |                    |                    |  |                    |
| Window putty  | Mastic               | 2Unit  | Throughout         | Minimal Damage (2) | Low (1)  | Low Priority (2-3) |
| 8101/B00D/R0006/Window putty/S39  |                      |        |                    |                    | <b>Chrysotile (white asbestos)</b>                   |                    |
| <b>B00D - R0008 - Movement (16.97 m2)</b>   |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00D - R0009 - Cleaning Store - Distributed (3 m2)</b>   |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00D - R0010 - Distribution Board Cupboard (0.73 m2)</b>   |                      |        |                    |                    | Note: No inspection of live electrical installation. |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00D - R0011 - Preparation (38.4 m2)</b>   |                      |        |                    |                    |  |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |  |                    |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8   |                      |        |                    |                    | <b>Limited Samples Taken</b>                         |                    |
| <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |                      |        |                    |                    |  |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 39m2   | All surfaces       | Good Condition (1) | Low (1)  | Low Priority (2-3) |
| 8101/B00D/R0003/Floor Coverings Res/Textile/S18   |                      |        |                    |                    | <b>No Asbestos Detected - Note 1</b>                 |                    |
| <b>B00D - R0012 - Laboratory L.S. (85.85 m2)</b>  |                      |        |                    |                    |  |                    |
| Ceiling Structures/Linings  | Vermiculite          |        |                    |                    |  |                    |
| 8101/B00C/R2006/Ceiling Structures/Linings/S8   |                      |        |                    |                    | <b>Limited Samples Taken</b>                         |                    |
| <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |                      |        |                    |                    |  |                    |
| Floor Coverings Res/Textile   | Vinyl Tiles          | 91m2   | All surfaces       | Good Condition (1) | Low (1)  | Low Priority (2-3) |
| 8101/B00D/R0003/Floor Coverings Res/Textile/S18   |                      |        |                    |                    | <b>No Asbestos Detected - Note 1</b>                 |                    |
| <b>B00D - R0013 - Movement (10.18 m2)</b>   |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00D - R0014 - Stairs (5.43 m2)</b>  |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00D - R1001 - General Storeroom (31.24 m2)</b>  |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00D - R1002 - Cleaning Supplies Store (10.68 m2)</b>  |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00D - R1003 - General Learning Space (55.18 m2)</b>   |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00D - R1004 - General Learning Space (53.84 m2)</b>   |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00D - R1005 - Cleaning Store - Distributed (4.32 m2)</b>  |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00D - R1006 - General Storeroom (4.11 m2)</b>   |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |
| <b>B00D - R1007 - General Learning Space (55.32 m2)</b>   |                      |        |                    |                    |  |                    |
| No Asbestos   |                      |        |                    |                    |  |                    |



| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status  | Control Priority |
|---|----------------------|--------|--------------------|--------------------|--|------------------|
| Sample No   |                      |        |                    |                    | Test Result  |                  |
| <b>B00D - R1008 - Leading Teacher (9.64 m2)</b>             |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B00D - R1009 - Movement (9.03 m2)</b>                    |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B00D - R1010 - Movement (57.66 m2)</b>                   |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B00D - R1011 - Staff Study (25.85 m2)</b>                |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B00D - R1012 - Staff Study (26.05 m2)</b>                |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B00D - R1013 - Movement (4.13 m2)</b>                    |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B00D - R1014 - Staff - Toilet (2.71 m2)</b>              |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B00D - R1015 - Staff - Toilet (2.75 m2)</b>              |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B00D - R1016 - Movement (8.44 m2)</b>                    |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B00D - R1017 - Darkroom Space (3.42 m2)</b>              |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B00D - R1018 - Distribution Board Cupboard (0.44 m2)</b> |                      |        |                    |                    | Note: No inspection of live electrical installation. |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B00D - R1019 - General Learning Space (64.21 m2)</b>     |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B00D - R1020 - General Learning Space (56.69 m2)</b>     |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B00D - R1021 - Staff Study (9.38 m2)</b>                 |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B00D - R1022 - Movement (9.02 m2)</b>                    |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B00D - R1023 - Stairs (13.86 m2)</b>                     |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00E - Various - 1920 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground

Ceiling Voids Non Accessible Area  
- Area inaccessible - generally raked stramit tiles 4-12m high.

**Interior**

**B00E - R0001 - Movement (47.86 m2)**

No Asbestos

**B00E - R0003 - Student Canteen (55.64 m2)**

|   |             |      |              |                    |                                      |                    |
|---|-------------|------|--------------|--------------------|--------------------------------------|--------------------|
| Floor Coverings Res/Textile                     | Vinyl Tiles | 56m2 | All surfaces | Good Condition (1) | Low (1)                              | Low Priority (2-3) |
| 8101/B00D/R0003/Floor Coverings Res/Textile/S18 |             |      |              |                    | <b>No Asbestos Detected - Note 1</b> |                    |

**B00E - R0004 - Staff - Toilet (2.57 m2)**

|  |                  |     |              |                    |                                    |                    |
|--|------------------|-----|--------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings                     | Flat AC Sheeting | 3m2 | All surfaces | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00E/R0004/Ceiling Structures/Linings/S19 |                  |     |              |                    | <b>Chrysotile (white asbestos)</b> |                    |

|   |             |     |              |                    |                                      |                    |
|---|-------------|-----|--------------|--------------------|--------------------------------------|--------------------|
| Floor Coverings Res/Textile                     | Vinyl Tiles | 3m2 | All surfaces | Good Condition (1) | Low (1)                              | Low Priority (2-3) |
| 8101/B00D/R0003/Floor Coverings Res/Textile/S18 |             |     |              |                    | <b>No Asbestos Detected - Note 1</b> |                    |

**B00E - R0005 - Staff Change (4.18 m2)**

|  |                  |     |              |                    |                                    |                    |
|--|------------------|-----|--------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings                     | Flat AC Sheeting | 5m2 | All surfaces | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00E/R0004/Ceiling Structures/Linings/S19 |                  |     |              |                    | <b>Chrysotile (white asbestos)</b> |                    |

|   |             |     |              |                    |                                      |                    |
|---|-------------|-----|--------------|--------------------|--------------------------------------|--------------------|
| Floor Coverings Res/Textile                     | Vinyl Tiles | 5m2 | All surfaces | Good Condition (1) | Low (1)                              | Low Priority (2-3) |
| 8101/B00D/R0003/Floor Coverings Res/Textile/S18 |             |     |              |                    | <b>No Asbestos Detected - Note 1</b> |                    |

**B00E - R0006 - General Storeroom (13.3 m2)**

|  |                  |      |              |                    |                                    |                    |
|--|------------------|------|--------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings                     | Flat AC Sheeting | 14m2 | All surfaces | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00E/R0004/Ceiling Structures/Linings/S19 |                  |      |              |                    | <b>Chrysotile (white asbestos)</b> |                    |

|   |             |      |              |                    |                                      |                    |
|---|-------------|------|--------------|--------------------|--------------------------------------|--------------------|
| Floor Coverings Res/Textile                     | Vinyl Tiles | 14m2 | All surfaces | Good Condition (1) | Low (1)                              | Low Priority (2-3) |
| 8101/B00D/R0003/Floor Coverings Res/Textile/S18 |             |      |              |                    | <b>No Asbestos Detected - Note 1</b> |                    |

**B00E - R0007 - Movement (29.57 m2)**

No Asbestos

**B00E - R0008 - Toilets-Boys (9.53 m2)**

No Asbestos

**B00E - R0009 - Shower/Change (60.73 m2)**

|                         |                   |     |              |                    |                                    |                    |
|-------------------------|-------------------|-----|--------------|--------------------|------------------------------------|--------------------|
| Flue                    | Fibre Cement Pipe | 10m | South facing | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00B/R0012/Flue/S6 |                   |     |              |                    | <b>Chrysotile (white asbestos)</b> |                    |

**B00E - R0010 - Toilets-Boys (9.88 m2)**

No Asbestos

**B00E - R0011 - Movement (10.66 m2)**

No Asbestos

**B00E - R0012 - Staff Study (7.2 m2)**

No Asbestos

**B00E - R0013 - Cleaning Store - Distributed (2.28 m2)**

No Asbestos

**B00E - R0014 - Sport Equipment Store (33.24 m2)**

No Asbestos

**B00E - R0015 - Multi-Purpose Space (473.96 m2)**

| Product  | Material Description                     | Extent | Location Reference | Material Condition | Risk Status | Control Priority                   |
|--|--|--------|--------------------|--------------------|-------------|------------------------------------|
| Sample No  |  |        |                    |                    | Test Result |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R0016 - Chair Store (44.3 m2)</b>                  |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R0017 - Cleaning Store - Distributed (2.43 m2)</b> |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R0018 - Staff Study (7.78 m2)</b>                  |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R0019 - Movement (10.34 m2)</b>                    |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R0020 - Toilets-Girls (9.92 m2)</b>                |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R0021 - Shower/Change (61.17 m2)</b>               |  |        |                    |                    |             |                                    |
| Flue   | Fibre Cement Pipe                        | 10m    | South facing       | Good Condition (1) | Low (1)     | Low Priority (2-3)                 |
|  | 8101/B00B/R0012/Flue/S6                  |        |                    |                    |             | <b>Chrysotile (white asbestos)</b> |
| <b>B00E - R0022 - Toilets-Girls (10.07 m2)</b>               |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R0024 - General Storeroom (11.61 m2)</b>           |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R0025 - Movement (2.74 m2)</b>                     |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R0026 - Stairs (0.92 m2)</b>                       |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R0027 - Lift (2.88 m2)</b>                         |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R0028 - Office/Store (3.27 m2)</b>                 |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R0029 - Office/Store (5.29 m2)</b>                 |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R0030 - Movement (9.18 m2)</b>                     |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R0031 - Stage (146.82 m2)</b>                      |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R1001 - Movement (59.34 m2)</b>                    |  |        |                    |                    |             |                                    |
| In-fill-panel  | Flat AC Sheeting                         | 4m2    | All surfaces       | Good Condition (1) | Low (1)     | Low Priority (2-3)                 |
|  | 8101/B00E/R1001/Infill Panel to Wall/S20 |        |                    |                    |             | <b>Chrysotile (white asbestos)</b> |
| <b>B00E - R1002 - Music Store (10.82 m2)</b>                 |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R1003 - Staff Study (15.08 m2)</b>                 |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R1004 - Music Learning Space (102.38 m2)</b>       |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R1005 - Music Learning Space (69.22 m2)</b>        |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |
| <b>B00E - R1006 - Stairs (14.73 m2)</b>                      |  |        |                    |                    |             |                                    |
| No Asbestos  |  |        |                    |                    |             |                                    |

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00F - General Learning/Technological & Applied Studies - 1980 - Brick/Block (Brick/Block)****Exterior**

|                     |   |      |   |                            |         |  |
|---------------------|---|------|---|----------------------------|---------|--|
| Roof                | Resinous Membrane<br>8101/B00F/Bituminous Membrane/S21  |      |   |                            |         | <b>No Asbestos Detected</b>                              |
| Gable Verge Linings | Flat AC Sheeting<br>8101/B00F/Verge cover strip./S22  | 20m2 | All surfaces  | Good Condition (1)         | Low (1) | Low Priority (2-3)<br><b>Chrysotile (white asbestos)</b> |
| Ceiling Voids       | Non Accessible Area<br>- Area inaccessible - Fixed ceilings/slab to lower level.<br>Generally fixed raked stramit tiles to upper level. No asbetsos found in cavity above FR0034. |      |   |                            |         |  |
| Underfloor Voids    | AC Fragments/Debris<br>8101/B00F/Underfloor Voids/S42   | NA   | Throughout  | Some Damage - Unsealed (3) | Low (1) | Low Priority (2-3)<br><b>Chrysotile (white asbestos)</b> |
| Underfloor Voids    | Flat AC Sheeting<br>8101/B00F/Underfloor Voids/S43  | NA   | Lining to cable runs (generally above access holes between subfloor rooms). | Good Condition (1)         | Low (1) | Low Priority (2-3)<br><b>Chrysotile (white asbestos)</b> |

**Interior****B00F - R0001 - Food Technology L.S. (93.22 m2)**

|                            |   |  |  |  |  |   |
|----------------------------|---|--|--|--|--|---|
| Ceiling Structures/Linings | Vermiculite<br>8101/B00F/R0012/Ceiling Structures/Linings/S24 |  |  |  |  | <b>Limited Samples Taken</b><br><b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |
|----------------------------|---|--|--|--|--|---|

**B00F - R0002 - Movement (256.46 m2)**

|                       |  |     |                                       |                    |         |  |
|-----------------------|--|-----|---------------------------------------|--------------------|---------|--|
| Wall Linings Internal | Flat AC Sheeting<br>8101/B00F/R0002/Exterior Room 19 Fire hydrant cavity/S23 | 1m2 | Fire Hydrant Cavity Outside Room 0019 | Good Condition (1) | Low (1) | Low Priority (2-3)<br><b>Chrysotile (white asbestos)</b> |
|-----------------------|--|-----|---------------------------------------|--------------------|---------|--|

**B00F - R0003 - Staff Study (7.02 m2)**

No Asbestos

**B00F - R0004 - General Storeroom (5.43 m2)**

No Asbestos

**B00F - R0005 - Cleaning Store - Distributed (1.74 m2)**

No Asbestos

**B00F - R0006 - Movement (3.78 m2)**

No Asbestos

**B00F - R0007 - Staff - Toilet (4.47 m2)**

No Asbestos

**B00F - R0008 - Staff Study (14.14 m2)**

|                            |   |  |  |  |  |   |
|----------------------------|---|--|--|--|--|---|
| Ceiling Structures/Linings | Vermiculite<br>8101/B00F/R0012/Ceiling Structures/Linings/S24 |  |  |  |  | <b>Limited Samples Taken</b><br><b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |
|----------------------------|---|--|--|--|--|---|

**B00F - R0009 - General Learning Space (50.3 m2)**

|                            |   |  |  |  |  |   |
|----------------------------|---|--|--|--|--|---|
| Ceiling Structures/Linings | Vermiculite<br>8101/B00F/R0012/Ceiling Structures/Linings/S24 |  |  |  |  | <b>Limited Samples Taken</b><br><b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |
|----------------------------|---|--|--|--|--|---|

**B00F - R0010 - General Learning Space (50.8 m2)**

|                            |   |  |  |  |  |   |
|----------------------------|---|--|--|--|--|---|
| Ceiling Structures/Linings | Vermiculite<br>8101/B00F/R0012/Ceiling Structures/Linings/S24 |  |  |  |  | <b>Limited Samples Taken</b><br><b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b> |
|----------------------------|---|--|--|--|--|---|

**B00F - R0011 - Staff Study (36.55 m2)**

| Product   | Material Description | Extent | Location Reference                             | Material Condition | Risk Status  | Control Priority            |
|---|----------------------|--------|--|--------------------|--|-----------------------------|
| Sample No   |                      |        |  |                    | Test Result  |                             |
| Ceiling Structures/Linings  | Vermiculite          |        | 8101/B00F/R0012/Ceiling Structures/Linings/S24 |                    |  | Limited Samples Taken       |
| <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |                      |        |  |                    |  |                             |
| <b>B00F - R0012 - General Learning Space (49.75 m2)</b>   |                      |        |  |                    |  |                             |
| Ceiling Structures/Linings  | Vermiculite          |        | 8101/B00F/R0012/Ceiling Structures/Linings/S24 |                    |  | Limited Samples Taken       |
| <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |                      |        |  |                    |  |                             |
| <b>B00F - R0013 - Distribution Board Cupboard (0.66 m2)</b>   |                      |        |  |                    | Note: No inspection of live electrical installation. |                             |
| No Asbestos   |                      |        |  |                    |  |                             |
| <b>B00F - R0014 - General Learning Space (49.37 m2)</b>   |                      |        |  |                    |  |                             |
| Ceiling Structures/Linings  | Vermiculite          |        | 8101/B00F/R0012/Ceiling Structures/Linings/S24 |                    |  | Limited Samples Taken       |
| <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |                      |        |  |                    |  |                             |
| <b>B00F - R0015 - General Learning Space (51.01 m2)</b>   |                      |        |  |                    |  |                             |
| Ceiling Structures/Linings  | Vermiculite          |        | 8101/B00F/R0012/Ceiling Structures/Linings/S24 |                    |  | Limited Samples Taken       |
| <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |                      |        |  |                    |  |                             |
| <b>B00F - R0016 - Materials Technology L.S. (68.53 m2)</b>  |                      |        |  |                    |  |                             |
| Ceiling Structures/Linings  | Vermiculite          |        | 8101/B00F/R0012/Ceiling Structures/Linings/S24 |                    |  | Limited Samples Taken       |
| <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |                      |        |  |                    |  |                             |
| <b>B00F - R0017 - General Storeroom (4.85 m2)</b>   |                      |        |  |                    |  |                             |
| Window putty  | Mastic               | 1Unit  | Throughout                                     | Minimal Damage (2) | Low (1)  | Low Priority (2-3)          |
|   |                      |        | 8101/B00F/R0017/Window putty/S41               |                    |  | Chrysotile (white asbestos) |
| <b>B00F - R0018 - General Storeroom (10.52 m2)</b>  |                      |        |  |                    |  |                             |
| Window putty  | Mastic               | 1Unit  | Throughout                                     | Minimal Damage (2) | Low (1)  | Low Priority (2-3)          |
|   |                      |        | 8101/B00F/R0017/Window putty/S41               |                    |  | Chrysotile (white asbestos) |
| <b>B00F - R0019 - Materials Technology L.S. (64.92 m2)</b>  |                      |        |  |                    |  |                             |
| Ceiling Structures/Linings  | Vermiculite          |        | 8101/B00F/R0012/Ceiling Structures/Linings/S24 |                    |  | Limited Samples Taken       |
| <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |                      |        |  |                    |  |                             |
| <b>B00F - R0020 - Toilets-Boys (30.7 m2)</b>  |                      |        |  |                    |  |                             |
| No Asbestos   |                      |        |  |                    |  |                             |
| <b>B00F - R0021 - Cleaning Store - Distributed (2.58 m2)</b>  |                      |        |  |                    |  |                             |
| No Asbestos   |                      |        |  |                    |  |                             |
| <b>B00F - R0022 - Plant (8.61 m2)</b>   |                      |        |  |                    |  |                             |
| No Asbestos   |                      |        |  |                    |  |                             |
| <b>B00F - R0023 - Distribution Board Cupboard (0.54 m2)</b>   |                      |        |  |                    | Note: No inspection of live electrical installation. |                             |
| No Asbestos   |                      |        |  |                    |  |                             |
| <b>B00F - R0024 - Toilets-Girls (33.4 m2)</b>   |                      |        |  |                    |  |                             |
| No Asbestos   |                      |        |  |                    |  |                             |
| <b>B00F - R0025 - Food Technology L.S. (93.2 m2)</b>  |                      |        |  |                    |  |                             |
| Ceiling Structures/Linings  | Vermiculite          |        | 8101/B00F/R0012/Ceiling Structures/Linings/S24 |                    |  | Limited Samples Taken       |
| <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |                      |        |  |                    |  |                             |
| <b>B00F - R0027 - Pantry (4.73 m2)</b>  |                      |        |  |                    |  |                             |
| Ceiling Structures/Linings  | Vermiculite          |        | 8101/B00F/R0012/Ceiling Structures/Linings/S24 |                    |  | Limited Samples Taken       |
| <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i> |                      |        |  |                    |  |                             |
| <b>B00F - R0029 - Laundry (16.49 m2)</b>  |                      |        |  |                    |  |                             |
| No Asbestos   |                      |        |  |                    |  |                             |

| Product   | Material Description   | Extent | Location Reference | Material Condition | Risk Status | Control Priority                                     |
|-----------|--|--------|--------------------|--------------------|-------------|--|
| Sample No |  |        |                    |                    | Test Result |  |
|           | <b>B00F - R0030 - Stairs (4.84 m2)</b>                       |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R0031 - Stairs (4.78 m2)</b>                       |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R0032 - Preparation (31.56 m2)</b>                 |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R0033 - Staff Kitchen (16.23 m2)</b>               |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R0034 - Pantry (6.98 m2)</b>                       |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R0035 - Pantry (5.41 m2)</b>                       |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R0036 - Pantry (2.81 m2)</b>                       |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R1001 - Movement (270.73 m2)</b>                   |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R1002 - Staff Study (17.45 m2)</b>                 |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R1003 - General Storeroom (3.24 m2)</b>            |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R1004 - Staff Study (32.81 m2)</b>                 |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R1005 - Cleaning Store - Distributed (1.74 m2)</b> |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R1006 - Movement (3.8 m2)</b>                      |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R1007 - Staff - Toilet (4.66 m2)</b>               |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R1008 - Staff Study (14.07 m2)</b>                 |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R1009 - General Learning Space (50.15 m2)</b>      |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R1010 - General Learning Space (51.88 m2)</b>      |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R1011 - General Learning Space (49.68 m2)</b>      |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R1012 - Distribution Board Cupboard (0.52 m2)</b>  |        |                    |                    |             | Note: No inspection of live electrical installation. |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R1013 - General Learning Space (49.6 m2)</b>       |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R1014 - General Learning Space (52.02 m2)</b>      |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R1015 - General Storeroom (19.3 m2)</b>            |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R1016 - General Storeroom (5.24 m2)</b>            |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |
|           | <b>B00F - R1017 - General Learning Space (56.7 m2)</b>       |        |                    |                    |             |  |
|           | No Asbestos  |        |                    |                    |             |  |

| Product  | Material Description | Extent | Location Reference | Material Condition                                   | Risk Status | Control Priority |
|--|----------------------|--------|--------------------|--|-------------|------------------|
| Sample No  |                      |        |                    |  | Test Result |                  |
| <b>B00F - R1018 - General Learning Space (48.9 m2)</b>       |                      |        |                    |  |             |                  |
| No Asbestos  |                      |        |                    |  |             |                  |
| <b>B00F - R1019 - General Storeroom (7.97 m2)</b>            |                      |        |                    |  |             |                  |
| No Asbestos  |                      |        |                    |  |             |                  |
| <b>B00F - R1020 - Staff Study (7.82 m2)</b>                  |                      |        |                    |  |             |                  |
| No Asbestos  |                      |        |                    |  |             |                  |
| <b>B00F - R1021 - Toilets-Boys (30.56 m2)</b>                |                      |        |                    |  |             |                  |
| No Asbestos  |                      |        |                    |  |             |                  |
| <b>B00F - R1022 - Cleaning Store - Distributed (2.55 m2)</b> |                      |        |                    |  |             |                  |
| No Asbestos  |                      |        |                    |  |             |                  |
| <b>B00F - R1023 - Plant (7.55 m2)</b>                        |                      |        |                    |  |             |                  |
| No Asbestos  |                      |        |                    |  |             |                  |
| <b>B00F - R1024 - Distribution Board Cupboard (0.58 m2)</b>  |                      |        |                    | Note: No inspection of live electrical installation. |             |                  |
| No Asbestos  |                      |        |                    |  |             |                  |
| <b>B00F - R1025 - Toilets-Girls (33.26 m2)</b>               |                      |        |                    |  |             |                  |
| No Asbestos  |                      |        |                    |  |             |                  |
| <b>B00F - R1026 - Stairs (10.34 m2)</b>                      |                      |        |                    |  |             |                  |
| No Asbestos  |                      |        |                    |  |             |                  |
| <b>B00F - R1027 - Stairs (9.43 m2)</b>                       |                      |        |                    |  |             |                  |
| No Asbestos  |                      |        |                    |  |             |                  |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00G - Physical Education - 1950 - Timber (Timber)**

**Exterior**

|                  |   |       |              |                    |         |  |
|------------------|---|-------|--------------|--------------------|---------|--|
| Wall Cladding    | Moulded wall cladding<br>8101/B00G/Wall Cladding/S14  | 100m2 | All surfaces | Good Condition (1) | Low (1) | Low Priority (2-3)<br><b>Chrysotile (white asbestos)</b> |
| Awnings          | Flat AC Sheeting<br>8101/B00G/Awnings/S27   | 5m2   | All surfaces | Good Condition (1) | Low (1) | Low Priority (2-3)<br><b>Chrysotile (white asbestos)</b> |
| Ceiling Voids    | Non Accessible Area<br>- Area inaccessible - fixed ceilings and/or height 4.5-6.5m. No asbetsos found in cavity above GR0011. |       |              |                    |         |  |
| Underfloor Voids | Non Accessible Area<br>- Area inaccessible - No designated access point. Clearance 30cm.                                      |       |              |                    |         |  |

**Interior**

**B00G - R0001 - Sport Equipment Store (28.06 m2)**

No Asbestos

**B00G - R0002 - General Storeroom (4.08 m2)**

No Asbestos

**B00G - R0003 - Cleaning Supplies Store (11.9 m2)**

No Asbestos

**B00G - R0004 - Cleaning Store - Distributed (2.95 m2)**

No Asbestos

**B00G - R0005 - General Assistants (25.78 m2)**

No Asbestos

**B00G - R0006 - General Storeroom (30.25 m2)**

No Asbestos

**B00G - R0007 - General Storeroom (3.56 m2)**

No Asbestos

**B00G - R0008 - Staff - Toilet (2.09 m2)**

No Asbestos

**B00G - R0009 - General Storeroom (8.73 m2)**

No Asbestos

**B00G - R0010 - Movement (3.04 m2)**

No Asbestos

**B00G - R0011 - Movement (19.82 m2)**

|                           |                |       |              |                    |         |                    |
|---------------------------|----------------|-------|--------------|--------------------|---------|--------------------|
| Electrical Mounting Board | Resinous Board | 1Unit | South facing | Good Condition (1) | Low (1) | Low Priority (2-3) |
|---------------------------|----------------|-------|--------------|--------------------|---------|--------------------|

**Assumed Asbestos - Electrical Hazard**

**B00G - R0012 - Cleaning Store - Distributed (9.94 m2)**

No Asbestos

**B00G - R0013 - Gymnasium (269.01 m2)**

No Asbestos



| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00L - General Learning - 1900 - Brick/Block (Brick/Block)**

**Exterior**

|                  |   |
|------------------|---|
| Underfloor Voids | Non Accessible Area<br>- Area inaccessible - no access point identified.                            |
| Ceiling Voids    | Non Accessible Area<br>- Area inaccessible - height generally 4.5m. Access hatch located in LR0014. |

**Interior**

**B00L - R0001 - Movement (109.97 m2)**

No Asbestos

**B00L - R0002 - Study Space (23.53 m2)**

No Asbestos

**B00L - R0003 - Movement (31.33 m2)**

No Asbestos

**B00L - R0004 - Study Space (17.93 m2)**

|               |  |  |  |  |  |                             |
|---------------|--|--|--|--|--|-----------------------------|
| In-fill-panel | Flat AC Sheeting<br>8101/B00L/R0004/Infill panel to fire place/S16 |  |  |  |  | <b>No Asbestos Detected</b> |
|---------------|--|--|--|--|--|-----------------------------|

**B00L - R0005 - Senior Study (15.22 m2)**

No Asbestos

**B00L - R0006 - Study Space (24.89 m2)**

No Asbestos

**B00L - R0007 - Staff - Toilet (6.82 m2)**

No Asbestos

**B00L - R0008 - Staff Kitchen (14.64 m2)**

|                   |  |  |  |  |  |                             |
|-------------------|--|--|--|--|--|-----------------------------|
| Splashback lining | Resinous Membrane<br>8101/B00L/R0008/Sink lining/S17 |  |  |  |  | <b>No Asbestos Detected</b> |
|-------------------|--|--|--|--|--|-----------------------------|

**B00L - R0009 - General Storeroom (9.29 m2)**

|   |             |      |              |                    |         |                                      |
|---|-------------|------|--------------|--------------------|---------|--------------------------------------|
| Floor Coverings Res/Textile                     | Vinyl Sheet | 10m2 | All surfaces | Good Condition (1) | Low (1) | Low Priority (2-3)                   |
| 8101/B00L/R0009/Floor Coverings Res/Textile/S15 |             |      |              |                    |         | <b>No Asbestos Detected - Note 1</b> |

**B00L - R0010 - Toilets-Boys (3.1 m2)**

No Asbestos

**B00L - R0011 - Toilets-Girls (3.1 m2)**

No Asbestos

**B00L - R0012 - Movement (16.01 m2)**

No Asbestos

**B00L - R0013 - Movement (22.84 m2)**

No Asbestos

**B00L - R0014 - Interview/Office - Type 1 (8.19 m2)**

No Asbestos

**B00L - R0015 - General Storeroom (34.81 m2)**

No Asbestos

**B00L - R0016 - Staff Study (17.97 m2)**

No Asbestos

**B00L - R0017 - Staff Study (16.62 m2)**

No Asbestos

**B00L - R0018 - Stairs (2.01 m2)**

No Asbestos

**B00L - R9001 - General Storeroom (14.27 m2)**

No Asbestos

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

B00L - R9002 - Stairs (0.88 m2)

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00M - Performing Arts - 2007 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground

Ceiling Voids                      No Asbestos Found

**Interior**

**B00M - R0001 - Movement (47.93 m2)**

No Asbestos

**B00M - R0002 - Movement (18 m2)**

No Asbestos

**B00M - R0003 - Staff Kitchen (12.06 m2)**

No Asbestos

**B00M - R0004 - Resources (3.78 m2)**

No Asbestos

**B00M - R0005 - Toilets-Unisex (4.46 m2)**

No Asbestos

**B00M - R0006 - Performance Workshop (96.93 m2)**

No Asbestos

**B00M - R0007 - Performance Workshop (62.99 m2)**

No Asbestos

**B00M - R0008 - Store (7.67 m2)**

No Asbestos

**B00M - R0009 - Store (7.53 m2)**

No Asbestos

**B00M - R0010 - Store (7.5 m2)**

No Asbestos

**B00M - R0011 - Performing Arts Store (7.67 m2)**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00N - Storage - 2013 - Metal Shed (Metal Shed)**

**Exterior**

|                 |                   |
|-----------------|-------------------|
| Ceiling Void    | No Asbestos Found |
| Underfloor Void | No Asbestos Found |

**Interior**

**B00N - R0001 - Garden Store Room (149.19 m2)**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B000 - Pupil Facilities - - Brick/Block (Brick/Block)**

**Exterior**

|                 |                   |
|-----------------|-------------------|
| Ceiling Void    | No Asbestos Found |
| Underfloor Void | No Asbestos Found |

**Interior**

**B000 - R0001 - Toilets-Boys (3.95 m2)**

No Asbestos

**B000 - R0002 - Toilets-Girls (3.95 m2)**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00X - Technological & Applied Studies - 1905 - Brick/Block (Brick/Block)**

**Exterior**

|                  |                   |
|------------------|-------------------|
| Ceiling Voids    | No Asbestos Found |
| Underfloor Voids | No Asbestos Found |

**Interior**

**B00X - R0002 - General Storeroom (88.8 m2)**

|  |                  |      |              |                    |                                    |                    |
|--|------------------|------|--------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings                     | Flat AC Sheeting | 90m2 | All surfaces | Good Condition (1) | Low (1)                            | Low Priority (2-3) |
| 8101/B00X/R0001/Ceiling Structures/Linings/S26 |                  |      |              |                    | <b>Chrysotile (white asbestos)</b> |                    |

**B00X - R0004 - Fitness Store (51.26 m2)**

No Asbestos

**B00X - R0005 - Gymnasium (50.8 m2)**

No Asbestos

**B00X - R0006 - Design/Technology L.S. (40.95 m2)**

No Asbestos

**B00X - R0007 - Wood Technology Bay (45.23 m2)**

No Asbestos

**B00X - R0008 - Dust Extraction Space (3.78 m2)**

No Asbestos

**B00X - R0009 - Garden Store Room (44.95 m2)**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00Y - Agricultural Science - 1940 - Brick/Block (Brick/Block)****Exterior**

|                           |                |          |              |                    |         |                    |
|---------------------------|----------------|----------|--------------|--------------------|---------|--------------------|
| Electrical Mounting Board | Resinous Board | 1Unit(s) | South facing | Good Condition (1) | Low (1) | Low Priority (2-3) |
|---------------------------|----------------|----------|--------------|--------------------|---------|--------------------|

**Assumed Asbestos - Electrical Hazard - board labelled**

Underfloor Voids - Slab on Ground

|                               |   |
|-------------------------------|---|
| Ceiling Voids - Raked Ceiling | Non Accessible Area<br>- Area inaccessible - fixed raked ceilings |
|-------------------------------|---|

**Interior****B00Y - R0001 - Plant Space (7.58 m2)**

|                            |   |                             |
|----------------------------|---|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>8101/B00Z/R0004/Wall Linings Internal/S25 | <b>No Asbestos Detected</b> |
|----------------------------|---|-----------------------------|

**B00Y - R0002 - General Storeroom (42.27 m2)**

|                            |   |                             |
|----------------------------|---|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>8101/B00Z/R0004/Wall Linings Internal/S25 | <b>No Asbestos Detected</b> |
|----------------------------|---|-----------------------------|

**B00Y - R0003 - Shower/Change (8.18 m2)**

|                            |   |                             |
|----------------------------|---|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>8101/B00Z/R0004/Wall Linings Internal/S25 | <b>No Asbestos Detected</b> |
|----------------------------|---|-----------------------------|

**B00Y - R0004 - Movement (4.34 m2)**

|                            |   |                             |
|----------------------------|---|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>8101/B00Z/R0004/Wall Linings Internal/S25 | <b>No Asbestos Detected</b> |
|----------------------------|---|-----------------------------|

**B00Y - R0005 - Machine Storage (34.28 m2)**

|                            |   |                             |
|----------------------------|---|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>8101/B00Z/R0004/Wall Linings Internal/S25 | <b>No Asbestos Detected</b> |
|----------------------------|---|-----------------------------|

**B00Y - R0006 - Animal Space (9.13 m2)**

|                            |   |                             |
|----------------------------|---|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>8101/B00Z/R0004/Wall Linings Internal/S25 | <b>No Asbestos Detected</b> |
|----------------------------|---|-----------------------------|

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00Z - Agricultural Science - 1979 - Timber (Timber)**

**Exterior**

|                           |                |          |              |                    |         |                    |
|---------------------------|----------------|----------|--------------|--------------------|---------|--------------------|
| Electrical Mounting Board | Resinous Board | 1Unit(s) | South facing | Good Condition (1) | Low (1) | Low Priority (2-3) |
|---------------------------|----------------|----------|--------------|--------------------|---------|--------------------|

**Assumed Asbestos - Electrical Hazard**

Underfloor Voids - Slab on Ground

Ceiling Voids No Asbestos Found

**Interior**

**B00Z - R0001 - Animal Space (4.25 m2)**

No Asbestos

**B00Z - R0002 - Animal Space (8.56 m2)**

No Asbestos

**B00Z - R0003 - Animal Space (8.56 m2)**

No Asbestos

**B00Z - R0004 - Class Tools Storage (39.03 m2)**

|              |                  |   |                             |
|--------------|------------------|---|-----------------------------|
| New Exterior | Flat AC Sheeting | 8101/B00Z/R0004/Wall Linings Internal/S25 | <b>No Asbestos Detected</b> |
|--------------|------------------|---|-----------------------------|

|                            |                  |   |                             |
|----------------------------|------------------|---|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 8101/B00Z/R0004/Wall Linings Internal/S25 | <b>No Asbestos Detected</b> |
|----------------------------|------------------|---|-----------------------------|

**B00Z - R0005 - General Storeroom (4.28 m2)**

No Asbestos

2017



| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

### Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10797 - Learning Unit - Standard With P.A.A. : Placement Date - 26/11/2014

#### Exterior

|             |                     |                  |          |
|-------------|---------------------|------------------|----------|
| Step Treads | Compressed AC Sheet | Assumed Asbestos | 1.08 m2  |
| Landing     | Compressed AC Sheet | Assumed Asbestos | 1.2 m2   |
| Eave Lining | Flat AC Sheet       | Assumed Asbestos | 11.52 m2 |

#### Interior

##### R1 - Learning space/withdrawal/entry

|         |               |                  |       |
|---------|---------------|------------------|-------|
| Ceiling | Flat AC Sheet | Assumed Asbestos | 70 m2 |
|---------|---------------|------------------|-------|

##### R2 - Home Base Store

|                |               |                  |       |
|----------------|---------------|------------------|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos | 18 m2 |
| Ceiling        | Flat AC Sheet | Assumed Asbestos | 3 m2  |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017