


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Auburn Girls High School (8253)  
**Region :** South Western Sydney  
**State Electorate :** Auburn  
**Local Government Area :** Auburn

**Initial Survey :** Noel Arnold & Associates : 21 - Mar - 2008  
**Reviewed By :** Greencap-NAA : 13 - Aug - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Multi Purpose Facilities - 1959 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00A - M0001 - Control Room**

No Asbestos

**B00A - M0002 - Movement**

No Asbestos

**B00A - R0001 - Toilets-Girls**

No Asbestos

**B00A - R0002 - Change**

No Asbestos

**B00A - R0003 - Uniform Shop**

No Asbestos

**B00A - R0005 - Movement**

No Asbestos

**B00A - R0006 - Movement**

No Asbestos

**B00A - R0007 - Multi-Purpose Space**

No Asbestos

**B00A - R0008 - Plant**

No Asbestos

**B00A - R0009 - Plant**

No Asbestos

**B00A - R0010 - Stage**

No Asbestos

**B00A - R0011 - External Movement**

No Asbestos

**B00A - R0012 - External Movement**

No Asbestos

**B00A - R9001 - General Storeroom**

No Asbestos

**B00A - R9002 - General Storeroom**

No Asbestos

**B00A - R9003 - General Storeroom**

No Asbestos

**B00A - R9004 - General Storeroom**

No Asbestos

**B00A - R9005 - Toilets-Boys**

Partition Walls (Cubicles)	Compressed AC Sheet 8253/B00A/R9005/Partition Walls (Cubicles)/S8
----------------------------	--

No Asbestos Detected

**B00A - R9007 - General Assistants**

No Asbestos

**B00A - R9008 - Garden Store Room**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Administration/General Learning/Science Learning - 1959 - Brick/Block (Brick/Block)**

**Exterior**

Shade Panels	Compressed AC Sheet 8253/B00B/Sun Shields/S1					<b>No Asbestos Detected</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00B - R0B01 - Administration - Clerical**

No Asbestos

**B00B - R0B02 - Commonroom**

No Asbestos

**B00B - R0B03 - Staff Kitchen**

No Asbestos

**B00B - R0B06 - Deputy Principal Office**

No Asbestos

**B00B - R0B07 - General Storeroom**

No Asbestos

**B00B - R0B08 - Staff - Toilet**

No Asbestos

**B00B - R0B09 - Tea Room**

No Asbestos

**B00B - R0B10 - General Storeroom**

No Asbestos

**B00B - R0B11 - General Storeroom**

No Asbestos

**B00B - R0B12 - Principal Office**

No Asbestos

**B00B - R0B13 - Administration - Clerical**

No Asbestos

**B00B - R0B14 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8253/B00B/R0C16/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>

**B00B - R0B15 - Pupil Entry**

No Asbestos

**B00B - R0B16 - Secure Storeroom**

No Asbestos

**B00B - R0B17 - External Movement**

No Asbestos

**B00B - R0B19 - Administration - Clerical**

No Asbestos

**B00B - R0B20 - Staff - Toilet**

No Asbestos

**B00B - R0B22 - Clinic - Girls**

No Asbestos

**B00B - R0B23 - Main Switch Board Cupboard**

Electrical Cover Board	Flat AC Sheeting 8253/B00B/R0B23/Electrical Cover Board/S4					<b>No Asbestos Detected</b>
------------------------	---	--	--	--	--	-----------------------------

**B00B - R0B24 - Archive Store**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0B25 - Deputy Principal Office</b>						
No Asbestos						
<b>B00B - R0B26 - Staff - Toilet</b>						
No Asbestos						
<b>B00B - R0B27 - Staff - Toilet</b>						
No Asbestos						
<b>B00B - R0B28 - Movement</b>						
No Asbestos						
<b>B00B - R0B29 - Student Drinking Facilities</b>						
No Asbestos						
<b>B00B - R0B30 - Stairs</b>						
No Asbestos						
<b>B00B - R0C01 - Staff Study</b>						
No Asbestos						
<b>B00B - R0C02 - Laundry</b>						
No Asbestos						
<b>B00B - R0C03 - Staff Kitchen</b>						
No Asbestos						
<b>B00B - R0C05 - Staff Study</b>						
No Asbestos						
<b>B00B - R0C06 - Tea Room</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
8253/B00B/R0C23/Floor Coverings Res/Textile/S5					<b>No Asbestos Detected</b>	
<b>B00B - R0C07 - Distribution Board Cupboard</b>						
					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00B - R0C09 - External Movement</b>						
No Asbestos						
<b>B00B - R0C10 - General Learning Space</b>						
No Asbestos						
<b>B00B - R0C11 - General Learning Space</b>						
No Asbestos						
<b>B00B - R0C12 - Preparation - Materials</b>						
No Asbestos						
<b>B00B - R0C13 - Resources Store</b>						
No Asbestos						
<b>B00B - R0C14 - Food Technology L.S.</b>						
No Asbestos						
<b>B00B - R0C15 - Sport Equipment Store</b>						
No Asbestos						
<b>B00B - R0C16 - External Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8253/B00B/R0C16/Ceiling Structures/Linings/S3				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00B - R0C17 - Computer Learning Space</b>						
No Asbestos						
<b>B00B - R0C18 - General Storeroom</b>						
No Asbestos						
<b>B00B - R0C19 - Resources Store</b>						
No Asbestos						
<b>B00B - R0C20 - Laboratory L.S.</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority	
	Sample No					Test Result	
No Asbestos							
<b>B00B - R0C21 - Preparation - Science</b>							
No Asbestos							
<b>B00B - R0C22 - Bulk Store</b>							
No Asbestos							
<b>B00B - R0C23 - Apparatus Storage</b>							
Floor Coverings Res/Textile	Vinyl Tiles						
8253/B00B/R0C23/Floor Coverings Res/Textile/S5					No Asbestos Detected		
<b>B00B - R0C24 - Public Entry</b>							
No Asbestos							
<b>B00B - R0C25 - External Movement</b>							
No Asbestos							
<b>B00B - R0C26 - Chemical Store</b>							
No Asbestos							
<b>B00B - R0C27 - Resources Store</b>							
No Asbestos							
<b>B00B - R0C28 - General Learning Space</b>							
No Asbestos							
<b>B00B - R0C29 - General Learning Space</b>							
No Asbestos							
<b>B00B - R0C30 - General Learning Space</b>							
No Asbestos							
<b>B00B - R0C31 - General Learning Space</b>							
No Asbestos							
<b>B00B - R0C32 - Movement</b>							
No Asbestos							
<b>B00B - R0C33 - External Movement</b>							
No Asbestos							
<b>B00B - R0C34 - Cleaning Store - Distributed</b>							
No Asbestos							
<b>B00B - R0C35 - Movement</b>							
No Asbestos							
<b>B00B - R0C36 - Staff Study</b>							
No Asbestos							
<b>B00B - R0C37 - Stairs</b>							
No Asbestos							
<b>B00B - R0C38 - Stairs</b>							
No Asbestos							
<b>B00B - R0C39 - Stairs</b>							
No Asbestos							
<b>B00B - R0D01 - Food Technology L.S.</b>							
No Asbestos							
<b>B00B - R0D02 - Resources Store</b>							
No Asbestos							
<b>B00B - R0D03 - Preparation - Materials</b>							
No Asbestos							
<b>B00B - R0D04 - Music Learning Space</b>							
No Asbestos							
<b>B00B - R0D05 - Music Store</b>							

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Floor Coverings Res/Textile	Vinyl Tiles					
	8253/B00B/R0C23/Floor Coverings Res/Textile/S5					No Asbestos Detected
<b>B00B - R0D06 - Music Learning Space</b>						
No Asbestos						
<b>B00B - R0D07 - Music Store</b>						
No Asbestos						
<b>B00B - R0D08 - Movement</b>						
No Asbestos						
<b>B00B - R0D09 - External Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	1.9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8253/B00B/R0C16/Ceiling Structures/Linings/S3					Chrysotile (white asbestos) , Amosite (brown asbestos)
<b>B00B - R0D10 - Movement</b>						
Wall Infill Panel	Compressed AC Sheet					
	8253/B00B/R1D09/Wall Infill Panel/S6					No Asbestos Detected
<b>B00B - R0D11 - Stairs</b>						
No Asbestos						
<b>B00B - R0E01 - Laboratory L.S.</b>						
No Asbestos						
<b>B00B - R0E02 - Printing/Photocopying</b>						
No Asbestos						
<b>B00B - R0E04 - General Learning Space</b>						
No Asbestos						
<b>B00B - R0E05 - Movement</b>						
No Asbestos						
<b>B00B - R0E07 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00B - R0E08 - Staff Study</b>						
No Asbestos						
<b>B00B - R0E09 - Tea Room</b>						
No Asbestos						
<b>B00B - R0E10 - General Storeroom</b>						
No Asbestos						
<b>B00B - R0E11 - Plant</b>						
No Asbestos						
<b>B00B - R1B02 - General Learning Space</b>						
No Asbestos						
<b>B00B - R1B03 - General Learning Space</b>						
No Asbestos						
<b>B00B - R1B04 - General Learning Space</b>						
No Asbestos						
<b>B00B - R1B05 - Computer Learning Space</b>						
No Asbestos						
<b>B00B - R1B06 - Computer Learning Space</b>						
No Asbestos						
<b>B00B - R1B07 - System Administrators Office</b>						
No Asbestos						
<b>B00B - R1B09 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00B - R1B10 - Movement</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00B - R1B11 - Stairs</b>						
No Asbestos						
<b>B00B - R1B12 - Tea Room</b>						
No Asbestos						
<b>B00B - R1B13 - Staff Study</b>						
No Asbestos						
<b>B00B - R1C01 - Performance Workshop</b>						
No Asbestos						
<b>B00B - R1C02 - Resources Store</b>						
No Asbestos						
<b>B00B - R1C03 - Other-Vacant</b>						
No Asbestos						
<b>B00B - R1C04 - Staff Study</b>						
No Asbestos						
<b>B00B - R1C05 - Materials Technology L.S.</b>						
No Asbestos						
<b>B00B - R1C06 - Resources Store</b>						
No Asbestos						
<b>B00B - R1C07 - Resources Store</b>						
No Asbestos						
<b>B00B - R1C08 - Resources Store</b>						
No Asbestos						
<b>B00B - R1C09 - Materials Technology L.S.</b>						
No Asbestos						
<b>B00B - R1C10 - Staff Study</b>						
No Asbestos						
<b>B00B - R1C11 - Computer Learning Space</b>						
No Asbestos						
<b>B00B - R1C12 - General Learning Space</b>						
No Asbestos						
<b>B00B - R1C13 - General Learning Space</b>						
No Asbestos						
<b>B00B - R1C14 - General Learning Space</b>						
No Asbestos						
<b>B00B - R1C15 - Staff Study</b>						
No Asbestos						
<b>B00B - R1C16 - Resources Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8253/B00B/R0C23/Floor Coverings Res/Textile/S5					<b>No Asbestos Detected</b>
<b>B00B - R1C18 - Interview/Office - Type 1</b>						
No Asbestos						
<b>B00B - R1C19 - Staff Study</b>						
No Asbestos						
<b>B00B - R1C20 - General Learning Space</b>						
No Asbestos						
<b>B00B - R1C21 - General Learning Space</b>						
No Asbestos						
<b>B00B - R1C22 - General Learning Space</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R1C24 - Interview/Office - Type 1</b>						
No Asbestos						
<b>B00B - R1C25 - Staff Study</b>						
No Asbestos						
<b>B00B - R1C26 - Movement</b>						
No Asbestos						
<b>B00B - R1C27 - Stairs</b>						
No Asbestos						
<b>B00B - R1C28 - Stairs</b>						
No Asbestos						
<b>B00B - R1C29 - Student Drinking Facilities</b>						
No Asbestos						
<b>B00B - R1C30 - Stairs</b>						
No Asbestos						
<b>B00B - R1D01 - General Learning Space</b>						
No Asbestos						
<b>B00B - R1D02 - General Storeroom</b>						
No Asbestos						
<b>B00B - R1D03 - General Storeroom</b>						
No Asbestos						
<b>B00B - R1D04 - General Learning Space</b>						
No Asbestos						
<b>B00B - R1D05 - Resources Store</b>						
No Asbestos						
<b>B00B - R1D06 - Resources Store</b>						
No Asbestos						
<b>B00B - R1D07 - General Learning Space</b>						
No Asbestos						
<b>B00B - R1D09 - Movement</b>						
No Asbestos						
<b>B00B - R1D10 - Stairs</b>						
No Asbestos						
<b>B00B - R1D11 - Movement</b>						
No Asbestos						
<b>B00B - R1D12 - Student Drinking Facilities</b>						
No Asbestos						
<b>B00B - R1E01 - Art Learning Space</b>						
No Asbestos						
<b>B00B - R1E02 - Art Learning Space</b>						
No Asbestos						
<b>B00B - R1E03 - Resources Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8253/B00B/R0C23/Floor Coverings Res/Textile/S5					<b>No Asbestos Detected</b>
<b>B00B - R1E04 - Kiln Space</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8253/B00B/R0C23/Floor Coverings Res/Textile/S5					<b>No Asbestos Detected</b>
Loose Sheeting	Compressed AC Sheet					
	8253/B00B/R1E04/Loose Sheeting/S7					<b>No Asbestos Detected</b>
<b>B00B - R1E05 - Art Learning Space</b>						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles					
	8253/B00B/R0C23/Floor Coverings Res/Textile/S5					No Asbestos Detected
<b>B00B - R1E06 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00B - R1E07 - Movement</b>						
No Asbestos						
<b>B00B - R9C02 - Toilets-Girls</b>						
No Asbestos						
<b>B00B - R9C03 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00B - R9C04 - Cleaning Supplies Store</b>						
No Asbestos						
<b>B00B - Room+1 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	0.5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8253/B00B/R0C16/Ceiling Structures/Linings/S3					Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Library/Science Learning - 1959 - Brick/Block (Brick/Block)**

**Exterior**

Shade Panels	Compressed AC Sheet 8253/B00F/Sun Shields/S2					No Asbestos Detected
Ceiling Voids	Non Accessible Area - No access points					
Underfloor Voids - Slab on Ground	No Asbestos Found					

**Interior**

**B00F - R0001 - Laboratory L.S.**

No Asbestos

**B00F - R0002 - Preparation - Science**

Heat Proof Tiles	Compressed AC Sheet 8253/B00F/R1001/Heat Proof Mats/S11					No Asbestos Detected
------------------	--	--	--	--	--	----------------------

**B00F - R0003 - Lift**

No Asbestos

**B00F - R0004 - Laboratory L.S.**

No Asbestos

**B00F - R0005 - Administration - Clerical**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8253/B00F/R0010/Floor Coverings Res/Textile/S9					No Asbestos Detected
-----------------------------	---	--	--	--	--	----------------------

**B00F - R0006 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

Electrical Mounting Board	Resinous Board 8253/B00F/R0006/Electrical Mounting Board/S10					No Asbestos Detected
---------------------------	---	--	--	--	--	----------------------

**B00F - R0007 - Movement**

No Asbestos

**B00F - R0008 - Movement**

Floor Coverings Res/Textile	Vinyl Tiles 8253/B00F/R0010/Floor Coverings Res/Textile/S9					No Asbestos Detected
-----------------------------	---	--	--	--	--	----------------------

**B00F - R0009 - Movement**

No Asbestos

**B00F - R0010 - Cleaning Store - Distributed**

Floor Coverings Res/Textile	Vinyl Tiles 8253/B00F/R0010/Floor Coverings Res/Textile/S9					No Asbestos Detected
-----------------------------	---	--	--	--	--	----------------------

**B00F - R0012 - Careers Advisers Office**

No Asbestos

**B00F - R0014 - Main Area**

No Asbestos

**B00F - R0019 - Resources Space**

No Asbestos

**B00F - R0020 - Librarian**

No Asbestos

**B00F - R0021 - Tea Room**

Floor Coverings Res/Textile	Vinyl Tiles 8253/B00F/R0010/Floor Coverings Res/Textile/S9					No Asbestos Detected
-----------------------------	---	--	--	--	--	----------------------

**B00F - R0022 - Audio Visual Workroom**

No Asbestos

**B00F - R0023 - General Storeroom**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00F - R0024 - Resources Space</b>						
No Asbestos						
<b>B00F - R0025 - External Movement</b>						
No Asbestos						
<b>B00F - R1001 - Laboratory L.S.</b>						
No Asbestos						
<b>B00F - R1005 - Laboratory L.S.</b>						
No Asbestos						
<b>B00F - R1007 - Distribution Board Cupboard</b>					Note: No inspection of live electrical installation.	
Electrical Mounting Board	Millboard					
	8253/B00F/R0006/Electrical Mounting Board/S10					<b>No Asbestos Detected</b>
<b>B00F - R1008 - Staff - Toilet</b>						
Wall Linings Internal	Flat AC Sheeting					
	8253/B00F/R1008/Wall Linings Internal/S12					<b>No Asbestos Detected</b>
<b>B00F - R1009 - Staff - Toilet</b>						
No Asbestos						
<b>B00F - R1010 - General Learning Space</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8253/B00F/R0010/Floor Coverings Res/Textile/S9					<b>No Asbestos Detected</b>
<b>B00F - R1012 - Distribution Board Cupboard</b>					Note: No inspection of live electrical installation.	
Ceiling Structures/Linings	Flat AC Sheeting	0.64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8253/B00F/R1012/Ceiling Structures/Linings/S15					<b>Chrysotile (white asbestos)</b>
<b>B00F - R1014 - Movement</b>						
No Asbestos						
<b>B00F - R1016 - Office/Store</b>						
No Asbestos						
<b>B00F - R1017 - Office/Store</b>						
No Asbestos						
<b>B00F - R1018 - Staff Study</b>						
No Asbestos						
<b>B00F - R1019 - Tea Room</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8253/B00F/R0010/Floor Coverings Res/Textile/S9					<b>No Asbestos Detected</b>
<b>B00F - R1020 - Staff Study</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8253/B00F/R0010/Floor Coverings Res/Textile/S9					<b>No Asbestos Detected</b>
<b>B00F - R1021 - Tea Room</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8253/B00F/R0010/Floor Coverings Res/Textile/S9					<b>No Asbestos Detected</b>
<b>B00F - R1022 - Staff Study</b>						
No Asbestos						
<b>B00F - R1023 - Tea Room</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	8253/B00F/R0010/Floor Coverings Res/Textile/S9					<b>No Asbestos Detected</b>
<b>B00F - R1024 - External Movement</b>						
No Asbestos						
<b>B00F - R1025 - Preparation - Science</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00F - R1026 - Movement</b>						
No Asbestos						
<b>B00F - R1027 - Plant</b>						
Gaskets	Encapsulated Insulation material within unit	1Unit	South West	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Encased in unit</b>						
<b>B00F - R1028 - Darkroom Space</b>						
No Asbestos						
<b>B00F - R1029 - Dark Room</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Physical Education/Pupil Facilities - 1959 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00G - R0001 - Sport Equipment Store**

Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8253/B00G/R0018/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0002 - Sport Equipment Store**

Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Some Damage / Unsealed (3)	Medium (2)	Low Priority (2-3)
8253/B00G/R0018/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0003 - Gymnasium**

No Asbestos

**B00G - R0005 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8253/B00G/R0018/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0007 - External Movement**

No Asbestos

**B00G - R0009 - Cleaning Store - Distributed**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8253/B00G/R0018/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0012 - Student Canteen**

No Asbestos

**B00G - R0013 - Pantry**

No Asbestos

**B00G - R0014 - General Storeroom**

No Asbestos

**B00G - R0015 - Staff - Toilet**

No Asbestos

**B00G - R0016 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting	38m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
8253/B00G/R0018/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0018 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting	79m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8253/B00G/R0018/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0020 - Toilets-Girls**

Ceiling Structures/Linings	Flat AC Sheeting	62.36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8253/B00G/R0018/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00G - R0021 - Toilets-Girls**

Ceiling Structures/Linings	Flat AC Sheeting	39.78m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8253/B00G/R0018/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
<b>B00G - R0022 - Change</b>						
Ceiling Structures/Linings	Flat AC Sheeting	88.27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8253/B00G/R0018/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0023 - Plant</b>						
Ceiling Structures/Linings	Flat AC Sheeting	0.8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8253/B00G/R0018/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0024 - General Storeroom</b>						
Ceiling Structures/Linings	Flat AC Sheeting	7.21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8253/B00G/R0018/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0025 - Staff Shower</b>						
Ceiling Structures/Linings	Flat AC Sheeting	1.31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8253/B00G/R0018/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0026 - Staff - Toilet</b>						
Ceiling Structures/Linings	Flat AC Sheeting	1.66m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8253/B00G/R0018/Ceiling Structures/Linings/S14				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0027 - Movement</b>						
Recently Modified Space	Requires Inspection					
<b>B00G - R0028 - Food Technology L.S.</b>						
Recently Modified Space	Requires Inspection					
<b>B00G - R0029 - Project Store - Type 1</b>						
Recently Modified Space	Requires Inspection					
<b>B00G - R0030 - Laundry</b>						
Recently Modified Space	Requires Inspection					
<b>B00G - R0031 - Pantry</b>						
Recently Modified Space	Requires Inspection					
<b>B00G - R0032 - Seminar/Technology Space</b>						
Recently Modified Space	Requires Inspection					
<b>B00G - R0033 - Plant</b>						
Recently Modified Space	Requires Inspection					
<b>B00G - R0034 - Pantry</b>						
Recently Modified Space	Requires Inspection					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Other-Community Use - 1950 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting 8253/B00H/Gable Ends/S16	13m2	North facing, South facing	Good Condition (1) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	Low (1)	Low Priority (2-3)
Gable Ends	Flat AC Sheeting 8253/B00H/Gable Ends/S16	18m2	East facing, West facing	Minimal Damage (2) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	Low (1)	Low Priority (2-3)
Gable verge lining	Flat AC Sheeting 8253/B00H/Gable verge lining/S17	24m	East facing, West facing	Minimal Damage (2) <b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>	Low (1)	Low Priority (2-3)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00H - R0001 - Staff Kitchen**

No Asbestos

**B00H - R0002 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 8253/B00H/Gable Ends/S16	3m2	All surfaces	Good Condition (1) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	Low (1)	Low Priority (2-3)
----------------------------	--	-----	--------------	---	---------	--------------------

**B00H - R0003 - General Storeroom**

No Asbestos

**B00H - R0004 - Staff - Toilet**

No Asbestos

**B00H - R0005 - Staff Shower**

No Asbestos

**B00H - R0006 - Cleaning Store - Distributed**

No Asbestos

**B00H - R0007 - Resources Store**

No Asbestos

**B00H - R0008 - Child Care Centre**

No Asbestos

**B00H - R0009 - Seminar**

No Asbestos

**B00H - R0010 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 8253/B00H/Gable Ends/S16	1.96m2	Throughout	Good Condition (1) <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	Low (1)	Low Priority (2-3)
----------------------------	--	--------	------------	---	---------	--------------------

**B00H - R0011 - Child Care Centre**

No Asbestos

**B00H - R0012 - Movement**

No Asbestos

**B00H - Room+1 - Study Area**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 600 - D10845 - Learning Unit - Small : Placement Date - 12/04/2000**

### Exterior

Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	8.64 m2

### Interior

#### R1 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

**OS 601 - D11175 - Learning Unit - Standard/Withdrawal : Placement Date - 22/02/2008**

### Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

### Interior

#### R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

#### R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

#### R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

**OS 601 - D11295 - Learning Unit - Standard/Withdrawal : Placement Date - 28/01/2003**

### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

### Interior

#### R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

#### R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

#### R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

**OS 601 - D12326 - Learning Unit - Standard/Withdrawal : Placement Date - 24/12/1999**

### Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Entry</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
<b>R2 - General Learning Space</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
<b>R3 - Store</b>						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
<b>OS 751 - D14591 - Learning Unit - ESL : Placement Date - 30/06/1995</b>						
<b>Exterior</b>						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
<b>Interior</b>						
<b>R1 - Es1</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
<b>R2 - Es1</b>						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
<b>NS 280 - D14592 - Wood Metal Technics/Heat Area/Storage : Placement Date - 30/06/1995</b>						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Materials Technology L.S.</b>						
No Asbestos Found.						
<b>R2 - Welding Area</b>						
No Asbestos Found.						
<b>R3 - Store</b>						
No Asbestos Found.						
<b>R4 - Entry</b>						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017