

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Ashcroft High School (8397)
Region : South Western Sydney
State Electorate : Liverpool
Local Government Area : Liverpool

Initial Survey : Noel Arnold & Associates : 23 - Apr - 2008
Reviewed By : Grencap-NAA : 26 - Aug - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Art/Music - 1964 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	100m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						
Eaves Linings	Non Accessible Area - Height Restricted - >8m High					
Underfloor Voids	No Asbestos Found					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					

Interior

B00A - R0001 - Music Learning Space (86.32 m2)

Ceiling Structures/Linings	Vermiculite	8397/B00E/R0017/Ceiling Structures/Linings/S4				Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00A - R0003 - Music Learning Space (85.94 m2)

Ceiling Structures/Linings	Vermiculite	8397/B00E/R0017/Ceiling Structures/Linings/S4				Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

Fume Cupboard	Flat AC Sheeting	2m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
8397/B00E/R0004/Fume Cupboard/S5				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0005 - Plant (15.83 m2)

No Asbestos

B00A - R0007 - General Storeroom (6.76 m2)

Ceiling Structures/Linings	Vermiculite	8397/B00E/R0017/Ceiling Structures/Linings/S4				Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00A - R0008 - General Assistants (19.43 m2)

Ceiling Structures/Linings	Vermiculite	8397/B00E/R0017/Ceiling Structures/Linings/S4				Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00A - R0009 - Plant (3.91 m2)

Ceiling Structures/Linings	Vermiculite	8397/B00E/R0017/Ceiling Structures/Linings/S4				Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

Flue	Fibre Cement Pipe	1m	North, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
8397/B00A/R1010/Flue/S27				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0010 - Art Learning Space (79.63 m2)

Ceiling Structures/Linings	Vermiculite	8397/B00E/R0017/Ceiling Structures/Linings/S4				Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

Floor Coverings Res/Textile	Vinyl Sheet	8397/B00A/R0015/Floor Coverings Res/Textile/S11				No Asbestos Detected
-----------------------------	-------------	---	--	--	--	----------------------

B00A - R0011 - Kiln Space (19.85 m2)

Ceiling Structures/Linings	Vermiculite	8397/B00E/R0017/Ceiling Structures/Linings/S4				Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

Floor Coverings Res/Textile	Vinyl Sheet	8397/B00A/R0015/Floor Coverings Res/Textile/S11				No Asbestos Detected
-----------------------------	-------------	---	--	--	--	----------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0012 - General Storeroom (9.24 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Sheet					
	8397/B00A/R0015/Floor Coverings Res/Textile/S11					No Asbestos Detected
B00A - R0013 - Materials Store (16.87 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Sheet					
	8397/B00A/R0015/Floor Coverings Res/Textile/S11					No Asbestos Detected
B00A - R0014 - Art Learning Space (65.38 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Sheet					
	8397/B00A/R0015/Floor Coverings Res/Textile/S11					No Asbestos Detected
B00A - R0015 - Materials Store (5.84 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Sheet					
	8397/B00A/R0015/Floor Coverings Res/Textile/S11					No Asbestos Detected
B00A - R0017 - Materials Store (3.26 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0018 - Cleaning Store - Distributed (3.31 m2)						
No Asbestos						
B00A - R0019 - Staff - Toilet (5.93 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0020 - Music Store (30.48 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Fume Cupboard	Flat AC Sheeting	2Unit	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8397/B00E/R0004/Fume Cupboard/S5					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R0022 - External Movement (28.79 m2)						
No Asbestos						
B00A - R0023 - Staff Study (37.81 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0024 - Tea Room (7.82 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite		8397/B00E/R0017/Ceiling Structures/Linings/S4			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0025 - General Storeroom (3.29 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00E/R0017/Ceiling Structures/Linings/S4			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0026 - General Storeroom (3.87 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00E/R0017/Ceiling Structures/Linings/S4			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0027 - Movement (2.35 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00E/R0017/Ceiling Structures/Linings/S4			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0028 - Stairs (6.25 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00E/R0017/Ceiling Structures/Linings/S4			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0029 - Movement (3.72 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00E/R0017/Ceiling Structures/Linings/S4			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0030 - Stairs (9.37 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00E/R0017/Ceiling Structures/Linings/S4			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0031 - Darkroom Space (2.7 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00E/R0017/Ceiling Structures/Linings/S4			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0032 - Dark Room (23.44 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00E/R0017/Ceiling Structures/Linings/S4			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R0033 - Movement (106.99 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00E/R0017/Ceiling Structures/Linings/S4			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R1001 - General Learning Space (53.44 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00E/R0017/Ceiling Structures/Linings/S4			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R1002 - General Learning Space (66.83 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00E/R0017/Ceiling Structures/Linings/S4			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Flue	Fibre Cement Pipe	4m	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8397/B00A/R1002/Flue/S10					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R1003 - General Storeroom (6.28 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00E/R0017/Ceiling Structures/Linings/S4			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Sheet					
	8397/B00A/R1003/Floor Coverings Res/Textile/S9					No Asbestos Detected
B00A - R1005 - Computer Learning Space (80.39 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R1006 - Audio Visual Workroom (26.39 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R1007 - Staff - Toilet (5.63 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R1010 - General Storeroom (26.57 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Flue	Fibre Cement Pipe	3m	North, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	8397/B00A/R1010/Flue/S27					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00A - R1011 - General Learning Space (53.67 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R1012 - General Learning Space (53.53 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R1013 - General Learning Space (53.09 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R1014 - Performing Arts Store (12.98 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R1015 - Movement (107.75 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00A - R1017 - Staff Study (50.41 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Sheet					
	8397/B00A/R0015/Floor Coverings Res/Textile/S11					No Asbestos Detected
B00A - R1018 - Staff Kitchen (3.11 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Floor Coverings Res/Textile Vinyl Sheet
 8397/B00A/R0015/Floor Coverings Res/Textile/S11 **No Asbestos Detected**

B00A - R1019 - Distribution Board Cupboard (1.01 m2) Note: No inspection of live electrical installation.

Ceiling Structures/Linings Vermiculite
 8397/B00E/R0017/Ceiling Structures/Linings/S4 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R1020 - Cleaning Store - Distributed (5.2 m2)

Ceiling Structures/Linings Vermiculite
 8397/B00E/R0017/Ceiling Structures/Linings/S4 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R1021 - Stairs (8.93 m2)

Ceiling Structures/Linings Vermiculite
 8397/B00E/R0017/Ceiling Structures/Linings/S4 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R1022 - Stairs (9.16 m2)

Ceiling Structures/Linings Vermiculite
 8397/B00E/R0017/Ceiling Structures/Linings/S4 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Pupil Facilities/Physical Education - 1964 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00B - R0002 - Shower (7.65 m2)

No Asbestos

B00B - R0003 - Movement (7.35 m2)

No Asbestos

B00B - R0004 - Change (45.85 m2)

No Asbestos

B00B - R0005 - Sport Equipment Store (11.26 m2)

No Asbestos

B00B - R0006 - General Storeroom (7.89 m2)

No Asbestos

B00B - R0007 - Machine Storage (28.68 m2)

No Asbestos

B00B - R0008 - Machine Storage (30.17 m2)

No Asbestos

B00B - R0009 - Fitness Laboratory (153.48 m2)

No Asbestos

B00B - R0010 - Staff - Toilet (2.42 m2)

No Asbestos

B00B - R0011 - Sport Equipment Store (16.68 m2)

No Asbestos

B00B - R0013 - Shower (7.62 m2)

No Asbestos

B00B - R0014 - Movement (7.23 m2)

No Asbestos

B00B - R0017 - Sport Equipment Store (31.67 m2)

No Asbestos

B00B - R0018 - Sport Equipment Store (2.43 m2)

No Asbestos

B00B - R0019 - Student Canteen (43.77 m2)

No Asbestos

B00B - R0020 - Staff - Toilet (3.66 m2)

No Asbestos

B00B - R0021 - General Storeroom (4.43 m2)

No Asbestos

B00B - R0022 - External Movement (115.39 m2)

No Asbestos

B00B - R0023 - Multi-Purpose Space (304.98 m2)

No Asbestos

B00B - R0024 - Student Drinking Facilities (17.6 m2)

No Asbestos

B00B - R0025 - Student Drinking Facilities (17.55 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00B - R0026 - Toilets-Boys (87.43 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	26m2	Central	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	---------------------	------	---------	--------------------	---------	--------------------

8397/B00B/R0026/Partition Walls (Cubicles)/S22

Chrysotile (white asbestos)

B00B - R0027 - Toilets-Girls (88 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	40m2	Central	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	---------------------	------	---------	--------------------	---------	--------------------

8397/B00B/R0026/Partition Walls (Cubicles)/S22

Chrysotile (white asbestos)

B00B - R0028 - General Storeroom (13.69 m2)

No Asbestos

B00B - R0029 - Handwashing Facilities (13.76 m2)

No Asbestos

B00B - R0030 - Change (44.74 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	14m2	Central	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	---------------------	------	---------	--------------------	---------	--------------------

8397/B00B/R0026/Partition Walls (Cubicles)/S22

Chrysotile (white asbestos)

B00B - R0031 - Plant (1.04 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Technological & Applied Studies/General Learning - 1964 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible
Underfloor Voids	No Asbestos Found
Wall Cladding	No Asbestos Found

Interior

B00C - R0001 - Sport Equipment Store (40.05 m2)

No Asbestos

B00C - R0002 - Laundry (8.02 m2)

No Asbestos

B00C - R0003 - Staff Study (52.8 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00C - R0004 - General Storeroom (6.48 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00C - R0005 - General Storeroom (5.39 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00C - R0010 - Staff - Toilet (5.83 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00C - R0017 - Computer Learning Space (52.51 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00C - R0019 - General Storeroom (5.69 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00C - R0020 - General Storeroom (3.26 m2)

No Asbestos

B00C - R0021 - Cleaning Store - Distributed (3.94 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00C - R0026 - Design L.S. (59.23 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00C - R0027 - Design L.S. (66.77 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13	Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>		

B00C - R0029 - External Movement (37.9 m2)

No Asbestos

B00C - R0030 - Maintenance Bulk Store (76.8 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting					
	8397/B00C/R0030/Wall Linings Internal/S24					No Asbestos Detected
B00C - R0031 - Distribution Board Cupboard (0.62 m2)					Note: No inspection of live electrical installation.	
No Asbestos						
B00C - R0034 - Staff Study (43.71 m2)						
No Asbestos						
B00C - R0035 - Staff Kitchen (2.35 m2)						
No Asbestos						
B00C - R0036 - Stairs (9.84 m2)						
No Asbestos						
B00C - R0037 - Stairs (6.45 m2)						
No Asbestos						
B00C - R0038 - Movement (3.45 m2)						
No Asbestos						
B00C - R0039 - Movement (3.48 m2)						
No Asbestos						
B00C - R0040 - Movement (103.42 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	103.38m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8397/B00C/R0040/Floor Coverings Res/Textile/S23					Chrysotile (white asbestos)
B00C - R0041 - Kitchen - Type 1 (114.38 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8397/B00C/R0043/Ceiling Structures/Linings/S36					<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00C - R0042 - Pantry (11.52 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8397/B00C/R0043/Ceiling Structures/Linings/S36					<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00C - R0043 - General Learning Space (58.76 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8397/B00C/R0043/Ceiling Structures/Linings/S36					<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00C - R1001 - Staff Study (26.32 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8397/B00F/R0012/Ceiling Structures/Linings/S13					<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00C - R1006 - Materials Store (7.49 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8397/B00F/R0012/Ceiling Structures/Linings/S13					<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00C - R1007 - Materials Store (5.69 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8397/B00F/R0012/Ceiling Structures/Linings/S13					<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00C - R1009 - Materials Store (19.85 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8397/B00F/R0012/Ceiling Structures/Linings/S13					<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00C - R1010 - Plant (4.66 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8397/B00F/R0012/Ceiling Structures/Linings/S13					<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00C - R1011 - Materials Store (14.53 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1012 - Wood Technology L.S. (80.5 m2)						
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1013 - Materials Store (26.39 m2)						
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1014 - Staff - Toilet (5.69 m2)						
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1016 - Materials Store (19 m2)						
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Wall Linings Internal	Flat AC Sheeting	8397/B00C/R1016/Wall Linings Internal/S25				No Asbestos Detected
B00C - R1017 - Wood Technology L.S. (95.51 m2)						
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Wall Linings Internal	Flat AC Sheeting	8397/B00C/R1016/Wall Linings Internal/S25				No Asbestos Detected
B00C - R1018 - Wood Technology Bay (26.32 m2)						
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1019 - Wood Technology L.S. (73.24 m2)						
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1020 - Metal Technology L.S. (87.75 m2)						
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1021 - Welding Area (6.54 m2)						
No Asbestos						
B00C - R1022 - Distribution Board Cupboard (0.17 m2)						
No Asbestos						
B00C - R1023 - Stairs (8.93 m2)						
No Asbestos						
B00C - R1024 - Movement (87.58 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	8397/B00C/R1024/Floor Coverings Res/Textile/S26				No Asbestos Detected
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1025 - Movement (17.88 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - R1026 - Stairs (9.03 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Administration/General Learning - 1964 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	200m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction - Height						

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible
---------------------------	--

Underfloor Voids	No Asbestos Found
------------------	-------------------

Interior**B00D - R0002 - Public Reception (70.18 m2)**

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8397/B00D/R0002/Floor Coverings Res/Textile/S18	70.15m2	Throughout	Good Condition (1)	Medium (2)	Low Priority (2-3) Chrysotile (white asbestos)

B00D - R0004 - First Aid (14.21 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8397/B00D/R0002/Floor Coverings Res/Textile/S18	14.2m2	Throughout	Good Condition (1)	Medium (2)	Low Priority (2-3) Chrysotile (white asbestos)

B00D - R0005 - Archive Store (8.81 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Sheet 8397/B00D/R1003/Floor Coverings Res/Textile/S15					No Asbestos Detected

B00D - R0006 - Administration - Clerical (14.32 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	---	--	--	--	--	---

B00D - R0007 - Principal Office (19 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8397/B00D/R0002/Floor Coverings Res/Textile/S18	18.99m2	Throughout	Good Condition (1)	Medium (2)	Low Priority (2-3) Chrysotile (white asbestos)

B00D - R0008 - Tea Room (2.94 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles 8397/B00D/R0027/Floor Coverings Res/Textile/S16					No Asbestos Detected

B00D - R0010 - General Storeroom (5.8 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
----------------------------	---	--	--	--	--	---

B00D - R0011 - General Learning Space (52.72 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00D - R0012 - General Learning Space (66.11 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8397/B00D/R0012/Floor Coverings Res/Textile/S20					No Asbestos Detected
B00D - R0014 - Staff - Toilet (5.83 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Incinerette	Encapsulated Insulation material within unit	1Unit(s)	South, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3) <i>Assumed Asbestos - Area inaccessible</i>
B00D - R0015 - Senior Study (25.89 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Sheet 8397/B00D/R1003/Floor Coverings Res/Textile/S15					No Asbestos Detected
B00D - R0016 - General Learning Space (53.02 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00D - R0017 - Museum (39.2 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00D - R0018 - Distribution Board Cupboard (0.83 m2) Note: No inspection of live electrical installation.						
No Asbestos						
B00D - R0019 - Administration - Clerical (7.52 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8397/B00D/R0002/Floor Coverings Res/Textile/S18	7.52m2	Throughout	Good Condition (1)	Medium (2)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
B00D - R0020 - Cleaning Store - Distributed (2.63 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00D - R0021 - Administration - Clerical (27.12 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8397/B00D/R0002/Floor Coverings Res/Textile/S18	27.12m2	Throughout	Good Condition (1)	Medium (2)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>
B00D - R0023 - Deputy Principal Office (19.05 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8397/B00D/R0002/Floor Coverings Res/Textile/S18	19.04m2	Throughout	Good Condition (1)	Medium (2)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R0024 - Deputy Principal Office (14.07 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 8397/B00D/R0002/Floor Coverings Res/Textile/S18	14.07m2	Throughout	Good Condition (1)	Medium (2)	Low Priority (2-3) Chrysotile (white asbestos)
B00D - R0025 - Interview/Office - Type 1 (14.21 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Sheet 8397/B00D/R0038/Floor Coverings Res/Textile/S19					No Asbestos Detected
B00D - R0028 - General Storeroom (3.23 m2)						
No Asbestos						
B00D - R0030 - External Movement (17.4 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R0031 - External Movement (53.69 m2)						
No Asbestos						
B00D - R0032 - Movement (31.54 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R0033 - Movement (3.99 m2)						
No Asbestos						
B00D - R0034 - Stairs (10.52 m2)						
No Asbestos						
B00D - R0035 - Toilet - Lobby (2.05 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R0036 - Staff - Toilet (6.99 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R0037 - Staff - Toilet (3.16 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
B00D - R0038 - General Storeroom (3.06 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Sheet					
	8397/B00D/R0038/Floor Coverings Res/Textile/S19					No Asbestos Detected
B00D - R0039 - Toilet - Lobby (2.08 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0040 - Staff - Toilet (7 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0041 - Printing/Photocopying (10.6 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	8397/B00D/R0038/Floor Coverings Res/Textile/S19					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite					
	8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0042 - Printing/Photocopying (14.78 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
	8397/B00D/R0038/Floor Coverings Res/Textile/S19					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite					
	8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0043 - General Storeroom (6.44 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0044 - General Storeroom (6.21 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8397/B00D/R0012/Floor Coverings Res/Textile/S20					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite					
	8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0045 - Movement (73.42 m2)						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	73.39m2	Throughout	Good Condition (1)	Medium (2)	Low Priority (2-3)
	8397/B00D/R0002/Floor Coverings Res/Textile/S18					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					
	8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0046 - Movement (3.8 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R0047 - Stairs (6.03 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1001 - General Learning Space (53.67 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R1002 - General Learning Space (53.67 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00F/R0012/Ceiling Structures/Linings/S13			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1003 - General Storeroom (9.37 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00F/R0012/Ceiling Structures/Linings/S13			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Sheet		8397/B00D/R1003/Floor Coverings Res/Textile/S15			No Asbestos Detected
B00D - R1004 - Cleaning Store - Distributed (3.13 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00F/R0012/Ceiling Structures/Linings/S13			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1005 - General Learning Space (53.15 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00F/R0012/Ceiling Structures/Linings/S13			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1006 - General Storeroom (5.83 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00F/R0012/Ceiling Structures/Linings/S13			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Sheet		8397/B00D/R1003/Floor Coverings Res/Textile/S15			No Asbestos Detected
B00D - R1007 - Distribution Board Cupboard (0.66 m2)						
No Asbestos				Note: No inspection of live electrical installation.		
B00D - R1008 - General Storeroom (5.85 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00F/R0012/Ceiling Structures/Linings/S13			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Sheet		8397/B00D/R1003/Floor Coverings Res/Textile/S15			No Asbestos Detected
B00D - R1009 - General Learning Space (53.37 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00F/R0012/Ceiling Structures/Linings/S13			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Sheet		8397/B00D/R1003/Floor Coverings Res/Textile/S15			No Asbestos Detected
B00D - R1010 - Staff - Toilet (6.41 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00F/R0012/Ceiling Structures/Linings/S13			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1011 - Seminar (26.32 m2)						
Ceiling Structures/Linings	Vermiculite		8397/B00F/R0012/Ceiling Structures/Linings/S13			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Sheet		8397/B00D/R1003/Floor Coverings Res/Textile/S15			No Asbestos Detected
B00D - R1012 - Computer Learning Space (53.3 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1014 - General Storeroom (13.11 m2)						
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Sheet	8397/B00D/R1003/Floor Coverings Res/Textile/S15				No Asbestos Detected
B00D - R1016 - General Storeroom (9.29 m2)						
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Sheet	8397/B00D/R1003/Floor Coverings Res/Textile/S15				No Asbestos Detected
B00D - R1018 - Movement (17.82 m2)						
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1019 - Commonroom (124.05 m2)						
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00D - R1020 - Tea Room (10.06 m2)						
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	8397/B00D/R0012/Floor Coverings Res/Textile/S20				No Asbestos Detected
B00D - R1021 - Staff Study (25.3 m2)						
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Sheet	8397/B00D/R1003/Floor Coverings Res/Textile/S15				No Asbestos Detected
B00D - R1022 - Staff Kitchen (3.95 m2)						
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	8397/B00D/R0012/Floor Coverings Res/Textile/S20				No Asbestos Detected
B00D - R1023 - Movement (146.46 m2)						
Ceiling Structures/Linings	Vermiculite	8397/B00F/R0012/Ceiling Structures/Linings/S13				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	8397/B00D/R1023/Floor Coverings Res/Textile/S21				No Asbestos Detected
B00D - R1024 - Stairs (10.42 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Ceiling Structures/Linings Vermiculite
 8397/B00F/R0012/Ceiling Structures/Linings/S13 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00D - R1025 - Stairs (8.79 m2)

Ceiling Structures/Linings Vermiculite
 8397/B00F/R0012/Ceiling Structures/Linings/S13 **Limited Samples Taken**
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Science Learning - 1964 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 8397/B00E/Eaves Linings/S36	200m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Underfloor Voids	Debris 8397/B00E/Underfloor Voids/S29	1m2	South-west	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		

Interior**B00E - R0001 - General Storeroom (2.5 m2)**

No Asbestos

B00E - R0002 - General Learning Space (52.58 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00E - R0003 - Laboratory L.S. (86.2 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00E - R0005 - Laboratory L.S. (86.34 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00E - R0006 - Cleaning Store - Distributed (3.24 m2)

No Asbestos

B00E - R0007 - Staff - Toilet (5.97 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00E - R0009 - Computer Learning Space (52.43 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00E - R0010 - General Learning Space (52.58 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00E - R0011 - General Storeroom (5.66 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00E - R0012 - General Storeroom (5.59 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

B00E - R0013 - Distribution Board Cupboard (0.95 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0014 - General Learning Space (52.58 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R0015 - General Learning Space (66.09 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00E - R0016 - Movement (126.29 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Sheet					
	8397/B00E/R0016/Floor Coverings Res/Textile/S7					No Asbestos Detected
B00E - R0017 - External Movement (27 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00E - R0018 - Student Drinking Facilities (26.43 m2)						
No Asbestos						
B00E - R0019 - External Movement (40.63 m2)						
No Asbestos						
B00E - R0020 - Movement (3.08 m2)						
No Asbestos						
B00E - R0021 - Stairs (3.39 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00E - R0022 - Stairs (6.11 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00E - R0023 - Movement (3.75 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00E - R0024 - Preparation - Science (29.74 m2)						
Fume Cupboard	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8397/B00E/R0024/Fume Cupboard/S30					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Flue	Moulded fibre cement	2m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8397/B00A/R1010/Flue/S27					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R0025 - General Storeroom (8.1 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00E - R0026 - Staff Study (23.38 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00E - R0027 - Tea Room (2.31 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00E - R1001 - General Learning Space (53.23 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R1002 - General Learning Space (53.08 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R1003 - General Learning Space (53.23 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Flue	Fibre Cement Pipe 8397/B00A/R1002/Flue/S10	4m	West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
B00E - R1004 - General Learning Space (53.16 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R1005 - General Learning Space (53.38 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R1006 - Staff - Toilet (5.79 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R1007 - Computer Room (25.85 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R1008 - General Learning Space (53.23 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R1010 - Distribution Board Cupboard (1.07 m2)						
No Asbestos					Note: No inspection of live electrical installation.	
B00E - R1012 - Staff Study (33.09 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R1013 - Computer Learning Space (66.65 m2)						
Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R1014 - General Storeroom (26.17 m2)						
Floor Coverings Res/Textile	Vinyl Tiles 8397/B00E/R1015/Floor Coverings Res/Textile/S8	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite 8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
B00E - R1016 - Movement (26.91 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1017 - Cleaning Store - Distributed (4.71 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	4.71m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8397/B00E/R1021/Floor Coverings Res/Textile/S28					Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1018 - General Learning Space (53.38 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	53.36m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8397/B00E/R1021/Floor Coverings Res/Textile/S28					Chrysotile (white asbestos)
B00E - R1019 - Stairs (9.61 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1020 - Stairs (23.8 m2)						
Ceiling Structures/Linings	Vermiculite					
	8397/B00E/R0017/Ceiling Structures/Linings/S4					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00E - R1021 - Movement (117 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	116.95m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8397/B00E/R1021/Floor Coverings Res/Textile/S28					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Library/Science Learning - 1973 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00F - M1001 - Plant (67.63 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00F - M1002 - Plant (4.8 m2)

No Asbestos

B00F - M1003 - Seminar (37.63 m2)

No Asbestos

B00F - M1005 - Plant (24.58 m2)

No Asbestos

B00F - M1006 - Interview/Office - Type 1 (15.11 m2)

No Asbestos

B00F - M1007 - Plant (24.74 m2)

No Asbestos

B00F - M1008 - Movement (69.54 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

B00F - M1009 - Stairs (4.03 m2)

No Asbestos

B00F - M1010 - Stairs (2.66 m2)

No Asbestos

B00F - R0001 - General Storeroom (2.57 m2)

No Asbestos

B00F - R0002 - Distribution Board Cupboard (0.62 m2)

Note: No inspection of live electrical installation.

Electrical Backing Board		2m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	--	-----	-------	--------------------	---------	--------------------

B00F - R0003 - Main Switch Board Cupboard (0.5 m2)

Electrical Backing Board	Resinous Board	2m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-----	-------	--------------------	---------	--------------------

Assumed Asbestos - Electrical Hazard

B00F - R0004 - Bulk Store (1.58 m2)

No Asbestos

B00F - R0005 - Plant (12.53 m2)

Heating Boiler	Encapsulated Insulation material within unit	1Unit(s)	South, Lower portion	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
----------------	--	----------	----------------------	----------------------	---------	--------------------

Assumed Asbestos - Area inaccessible

B00F - R0006 - Bulk Store (27.51 m2)

Ceiling Structures/Linings	Vermiculite 8397/B00F/R0012/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Floor Coverings Res/Textile	Vinyl Tiles	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos)
8397/B00F/R0017/Floor Coverings Res/Textile/S12						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R0007 - Staff Study (33.04 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8397/B00F/R0012/Ceiling Structures/Linings/S13					
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8397/B00F/R0017/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)
B00F - R0008 - Staff - Toilet (4 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8397/B00F/R0012/Ceiling Structures/Linings/S13					
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00F - R0009 - Staff - Toilet (4 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8397/B00F/R0012/Ceiling Structures/Linings/S13					
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00F - R0010 - Preparation - Science (44.28 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8397/B00F/R0012/Ceiling Structures/Linings/S13					
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8397/B00F/R0017/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)
B00F - R0011 - General Storeroom (3.48 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8397/B00F/R0012/Ceiling Structures/Linings/S13					
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8397/B00F/R0017/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)
B00F - R0012 - Laboratory L.S. (91.14 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8397/B00F/R0012/Ceiling Structures/Linings/S13					
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles	91m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8397/B00F/R0017/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)
B00F - R0013 - Laboratory L.S. (91.15 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8397/B00F/R0012/Ceiling Structures/Linings/S13					
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles	92m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8397/B00F/R0017/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)
B00F - R0014 - Chemical Store (3.49 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8397/B00F/R0012/Ceiling Structures/Linings/S13					
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8397/B00F/R0017/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)
B00F - R0015 - Preparation - Science (44.19 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	8397/B00F/R0012/Ceiling Structures/Linings/S13					
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8397/B00F/R0017/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)	
B00F - R0016 - Laboratory L.S. (91.34 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8397/B00F/R0012/Ceiling Structures/Linings/S13					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Floor Coverings Res/Textile	Vinyl Tiles	92m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8397/B00F/R0017/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)	
B00F - R0017 - Movement (67.99 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	72m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8397/B00F/R0017/Floor Coverings Res/Textile/S12					Chrysotile (white asbestos)	
B00F - R0019 - Stairs (7.71 m2)						
No Asbestos						
B00F - R0020 - Cleaning Store - Distributed (7.74 m2)						
No Asbestos						
B00F - R0021 - Movement (3.98 m2)						
No Asbestos						
B00F - R0022 - Movement (3.04 m2)						
No Asbestos						
B00F - R0023 - External Movement (21.02 m2)						
No Asbestos						
B00F - R1003 - Library Administration (17.78 m2)						
No Asbestos						
B00F - R1004 - Computer Room (12.41 m2)						
No Asbestos						
B00F - R1005 - General Storeroom (27.8 m2)						
No Asbestos						
B00F - R1006 - Librarian (11.1 m2)						
No Asbestos						
B00F - R1007 - Audio Visual Workroom (69.78 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8397/B00F/R0012/Ceiling Structures/Linings/S13					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00F - R1008 - Main Area (320.37 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
8397/B00F/R0012/Ceiling Structures/Linings/S13					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00F - R1011 - Plant (6.14 m2)						
No Asbestos						
B00F - R1012 - Plant (5.61 m2)						
No Asbestos						
B00F - R1014 - External Movement (24.93 m2)						
No Asbestos						
B00F - R1015 - External Stairs (16.46 m2)						
No Asbestos						
B00F - R1016 - Movement (4.67 m2)						
No Asbestos						
B00F - R1017 - Cleaning Store - Distributed (0.34 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
Electrical Mounting Board	Resinous Board	1m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)

8397/B00F/R1017/Electrical Mounting Board/S32

Chrysotile (white asbestos)

B00F - R1018 - Distribution Board Cupboard (0.27 m2) Note: No inspection of live electrical installation.

No Asbestos

B00F - R1021 - Computer Resource (11.17 m2)

No Asbestos

B00F - R1022 - Office/Store (13.18 m2)

No Asbestos

B00F - R1023 - Seminar Space (24.7 m2)

No Asbestos

B00F - R1024 - Staff - Toilet (3.07 m2)

No Asbestos

B00F - R1025 - Staff - Toilet (3.1 m2)

No Asbestos

B00F - R1026 - Stairs (1.3 m2)

No Asbestos

B00F - R1027 - Stairs (1.3 m2)

No Asbestos

B00F - R1028 - External Movement (6.65 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Movement Complex - 1972 - Timber (Timber)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Voids	Non Accessible Area - Area inaccessible

Interior

B00G - R0001 - Movement Studio (109.41 m2)

No Asbestos

B00G - R0003 - General Storeroom (11.5 m2)

Wall Linings Internal	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8397/B00G/R0004/Wall Linings Internal/S33					Chrysotile (white asbestos)	

B00G - R0004 - Movement (20.06 m2)

Wall Linings Internal	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8397/B00G/R0004/Wall Linings Internal/S33					Chrysotile (white asbestos)	

B00G - R0005 - Change (2.86 m2)

Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8397/B00G/R0004/Wall Linings Internal/S33					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning/Performance Learning - 1972 - Timber (Timber)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00H - R0001 - General Learning Space (47.01 m2)

No Asbestos

B00H - R0002 - External Movement (24.74 m2)

No Asbestos

B00H - R0003 - Performance Workspace (46.95 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Multi Purpose Facilities - 1973 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible
Underfloor Voids	No Asbestos Found

Interior

B00K - M0002 - Stairs (5.24 m2)

No Asbestos

B00K - M0003 - Movement (3.37 m2)

No Asbestos

B00K - M0004 - Control Room (3.28 m2)

Floor Coverings Res/Textile	Compressed AC Sheet							
	8397/B00K/M0004/Floor Coverings Res/Textile/S3							No Asbestos Detected
Electrical Backing Board	Resinous Board	2m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)		
	8397/B00K/M0004/Electrical Backing Board/S34							Chrysotile (white asbestos)

B00K - M0005 - Stairs (5.06 m2)

No Asbestos

B00K - M0006 - Movement (3.47 m2)

No Asbestos

B00K - M0007 - Movement (2.9 m2)

No Asbestos

B00K - R0005 - Distribution Board Cupboard (0.41 m2)

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1.m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)		
	8397/B00K/R0005/Electrical Backing Board/S35							Chrysotile (white asbestos)

B00K - R0009 - Toilets-Girls (4.6 m2)

Wall Linings Internal	Flat AC Sheeting	5m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)		
	8397/B00K/R0009/Wall Linings Internal/S2							Chrysotile (white asbestos)

B00K - R0010 - Toilets-Boys (9.16 m2)

No Asbestos

B00K - R0011 - Entry (22.59 m2)

No Asbestos

B00K - R0012 - Staff Kitchen (16.64 m2)

Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)		
	8397/B00K/R0012/Floor Coverings Res/Textile/S1							Chrysotile (white asbestos)

B00K - R0013 - External Movement (8.95 m2)

No Asbestos

B00K - R0014 - External Movement (3.46 m2)

No Asbestos

B00K - R0015 - External Movement (3.83 m2)

No Asbestos

B00K - R0016 - External Movement (3.87 m2)

No Asbestos

B00K - R0017 - External Movement (3.48 m2)

No Asbestos

B00K - R0022 - Multi-Purpose Space (433.56 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00K - R0023 - Stage (98.79 m2)						
No Asbestos						
B00K - R0025 - Movement (6.69 m2)						
No Asbestos						
B00K - R0026 - Stairs (1.67 m2)						
No Asbestos						
B00K - R0027 - Movement (6.6 m2)						
No Asbestos						
B00K - R0028 - Stairs (1.71 m2)						
No Asbestos						
B00K - R9001 - Movement (2.87 m2)						
No Asbestos						
B00K - R9002 - Toilets-Unisex (5.72 m2)						
No Asbestos						
B00K - R9003 - Change (18.77 m2)						
No Asbestos						
B00K - R9004 - Movement (24.48 m2)						
No Asbestos						
B00K - R9005 - Change (18.86 m2)						
No Asbestos						
B00K - R9006 - Toilets-Unisex (5.87 m2)						
No Asbestos						
B00K - R9007 - Movement (2.88 m2)						
No Asbestos						
B00K - R9008 - Stairs (1.89 m2)						
No Asbestos						
B00K - R9009 - Stairs (1.89 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Building Services - 2009 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids No Asbestos Found

Interior

B00L - R0001 - Plant (7.12 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00M - R0001 - Computer Learning Space (92.17 m2)

No Asbestos

B00M - R0002 - Seminar (18.92 m2)

No Asbestos

B00M - R0003 - Archive Store (10.08 m2)

No Asbestos

B00M - R0004 - Secure Storeroom (9.1 m2)

No Asbestos

B00M - R0005 - External Movement (28.23 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017