


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Alexandria Park Community School (8556)  
**Region :** Sydney  
**State Electorate :** Heffron  
**Local Government Area :** Sydney

**Initial Survey :** Noel Arnold & Associates : 10 - Mar - 2008  
**Reviewed By :** Greencap-NAA : 13 - Aug - 2014



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration - 1982 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

**Interior****B00A - R0001 - Schools As Community Centres Program (12.67 m2)**

No Asbestos

**B00A - R0002 - Schools As Community Centres Program (13.5 m2)**

No Asbestos

**B00A - R0003 - Schools As Community Centres Program (12.93 m2)**

No Asbestos

**B00A - R0004 - Schools As Community Centres Program (2.28 m2)**

No Asbestos

**B00A - R0005 - Schools As Community Centres Program (12.94 m2)**

No Asbestos

**B00A - R0006 - Schools As Community Centres Program (2.28 m2)**

No Asbestos

**B00A - R0007 - Schools As Community Centres Program (12.95 m2)**

No Asbestos

**B00A - R0008 - Schools As Community Centres Program (13.53 m2)**

No Asbestos

**B00A - R0012 - Staff - Toilet (2.95 m2)**

No Asbestos

**B00A - R0013 - Staff - Toilet (2.95 m2)**

No Asbestos

**B00A - R0016 - Cleaning Supplies Store (4.22 m2)**

No Asbestos

**B00A - R0018 - Staff Room Annexe (18.57 m2)**

No Asbestos

**B00A - R0019 - Disabled Toilet (4.43 m2)**

No Asbestos

**B00A - R0020 - Toilets - Boys (29.84 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	---------------------	-----	--------------	--------------------	---------	--------------------

8556/B00C/R0030/Partition Walls (Cubicles)/S1

**Chrysotile (white asbestos)****B00A - R0021 - Cleaning Supplies Store (2.45 m2)**

No Asbestos

**B00A - R0022 - Schools As Community Centres Program (26.07 m2)**

No Asbestos

**B00A - R0023 - Schools As Community Centres Program (18.27 m2)**

No Asbestos

**B00A - R0024 - Schools As Community Centres Program (28.48 m2)**

No Asbestos

**B00A - R0025 - Parents As Teachers Program (23.86 m2)**

No Asbestos

**B00A - R0026 - General Assistant/Bulk Store (1.84 m2)**

No Asbestos

**B00A - R0027 - Main Switch Board (11.17 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Electrical Backing Board	Resinous Board	1Unit	North	Good Condition (1)	Low (1)	Low Priority (2-3)

**Assumed Asbestos - unit live****B00A - R0028 - Toilets - Girls (23.23 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8556/B00C/R0030/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>	

**B00A - R0035 - Home Base Store (22.16 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
8556/B00A/R0035/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>	

**B00A - R0036 - Cleaning Supplies Store (1.33 m2)**

No Asbestos

**B00A - R0037 - Home Base Store (8.76 m2)**

No Asbestos

**B00A - R0038 - Distribution Board (0.78 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0039 - Staff Room Annexe (23.6 m2)**

No Asbestos

**B00A - R0041 - Movement (69.52 m2)**

No Asbestos

**B00A - R0045 - Movement (21.47 m2)**

No Asbestos

**B00A - R0046 - Stairs (15.29 m2)**

No Asbestos

**B00A - R0047 - Schools As Community Centres Program (61.14 m2)**

No Asbestos

**B00A - R0048 - Movement (64.97 m2)**

No Asbestos

**B00A - R0049 - Handwashing Facilities (14.97 m2)**

No Asbestos

**B00A - R0050 - Disabled Toilet (6.25 m2)**

No Asbestos

**B00A - R0051 - Movement (2.91 m2)**

No Asbestos

**B00A - R0052 - Schools As Community Centres Program (7.04 m2)**

No Asbestos

**B00A - R0053 - Movement (86.8 m2)**

No Asbestos

**B00A - R0054 - Communications Cupboard (0.79 m2)**

No Asbestos

**B00A - R0055 - Home Base (98.98 m2)**

No Asbestos

**B00A - R0056 - Withdrawal Space - 1hb (11.43 m2)**

No Asbestos

**B00A - R0057 - Plant (1.05 m2)**

No Asbestos

**B00A - R0058 - Practical Activities - 1hb (17.13 m2)**

No Asbestos

**B00A - R0059 - Darkroom Space (11.43 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	<b>B00A - R0060 - Darkroom Space (17.46 m2)</b>					
	No Asbestos					
	<b>B00A - R0061 - Withdrawal Space - 1hb (7.81 m2)</b>					
	No Asbestos					
	<b>B00A - R0062 - Plant (1.04 m2)</b>					
	No Asbestos					
	<b>B00A - R0063 - Withdrawal Space - 1hb (9.07 m2)</b>					
	No Asbestos					
	<b>B00A - R0064 - Practical Activities - 1hb (17.37 m2)</b>					
	No Asbestos					
	<b>B00A - R0065 - Home Base (54.46 m2)</b>					
	No Asbestos					
	<b>B00A - R0066 - Plant (1.08 m2)</b>					
	No Asbestos					
	<b>B00A - R0067 - Home Base Store (6.39 m2)</b>					
	No Asbestos					
	<b>B00A - R0068 - Home Base (30.78 m2)</b>					
	No Asbestos					
	<b>B00A - R0069 - Home Base Store (6.38 m2)</b>					
	No Asbestos					
	<b>B00A - R0070 - Plant (1.08 m2)</b>					
	No Asbestos					
	<b>B00A - R0071 - Home Base (54.02 m2)</b>					
	No Asbestos					
	<b>B00A - R0072 - Practical Activities - 1hb (16.88 m2)</b>					
	No Asbestos					
	<b>B00A - R0073 - Withdrawal Space - 1hb (9.07 m2)</b>					
	No Asbestos					
	<b>B00A - R0074 - Practical Activities - 1hb (17.42 m2)</b>					
	No Asbestos					
	<b>B00A - R0075 - Home Base (54.97 m2)</b>					
	No Asbestos					
	<b>B00A - R0076 - External Movement (23.18 m2)</b>					
	No Asbestos					
	<b>B00A - R0077 - General Assistant/Bulk Store (16.85 m2)</b>					
	No Asbestos					
	<b>B00A - R0078 - External Movement (8.6 m2)</b>					
	No Asbestos					
	<b>B00A - R0079 - External Movement (14.91 m2)</b>					
	No Asbestos					
	<b>B00A - R0080 - External Movement (51.75 m2)</b>					
	No Asbestos					
	<b>B00A - R0081 - Movement (140.79 m2)</b>					
	No Asbestos					
	<b>B00A - R0082 - Lift (2.27 m2)</b>					
	No Asbestos					
	<b>B00A - R1001 - General Learning Space (45.79 m2)</b>					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	<b>B00A - R1003 - General Storeroom (27.98 m2)</b>					
	No Asbestos					
	<b>B00A - R1004 - General Storeroom (3.34 m2)</b>					
	No Asbestos					
	<b>B00A - R1005 - General Learning Space (21.86 m2)</b>					
	No Asbestos					
	<b>B00A - R1006 - General Learning Space (15.89 m2)</b>					
	No Asbestos					
	<b>B00A - R1007 - Plant (19.66 m2)</b>					
	No Asbestos					
	<b>B00A - R1008 - Distribution Board Cupboard (0.74 m2)</b>				Note: No inspection of live electrical installation.	
	No Asbestos					
	<b>B00A - R1009 - Disabled Toilet (5.1 m2)</b>					
	No Asbestos					
	<b>B00A - R1010 - Staff - Toilet (2.42 m2)</b>					
	No Asbestos					
	<b>B00A - R1012 - Toilets - Boys (2.18 m2)</b>					
	No Asbestos					
	<b>B00A - R1013 - Toilets - Boys (2.18 m2)</b>					
	No Asbestos					
	<b>B00A - R1014 - Toilets - Girls (2.18 m2)</b>					
	No Asbestos					
	<b>B00A - R1015 - Toilets - Girls (2.18 m2)</b>					
	No Asbestos					
	<b>B00A - R1016 - Plant (10.47 m2)</b>					
	No Asbestos					
	<b>B00A - R1017 - General Learning Space (94.17 m2)</b>					
	No Asbestos					
	<b>B00A - R1018 - Music Learning Space (46.29 m2)</b>					
	No Asbestos					
	<b>B00A - R1019 - Music Learning Space (45.2 m2)</b>					
	No Asbestos					
	<b>B00A - R1021 - Covered Area (13.7 m2)</b>					
	No Asbestos					
	<b>B00A - R1022 - Covered Area (11.29 m2)</b>					
	No Asbestos					
	<b>B00A - R1023 - Covered Area (12.02 m2)</b>					
	No Asbestos					
	<b>B00A - R1024 - Stairs (22.34 m2)</b>					
	No Asbestos					
	<b>B00A - R1025 - General Storeroom (29.54 m2)</b>					
	No Asbestos					
	<b>B00A - R1026 - Movement (171.21 m2)</b>					
	No Asbestos					
	<b>B00A - R1027 - Lift (2.27 m2)</b>					
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning - 1982 - Brick/Block (Brick/Block)**

**Exterior**

Plant room infill panels	Compressed AC Sheet	3m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8556/B00B/Plant room infill panels/S9					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	No Asbestos Found					

**Interior**

**B00B - R0003 - Administration - Clerical (28.44 m2)**

No Asbestos

**B00B - R0004 - Security Store (3.25 m2)**

No Asbestos

**B00B - R0005 - Staff Room Annexe (11.02 m2)**

No Asbestos

**B00B - R0007 - Toilets - Girls (2.27 m2)**

No Asbestos

**B00B - R0008 - Toilets - Boys (3.73 m2)**

No Asbestos

**B00B - R0009 - Distribution Board (0.71 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0011 - Special Programs Room (10.88 m2)**

No Asbestos

**B00B - R0012 - General Assistant/Bulk Store (3.22 m2)**

No Asbestos

**B00B - R0013 - Home Base (27.58 m2)**

No Asbestos

**B00B - R0014 - Home Base (45.14 m2)**

No Asbestos

**B00B - R0015 - Home Base (47.74 m2)**

Ceiling Structures/Linings Vermiculite  
8556/B0AA/R0015/Ceiling Structures/Linings/S3

**Limited Samples Taken**

**Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works**

**B00B - R0016 - Commonroom (46.42 m2)**

No Asbestos

**B00B - R0017 - Commonroom (48.12 m2)**

No Asbestos

**B00B - R0021 - Laundry (20.56 m2)**

Hot water service packing	Flat AC Sheeting	1m2	West	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	8556/B00B/R0021/Hot water service packing/S10					<b>Chrysotile (white asbestos)</b>

**B00B - R0022 - General Learning Space (20.4 m2)**

No Asbestos

**B00B - R0027 - Commonroom (16.27 m2)**

No Asbestos

**B00B - R0028 - Staff Kitchen (5.66 m2)**

No Asbestos

**B00B - R0029 - Staff - Toilet (3.69 m2)**

No Asbestos

**B00B - R0030 - Staff - Toilet (7.03 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0031 - General Assistant/Bulk Store (3.53 m2)</b>						
No Asbestos						
<b>B00B - R0032 - General Assistant/Bulk Store (2.4 m2)</b>						
No Asbestos						
<b>B00B - R0033 - Toilets - Boys (18.55 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8556/B00C/R0030/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)	
<b>B00B - R0034 - Toilets - Girls (13.89 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8556/B00C/R0030/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)	
<b>B00B - R0038 - Special Programs Room (14.63 m2)</b>						
No Asbestos						
<b>B00B - R0039 - Home Base Store (14.47 m2)</b>						
No Asbestos						
<b>B00B - R0044 - Staff Room Annexe (22.95 m2)</b>						
No Asbestos						
<b>B00B - R0045 - Home Base Store (6.95 m2)</b>						
No Asbestos						
<b>B00B - R0046 - Practical Activities/Movement - 2hb (76.62 m2)</b>						
No Asbestos						
<b>B00B - R0047 - Movement (14.95 m2)</b>						
No Asbestos						
<b>B00B - R0048 - Distribution Board (0.66 m2)</b>						
No Asbestos					Note: No inspection of live electrical installation.	
<b>B00B - R0049 - Cleaning Supplies Store (0.67 m2)</b>						
No Asbestos						
<b>B00B - R0050 - Movement (255.69 m2)</b>						
No Asbestos						
<b>B00B - R0051 - Movement (217.33 m2)</b>						
No Asbestos						
<b>B00B - R0052 - Distribution Board (1.2 m2)</b>						
No Asbestos					Note: No inspection of live electrical installation.	
<b>B00B - R0053 - General Assistant/Bulk Store (16.76 m2)</b>						
No Asbestos						
<b>B00B - R0054 - Movement (38.97 m2)</b>						
No Asbestos						
<b>B00B - R0055 - Covered Area (10.26 m2)</b>						
No Asbestos						
<b>B00B - R0056 - Movement (24.34 m2)</b>						
No Asbestos						
<b>B00B - R0057 - Movement (26.4 m2)</b>						
No Asbestos						
<b>B00B - R0058 - Movement (35.18 m2)</b>						
No Asbestos						
<b>B00B - R0059 - Stairs (2.08 m2)</b>						
No Asbestos						
<b>B00B - R0060 - External Movement (27.1 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00B - R0061 - Principal Office (22.13 m2)</b>						
No Asbestos						
<b>B00B - R0062 - Administration - Clerical (35.07 m2)</b>						
No Asbestos						
<b>B00B - R0063 - Security Store (23.21 m2)</b>						
No Asbestos						
<b>B00B - R0064 - Duplicating Workroom (21.65 m2)</b>						
No Asbestos						
<b>B00B - R0065 - Teachers Aide Special Ed (16.29 m2)</b>						
No Asbestos						
<b>B00B - R0066 - Security Store (6.53 m2)</b>						
No Asbestos						
<b>B00B - R0067 - Movement (70.15 m2)</b>						
No Asbestos						
<b>B00B - R0068 - Administration - Clerical (16.93 m2)</b>						
No Asbestos						
<b>B00B - R0069 - Deputy Principal Office (17.16 m2)</b>						
No Asbestos						
<b>B00B - R0070 - Security Store (6.59 m2)</b>						
No Asbestos						
<b>B00B - R0071 - Staff Kitchen (4.62 m2)</b>						
No Asbestos						
<b>B00B - R0072 - Sick Bay (11.58 m2)</b>						
No Asbestos						
<b>B00B - R0073 - Sick Bay (10.85 m2)</b>						
No Asbestos						
<b>B00B - R0074 - Staff Room Annexe (9.95 m2)</b>						
No Asbestos						
<b>B00B - R0075 - External Movement (34.04 m2)</b>						
No Asbestos						
<b>B00B - R0076 - General Storeroom (15.52 m2)</b>						
No Asbestos						
<b>B00B - R0077 - General Learning Space (73.02 m2)</b>						
No Asbestos						
<b>B00B - R0078 - Plant (1.04 m2)</b>						
No Asbestos						
<b>B00B - R0079 - Food Technology L.S. (105.54 m2)</b>						
No Asbestos						
<b>B00B - R0080 - Plant (1.11 m2)</b>						
No Asbestos						
<b>B00B - R0081 - Pantry (13.08 m2)</b>						
No Asbestos						
<b>B00B - R0082 - Plant (1.2 m2)</b>						
No Asbestos						
<b>B00B - R0083 - Chemical Store (11.56 m2)</b>						
Chemical store shelving	Compressed AC Sheet	3m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)

8556/B00B/Plant room infill panels/S9

Chrysotile (white asbestos)



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0084 - Preparation (19.09 m2)</b>						
No Asbestos						
<b>B00B - R0085 - Laboratory L.S. (87.85 m2)</b>						
No Asbestos						
<b>B00B - R0086 - Plant (1.31 m2)</b>						
No Asbestos						
<b>B00B - R0087 - Movement (31.51 m2)</b>						
No Asbestos						
<b>B00B - R0088 - Home Base (74.88 m2)</b>						
No Asbestos						
<b>B00B - R0089 - Plant (0.98 m2)</b>						
No Asbestos						
<b>B00B - R0090 - Plant (1.05 m2)</b>						
No Asbestos						
<b>B00B - R0091 - Home Base (62.75 m2)</b>						
No Asbestos						
<b>B00B - R0092 - Withdrawal Space - 2hb (17.57 m2)</b>						
No Asbestos						
<b>B00B - R0093 - Home Base (62.55 m2)</b>						
No Asbestos						
<b>B00B - R0094 - Practical Activities - 1hb (18.63 m2)</b>						
No Asbestos						
<b>B00B - R0095 - Plant (1.1 m2)</b>						
No Asbestos						
<b>B00B - R0096 - Practical Activities - 1hb (18.54 m2)</b>						
No Asbestos						
<b>B00B - R0097 - Toilets - Boys (19.04 m2)</b>						
No Asbestos						
<b>B00B - R0098 - Movement (5.32 m2)</b>						
No Asbestos						
<b>B00B - R0099 - Disabled Toilet (5.95 m2)</b>						
No Asbestos						
<b>B00B - R0100 - Toilets - Girls (23.69 m2)</b>						
No Asbestos						
<b>B00B - R1003 - Plant (22.53 m2)</b>						
No Asbestos						
<b>B00B - R1004 - General Storeroom (26.69 m2)</b>						
No Asbestos						
<b>B00B - R1005 - General Storeroom (3.49 m2)</b>						
No Asbestos						
<b>B00B - R1006 - Art Learning Space (22.79 m2)</b>						
No Asbestos						
<b>B00B - R1007 - General Storeroom (5.81 m2)</b>						
No Asbestos						
<b>B00B - R1008 - Distribution Board (0.7 m2)</b>						
No Asbestos						
<b>B00B - R1009 - Cleaning Supplies Store (2.06 m2)</b>						
No Asbestos						
<b>B00B - R1008 - Distribution Board (0.7 m2)</b> <span style="float: right;">Note: No inspection of live electrical installation.</span>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R1010 - Art Learning Space (22.9 m2)</b>						
No Asbestos						
<b>B00B - R1011 - Staff Study (28.08 m2)</b>						
No Asbestos						
<b>B00B - R1012 - Plant (21.67 m2)</b>						
No Asbestos						
<b>B00B - R1013 - General Storeroom (4.84 m2)</b>						
No Asbestos						
<b>B00B - R1014 - General Learning Space (46.17 m2)</b>						
No Asbestos						
<b>B00B - R1015 - General Learning Space (48.02 m2)</b>						
No Asbestos						
<b>B00B - R1016 - General Learning Space (47.56 m2)</b>						
No Asbestos						
<b>B00B - R1017 - General Learning Space (50.51 m2)</b>						
No Asbestos						
<b>B00B - R1021 - Movement (12.22 m2)</b>						
No Asbestos						
<b>B00B - R1022 - Reading Area (266.32 m2)</b>						
No Asbestos						
<b>B00B - R1023 - Seminar (13.25 m2)</b>						
No Asbestos						
<b>B00B - R1024 - Seminar (13.25 m2)</b>						
No Asbestos						
<b>B00B - R1025 - K.L.A. Store (24.58 m2)</b>						
No Asbestos						
<b>B00B - R1026 - Library Office/Workroom (13.34 m2)</b>						
No Asbestos						
<b>B00B - R1027 - Library Office/Workroom (21.51 m2)</b>						
No Asbestos						
<b>B00B - R1028 - Communications Room (22.37 m2)</b>						
No Asbestos						
<b>B00B - R1029 - Distribution Board (0.95 m2)</b>						
No Asbestos					Note: No inspection of live electrical installation.	
<b>B00B - R1030 - Cleaning Supplies Store (2.54 m2)</b>						
No Asbestos						
<b>B00B - R1031 - Staff - Toilet (2.21 m2)</b>						
No Asbestos						
<b>B00B - R1032 - Staff Study (64.08 m2)</b>						
No Asbestos						
<b>B00B - R1033 - Staff Study (10.54 m2)</b>						
No Asbestos						
<b>B00B - R1034 - Staff Study (10.48 m2)</b>						
No Asbestos						
<b>B00B - R1035 - Covered Area (11.34 m2)</b>						
No Asbestos						
<b>B00B - R1036 - Covered Area (11.32 m2)</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R1037 - Covered Area (11.26 m2)</b>						
No Asbestos						
<b>B00B - R1038 - Movement (20.21 m2)</b>						
No Asbestos						
<b>B00B - R1039 - Covered Area (11.34 m2)</b>						
No Asbestos						
<b>B00B - R1040 - Movement (10.86 m2)</b>						
No Asbestos						
<b>B00B - R1041 - Stairs (23.75 m2)</b>						
No Asbestos						
<b>B00B - R1042 - Home Base (49.34 m2)</b>						
No Asbestos						
<b>B00B - R1043 - Practical Activities - 1hb (46.58 m2)</b>						
No Asbestos						
<b>B00B - R1044 - Home Base (60.02 m2)</b>						
No Asbestos						
<b>B00B - R1045 - Practical Activities - 1hb (27.66 m2)</b>						
No Asbestos						
<b>B00B - R1046 - Withdrawal Space - 2hb (14.1 m2)</b>						
No Asbestos						
<b>B00B - R1047 - K.L.A. Store (14.25 m2)</b>						
No Asbestos						
<b>B00B - R1048 - Movement (145.68 m2)</b>						
No Asbestos						
<b>B00B - R2001 - Movement (5.65 m2)</b>						
No Asbestos						
<b>B00B - R2002 - Plant (93.65 m2)</b>						
Boiler gasket	Rope gasket	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
8556/B00B/R2002/Boiler gasket/S8					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### B00C - Physical Education/Technological & Applied Studies - 1982 - Brick/Block (Brick/Block)

#### Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

#### Interior

##### B00C - M0001 - Sport Equipment Store (10.06 m2)

No Asbestos

##### B00C - M0006 - Aboriginal Resource Centre (13.79 m2)

No Asbestos

##### B00C - M0007 - Aboriginal Resource Centre (18.81 m2)

No Asbestos

##### B00C - M0008 - Aboriginal Resource Centre (10.14 m2)

No Asbestos

##### B00C - M0009 - Aboriginal Resource Centre (10 m2)

No Asbestos

##### B00C - M0010 - Aboriginal Resource Centre (18.89 m2)

No Asbestos

##### B00C - M0011 - Aboriginal Resource Centre (0.65 m2)

No Asbestos

##### B00C - M0012 - Aboriginal Resource Centre (5.27 m2)

No Asbestos

##### B00C - M0013 - Aboriginal Resource Centre (1.28 m2)

No Asbestos

##### B00C - M0014 - Aboriginal Resource Centre (2.53 m2)

No Asbestos

##### B00C - M0015 - Aboriginal Resource Centre (2.7 m2)

No Asbestos

##### B00C - M0016 - Aboriginal Resource Centre (6.15 m2)

No Asbestos

##### B00C - R0001 - Staff - Toilet (2.31 m2)

No Asbestos

##### B00C - R0002 - Office/Store (4.4 m2)

No Asbestos

##### B00C - R0003 - Student Canteen (54.19 m2)

No Asbestos

##### B00C - R0004 - Cleaning Store - Distributed (3.79 m2)

No Asbestos

##### B00C - R0005 - Movement (3.26 m2)

No Asbestos

##### B00C - R0006 - Cleaning Supplies Store (3.15 m2)

No Asbestos

##### B00C - R0007 - Plant (2.23 m2)

No Asbestos

##### B00C - R0008 - Movement (10.06 m2)

No Asbestos

##### B00C - R0009 - Chair Store (34.69 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00C - R0010 - General Assistant/Bulk Store (15 m2)</b>						
No Asbestos						
<b>B00C - R0011 - Staff Room Annexe (15 m2)</b>						
No Asbestos						
<b>B00C - R0012 - General Assistant/Bulk Store (12.34 m2)</b>						
No Asbestos						
<b>B00C - R0013 - General Assistant/Bulk Store (11.38 m2)</b>						
No Asbestos						
<b>B00C - R0014 - Movement (5.97 m2)</b>						
No Asbestos						
<b>B00C - R0015 - Sport Equipment Store (12.61 m2)</b>						
No Asbestos						
<b>B00C - R0016 - Shower/Change (39.02 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8556/B00C/R0030/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)	
<b>B00C - R0018 - Movement (8.22 m2)</b>						
No Asbestos						
<b>B00C - R0019 - Raised Platform (94.18 m2)</b>						
No Asbestos						
<b>B00C - R0020 - Movement (8 m2)</b>						
No Asbestos						
<b>B00C - R0022 - Shower/Change (36.15 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8556/B00C/R0030/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)	
<b>B00C - R0023 - General Assistant/Bulk Store (15.45 m2)</b>						
No Asbestos						
<b>B00C - R0026 - Chair Store (8.26 m2)</b>						
No Asbestos						
<b>B00C - R0027 - Movement (6.44 m2)</b>						
No Asbestos						
<b>B00C - R0028 - Movement (5.04 m2)</b>						
No Asbestos						
<b>B00C - R0029 - Toilets - Girls (21.78 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8556/B00C/R0030/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)	
<b>B00C - R0030 - Toilets - Boys (17.86 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
8556/B00C/R0030/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)	
<b>B00C - R0031 - Movement (5.07 m2)</b>						
No Asbestos						
<b>B00C - R0032 - Movement (6.48 m2)</b>						
No Asbestos						
<b>B00C - R0033 - Communal Space (421.19 m2)</b>						
No Asbestos						
<b>B00C - R0034 - Sport Equipment Store (8.32 m2)</b>						
No Asbestos						
<b>B00C - R0037 - Canteen Covered Area (65.7 m2)</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
		No Asbestos				
	<b>B00C - R0038 - Distribution Board (0.63 m2)</b>					Note: No inspection of live electrical installation.
		No Asbestos				
	<b>B00C - R0039 - Movement (62.25 m2)</b>					
		No Asbestos				
	<b>B00C - R0040 - Materials Store (6.67 m2)</b>					
		No Asbestos				
	<b>B00C - R0041 - Materials Technology L.S. (114.9 m2)</b>					
		No Asbestos				
	<b>B00C - R0048 - Wood Technology Bay (32.38 m2)</b>					
		No Asbestos				
	<b>B00C - R0049 - Movement (127.7 m2)</b>					
		No Asbestos				
	<b>B00C - R0050 - Materials Technology L.S. (18.19 m2)</b>					
		No Asbestos				
	<b>B00C - R0054 - Movement (11.31 m2)</b>					
		No Asbestos				
	<b>B00C - R0056 - Movement (31.03 m2)</b>					
		No Asbestos				
	<b>B00C - R0057 - Movement (23 m2)</b>					
		No Asbestos				
	<b>B00C - R0059 - Plant (0.49 m2)</b>					
		No Asbestos				
	<b>B00C - R0060 - Plant (1.47 m2)</b>					
		No Asbestos				
	<b>B00C - R0061 - Sport Equipment Store (11.52 m2)</b>					
		No Asbestos				
	<b>B00C - R0062 - Movement (15.38 m2)</b>					
		No Asbestos				
	<b>B00C - R0063 - Plant (1.47 m2)</b>					
		No Asbestos				
	<b>B00C - R0064 - General Assistant/Bulk Store (7.95 m2)</b>					
		No Asbestos				
	<b>B00C - R0065 - Child Care Centre (5.49 m2)</b>					
		No Asbestos				
	<b>B00C - R0066 - Child Care Centre (3.74 m2)</b>					
		No Asbestos				
	<b>B00C - R0067 - Child Care Centre (5.59 m2)</b>					
		No Asbestos				
	<b>B00C - R0068 - Child Care Centre (7.23 m2)</b>					
		No Asbestos				
	<b>B00C - R0069 - Child Care Centre (92.19 m2)</b>					
		No Asbestos				
	<b>B00C - R0070 - Child Care Centre (18.65 m2)</b>					
		No Asbestos				
	<b>B00C - R0071 - Child Care Centre (2.15 m2)</b>					
		No Asbestos				
	<b>B00C - R0072 - Child Care Centre (1.44 m2)</b>					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

**B00C - R0073 - Child Care Centre (4.22 m2)**

No Asbestos

**B00C - R0074 - Child Care Centre (6.4 m2)**

No Asbestos

**B00C - R0075 - Child Care Centre (1.4 m2)**

No Asbestos

**B00C - R0076 - Child Care Centre (1.43 m2)**

No Asbestos

**B00C - R0077 - Child Care Centre (45.41 m2)**

No Asbestos

**B00C - R0078 - Child Care Centre (4.63 m2)**

No Asbestos

**B00C - R0079 - Child Care Centre (14.44 m2)**

No Asbestos

**B00C - R0080 - Child Care Centre (9.88 m2)**

No Asbestos

**B00C - R0081 - Child Care Centre (54.64 m2)**

No Asbestos

**B00C - R0082 - Child Care Centre (54.49 m2)**

No Asbestos

**B00C - R0083 - Child Care Centre (27.06 m2)**

No Asbestos

**B00C - R0084 - Child Care Centre (33.82 m2)**

No Asbestos

**B00C - R0085 - Child Care Centre (5.13 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0AA - Library/Administration - 1979 - Brick/Block (Brick/Block)****Exterior**

Gable Verge Lining	Flat AC Sheeting	60m	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8556/B0AA/Gable Verge Lining/S12					<b>Chrysotile (white asbestos)</b>
Eaves Linings	Flat AC Sheeting	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8556/B0AA/Gable Verge Lining/S12					<b>Chrysotile (white asbestos)</b>

**Interior****B0AA - R0001 - Movement (70.67 m2)**

No Asbestos

**B0AA - R0002 - Toilets - Boys (25.42 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8556/B0AA/R0002/Partition Walls (Cubicles)/S4					<b>Chrysotile (white asbestos)</b>

**B0AA - R0003 - Toilets - Girls (21.79 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8556/B0AA/R0002/Partition Walls (Cubicles)/S4					<b>Chrysotile (white asbestos)</b>

**B0AA - R0004 - Cleaning Store - Distributed (1.77 m2)**

No Asbestos

**B0AA - R0005 - Staff - Toilet (5.91 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8556/B0AA/R0002/Partition Walls (Cubicles)/S4					<b>Chrysotile (white asbestos)</b>

**B0AA - R0006 - Staff - Toilet (5.9 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8556/B0AA/R0002/Partition Walls (Cubicles)/S4					<b>Chrysotile (white asbestos)</b>

**B0AA - R0007 - Clinic - Boys (12.49 m2)**

No Asbestos

**B0AA - R0009 - General Assistant/Bulk Store (15.47 m2)**

No Asbestos

**B0AA - R0010 - Deputy Principal Office (22.25 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8556/B0AA/R0015/Ceiling Structures/Linings/S3					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B0AA - R0014 - Principal Office (21.95 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8556/B0AA/R0015/Ceiling Structures/Linings/S3					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B0AA - R0015 - Duplicating Workroom (9.02 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8556/B0AA/R0015/Ceiling Structures/Linings/S3					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					<b>No Asbestos Detected</b>
	8556/B0AA/R1004/Floor Coverings Res/Textile/S5					

**B0AA - R0017 - Public Reception (15.58 m2)**

Ceiling Structures/Linings	Vermiculite					<b>Limited Samples Taken</b>
	8556/B0AA/R0015/Ceiling Structures/Linings/S3					<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>

**B0AA - R0021 - Movement (7.33 m2)**



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8556/B0AA/R1011/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos)</b>		
<b>B0AA - R0022 - Cleaning Store - Distributed (4.96 m2)</b>						
No Asbestos						
<b>B0AA - R0023 - Movement (9.14 m2)</b>						
No Asbestos						
<b>B0AA - R0024 - Stairs (0.44 m2)</b>						
No Asbestos						
<b>B0AA - R0025 - Access Staff Shower/Toilet (7.92 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8556/B0AA/R0015/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B0AA - R0026 - Clinic-Toilets (4.04 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8556/B0AA/R0015/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B0AA - R0027 - Pupil Entry (34.42 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8556/B0AA/R0015/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B0AA - R0028 - Staff Study (37.52 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8556/B0AA/R0015/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B0AA - R0029 - Cleaning Supplies Store (8.07 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8556/B0AA/R0015/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B0AA - R0030 - Administration - Clerical (26.21 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8556/B0AA/R0015/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B0AA - R0031 - Movement (31.14 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Main entrance foyer	Good Condition (1)	Low (1)	Low Priority (2-3)
8556/B0AA/R1011/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos)</b>		
<b>B0AA - R0032 - Movement (41.58 m2)</b>						
No Asbestos						
<b>B0AA - R0033 - Lift (2.1 m2)</b>						
No Asbestos						
<b>B0AA - R0034 - Movement (3.66 m2)</b>						
No Asbestos						
<b>B0AA - R1003 - Administration - Clerical (16.48 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8556/B0AA/R0015/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	8556/B0AA/R1004/Floor Coverings Res/Textile/S5					<b>No Asbestos Detected</b>
<b>B0AA - R1004 - Security Store (24.78 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8556/B0AA/R0015/Ceiling Structures/Linings/S3					<b>Limited Samples Taken</b>
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Floor Coverings Res/Textile	Vinyl Tiles					
	8556/B0AA/R1004/Floor Coverings Res/Textile/S5				<b>No Asbestos Detected</b>	
<b>B0AA - R1006 - Toilets - Girls (14.65 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8556/B0AA/R0002/Partition Walls (Cubicles)/S4				<b>Chrysotile (white asbestos)</b>	
<b>B0AA - R1007 - Toilets - Boys (11.56 m2)</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	8556/B0AA/R0002/Partition Walls (Cubicles)/S4				<b>Chrysotile (white asbestos)</b>	
<b>B0AA - R1008 - Staff - Toilet (2.85 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8556/B0AA/R1011/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos)</b>	
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	8556/B0AA/R0002/Partition Walls (Cubicles)/S4				<b>Chrysotile (white asbestos)</b>	
<b>B0AA - R1009 - Cleaning Store - Distributed (2.89 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8556/B0AA/R1011/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos)</b>	
<b>B0AA - R1010 - Movement (10.56 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8556/B0AA/R0015/Ceiling Structures/Linings/S3				<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B0AA - R1011 - Main Switch Board (2.84 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8556/B0AA/R1011/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos)</b>	
<b>B0AA - R1012 - Staff - Toilet (2.84 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	8556/B0AA/R1011/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos)</b>	
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	8556/B0AA/R0002/Partition Walls (Cubicles)/S4				<b>Chrysotile (white asbestos)</b>	
<b>B0AA - R1013 - Movement (56.79 m2)</b>						
No Asbestos						
<b>B0AA - R1014 - Movement (44.02 m2)</b>						
No Asbestos						
<b>B0AA - R1015 - Stairs (14.67 m2)</b>						
No Asbestos						
<b>B0AA - R1016 - Main Area (115.23 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8556/B0AA/R0015/Ceiling Structures/Linings/S3				<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B0AA - R1017 - Audio Visual Workroom (55.02 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8556/B0AA/R0015/Ceiling Structures/Linings/S3				<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						
<b>B0AA - R1018 - K.L.A. Store (16 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	8556/B0AA/R0015/Ceiling Structures/Linings/S3				<b>Limited Samples Taken</b>	
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B0AA - R1019 - Lift (2.1 m2)</b>						
No Asbestos						
<b>B0AA - R1020 - Movement (10.02 m2)</b>						
No Asbestos						
<b>B0AA - R2001 - Plant (11.55 m2)</b>						
No Asbestos						
<b>B0AA - R2002 - Movement (12.57 m2)</b>						
No Asbestos						
<b>B0AA - R2003 - Stairs (14.67 m2)</b>						
No Asbestos						
<b>B0AA - R9002 - Main Switchroom (12.5 m2)</b>						
No Asbestos						
<b>B0AA - R9003 - General Storeroom (11.73 m2)</b>						
No Asbestos						
<b>B0AA - R9004 - Garden Store Room (12.5 m2)</b>						
No Asbestos						
<b>B0AA - R9005 - Plant (78.98 m2)</b>						
No Asbestos						
<b>B0AA - R9006 - Plant (6.13 m2)</b>						
No Asbestos						
<b>B0AA - R9007 - External Movement (28.38 m2)</b>						
No Asbestos						
<b>B0AA - R9008 - Lift (2.1 m2)</b>						
No Asbestos						
<b>B0AA - R9009 - Movement (13.25 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0BB - General Learning/Pupil Facilities - 1979 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting 8556/B0AA/Gable Verge Lining/S12	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Gable Verge Lining	Flat AC Sheeting 8556/B0AA/Gable Verge Lining/S12	40m	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Ceiling Voids	No Asbestos Found					

**Interior****B0BB - R0001 - Movement (84.38 m2)**

No Asbestos

**B0BB - R0008 - Toilets - Boys (25.7 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet 8556/B0AA/R0002/Partition Walls (Cubicles)/S4	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
----------------------------	--	-----	--------------	--------------------	---------	--

**B0BB - R0009 - Toilets - Girls (25.6 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet 8556/B0AA/R0002/Partition Walls (Cubicles)/S4	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
----------------------------	--	------	--------------	--------------------	---------	--

**B0BB - R0010 - Stairs (0.35 m2)**

No Asbestos

**B0BB - R0011 - Stairs (6.75 m2)**

No Asbestos

**B0BB - R0012 - Materials Technology L.S. (82.16 m2)**

Ceiling Structures/Linings	Vermiculite 8556/B0AA/R0015/Ceiling Structures/Linings/S3					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	--	--	--	--	--	--

**B0BB - R0013 - Welding/Hot Metals Area (12.95 m2)**

Ceiling Structures/Linings	Vermiculite 8556/B0AA/R0015/Ceiling Structures/Linings/S3					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	--	--	--	--	--	--

**B0BB - R0014 - Resource/Project Store (11.18 m2)**

Ceiling Structures/Linings	Vermiculite 8556/B0AA/R0015/Ceiling Structures/Linings/S3					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	--	--	--	--	--	--

**B0BB - R0015 - Food Technology L.S. (58.34 m2)**

Ceiling Structures/Linings	Vermiculite 8556/B0AA/R0015/Ceiling Structures/Linings/S3					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	--	--	--	--	--	--

**B0BB - R0016 - Pantry (13.49 m2)**

Ceiling Structures/Linings	Vermiculite 8556/B0AA/R0015/Ceiling Structures/Linings/S3					Limited Samples Taken <b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>
----------------------------	--	--	--	--	--	--

**B0BB - R1001 - Movement (53.65 m2)**

No Asbestos

**B0BB - R1008 - Stairs (15.98 m2)**

No Asbestos

**B0BB - R1009 - Art Learning Space (53.03 m2)**

No Asbestos

**B0BB - R1010 - Darkroom Space (7.72 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B0BB - R1011 - Resources Store (10.32 m2)</b>						
No Asbestos						
<b>B0BB - R1012 - Workshop (72.22 m2)</b>						
No Asbestos						
<b>B0BB - R1013 - Bulk Store (8.21 m2)</b>						
No Asbestos						
<b>B0BB - R1014 - Kiln Space (7.98 m2)</b>						
No Asbestos						
<b>B0BB - R1015 - Computer Learning Space (56.02 m2)</b>						
No Asbestos						
<b>B0BB - R9001 - Movement (13.22 m2)</b>						
No Asbestos						
<b>B0BB - R9002 - Distribution Board Cupboard (0.98 m2)</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B0BB - R9003 - Stairs (6.75 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0CC - Communal Facilities - 1890 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B0CC - R0001 - Communal Space (178.94 m2)**

Blockwork pointing	Putty					
		8556/B0CC/R0001/Blockwork pointing/S7				<b>No Asbestos Detected</b>

**B0CC - R0002 - Cleaning Supplies Store (8.7 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
		8556/B0CC/R0002/Floor Coverings Res/Textile/S6				<b>No Asbestos Detected</b>

**B0CC - R0003 - Chair Store (13.81 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B0DD - General Learning/Other-D.E.C. Admin - 1903 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	30m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	8556/B0AA/Gable Verge Lining/S12					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

**Interior****B0DD - R0001 - Movement (21.56 m2)**

No Asbestos

**B0DD - R0002 - Home Base (50.88 m2)**

No Asbestos

**B0DD - R0003 - Practical Activities - 1hb (16.3 m2)**

No Asbestos

**B0DD - R0004 - Home Base (51.77 m2)**

No Asbestos

**B0DD - R0005 - Personal Effects Storage (12.98 m2)**

No Asbestos

**B0DD - R0007 - Cleaning Supplies Store (2.56 m2)**

No Asbestos

**B0DD - R0008 - Home Base (46.3 m2)**

No Asbestos

**B0DD - R0018 - Computer Learning Space (25.06 m2)**

No Asbestos

**B0DD - R0019 - Toilets - Girls (12.09 m2)**

No Asbestos

**B0DD - R0020 - Stairs (3.22 m2)**

No Asbestos

**B0DD - R0021 - Stairs (15.54 m2)**

No Asbestos

**B0DD - R0022 - Movement (28.96 m2)**

No Asbestos

**B0DD - R0023 - Movement (68.24 m2)**

No Asbestos

**B0DD - R0024 - General Learning Space (56.99 m2)**

No Asbestos

**B0DD - R0025 - General Learning Space (42.63 m2)**

No Asbestos

**B0DD - R0026 - Computer Learning Space (49.69 m2)**

No Asbestos

**B0DD - R0027 - Computer Learning Space (50.11 m2)**

No Asbestos

**B0DD - R0028 - Movement (15.8 m2)**

No Asbestos

**B0DD - R0029 - Movement (6.73 m2)**

No Asbestos

**B0DD - R0030 - Movement (5 m2)**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B0DD - R0031 - Lift (2.1 m2)</b>						
No Asbestos						
<b>B0DD - R0032 - Movement (4.7 m2)</b>						
No Asbestos						
<b>B0DD - R1001 - Movement (21.69 m2)</b>						
No Asbestos						
<b>B0DD - R1002 - Home Base (53.63 m2)</b>						
No Asbestos						
<b>B0DD - R1017 - Stairs (15.45 m2)</b>						
No Asbestos						
<b>B0DD - R1018 - Stairs (6.24 m2)</b>						
No Asbestos						
<b>B0DD - R1019 - Performing Arts Store (15.91 m2)</b>						
No Asbestos						
<b>B0DD - R1020 - Performance Workspace (15.04 m2)</b>						
No Asbestos						
<b>B0DD - R1021 - Performance Workspace (87.73 m2)</b>						
No Asbestos						
<b>B0DD - R1022 - Movement (80.02 m2)</b>						
No Asbestos						
<b>B0DD - R1023 - General Learning Space (56.84 m2)</b>						
No Asbestos						
<b>B0DD - R1024 - General Learning Space (42.7 m2)</b>						
No Asbestos						
<b>B0DD - R1025 - Cleaning Supplies Store (10.78 m2)</b>						
No Asbestos						
<b>B0DD - R1026 - Staff Study (100.89 m2)</b>						
No Asbestos						
<b>B0DD - R1027 - Interview/Office - Type 1 (13.41 m2)</b>						
No Asbestos						
<b>B0DD - R1028 - Duplicating Workroom (7.91 m2)</b>						
No Asbestos						
<b>B0DD - R1029 - Security Store (6.95 m2)</b>						
No Asbestos						
<b>B0DD - R1030 - Toilets-Unisex (4.32 m2)</b>						
No Asbestos						
<b>B0DD - R1031 - Self Help Toilet (8.69 m2)</b>						
No Asbestos						
<b>B0DD - R1032 - Movement (26.14 m2)</b>						
No Asbestos						
<b>B0DD - R1033 - Movement (5 m2)</b>						
No Asbestos						
<b>B0DD - R9003 - Movement (8.93 m2)</b>						
Blockwork pointing	Putty					
			8556/B0CC/R0001/Blockwork pointing/S7			No Asbestos Detected
<b>B0DD - R9004 - Kiln Space (3.92 m2)</b>						
Blockwork pointing	Putty					
			8556/B0CC/R0001/Blockwork pointing/S7			No Asbestos Detected
<b>B0DD - R9005 - General Storeroom (3.99 m2)</b>						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Blockwork pointing	Putty					
	8556/B0CC/R0001/Blockwork pointing/S7					No Asbestos Detected
<b>B0DD - R9011 - Stairs (3.92 m2)</b>						
Blockwork pointing	Putty					
	8556/B0CC/R0001/Blockwork pointing/S7					No Asbestos Detected
<b>B0DD - R9012 - Disabled Toilet (8.2 m2)</b>						
No Asbestos						
<b>B0DD - R9013 - Gymnasium (86.8 m2)</b>						
No Asbestos						
<b>B0DD - R9014 - Movement (29.69 m2)</b>						
No Asbestos						
<b>B0DD - R9015 - Student Canteen (44.87 m2)</b>						
Blockwork pointing	Putty					
	8556/B0CC/R0001/Blockwork pointing/S7					No Asbestos Detected
<b>B0DD - R9016 - Canteen Office/Store (15.17 m2)</b>						
Blockwork pointing	Putty					
	8556/B0CC/R0001/Blockwork pointing/S7					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

## Demountables

### Demountable details as per the AMS records as of 15 Feb 2017.

#### OS 520 - D10423 - Staff Study : Placement Date - 23/12/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - Staff Room

No Asbestos Found.

#### OS 600 - D10526 - Learning Unit - Small : Placement Date - 23/12/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - General Learning Space

No Asbestos Found.

#### OS 600 - D10804 - Learning Unit - Small : Placement Date - 8/12/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - General Learning Space

No Asbestos Found.

#### OS 801 - D10856 - FSU : Placement Date - 14/01/2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - Canteen

No Asbestos Found.

##### R2 - Covered Area

No Asbestos Found.

#### OS 720 - D10894 - Science Laboratory/Prep Room : Placement Date - 14/12/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

#### Interior

##### R1 - Laboratory L.S.

No Asbestos Found.

##### R2 - Preparation

No Asbestos Found.

#### OS 711 - D10918 - Home Science/Art/Science Dem/Computer : Placement Date - 13/12/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

#### Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Interior****R1 - Computer Room**

No Asbestos Found.

**R2 - Food Technology L.S.**

No Asbestos Found.

**R3 - Storeroom**

No Asbestos Found.

**OS 520 - D10963 - Staff Study : Placement Date - 29/11/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior****R1 - Staff Room**

No Asbestos Found.

**OS 840 - D10990 - Girls Toilet : Placement Date - 29/11/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior****R1 - Toilets-Girls**

No Asbestos Found.

**OS 840 - D11110 - Girls Toilet : Placement Date - 2/12/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior****R1 - Toilets-Girls**

No Asbestos Found.

**OS 508 - D11544 - Administration : Placement Date - 5/12/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Interior**

**R1 - Security Store**

No Asbestos Found.

**R2 - Principal**

No Asbestos Found.

**R3 - Clerical Office**

No Asbestos Found.

**R4 - Duplicating Workroom**

No Asbestos Found.

**R5 - Sick Bay - Shower/Toilet**

No Asbestos Found.

**R6 - Sick Bay**

No Asbestos Found.

**R7 - Interview**

No Asbestos Found.

**R8 - Entry Vestibule**

No Asbestos Found.

**R9 - Store**

No Asbestos Found.

**OS 534 - D11919 - Library/Group Study/Office/A V Store : Placement Date - 8/12/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Clerical Office**

No Asbestos Found.

**R2 - Staff Room**

No Asbestos Found.

**R3 - Security Store**

No Asbestos Found.

**R4 - Principal**

No Asbestos Found.

**R5 - Staff Toilet**

No Asbestos Found.

**R6 - Staff Toilet**

No Asbestos Found.

**R7 - Reading Area**

No Asbestos Found.

**R8 - Entry**

No Asbestos Found.

**OS 841 - D11980 - Boys Toilet : Placement Date - 13/12/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
<b>Interior</b>						
<b>R1 - Toilets-Boys</b>						
No Asbestos Found.						
<b>OS 840 - D11983 - Girls Toilet : Placement Date - 2/12/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Toilets-Girls</b>						
No Asbestos Found.						
<b>OS 840 - D11987 - Girls Toilet : Placement Date - 5/12/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Toilets-Girls</b>						
No Asbestos Found.						
<b>OS 841 - D12739 - Boys Toilet : Placement Date - 13/12/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Toilets-Boys</b>						
No Asbestos Found.						
<b>OS 520 - D12779 - Staff Study : Placement Date - 13/12/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Staff Room</b>						
No Asbestos Found.						
<b>OS 600 - D12954 - Learning Unit - Small : Placement Date - 29/11/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - General Learning Space</b>						
No Asbestos Found.						
<b>OS 523 - D13108 - Staff Study With Toilets : Placement Date - 29/11/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>Interior</b>						
<b>R1 - Entry</b>						
No Asbestos Found.						
<b>R2 - Staff Room</b>						
No Asbestos Found.						
<b>R3 - Staff Toilet</b>						
No Asbestos Found.						
<b>OS 841 - D13381 - Boys Toilet : Placement Date - 29/11/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Toilets-Boys</b>						
No Asbestos Found.						
<b>OS 837 - D13907 - Hcap Shower/Change/Toilet : Placement Date - 20/12/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Disabled Shower/Toilet</b>						
No Asbestos Found.						
<b>OS 600 - D13942 - Learning Unit - Small : Placement Date - 5/12/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - General Learning Space</b>						
No Asbestos Found.						
<b>OS 600 - D15016 - Learning Unit - Small : Placement Date - 20/12/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - General Learning Space</b>						
No Asbestos Found.						
<b>OS 720 - D15935 - Science Laboratory/Prep Room : Placement Date - 14/12/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Laboratory L.S.</b>						
No Asbestos Found.						
<b>R2 - Preparation</b>						
No Asbestos Found.						
<b>OS 700 - D16888 - Art Learning Space/Workshop/Store : Placement Date - 14/12/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Entry**

No Asbestos Found.

**R2 - Art Learning Space**

No Asbestos Found.

**R3 - Store**

No Asbestos Found.

**OS 837 - D17116 - Hcap Shower/Change/Toilet : Placement Date - 20/12/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Disabled Shower/Toilet**

No Asbestos Found.

**OS 971 - D17388 - Shed - Container (Garden/Sports/Bulk) : Placement Date - 14/12/2016**

**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	2.88 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2

**Interior**

**R1 - Garden Store**

End wall panel	Flat AC Sheet	Assumed Asbestos	36 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	18 m2

**OS 600 - D17947 - Learning Unit - Small : Placement Date - 23/12/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - General Learning Space**

No Asbestos Found.

**OS 600 - D18156 - Learning Unit - Small : Placement Date - 2/12/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - General Learning Space**

No Asbestos Found.

**OS 600 - D18157 - Learning Unit - Small : Placement Date - 2/12/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - General Learning Space**

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>OS 520 - D18217 - Staff Study : Placement Date - 3/01/2017</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Staff Room</b>						
No Asbestos Found.						
<b>OS 600 - D18249 - Learning Unit - Small : Placement Date - 2/12/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - General Learning Space</b>						
No Asbestos Found.						
<b>OS 600 - D18250 - Learning Unit - Small : Placement Date - 14/01/2017</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - General Learning Space</b>						
No Asbestos Found.						
<b>OS 600 - D18251 - Learning Unit - Small : Placement Date - 14/01/2017</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - General Learning Space</b>						
No Asbestos Found.						
<b>OS 600 - D18252 - Learning Unit - Small : Placement Date - 9/12/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - General Learning Space</b>						
No Asbestos Found.						
<b>OS 600 - D18253 - Learning Unit - Small : Placement Date - 23/12/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - General Learning Space</b>						
No Asbestos Found.						
<b>OS 600 - D18254 - Learning Unit - Small : Placement Date - 20/12/2016</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Interior**

**R1 - General Learning Space**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017