

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Albion Park High School (8586)  
**Region :** Illawarra and South East  
**State Electorate :** Kiama  
**Local Government Area :** Shellharbour

**Initial Survey :** Noel Arnold & Associates : 31 - Mar - 2008  
**Register Issue Date :** 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00A - Multi Purpose Facilities/Pupil Facilities - 1989 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00A - R0001 - Sport Equipment Store**

No Asbestos

**B00A - R0002 - Shower/Change**

No Asbestos

**B00A - R0003 - Chair Store**

No Asbestos

**B00A - R0004 - Sport Equipment Store**

No Asbestos

**B00A - R0005 - Control Room**

No Asbestos

**B00A - R0006 - Shower/Change**

No Asbestos

**B00A - R0007 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0008 - Staff Shower**

No Asbestos

**B00A - R0009 - Staff - Toilet**

No Asbestos

**B00A - R0010 - Cleaning Supplies Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0011 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0012 - Multi-Purpose Space**

No Asbestos

**B00A - R0013 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0014 - General Assistants**

No Asbestos

**B00A - R0015 - Cleaning Supplies Store**

No Asbestos

**B00A - R0016 - Maintenance Bulk Store**

No Asbestos

**B00A - R0017 - Garden Store Room**

No Asbestos

**B00A - R0018 - Gymnasium**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Administration - 1989 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00B - R0002 - Movement**

No Asbestos

**B00B - R0003 - Ancillary Staff**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0004 - Staff - Toilet**

No Asbestos

**B00B - R0005 - Interview/Office - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0006 - Toilets-Boys**

No Asbestos

**B00B - R0007 - Toilets-Boys**

No Asbestos

**B00B - R0008 - Toilets-Girls**

No Asbestos

**B00B - R0009 - Clinic - Girls**

No Asbestos

**B00B - R0010 - Deputy Principal Office**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0011 - Movement**

No Asbestos

**B00B - R0012 - Administration - Clerical**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0014 - Staff Study**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0015 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0016 - Principal Office**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0017 - Interview/Office - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0018 - Secure Storeroom**

No Asbestos

**B00B - R0019 - Duplicating Workroom**

No Asbestos

**B00B - R0020 - Teachers Aides**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0021 - Interview/Office - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00B - R0022 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00B - R0023 - Cleaning Store - Distributed**

No Asbestos

**B00B - R0024 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0025 - Pupil Entry**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0026 - Public Entry**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0027 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Physical Education/Variou - 1989 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00C - R0001 - Cleaning Store - Distributed**

No Asbestos

**B00C - R0002 - Performance Workspace**

No Asbestos

**B00C - R0003 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00C - R0004 - Staff Shower**

No Asbestos

**B00C - R0005 - Movement**

No Asbestos

**B00C - R0006 - Toilets-Boys**

No Asbestos

**B00C - R0007 - Toilets-Girls**

No Asbestos

**B00C - R0008 - Movement**

No Asbestos

**B00C - R0009 - Staff Shower**

No Asbestos

**B00C - R0010 - Staff - Toilet**

No Asbestos

**B00C - R0011 - Music Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0012 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0013 - Resources**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0014 - Design L.S.**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0015 - Resource/Project Store**

No Asbestos

**B00C - R0016 - Staff Study**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00C - R0017 - Movement**

No Asbestos

**B00C - R0018 - Design L.S.**

No Asbestos

**B00C - R0019 - Laundry**

No Asbestos

**B00C - R0020 - Food Technology L.S.**

No Asbestos

**B00C - R0021 - Food/Research Space**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00C - R0022 - Seminar/Technology Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B00C - R0023 - Food Technology L.S.</b>						
No Asbestos						
<b>B00C - R0024 - Movement</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B00C - R0025 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00C - R0026 - Staff Study</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B00C - R0027 - Practice/Seminar</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B00C - R0028 - Distribution Board Cupboard</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00C - R0029 - Music Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B00C - R0030 - Practice/Seminar</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B00C - R0031 - Music Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
<b>B00C - R0032 - Movement</b>						
No Asbestos						
<b>B00C - R0033 - Staff Kitchen</b>						
No Asbestos						
<b>B00C - R0034 - Chair Store</b>						
No Asbestos						
<b>B00C - R0035 - Main Switchroom</b>						
No Asbestos						
<b>B00C - R0036 - Plant</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Various/General Learning - 1989 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00D - R0001 - Movement**

No Asbestos

**B00D - R0002 - Movement**

No Asbestos

**B00D - R0003 - Staff - Toilet**

No Asbestos

**B00D - R0004 - Staff - Toilet**

No Asbestos

**B00D - R0007 - Staff Study**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0008 - Study Space**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0009 - Interview/Office - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0010 - Study Space**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0011 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0012 - Toilets-Boys**

No Asbestos

**B00D - R0013 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0014 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0015 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0016 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0017 - Secure Storeroom**

No Asbestos

**B00D - R0018 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0019 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0020 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00D - R0021 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00D - R0022 - Computer Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R0023 - Computer Resource</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R0024 - Computer Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R0025 - Commonroom</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R0026 - Toilets-Disabled</b>						
No Asbestos						
<b>B00D - R0027 - Stairs</b>						
No Asbestos						
<b>B00D - R0028 - Stairs</b>						
No Asbestos						
<b>B00D - R1001 - Movement</b>						
No Asbestos						
<b>B00D - R1002 - Staff Study</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R1003 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00D - R1004 - Secure Storeroom</b>						
No Asbestos						
<b>B00D - R1005 - Staff Study</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R1006 - Staff Study</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R1007 - Study Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R1008 - Distribution Board Cupboard</b>						
No Asbestos					Note: No inspection of live electrical installation.	
<b>B00D - R1009 - Toilets-Boys</b>						
No Asbestos						
<b>B00D - R1010 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R1011 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R1012 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R1013 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R1014 - Secure Storeroom</b>						
No Asbestos						
<b>B00D - R1015 - General Learning Space</b>						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R1016 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R1017 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R1018 - Distribution Board Cupboard</b>				Note: No inspection of live electrical installation.		
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R1019 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R1020 - General Learning Space</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00D - R1021 - Stairs</b>						
No Asbestos						
<b>B00D - R1022 - Stairs</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00E - Various/General Learning - 1989 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00E - R0001 - Movement**

No Asbestos

**B00E - R0003 - Interview/Office - Type 1**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00E - R0004 - Toilets-Disabled**

No Asbestos

**B00E - R0005 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0006 - General Storeroom**

No Asbestos

**B00E - R0007 - General Learning Space**

No Asbestos

**B00E - R0008 - General Learning Space**

No Asbestos

**B00E - R0009 - Computer Learning Space**

No Asbestos

**B00E - R0010 - Toilets-Girls**

No Asbestos

**B00E - R0011 - Study Space**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00E - R0012 - Staff Study**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00E - R0013 - Stairs**

No Asbestos

**B00E - R0014 - Lift**

No Asbestos

**B00E - R1001 - Secure Storeroom**

No Asbestos

**B00E - R1002 - Secure Storeroom**

No Asbestos

**B00E - R1003 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R1004 - Interview/Office - Type 1**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00E - R1005 - General Learning Space**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00E - R1006 - General Learning Space**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00E - R1007 - General Learning Space**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00E - R1008 - General Learning Space**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R1009 - Toilets-Girls**

No Asbestos

**B00E - R1010 - Study Space**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R1011 - Staff Study**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00E - R1012 - Stairs**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00F - Science Learning - 1989 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00F - R0001 - Movement**

No Asbestos

**B00F - R0002 - Laboratory L.S.**

No Asbestos

**B00F - R0003 - Laboratory L.S.**

No Asbestos

**B00F - R0004 - Movement**

No Asbestos

**B00F - R0005 - Laboratory L.S.**

No Asbestos

**B00F - R0006 - Laboratory L.S.**

No Asbestos

**B00F - R0007 - Laboratory L.S.**

No Asbestos

**B00F - R0008 - Movement**

No Asbestos

**B00F - R0009 - Apparatus Store**

No Asbestos

**B00F - R0010 - Preparation**

No Asbestos

**B00F - R0011 - Chemical Store**

No Asbestos

**B00F - R0012 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0013 - Laboratory L.S.**

No Asbestos

**B00F - R0014 - Movement**

No Asbestos

**B00F - R0015 - Cleaning Store - Distributed**

No Asbestos

**B00F - R0016 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Technological & Applied Studies - 1989 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00G - M0001 - Resource/Project Store**

No Asbestos

**B00G - M0002 - Resource/Project Store**

No Asbestos

**B00G - M0003 - Resource/Project Store**

No Asbestos

**B00G - M0004 - Stairs**

No Asbestos

**B00G - M0005 - Stairs**

No Asbestos

**B00G - R0001 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0002 - G.L.S. Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0003 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0005 - Machine Storage**

No Asbestos

**B00G - R0006 - Metal Technology Bay**

No Asbestos

**B00G - R0007 - General Learning Space**

No Asbestos

**B00G - R0008 - Materials Store**

No Asbestos

**B00G - R0009 - Staff Study**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0010 - General Learning Space**

No Asbestos

**B00G - R0011 - Wood Technology Bay**

No Asbestos

**B00G - R0012 - Dust Extraction Space**

No Asbestos

**B00G - R0013 - Cleaning Store - Distributed**

No Asbestos

**B00G - R0014 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00G - R0015 - Staff - Toilet**

No Asbestos

**B00G - R0016 - Staff Study**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00G - R0017 - Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00G - R0018 - Resource/Project Store</b>						
No Asbestos						
<b>B00G - R0019 - General Learning Space</b>						
No Asbestos						
<b>B00G - R0020 - Materials Workshop - Type 2</b>						
No Asbestos						
<b>B00G - R0021 - Stairs</b>						
No Asbestos						
<b>B00G - R0022 - Stairs</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Art/Pupil Facilities - 1989 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00H - R0001 - Movement**

No Asbestos

**B00H - R0002 - Toilets-Girls**

No Asbestos

**B00H - R0003 - Staff Study**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00H - R0004 - Art Learning Space**

No Asbestos

**B00H - R0005 - Bulk Store**

No Asbestos

**B00H - R0006 - Study Space**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00H - R0007 - General Storeroom**

No Asbestos

**B00H - R0008 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00H - R0009 - Art Learning Space**

No Asbestos

**B00H - R0010 - Darkroom Space**

No Asbestos

**B00H - R0011 - Art Learning Space**

No Asbestos

**B00H - R0012 - Kiln Space**

No Asbestos

**B00H - R0013 - Art Learning Space**

No Asbestos

**B00H - R0014 - Cleaning Store - Distributed**

No Asbestos

**B00H - R0015 - Interview/Office - Type 1**Vinyl Tiles (Under Floor  
Covering/Carpet) No Asbestos Found**B00H - R0016 - Movement**

No Asbestos

**B00H - R0017 - Toilets-Boys**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00I - Library - 1989 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00I - R0001 - Main Area**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R0002 - Audio Visual Workroom**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R0003 - Workroom**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R0004 - Librarian**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R0005 - Movement**

No Asbestos

**B00I - R0006 - Cleaning Store - Distributed**

No Asbestos

**B00I - R0007 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00I - R0008 - Seminar**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R0009 - Seminar**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R0010 - Seminar**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R0011 - Seminar**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00I - R0012 - Seminar**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Agricultural Science - 1989 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00J - R0001 - Animal Space**

No Asbestos

**B00J - R0002 - Staff - Toilet**

No Asbestos

**B00J - R0003 - Class Tools Storage**

No Asbestos

**B00J - R0004 - Machine Storage**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Other - 1989 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00K - R0001 - Student Canteen**

No Asbestos

**B00K - R0002 - Office/Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 601 - D10671 - Learning Unit - Standard/Withdrawal : Placement Date - 2/02/1995**

### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

### Interior

#### R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

#### R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

#### R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

**OS 601 - D11076 - Learning Unit - Standard/Withdrawal : Placement Date - 12/11/2009**

### Exterior

No Asbestos Found.

### Interior

#### R1 - Entry

No Asbestos Found.

#### R2 - General Learning Space

No Asbestos Found.

#### R3 - Store

No Asbestos Found.

**OS 601 - D12925 - Learning Unit - Standard/Withdrawal : Placement Date - 20/04/2012**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

### Exterior

No Asbestos Found.

### Interior

#### R1 - Entry

No Asbestos Found.

#### R2 - General Learning Space

No Asbestos Found.

#### R3 - Store

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**Available Asbestos Related Electronic Files**

8586\_ASB\_171210\_AMP.pdf

\* Note : Refer to AMS for details of the attachment(s).

2017