


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Ballina Public School (1112)
Region : North Coast
State Electorate : Ballina
Local Government Area : Ballina

Initial Survey : Noel Arnold & Associates : 10 - Jun - 2008
Reviewed By : Parsons Brinckerhoff : 08 - Oct - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1968 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	60m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00A/Eaves Linings/S18					Chrysotile (white asbestos)

Interior**B00A - R0001 - Movement (169.2 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	160m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00A/R1001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)

B00A - R0002 - Cleaning Supplies (12.01 m2)

No Asbestos

B00A - R0003 - Practical Activities - 1hb (22.5 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	1112/B00A/R0005/Ceiling Structures/Linings/S6					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	1112/B00A/R0005/Ceiling Structures/Linings/S6					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	1112/B00A/R0006/Floor Coverings Res/Textile/S7					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	1112/B00A/R0006/Floor Coverings Res/Textile/S7					No Asbestos Detected

B00A - R0004 - Home Base (53.76 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	1112/B00A/R0005/Ceiling Structures/Linings/S6					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0005 - Home Base (54 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	1112/B00A/R0005/Ceiling Structures/Linings/S6					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0006 - Practical Activities - 1hb (18.29 m2)

Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	1112/B00A/R0006/Floor Coverings Res/Textile/S7					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	1112/B00A/R0005/Ceiling Structures/Linings/S6					No Asbestos Detected
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	1112/B00A/R0006/Floor Coverings Res/Textile/S7					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
	1112/B00A/R0005/Ceiling Structures/Linings/S6					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00A - R0007 - Distribution Board (0.17 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0012 - Sports Store (7.2 m2)

No Asbestos

B00A - R0013 - Movement (11.82 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00A - R0014 - Staff Toilet (4.83 m2)						
No Asbestos						
B00A - R0015 - Staff Shower/Change (3.48 m2)						
No Asbestos						
B00A - R0016 - Canteen (34.93 m2)						
No Asbestos						
B00A - R0017 - Canteen Office/Store (8.41 m2)						
No Asbestos						
B00A - R0018 - General Storeroom (12.07 m2)						
No Asbestos						
B00A - R0019 - Sports Store (11.75 m2)						
No Asbestos						
B00A - R0020 - Special Programs Room (69.8 m2)						
No Asbestos						
B00A - R0021 - Stairs (5.73 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1112/B00A/R1001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)	
B00A - R0022 - Stairs (5.72 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1112/B00A/R1001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)	
B00A - R1001 - Movement (80.53 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1112/B00A/R1001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)	
B00A - R1002 - Practical Activities - 1hb (18.34 m2)						
No Asbestos						
B00A - R1003 - Home Base (53.99 m2)						
No Asbestos						
B00A - R1004 - Home Base (53.92 m2)						
No Asbestos						
B00A - R1005 - Practical Activities - 1hb (18.34 m2)						
No Asbestos						
B00A - R1006 - Practical Activities - 1hb (18.04 m2)						
No Asbestos						
B00A - R1007 - Home Base (54.53 m2)						
No Asbestos						
B00A - R1008 - Home Base (54.06 m2)						
No Asbestos						
B00A - R1009 - Practical Activities - 1hb (18.12 m2)						
No Asbestos						
B00A - R1010 - Stairs (18.27 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1112/B00A/R1001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)	
B00A - R1011 - Stairs (18.19 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1112/B00A/R1001/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration/Staff Facilities - 1897 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	34m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00B/Eaves Linings/S19					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00B - R0001 - Movement (3.92 m2)**

No Asbestos

B00B - R0002 - Principal (19.97 m2)

No Asbestos

B00B - R0003 - Deputy Principal (13.41 m2)

No Asbestos

B00B - R0004 - Entry Vestibule (9.53 m2)

No Asbestos

B00B - R0005 - General Storeroom (7.17 m2)

No Asbestos

B00B - R0006 - Movement (23.25 m2)

No Asbestos

B00B - R0007 - Sick Bay (9.49 m2)

No Asbestos

B00B - R0009 - Distribution Board (0.34 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0010 - Clerical Office (26.69 m2)

No Asbestos

B00B - R0012 - Duplicating Workroom (7.97 m2)

No Asbestos

B00B - R0013 - Cleaning Distributed Store (3.16 m2)

No Asbestos

B00B - R0015 - Movement (40.77 m2)

Ceiling Structures/Linings	Flat AC Sheeting	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

1112/B00B/R0015/Ceiling Structures/Linings/S25

Chrysotile (white asbestos) , Amosite (brown asbestos)**B00B - R0016 - Kiln Room (13.91 m2)**

No Asbestos

B00B - R0017 - General Assistant/Bulk Store (13.51 m2)

No Asbestos

B00B - R0018 - Toilet - Lobby (2.61 m2)

No Asbestos

B00B - R0019 - Toilet - Lobby (2.31 m2)

No Asbestos

B00B - R0020 - Staff Toilet (1.53 m2)

No Asbestos

B00B - R0021 - Staff Toilet (1.85 m2)

No Asbestos

B00B - R0022 - Staff Kitchen (11.22 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00B - R0023 - Staff Room (44.36 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Library - 1881 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00C/Eaves Linings/S20					Chrysotile (white asbestos)

Interior

B00C - M0001 - Store (67.36 m2)

No Asbestos

B00C - M0002 - Stairs (1.89 m2)

No Asbestos

B00C - R0002 - Staff Toilet (4 m2)

No Asbestos

B00C - R0003 - Movement (4.7 m2)

No Asbestos

B00C - R0004 - General Storeroom (0.95 m2)

No Asbestos

B00C - R0005 - Distribution Board (0.85 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0006 - Communications Room (8.27 m2)

No Asbestos

B00C - R0007 - Library Office/Workroom (18.1 m2)

No Asbestos

B00C - R0008 - Library Office/Workroom (7.68 m2)

No Asbestos

B00C - R0009 - Movement (10.69 m2)

No Asbestos

B00C - R0010 - K.L.A. Store (10.77 m2)

No Asbestos

B00C - R0011 - Movement (1.53 m2)

No Asbestos

B00C - R0012 - Stairs (0.19 m2)

No Asbestos

B00C - R0013 - Reading Area (113.3 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1913 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00D - R0001 - Home Base (46.58 m2)**

No Asbestos

B00D - R0002 - Home Base (51.74 m2)

No Asbestos

B00D - R0003 - Movement (68.67 m2)

Ceiling Structures/Linings	Flat AC Sheeting	68m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1112/B00D/R0003/Ceiling Structures/Linings/S26					Chrysotile (white asbestos)	

B00D - R0004 - Movement (28.89 m2)

No Asbestos

B00D - R0005 - Movement (3.93 m2)

Floor Coverings Res/Textile	Vinyl Tiles				
1112/B00D/R0008/Floor Coverings Res/Textile/S5					No Asbestos Detected

B00D - R0006 - Withdrawal Space - 1hb (11.26 m2)

No Asbestos

B00D - R0007 - Interview (10.07 m2)

No Asbestos

B00D - R0008 - Practical Activities - 1hb (36.05 m2)

Floor Coverings Res/Textile	Vinyl Tiles				
1112/B00D/R0008/Floor Coverings Res/Textile/S5					No Asbestos Detected

B00D - R0009 - Home Base (47.77 m2)

No Asbestos

B00D - R0010 - Home Base (47.44 m2)

No Asbestos

B00D - R0011 - Cleaning Distributed Store (2.86 m2)

No Asbestos

B00D - R0012 - Stairs (6.35 m2)

Floor Coverings Res/Textile	Vinyl Tiles				
1112/B00D/R0008/Floor Coverings Res/Textile/S5					No Asbestos Detected

B00D - R1001 - Home Base (48.39 m2)

No Asbestos

B00D - R1002 - Home Base (53.57 m2)

No Asbestos

B00D - R1003 - Practical Activities - 1hb (2.87 m2)

No Asbestos

B00D - R1004 - Movement (27.26 m2)

No Asbestos

B00D - R1005 - Practical Activities - 1hb (36.92 m2)

Floor Coverings Res/Textile	Vinyl Tiles				
1112/B00D/R0008/Floor Coverings Res/Textile/S5					No Asbestos Detected

B00D - R1006 - Home Base (49.38 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - R1007 - Home Base (50.08 m2)

No Asbestos

B00D - R1008 - Stairs (11.48 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
		1112/B00D/R0008/Floor Coverings Res/Textile/S5				No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Music - 1947 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting 1112/B00E/Eaves Linings/S22	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Void	Flat AC Sheeting 1112/B00E/Ceiling Void/S21	10m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5) Chrysotile (white asbestos)
Underfloor Void	No Asbestos Found					

Interior**B00E - R0003 - Movement (3.36 m2)**

Wall Linings Internal	Flat AC Sheeting 1112/B00E/R0003/Wall Linings Internal/S16					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 1112/B00E/R0003/Ceiling Structures/Linings/S27	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00E - R0004 - External Movement (54.31 m2)

No Asbestos

B00E - R0005 - Home Base (93.03 m2)

Wall Linings Internal	Flat AC Sheeting 1112/B00E/R0005/Wall Linings Internal/S15	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 1112/B00E/R0005/Ceiling Structures/Linings/S28	83m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00E - R0007 - Home Base Store (11.25 m2)

Wall Linings Internal	Flat AC Sheeting 1112/B00E/R0007/Wall Linings Internal/S15	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 1112/B00E/R0007/Ceiling Structures/Linings/S30	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

B00E - R0008 - Staff Room Annexe (6.74 m2)

Wall Linings Internal	Flat AC Sheeting 1112/B00E/R0008/Wall Linings Internal/S16					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 1112/B00E/R0008/Ceiling Structures/Linings/S31	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1975 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	12m2	East, West, Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00F/Eaves Linings/S2					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00F - R0002 - Toilets - Girls (1.48 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00F/R0002/Ceiling Structures/Linings/S32					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00F - R0003 - Toilets - Girls (1.49 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00F/R0003/Ceiling Structures/Linings/S33					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00F - R0004 - Toilets - Girls (44.86 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00F/R0004/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00F/R0004/Ceiling Structures/Linings/S34					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00F - R0005 - Disabled Toilet (7.46 m2)

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00F/R0005/Ceiling Structures/Linings/S35					Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1975 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	NA	North, South, Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00F/Eaves Linings/S2					Chrysotile (white asbestos)
Downpipes	Fibre Cement Pipe	5m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00G/Downpipes/S3					Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids	No Asbestos Found					
Ceiling Voids	No Asbestos Found					

Interior**B00G - R0001 - Toilets - Boys (52.82 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00F/R0004/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	53m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00G/R0001/Ceiling Structures/Linings/S36					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00G - R0002 - Staff Toilet (1.49 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00G/R0002/Ceiling Structures/Linings/S37					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00G - R0003 - Staff Toilet (1.5 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00G/R0003/Ceiling Structures/Linings/S38					Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Administration/General Learning - 1975 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00H/Eaves Linings/S23				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00H - R0001 - Movement (1.24 m2)**

No Asbestos

B00H - R0002 - Movement (5.84 m2)

No Asbestos

B00H - R0003 - Cleaning Distributed Store (3.22 m2)

No Asbestos

B00H - R0004 - Toilets - Boys (28.61 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00F/R0004/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)	

B00H - R0005 - Movement (177.34 m2)

No Asbestos

B00H - R0006 - Uniform Shop (3.21 m2)

No Asbestos

B00H - R0007 - Craft Store (3.01 m2)

No Asbestos

B00H - R0008 - Canteen (17.37 m2)

No Asbestos

B00H - R0011 - Movement (66.85 m2)

No Asbestos

B00H - R0012 - Cleaning Distributed Store (6.24 m2)

No Asbestos

B00H - R0013 - Sports Store (7.82 m2)

No Asbestos

B00H - R0014 - Toilets - Girls (30.67 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00F/R0004/Partition Walls (Cubicles)/S1				Chrysotile (white asbestos)	

B00H - R0015 - Special Programs Room (44.74 m2)

Floor Coverings Res/Textile	Vinyl Tiles	45m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00H/R0015/Floor Coverings Res/Textile/S11				Chrysotile (white asbestos)	

B00H - R0016 - General Storeroom (8.82 m2)

No Asbestos

B00H - R0017 - Stairs (3.96 m2)

No Asbestos

B00H - R0018 - Stairs (3.22 m2)

No Asbestos

B00H - R1001 - Movement (71.8 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	72m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1112/B00H/R1001/Ceiling Structures/Linings/S39				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00H - R1002 - Staff Toilet (4.19 m2)						
Wall Linings Internal	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1112/B00H/R1002/Wall Linings Internal/S8				Chrysotile (white asbestos)		
B00H - R1003 - Entry Vestibule (11.14 m2)						
No Asbestos						
B00H - R1004 - Staff Room (28.8 m2)						
No Asbestos						
B00H - R1005 - Movement (15.35 m2)						
No Asbestos						
B00H - R1006 - Deputy Principal (12.8 m2)						
No Asbestos						
B00H - R1007 - Clerical Office (8.38 m2)						
No Asbestos						
B00H - R1008 - Distribution Board (0.65 m2)				Note: No inspection of live electrical installation.		
No Asbestos						
B00H - R1009 - Home Base (52.15 m2)						
No Asbestos						
B00H - R1010 - Practical Activities - 1hb (4.74 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
1112/B00H/R1015/Floor Coverings Res/Textile/S9				No Asbestos Detected		
B00H - R1011 - Home Base Store (3.98 m2)						
No Asbestos						
B00H - R1012 - Practical Activities - 1hb (8.95 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
1112/B00H/R1015/Floor Coverings Res/Textile/S9				No Asbestos Detected		
B00H - R1013 - Home Base (58.45 m2)						
No Asbestos						
B00H - R1014 - Home Base (88.06 m2)						
No Asbestos						
B00H - R1015 - Practical Activities - 1hb (12.63 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
1112/B00H/R1015/Floor Coverings Res/Textile/S9				No Asbestos Detected		
B00H - R1016 - Toilets - Boys/Girls (4.67 m2)						
Wall Linings Internal	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1112/B00H/R1002/Wall Linings Internal/S8				Chrysotile (white asbestos)		
Downpipe	Fibre Cement Pipe	2m	North	Good Condition (1)	Low (1)	Low Priority (2-3)
1112/B00H/R1016/Downpipe/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00H - R1017 - General Storeroom (2.35 m2)						
No Asbestos						
B00H - R1018 - Stairs (10.76 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1112/B00H/R1018/Ceiling Structures/Linings/S40				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00H - R1019 - Stairs (8.35 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - General Learning - 1975 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B001/Eaves Linings/S24					Chrysotile (white asbestos)

Interior**B001 - R0001 - Toilets - Boys (33.63 m2)**

Partition Walls (Cubicles)	Vinyl Tiles	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B001/R0001/Partition Walls (Cubicles)/S12					Chrysotile (white asbestos)

B001 - R0002 - Toilets - Girls (33.48 m2)

Partition Walls (Cubicles)	Vinyl Tiles	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B001/R0001/Partition Walls (Cubicles)/S12					Chrysotile (white asbestos)

B001 - R0004 - Home Base Store (4.68 m2)

Ceiling Structures/Linings	Vermiculite					
	1112/B001/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0005 - Home Base Store (2.72 m2)

Ceiling Structures/Linings	Vermiculite					
	1112/B001/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0006 - Toilets - Boys/Girls (3.86 m2)

Ceiling Structures/Linings	Vermiculite					
	1112/B001/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0007 - Home Base (81.8 m2)

Ceiling Structures/Linings	Vermiculite					
	1112/B001/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0008 - Practical Activities - 1hb (4.78 m2)

Ceiling Structures/Linings	Vermiculite					
	1112/B001/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Floor Coverings Res/Textile	Vinyl Tiles					
	1112/B001/R0008/Floor Coverings Res/Textile/S14					No Asbestos Detected

B001 - R0009 - Cleaning Distributed Store (3.05 m2)

No Asbestos

B001 - R0010 - Distribution Board (0.54 m2)

Note: No inspection of live electrical installation.

No Asbestos

B001 - R0011 - Home Base Store (5.67 m2)

Ceiling Structures/Linings	Vermiculite					
	1112/B001/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0012 - Home Base Store (3.92 m2)

Ceiling Structures/Linings	Vermiculite					
	1112/B001/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0013 - Home Base (52.35 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	1112/B001/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B001 - R0014 - Practical Activities - 1hb (4.94 m2)						
Ceiling Structures/Linings	Vermiculite					
	1112/B001/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles					
	1112/B001/R0008/Floor Coverings Res/Textile/S14					No Asbestos Detected
B001 - R0015 - Garden Store (5.07 m2)						
No Asbestos						
B001 - R0016 - Movement (26.6 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B001/R0016/Ceiling Structures/Linings/S41					Chrysotile (white asbestos)
B001 - R0017 - Special Programs Room (15.97 m2)						
Ceiling Structures/Linings	Vermiculite					
	1112/B001/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B001 - R0018 - Movement (40.34 m2)						
No Asbestos						
B001 - R0019 - Movement (57.04 m2)						
Wall Linings Internal	Flat AC Sheeting					
	1112/B001/R0019/Wall Linings Internal/S42					No Asbestos Detected
B001 - R0020 - Stairs (3.08 m2)						
Ceiling Structures/Linings	No Asbestos Found					
B001 - R1001 - Sick Bay (21.92 m2)						
Ceiling Structures/Linings	Vermiculite					
	1112/B001/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B001 - R1002 - Sick Bay - Shower/Toilet (2.03 m2)						
Ceiling Structures/Linings	Vermiculite					
	1112/B001/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B001 - R1004 - Home Base (51.9 m2)						
Ceiling Structures/Linings	Vermiculite					
	1112/B001/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B001 - R1005 - Practical Activities - 1hb (4.7 m2)						
Ceiling Structures/Linings	Vermiculite					
	1112/B001/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles					
	1112/B001/R0008/Floor Coverings Res/Textile/S14					No Asbestos Detected
B001 - R1006 - Home Base Store (4.14 m2)						
Ceiling Structures/Linings	Vermiculite					
	1112/B001/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B001 - R1008 - Home Base (52.67 m2)						
Ceiling Structures/Linings	Vermiculite					
	1112/B001/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00I - R1009 - Practical Activities - 1hb (4.68 m2)						
Ceiling Structures/Linings	Vermiculite					
	1112/B00I/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles					
	1112/B00I/R0008/Floor Coverings Res/Textile/S14					No Asbestos Detected
B00I - R1010 - General Storeroom (4.13 m2)						
Ceiling Structures/Linings	Vermiculite					
	1112/B00I/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00I - R1011 - Home Base Store (3.97 m2)						
Ceiling Structures/Linings	Vermiculite					
	1112/B00I/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00I - R1012 - Home Base (51.58 m2)						
Ceiling Structures/Linings	Vermiculite					
	1112/B00I/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00I - R1013 - Practical Activities - 1hb (4.98 m2)						
Ceiling Structures/Linings	Vermiculite					
	1112/B00I/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
Floor Coverings Res/Textile	Vinyl Tiles					
	1112/B00I/R0008/Floor Coverings Res/Textile/S14					No Asbestos Detected
B00I - R1014 - Distribution Board (0.55 m2)						
No Asbestos				Note: No inspection of live electrical installation.		
B00I - R1015 - General Storeroom (5.57 m2)						
Ceiling Structures/Linings	Vermiculite					
	1112/B00I/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00I - R1016 - Movement (82.99 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	76m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00I/R1016/Ceiling Structures/Linings/S43					Chrysotile (white asbestos)
B00I - R1017 - Interview (13.42 m2)						
Ceiling Structures/Linings	Vermiculite					
	1112/B00I/R1002/Ceiling Structures/Linings/S13					Limited Samples Taken
	<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>					
B00I - R1018 - Stairs (7.38 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1112/B00I/R1018/Ceiling Structures/Linings/S44					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Shed - 1997 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00K - R0001 - General Storeroom (40.22 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Communal Facilities - 2011 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior**B00L - R0001 - Communal Space (147.11 m2)**

No Asbestos

B00L - R0002 - Raised Platform (61.36 m2)

No Asbestos

B00L - R0003 - Hall Chair Store (9.49 m2)

No Asbestos

B00L - R0004 - Communal/Performance Store (9.49 m2)

No Asbestos

B00L - R0005 - P.E. Store (12.97 m2)

No Asbestos

B00L - R0006 - Toilet - Lobby (2.4 m2)

No Asbestos

B00L - R0007 - Toilets - Girls (7.19 m2)

No Asbestos

B00L - R0008 - Sound Cupboard (1.89 m2)

No Asbestos

B00L - R0009 - Toilet - Lobby (3.42 m2)

No Asbestos

B00L - R0010 - Toilets - Boys (5.8 m2)

No Asbestos

B00L - R0011 - Cleaning Distributed Store (3.61 m2)

No Asbestos

B00L - R0012 - Plant (1.65 m2)

No Asbestos

B00L - R0013 - Distribution Board (3.04 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0014 - Access Shower/Toilet/Change (7.08 m2)

No Asbestos

B00L - R0015 - Covered Outdoor Learning Area (160.99 m2)

No Asbestos

B00L - R0016 - Movement (6.35 m2)

No Asbestos

B00L - R0017 - Ramp (11.28 m2)

No Asbestos

B00L - R0018 - Movement (12.16 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 502 - D10814 - Admin Staff/Principal/Clerk/Dup/Clinic : Placement Date - 10/12/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Clerical Office

No Asbestos Found.

R10 - Store

No Asbestos Found.

R2 - Security Store

No Asbestos Found.

R3 - Duplicating Wookroom

No Asbestos Found.

R4 - Clinic-Waiting

No Asbestos Found.

R5 - Staff Room

No Asbestos Found.

R6 - Principal

No Asbestos Found.

R7 - Staff Toilet

No Asbestos Found.

R8 - Staff Toilet

No Asbestos Found.

R9 - Entry

No Asbestos Found.

OS 532 - D13327 - Library : Placement Date - 16/12/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Reading Area

No Asbestos Found.

R2 - Library Office/Workroom

No Asbestos Found.

R3 - Communications Room

No Asbestos Found.

OS 840 - D14602 - Girls Toilet : Placement Date - 14/10/2016

Exterior

No Asbestos Found.

Interior

R1 - Toilets-Girls

No Asbestos Found.

OS 532 - D14678 - Library : Placement Date - 12/12/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Exterior						
No Asbestos Found.						
Interior						
R1 - Reading Area						
No Asbestos Found.						
R2 - Library Office/Workroom						
No Asbestos Found.						
R3 - Communications Room						
No Asbestos Found.						
OS 535 - D15345 - Library/Group Study/Office/A V Store : Placement Date - 16/12/2015						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				28.8 m2
Interior						
R1 - Clerical Office						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - Staff Room						
Ceiling	Flat AC Sheet	Assumed Asbestos				36 m2
R3 - Security Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R4 - Principal						
Ceiling	Flat AC Sheet	Assumed Asbestos				16 m2
R5 - Staff Toilet						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				4 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				5 m2
R6 - Staff Toilet						
Toilet partitions	Compressed AC Sheet	Assumed Asbestos				4 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				5 m2
R7 - Reading Area						
Ceiling	Flat AC Sheet	Assumed Asbestos				90 m2
R8 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				14 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017