

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bankstown North Public School (1124)
Region : South Western Sydney
State Electorate : Bankstown
Local Government Area : Bankstown

Initial Survey : Noel Arnold & Associates : 24 - Apr - 2008
Reviewed By : Parsons Brinckerhoff : 03 - Jan - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00A - Library/Various - 1924 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 1124/B00B/Eaves Linings/S26	10m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Eaves Linings	Flat AC Sheeting 1124/B00B/Eaves Linings/S26	10m2	North, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Eaves Linings	Flat AC Sheeting 1124/B00A/Eaves Linings/S1	10m2	North, South, East, Lower portion, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
Ceiling Void	Non Accessible Area - No manhole located - suspended ceiling makes access impossible					
Underfloor Voids	No Asbestos Found					

Interior**B00A - R0001 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting 1124/B00A/R0001/Ceiling Structures/Linings/S2	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		

B00A - R0002 - Cleaning Distributed Store

No Asbestos

B00A - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 1124/B00A/R0003/Ceiling Structures/Linings/S3	37m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Vinyl Sheet 1124/B00A/R0003/Floor Coverings Res/Textile/S4					No Asbestos Detected

B00A - R0004 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 1124/B00A/R0001/Ceiling Structures/Linings/S2	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		

B00A - R0005 - Security Store

Ceiling Structures/Linings	Flat AC Sheeting 1124/B00A/R0005/Ceiling Structures/Linings/S31	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0006 - Other - D.E.T. Admin

No Asbestos

B00A - R0007 - Other - D.E.T. Admin

In-fill-panel	Flat AC Sheeting 1124/B00A/R0007/In-fill-panel/S9	5m	North, East, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		

B00A - R0008 - Special Programs Room

No Asbestos

B00A - R0009 - K.L.A. Store

No Asbestos

B00A - R0010 - Staff Toilet

Floor Coverings Res/Textile	Vinyl Sheet 1124/B00A/R0012/Floor Coverings Res/Textile/S5					No Asbestos Detected
-----------------------------	---	--	--	--	--	-----------------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting	7m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
1124/B00A/R0012/Wall Linings Internal/S6					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1124/B00A/R0010/Ceiling Structures/Linings/S7					Chrysotile (white asbestos)	
B00A - R0011 - Movement						
Floor Coverings Res/Textile	Vinyl Sheet					
1124/B00A/R0012/Floor Coverings Res/Textile/S5					No Asbestos Detected	
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1124/B00A/R0003/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R0012 - Staff Kitchen						
Floor Coverings Res/Textile	Vinyl Sheet					
1124/B00A/R0012/Floor Coverings Res/Textile/S5					No Asbestos Detected	
Wall Linings Internal	Flat AC Sheeting	7m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
1124/B00A/R0012/Wall Linings Internal/S6					Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1124/B00A/R0003/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R0015 - Movement						
Floor Coverings Res/Textile	Vinyl Sheet					
1124/B00A/R0003/Floor Coverings Res/Textile/S4					No Asbestos Detected	
B00A - R0016 - Hall Chair Store						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1124/B00A/R0003/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R0017 - General Storeroom						
No Asbestos						
B00A - R0018 - External Movement						
No Asbestos						
B00A - R0019 - Movement						
Floor Coverings Res/Textile	Vinyl Sheet					
1124/B00A/R0012/Floor Coverings Res/Textile/S5					No Asbestos Detected	
B00A - R0020 - External Movement						
No Asbestos						
B00A - R0021 - Stairs						
No Asbestos						
B00A - R0022 - Stairs						
No Asbestos						
B00A - R0023 - Reading Area						
No Asbestos						
B00A - R1001 - Other - D.E.T. Admin						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1124/B00A/R0005/Ceiling Structures/Linings/S31					Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00A - R1002 - Other - D.E.T. Admin						
No Asbestos						
B00A - R1003 - Other - D.E.T. Admin						
No Asbestos						
B00A - R1004 - Other - D.E.T. Admin						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1124/B00A/R0003/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R1005 - Other - D.E.T. Admin						
No Asbestos						
B00A - R1006 - Other - D.E.T. Admin						
No Asbestos						
B00A - R1007 - Other - D.E.T. Admin						
No Asbestos						
B00A - R1008 - Other - D.E.T. Admin						
No Asbestos						
B00A - R1009 - Other - D.E.T. Admin						
No Asbestos						
B00A - R1010 - Other - D.E.T. Admin						
Wall Linings Internal	Flat AC Sheeting		1124/B00A/R1012/Wall Linings Internal/S8			No Asbestos Detected
B00A - R1011 - Other - D.E.T. Admin						
Wall Linings Internal	Flat AC Sheeting		1124/B00A/R1012/Wall Linings Internal/S8			No Asbestos Detected
B00A - R1012 - Other - D.E.T. Admin						
Wall Linings Internal	Flat AC Sheeting		1124/B00A/R1012/Wall Linings Internal/S8			No Asbestos Detected
B00A - R1013 - Other - D.E.T. Admin						
Wall Linings Internal	Flat AC Sheeting		1124/B00A/R1012/Wall Linings Internal/S8			No Asbestos Detected
B00A - R1014 - Other - D.E.T. Admin						
No Asbestos						
B00A - R1015 - Other - D.E.T. Admin						
No Asbestos						
B00A - R1016 - Other - D.E.T. Admin						
No Asbestos						
B00A - R1017 - Other - D.E.T. Admin						
No Asbestos						
B00A - R1018 - Other - D.E.T. Admin						
No Asbestos						
B00A - R1021 - Stairs						
No Asbestos						
B00A - R1022 - Clerical Office						
No Asbestos						
B00A - R1023 - Entry Vestibule						
No Asbestos						
B00A - R1024 - Stairs						
No Asbestos						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Special Purpose - 1959 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	24m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1124/B00B/Eaves Linings/S26				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Gable Verge Lining	Flat AC Sheeting	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1124/B00B/Gable Verge Lining/S27				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Void	No Asbestos Found					
Underfloor Voids	Flat AC Sheeting					
	1124/B00B/Underfloor Voids/S30				No Asbestos Detected	

Interior

B00B - R0002 - Movement

Floor Coverings Res/Textile	Vinyl Sheet					
	1124/B00B/R0003/Floor Coverings Res/Textile/S13				No Asbestos Detected	

B00B - R0003 - Cleaning Distributed Store

No Asbestos

B00B - R0004 - Music Store

No Asbestos

B00B - R0005 - Cleaning Distributed Store

No Asbestos

B00B - R0006 - Home Base

Floor Coverings Res/Textile	Vinyl Tiles	3m2	South-East adjacent to sink	Good Condition (1)	Low (1)	Low Priority (2-3)
	1124/B00B/R0006/Floor Coverings Res/Textile/S11				Chrysotile (white asbestos)	

B00B - R0007 - Communal/Performance Store

No Asbestos

B00B - R0008 - Home Base

Wall Linings Internal	Flat AC Sheeting adjacent to heater	2m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1124/B00B/R0008/Wall Linings Internal/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Structures/Linings	Vinyl Tiles	4m2	South, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	1124/B00B/R0006/Floor Coverings Res/Textile/S11				Chrysotile (white asbestos)	

B00B - R0009 - Hall Chair Store

No Asbestos

B00B - R0010 - Movement

Floor Coverings Res/Textile	Vinyl Sheet					
	1124/B00B/R0003/Floor Coverings Res/Textile/S13				No Asbestos Detected	

B00B - R0011 - General Storeroom

No Asbestos

B00B - R0012 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	1124/B00B/R0001/Ceiling Structures/Linings/S10				No Asbestos Detected	

B00B - R0013 - Staff Room

No Asbestos

B00B - R0014 - Staff Toilet

No Asbestos

B00B - R0015 - K.L.A. Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0016 - Staff Room Annexe						
No Asbestos						
B00B - R0017 - Staff Kitchen						
Floor Coverings Res/Textile	Vinyl Sheet					
1124/B00B/R0017/Floor Coverings Res/Textile/S23					No Asbestos Detected	
B00B - R0018 - Movement						
No Asbestos						
B00B - R0019 - General Storeroom						
No Asbestos						
B00B - R0020 - No Access						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1124/B00B/R0020/Ceiling Structures/Linings/S32					Chrysotile (white asbestos)	
B00B - R0021 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1955 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00C - R0001 - Cleaning Distributed Store

No Asbestos

B00C - R0002 - Movement

No Asbestos

B00C - R0003 - Toilets - Girls

No Asbestos

B00C - R0004 - Handwashing Facilities

No Asbestos

B00C - R0005 - Cleaning Distributed Store

No Asbestos

B00C - R0006 - Movement

No Asbestos

B00C - R0007 - Toilets - Boys

No Asbestos

B00C - R0009 - Disabled Shower/Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 2006 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00D - R0001 - Movement

No Asbestos

B00D - R0002 - Practical Activities - 1hb

No Asbestos

B00D - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 1953 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids	Flat AC Sheeting	1m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	1124/B00I/Underfloor Voids/S28					Chrysotile (white asbestos)
Ceiling Void	No Asbestos Found					

Interior**B00I - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1124/B00I/R0001/Ceiling Structures/Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00I - R0002 - Staff Toilet

No Asbestos

B00I - R0003 - Handwashing Facilities

No Asbestos

B00I - R0004 - Home Base

No Asbestos

B00I - R0005 - Security Store

No Asbestos

B00I - R0006 - Home Base

No Asbestos

B00I - R0007 - Home Base

No Asbestos

B00I - R0008 - Home Base

No Asbestos

B00I - R0009 - Withdrawal Space - 1hb

No Asbestos

B00I - R0010 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles					
	1124/B00I/R0014/Floor Coverings Res/Textile/S14					No Asbestos Detected

B00I - R0011 - Staff Toilet

No Asbestos

B00I - R0012 - General Storeroom

No Asbestos

B00I - R0013 - K.L.A. Store

No Asbestos

B00I - R0014 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Tiles					
	1124/B00I/R0014/Floor Coverings Res/Textile/S14					No Asbestos Detected

B00I - R0015 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles					
	1124/B00I/R0014/Floor Coverings Res/Textile/S14					No Asbestos Detected

B00I - R0016 - Movement

No Asbestos

B00I - R0017 - Raised Platform

No Asbestos

B00I - R0018 - External Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1124/B001/R0001/Ceiling Structures/Linings/S15				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B001 - R0019 - External Movement

No Asbestos

B001 - R0020 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Building Services - 1953 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Void	AC Fragments/Debris	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	1124/B00J/Ceiling Void/S29					Chrysotile (white asbestos)

Interior**B00J - R0001 - Garden Store**

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1124/B00J/R0001/Ceiling Structures/Linings/S22					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00J - R0002 - Hall Chair Store

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1124/B00J/R0001/Ceiling Structures/Linings/S22					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00J - R0003 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1124/B00J/R0001/Ceiling Structures/Linings/S22					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00J - R0004 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1124/B00J/R0001/Ceiling Structures/Linings/S22					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00J - R0005 - Garden Store

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1124/B00J/R0005/Ceiling Structures/Linings/S33					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00J - R0006 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1124/B00J/R0001/Ceiling Structures/Linings/S22					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00J - R0007 - Hall Chair Store

Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1124/B00J/R0001/Ceiling Structures/Linings/S22					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00J - R0008 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1124/B00J/R0001/Ceiling Structures/Linings/S22					Chrysotile (white asbestos) , Amosite (brown asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Other-Regional Use - 1955 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00K - R0001 - Other - Regional Use

No Asbestos

B00K - R0002 - Other - Regional Use

No Asbestos

B00K - R0003 - Other - Regional Use

No Asbestos

B00K - R0004 - Other - Regional Use

No Asbestos

B00K - R0005 - Other - Regional Use

No Asbestos

B00K - R0006 - Other - Regional Use

No Asbestos

B00K - R0007 - Other - Regional Use

Floor Coverings Res/Textile	Vinyl Tiles					
		1124/B00K/R0007/Floor Coverings Res/Textile/S24				No Asbestos Detected

B00K - R0008 - Other - Regional Use

Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
		1124/B00K/R0009/Wall Linings Internal/S25				Chrysotile (white asbestos)

B00K - R0009 - Other - Regional Use

Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
		1124/B00K/R0009/Wall Linings Internal/S25				Chrysotile (white asbestos)

B00K - R0010 - Other - Regional Use

Floor Coverings Res/Textile	Vinyl Tiles					
		1124/B00K/R0007/Floor Coverings Res/Textile/S24				No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Other-Commercial - 1955 - Steel (Steel)**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00M - R0001 - Other-Commercial**

No Asbestos

B00M - R0002 - Other-Commercial

Floor Coverings Res/Textile	Vinyl Sheet	1124/B00M/R0004/Floor Coverings Res/Textile/S20	No Asbestos Detected
-----------------------------	-------------	---	----------------------

B00M - R0003 - Other-Commercial

Floor Coverings Res/Textile	Vinyl Sheet	1124/B00M/R0004/Floor Coverings Res/Textile/S20	No Asbestos Detected
-----------------------------	-------------	---	----------------------

B00M - R0004 - No Access

Floor Coverings Res/Textile	Vinyl Sheet	1124/B00M/R0004/Floor Coverings Res/Textile/S20	No Asbestos Detected
-----------------------------	-------------	---	----------------------

B00M - R0005 - Other-Commercial

Floor Coverings Res/Textile	Vinyl Sheet	1124/B00M/R0004/Floor Coverings Res/Textile/S20	No Asbestos Detected
-----------------------------	-------------	---	----------------------

B00M - R0006 - Other-Commercial

Floor Coverings Res/Textile	Vinyl Sheet	1124/B00M/R0004/Floor Coverings Res/Textile/S20	No Asbestos Detected
-----------------------------	-------------	---	----------------------

B00M - R0007 - Other-Commercial

Floor Coverings Res/Textile	Vinyl Sheet	1124/B00M/R0004/Floor Coverings Res/Textile/S20	No Asbestos Detected
-----------------------------	-------------	---	----------------------

B00M - R0008 - Other-Commercial

Floor Coverings Res/Textile	Vinyl Sheet	1124/B00M/R0004/Floor Coverings Res/Textile/S20	No Asbestos Detected
-----------------------------	-------------	---	----------------------

B00M - R0009 - Other-Commercial

Floor Coverings Res/Textile	Vinyl Sheet	1124/B00M/R0004/Floor Coverings Res/Textile/S20	No Asbestos Detected
-----------------------------	-------------	---	----------------------

B00M - R0010 - Other-Commercial

Floor Coverings Res/Textile	Vinyl Sheet	1124/B00M/R0004/Floor Coverings Res/Textile/S20	No Asbestos Detected
-----------------------------	-------------	---	----------------------

B00M - R0011 - Other-Commercial

No Asbestos

B00M - R0012 - Other-Commercial

No Asbestos

B00M - R0013 - Other-Commercial

Floor Coverings Res/Textile	Vinyl Sheet	1124/B00M/R0004/Floor Coverings Res/Textile/S20	No Asbestos Detected
-----------------------------	-------------	---	----------------------

B00M - R0014 - Other-Commercial

Floor Coverings Res/Textile	Vinyl Sheet	1124/B00M/R0004/Floor Coverings Res/Textile/S20	No Asbestos Detected
-----------------------------	-------------	---	----------------------

B00M - R0015 - Other-Commercial

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting		1124/B00M/R0015/Wall Linings Internal/S19			No Asbestos Detected
B00M - R0016 - Other-Commercial						
Ceiling Structures/Linings	Flat AC Sheeting		1124/B00M/R0016/Ceiling Structures/Linings/S18			No Asbestos Detected
B00M - R0017 - Other-Commercial						
Ceiling Structures/Linings	Flat AC Sheeting		1124/B00M/R0017/Ceiling Structures/Linings/S21			No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Multi Purpose Facilities - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00N - R0001 - Communal Space**

No Asbestos

B00N - R0002 - Raised Platform

No Asbestos

B00N - R0003 - Movement

No Asbestos

B00N - R0004 - Ramp

No Asbestos

B00N - R0005 - Hall Chair Store

No Asbestos

B00N - R0006 - Communal/Performance Store

No Asbestos

B00N - R0007 - P.E. Store

No Asbestos

B00N - R0008 - Toilet - Lobby

No Asbestos

B00N - R0009 - Toilets - Girls

No Asbestos

B00N - R0010 - Sound Cupboard

No Asbestos

B00N - R0011 - Toilet - Lobby

No Asbestos

B00N - R0012 - Toilets - Boys

No Asbestos

B00N - R0013 - Cleaning Distributed Store

No Asbestos

B00N - R0014 - Plant

No Asbestos

B00N - R0015 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00N - R0016 - Access Shower/Toilet/Change

No Asbestos

B00N - R0017 - Covered Outdoor Learning Area

No Asbestos

B00N - R0018 - Canteen

No Asbestos

B00N - R0019 - Canteen Office/Store

No Asbestos

B00N - R0020 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

NS 101 - D11072 - Learning Unit - Double Primary/PAA : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Home Base

No Asbestos Found.

R3 - Entry

No Asbestos Found.

R4 - Practical Activity Area

No Asbestos Found.

R5 - Home Base Store

No Asbestos Found.

R6 - Practical Activity Area

No Asbestos Found.

R7 - Entry

No Asbestos Found.

NS 100 - D11377 - Learning Unit - Single Primary/PAA : Placement Date - 14/08/2008

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.

OS 601 - D11532 - Learning Unit - Standard/Withdrawal : Placement Date - 5/04/2002

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
OS 601 - D13994 - Learning Unit - Standard/Withdrawal : Placement Date - 17/02/2003						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
NS 250 - D15125 - Learning Unit - Single E.S.L./Store : Placement Date - 30/06/1995						
Exterior						
No Asbestos Found.						
Interior						
R1 - Esl						
No Asbestos Found.						
R2 - Store						
No Asbestos Found.						
R3 - Entry						
No Asbestos Found.						
NS 110 - D15243 - Learning Unit - Single Secondary/Secure : Placement Date - 30/06/1995						
Exterior						
No Asbestos Found.						
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - Entry						
No Asbestos Found.						
R3 - Secure Storeroom						
No Asbestos Found.						
OS 602 - D15583 - Learning Unit - Standard With P.A.A. : Placement Date - 1/12/2011						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
NS 002 - D15886 - Admin 14 Principal/Deputy/Dup/Work : Placement Date - 30/06/1995						
Exterior						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Deputy Principal						
No Asbestos Found.						
R10 - Staff Room						
No Asbestos Found.						
R11 - Cleaning Supplies						
No Asbestos Found.						
R12 - Duplicating Workroom						
No Asbestos Found.						
R13 - Clerical Office						
No Asbestos Found.						
R2 - Principal						
No Asbestos Found.						
R3 - Security Store						
No Asbestos Found.						
R4 - Staff Toilet						
No Asbestos Found.						
R5 - Staff Toilet						
No Asbestos Found.						
R6 - Sick Bay						
No Asbestos Found.						
R7 - Principal						
No Asbestos Found.						
R8 - Entry						
No Asbestos Found.						
R9 - Entry Vestibule						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

1124_ASB_261112_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017