

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Barham Public School (1135)
Region : Riverina
State Electorate : Murray
Local Government Area : Wakool

Initial Survey : Noel Arnold & Associates : 15 - Feb - 2017
Reviewed By : Parsons Brinckerhoff : 15 - Feb - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Administration - 1972 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Vermiculite 1135/B00A/R0009/Ceiling Structures/Linings/S11					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>

Interior**B00A - R0001 - Principal (23.46 m2)**

Ceiling Structures/Linings	Vermiculite 1135/B00A/R0009/Ceiling Structures/Linings/S11					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	---	--	--	--	--	--

B00A - R0002 - Clerical Office (12.92 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00A/R0009/Ceiling Structures/Linings/S11					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	---	--	--	--	--	--

B00A - R0003 - Movement (12.63 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00A/R0009/Ceiling Structures/Linings/S11					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	---	--	--	--	--	--

B00A - R0004 - Home Base (57.08 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00A/R0009/Ceiling Structures/Linings/S11					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	---	--	--	--	--	--

B00A - R0005 - Home Base Store (6.04 m2)

Ceiling Structures/Linings	No Asbestos Found					
----------------------------	-------------------	--	--	--	--	--

B00A - R0006 - Distribution Board (6.04 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	No Asbestos Found					
----------------------------	-------------------	--	--	--	--	--

B00A - R0007 - Personal Effects Storage (15.26 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00A/R0009/Ceiling Structures/Linings/S11					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	---	--	--	--	--	--

B00A - R0008 - Staff Room Annexe (29.13 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00A/R0009/Ceiling Structures/Linings/S11					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	---	--	--	--	--	--

B00A - R0009 - Movement (91.2 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00A/R0009/Ceiling Structures/Linings/S11					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	---	--	--	--	--	--

B00A - R0010 - Staff Toilet (7.2 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00A/R0009/Ceiling Structures/Linings/S11					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	---	--	--	--	--	--

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1972 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Vermiculite 1135/B00B/R0001/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>

Interior**B00B - R0001 - Movement (53.93 m2)**

Ceiling Structures/Linings	Vermiculite 1135/B00B/R0001/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	--

B00B - R0002 - Personal Effects Storage (7.47 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00B/R0001/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
Floor Coverings Res/Textile	Vinyl Tiles 1135/B00B/R0002/Floor Coverings Res/Textile/S4	8m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3) <i>Chrysotile (white asbestos)</i>

B00B - R0003 - Home Base Store (3.48 m2)

Non Accessible

B00B - R0004 - Toilets - Boys/Girls (3.7 m2)

Ceiling Structures/Linings No Asbestos Found

B00B - R0005 - Home Base (85.16 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00B/R0001/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	--

B00B - R0006 - Home Base (56.6 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00B/R0001/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	--

B00B - R0007 - Home Base Store (6.19 m2)

Ceiling Structures/Linings No Asbestos Found

B00B - R0008 - Personal Effects Storage (8.65 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00B/R0001/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Library - 1972 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Vermiculite 1135/B00C/R0005/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>

Interior**B00C - R0001 - Movement (46.45 m2)**

Ceiling Structures/Linings	Vermiculite 1135/B00C/R0005/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	--

B00C - R0002 - Home Base (58.12 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00C/R0005/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	--

B00C - R0003 - General Storeroom (5.71 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00C/R0005/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	--

B00C - R0004 - Staff Toilet (5.66 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00C/R0005/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	--

B00C - R0005 - Movement (15.83 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00C/R0005/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	--

B00C - R0006 - Staff Room Annexe (27.75 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00C/R0005/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	--

B00C - R0007 - Distribution Board (0.43 m2)

No Asbestos						Note: No inspection of live electrical installation.
-------------	--	--	--	--	--	--

B00C - R0008 - Staff Toilet (5.2 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00C/R0005/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	--

B00C - R0009 - Movement (14.96 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00C/R0005/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	--

B00C - R0010 - Stairs (7.63 m2)

No Asbestos						
-------------	--	--	--	--	--	--

B00C - R1002 - Reading Area (90.65 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00C/R0005/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	--

B00C - R1003 - Library Office/Workroom (10.22 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00C/R0005/Ceiling Structures/Linings/S5					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	--

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R1004 - General Storeroom (14.84 m2)						
Ceiling Structures/Linings	Vermiculite		1135/B00C/R0005/Ceiling Structures/Linings/S5			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1005 - Cleaning Distributed Store (0.41 m2)						
No Asbestos						
B00C - R1006 - Movement (11.87 m2)						
Ceiling Structures/Linings	Vermiculite		1135/B00C/R0005/Ceiling Structures/Linings/S5			Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00C - R1007 - Stairs (15.35 m2)						
No Asbestos						
B00C - R1008 - Movement (28.85 m2)						
No Asbestos						
B00C - R1009 - Library Office/Workroom (19.86 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1972 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Vermiculite 1135/B00B/R0001/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>

Interior**B00D - R0001 - Movement (61.83 m2)**

Ceiling Structures/Linings	Vermiculite 1135/B00B/R0001/Ceiling Structures/Linings/S1					Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>
----------------------------	--	--	--	--	--	--

B00D - R0002 - General Storeroom (3.16 m2)

Ceiling Structures/Linings	No Asbestos Found					
----------------------------	-------------------	--	--	--	--	--

B00D - R0003 - Toilets - Boys (47.92 m2)

Ceiling Structures/Linings	No Asbestos Found					
----------------------------	-------------------	--	--	--	--	--

B00D - R0004 - Plant (5.16 m2)

Non Accessible						
----------------	--	--	--	--	--	--

B00D - R0006 - Cleaning Distributed Store (3.16 m2)

Ceiling Structures/Linings	No Asbestos Found					
----------------------------	-------------------	--	--	--	--	--

B00D - R0007 - Toilets - Girls (34.96 m2)

No Asbestos						
-------------	--	--	--	--	--	--

B00D - R0008 - Disabled Toilet (10.11 m2)

No Asbestos						
-------------	--	--	--	--	--	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1972 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Vermiculite 1135/B00B/R0001/Ceiling Structures/Linings/S1	Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>				
Ceiling Voids	AC Fragments/Debris	1m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	1135/B00E/Ceiling Voids/S12	Chrysotile (white asbestos)				

Interior

B00E - R0001 - Movement (24.31 m2)

No Asbestos

B00E - R0002 - Toilets - Girls (31.87 m2)

Ceiling Structures/Linings No Asbestos Found

B00E - R0003 - Toilets - Boys (31.27 m2)

Ceiling Structures/Linings No Asbestos Found

B00E - R0004 - General Storeroom (3.4 m2)

Ceiling Structures/Linings No Asbestos Found

B00E - R0005 - Cleaning Distributed Store (2.98 m2)

Partition Walls (Cubicles) No Asbestos Found

Ceiling Structures/Linings No Asbestos Found

B00E - R0006 - Movement (59.51 m2)

Ceiling Structures/Linings	Vermiculite 1135/B00B/R0001/Ceiling Structures/Linings/S1	Limited Samples Taken <i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>				
----------------------------	--	---	--	--	--	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1925 - Timber (Timber)**Exterior**

Underfloor Voids - Packing to Floor Joists
No Asbestos Found

Ceiling Voids - Raked Ceiling
No Asbestos Found

Interior**B00F - R0001 - Movement (68.09 m2)**

No Asbestos

B00F - R0002 - Home Base Store (10.46 m2)

No Asbestos

B00F - R0003 - Staff Room Annexe (5.65 m2)

No Asbestos

B00F - R0004 - Home Base (67.02 m2)

Wall Linings Internal	Flat AC Sheeting	45m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	1135/B00F/R0004/Wall Linings Internal/S2					Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting	60m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Not able to be sampled due to ceiling					

B00F - R0005 - Home Base (72.66 m2)

In-fill-panel	Flat AC Sheeting	1m2	Under heater	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	1135/B00F/R0005/Panel under heater/S3					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting	4m2	Behind heater	Good Condition (1)	Low (1)	Low Priority (2-3)
	1135/B00F/R0005/Panel under heater/S3					Chrysotile (white asbestos)

B00F - R0006 - Home Base (45.48 m2)

In-fill-panel	Flat AC Sheeting	2m2	Behind Heater	Good Condition (1)	Low (1)	Low Priority (2-3)
	1135/B00F/R0005/Panel under heater/S3					Chrysotile (white asbestos)

B00F - R0007 - Home Base (45.35 m2)

In-fill-panel	Compressed AC Sheet	2m2	Behind Heaters	Good Condition (1)	Low (1)	Low Priority (2-3)
	1135/B00F/R0005/Panel under heater/S3					Chrysotile (white asbestos)

B00F - R0008 - Sports Store (8.51 m2)

No Asbestos

B00F - R0012 - Movement (11.54 m2)

No Asbestos

B00F - R0013 - Practical Activities (15.75 m2)

No Asbestos

B00F - R0014 - Staff Toilet (2.87 m2)

No Asbestos

B00F - R0015 - General Storeroom (13.13 m2)

No Asbestos

B00F - R0016 - Home Base Store (9.98 m2)

No Asbestos

B00F - R0017 - Practical Activities (13.46 m2)

No Asbestos

B00F - R0018 - Practical Activities (16.64 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R0019 - Home Base Store (5.81 m2)						
No Asbestos						
B00F - R0020 - Special Programs Room (30.44 m2)						
No Asbestos						
B00F - R0021 - Movement (21.86 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00G - Special Purpose - 1940 - Timber (Timber)**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1135/B00G/R0005/Ceiling Structures/Linings/S6			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior**B00G - R0001 - Movement (14.19 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1135/B00G/R0005/Ceiling Structures/Linings/S6			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Floor Coverings Res/Textile	Compressed AC Sheet					
	1135/B00G/R0001/Floor Coverings Res/Textile/S9			No Asbestos Detected		

B00G - R0002 - Special Programs Room (41.35 m2)

Ceiling Structures/Linings	Flat AC Sheeting	42m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1135/B00G/R0005/Ceiling Structures/Linings/S6			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting	65m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	1135/B00G/R0002/Wall Linings Internal/S8			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00G - R0003 - General Storeroom (4.35 m2)

Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1135/B00G/R0005/Ceiling Structures/Linings/S6			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00G - R0004 - Craft Store (6.31 m2)

Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1135/B00G/R0005/Ceiling Structures/Linings/S6			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Floor Coverings Res/Textile	Vinyl Tiles					
	1135/B00G/R0005/Floor Coverings Res/Textile/S7			No Asbestos Detected		

B00G - R0005 - General Storeroom (5.49 m2)

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1135/B00G/R0005/Ceiling Structures/Linings/S6			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Floor Coverings Res/Textile	Vinyl Tiles					
	1135/B00G/R0005/Floor Coverings Res/Textile/S7			No Asbestos Detected		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1940 - Timber (Timber)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1135/B00H/R0001/Wall Linings Internal/S10			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Underfloor Voids	AC Fragments/Debris	2m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	1135/B00H/Underfloor Voids/S13			Chrysotile (white asbestos)		

Interior

B00H - R0002 - Withdrawal Space - 1hb (14.77 m2)

No Asbestos

B00H - R0003 - General Storeroom (10.81 m2)

No Asbestos

B00H - R0004 - Home Base (53.12 m2)

No Asbestos

B00H - R0006 - General Storeroom (6.21 m2)

No Asbestos

B00H - R0007 - Home Base (27.26 m2)

No Asbestos

B00H - R0008 - General Storeroom (25.43 m2)

No Asbestos

B00H - R0009 - General Storeroom (5.91 m2)

No Asbestos

B00H - R0010 - Movement (26.36 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 2011 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00I - R0001 - Home Base (59.69 m2)**

No Asbestos

B00I - R0002 - Home Base Store (6.22 m2)

No Asbestos

B00I - R0003 - Practical Activities (18.78 m2)

No Asbestos

B00I - R0004 - Withdrawal Space - 2hb (11.47 m2)

No Asbestos

B00I - R0005 - Practical Activities (18.89 m2)

No Asbestos

B00I - R0006 - Home Base (59.9 m2)

No Asbestos

B00I - R0007 - Home Base Store (6.26 m2)

No Asbestos

B00I - R0008 - Special Programs Room (38.53 m2)

No Asbestos

B00I - R0009 - Special Programs Store (5.48 m2)

No Asbestos

B00I - R0010 - Special Programs Store (6.84 m2)

No Asbestos

B00I - R0011 - External Movement (55.56 m2)

No Asbestos

B00I - R0012 - Distribution Board (0.51 m2)

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Building Services - 2009 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00J - R0001 - Garden Store (9.18 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Building Services - 2009 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00K - R0001 - General Assistant/Bulk Store (23.55 m2)

No Asbestos

B00K - R0002 - Sports Store (54.95 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Agricultural Science - 2013 - Greenhouse (Greenhouse)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00L - R0001 - Plant Space (17.75 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Storage - 1990 - Metal Shed (Metal Shed)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00M - R0001 - Garden Store (8.7 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017