


Asbestos Register

(Hazardous Materials and Risk Assessment)



School : Barkers Vale Public School (1136)
Region : North Coast
State Electorate : Lismore
Local Government Area : Kyogle

Initial Survey : Noel Arnold & Associates : 10 - Jun - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1991 - Timber (Timber)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - General Storeroom**

No Asbestos

B00A - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0003 - Practical Activities - 1hb

No Asbestos

B00A - R0004 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0005 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0006 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0007 - Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0008 - Home Base

No Asbestos

B00A - R0009 - Practical Activities - 1hb

No Asbestos

B00A - R0010 - Home Base

No Asbestos

B00A - R0011 - Home Base

No Asbestos

B00A - R0012 - Movement

No Asbestos

B00A - R0013 - Movement

No Asbestos

B00A - R0014 - Movement

No Asbestos

B00A - R9001 - Movement

No Asbestos

B00A - R9002 - Security Store

No Asbestos

B00A - R9003 - Movement

No Asbestos

B00A - R9004 - Movement

No Asbestos

B00A - R9005 - Toilets - Boys

No Asbestos

B00A - R9006 - Toilets - Girls

No Asbestos

B00A - R9007 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library/Staff Facilities - 1933 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	------------	--------------------	---------	--------------------

Assumed Asbestos

Ceiling Voids	Requires Inspection
---------------	---------------------

Underfloor Voids	Requires Inspection
------------------	---------------------

Interior**B00B - R0001 - Movement**

No Asbestos

B00B - R0002 - Home Base

No Asbestos

B00B - R0003 - Practical Activities - 1hb

No Asbestos

B00B - R0004 - Home Base Store

Ceiling Structures/Linings	Flat AC Sheeting	12m2	North, Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	-------------------	--------------------	---------	--------------------

1136/B00B/R0004/Ceiling Structures/Linings/S1

Chrysotile (white asbestos)**B00B - R0005 - Withdrawal Space - 1hb**

No Asbestos

B00B - R0006 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Communal Facilities - 1991 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	6m2	East, Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Requires Inspection					

Interior

B00C - R0001 - Library Office/Workroom

No Asbestos

B00C - R0003 - Movement

No Asbestos

B00C - R0004 - Library Office/Workroom

No Asbestos

B00C - R0005 - Communal Space

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1991 - Timber (Timber)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00D - R0001 - P.E. Store**

No Asbestos

B00D - R0002 - Practical Activities - 1hb

No Asbestos

B00D - R0003 - Movement

No Asbestos

B00D - R0004 - Cleaning Distributed Store

No Asbestos

B00D - R0005 - Home Base Store

No Asbestos

B00D - R0006 - Toilets - Boys

No Asbestos

B00D - R0007 - Toilets - Girls

No Asbestos

B00D - R0008 - Staff Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Shed - 1988 - Sandstone (Sandstone)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Canteen

No Asbestos

B00E - R0002 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1991 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - Canteen

No Asbestos

B00F - R0002 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities/Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Canteen

No Asbestos

B00G - R0002 - Canteen Office/Store

No Asbestos

B00G - R0003 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Other - 2009 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017