

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Barmedman Public School (1137)
Region : Riverina
State Electorate : Cootamundra
Local Government Area : Bland

Initial Survey : Noel Arnold & Associates : 09 - May - 2008
Reviewed By : Greencap-NAA : 15 - Jun - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1935 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	Non Accessible Area - Height Restriction 4m height
Underfloor Voids	Non Accessible Area - Area inaccessible

Interior**B00A - R0003 - Home Base**

No Asbestos

B00A - R0004 - Home Base

No Asbestos

B00A - R0005 - Principal

Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1137/B00A/R0008/Ceiling Structures/Linings/S6				Chrysotile (white asbestos)	
infill panel behind heater	Flat AC Sheeting	1m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	1137/B00A/R0008/Ceiling Structures/Linings/S6				Chrysotile (white asbestos)	

B00A - R0006 - Clerical Office

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1137/B00A/R0008/Ceiling Structures/Linings/S6				Chrysotile (white asbestos)	

B00A - R0007 - Movement

No Asbestos

B00A - R0008 - Staff Kitchen

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1137/B00A/R0008/Ceiling Structures/Linings/S6				Chrysotile (white asbestos)	

B00A - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	37m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1137/B00A/R0008/Ceiling Structures/Linings/S6				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1935 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids	Non Accessible Area - Height Restriction 4m height					
Eaves Linings	Flat AC Sheeting 1137/B00B/Eaves Linings/S9					No Asbestos Detected
Electrical Backing Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)

Assumed Asbestos - Electrical Hazard

Interior

B00B - R0001 - Sports Store

No Asbestos

B00B - R0002 - Cleaning Supplies

No Asbestos

B00B - R0003 - Home Base

Floor Coverings Res/Textile	Vinyl sheet under carpet 1137/B00B/R0003/Floor Coverings Res/Textile/S7					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive 1137/B00B/R0003/Floor Coverings Res/Textile/S8					No Asbestos Detected

B00B - R0004 - Withdrawal Space - 1hb

No Asbestos

B00B - R0005 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Library - 1900 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1137/B00C/R0001/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	
Ceiling Voids	Non Accessible Area - Height Restriction 4m height					
Underfloor Voids	No Asbestos Found					

Interior**B00C - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	27m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1137/B00C/R0001/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

B00C - R0002 - Darkroom Space

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1137/B00C/R0001/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

B00C - R0003 - Reading Area

Heater Surround	Flat AC Sheeting	4m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	1137/B00C/R0003/Heater Surround/S10				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1930 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground Non Accessible Area

- Area inaccessible

Ceiling Voids No Asbestos Found

Interior**B00D - R0001 - Movement**

Ceiling Structures/Linings Flat AC Sheeting 20m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

1137/B00D/R0001/Ceiling Structures/Linings/S1

Chrysotile (white asbestos)

Window In-fill-panel Flat AC Sheeting 2m2 North facing Good Condition (1) Low (1) Low Priority (2-3)

1137/B00D/R0001/Ceiling Structures/Linings/S1

Chrysotile (white asbestos)

B00D - R0002 - Toilets - Boys

Ceiling Structures/Linings Flat AC Sheeting 13m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

1137/B00D/R0001/Ceiling Structures/Linings/S1

Chrysotile (white asbestos)

Partition Walls (Cubicles) Compressed AC Sheet

1137/B00D/R0002/Partition Walls (Cubicles)/S2

No Asbestos Detected

B00D - R0003 - Toilets - Girls

Ceiling Structures/Linings Flat AC Sheeting 13m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

1137/B00D/R0001/Ceiling Structures/Linings/S1

Chrysotile (white asbestos)

Partition Walls (Cubicles) Compressed AC Sheet

1137/B00D/R0002/Partition Walls (Cubicles)/S2

No Asbestos Detected

B00D - R0004 - Staff Toilet

Ceiling Structures/Linings Flat AC Sheeting 4m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

1137/B00D/R0001/Ceiling Structures/Linings/S1

Chrysotile (white asbestos)

Incinerator Encapsulated Insulation material within unit

1Unit(s) North

Friable Asbestos (5)

Low (1) Low Priority (2-3)

Assumed Asbestos - Live services/inaccessible

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Communal Facilities - 1935 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Gable Ends	Flat AC Sheeting 1137/B00F/Gable Ends/S3	4m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					

Interior

B00F - R0001 - Drinking Facilities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Building Services - 1950 - Timber Shed (Timber Shed)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B00G - R0001 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017