


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Batemans Bay Public School (1149)
Region : Illawarra and South East
State Electorate : Bega
Local Government Area : Eurobodalla

Initial Survey : Noel Arnold & Associates : 08 - May - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00M - General Learning - 2011 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00M - R0001 - Practical Activities - 1hb**

No Asbestos

B00M - R0002 - Special Programs Room

No Asbestos

B00M - R0003 - Staff Kitchen

No Asbestos

B00M - R0004 - Access Shower/Toilet

No Asbestos

B00M - R0005 - Withdrawal Space - 1hb

No Asbestos

B00M - R0006 - General Storeroom

No Asbestos

B00M - R0007 - General Storeroom

No Asbestos

B00M - R0008 - Home Base Store

No Asbestos

B00M - R0009 - Home Base

No Asbestos

B00M - R0010 - Practical Activities - 1hb

No Asbestos

B00M - R0011 - Withdrawal Space - 2hb

No Asbestos

B00M - R0012 - Home Base

No Asbestos

B00M - R0013 - Practical Activities - 1hb

No Asbestos

B00M - R0014 - Home Base Store

No Asbestos

B00M - R0015 - Home Base Store

No Asbestos

B00M - R0016 - Home Base

No Asbestos

B00M - R0017 - Practical Activities - 1hb

No Asbestos

B00M - R0018 - Withdrawal Space - 2hb

No Asbestos

B00M - R0019 - Home Base

No Asbestos

B00M - R0020 - Practical Activities - 1hb

No Asbestos

B00M - R0021 - Home Base Store

No Asbestos

B00M - R0022 - Special Programs Room

No Asbestos

B00M - R0023 - Special Programs Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00M - R0024 - Communications Room

No Asbestos

B00M - R0026 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Storage - 2010 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00N - R0001 - Other

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Storage - 2010 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B000 - R0001 - Other

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Storage - 2010 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00P - R0001 - Other

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0AA - Administration/Staff Facilities - 2002 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B0AA - R0002 - Main Switch Board**

No Asbestos

B0AA - R0003 - Cleaning Distributed Store

No Asbestos

B0AA - R0007 - Security Store

No Asbestos

B0AA - R0008 - PrincipalVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0AA - R0009 - Duplicating Workroom**

No Asbestos

B0AA - R0010 - Entry VestibuleVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0AA - R0011 - Clerical Office**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0AA - R0012 - Sick Bay**

No Asbestos

B0AA - R0013 - Access Shower/Toilet

No Asbestos

B0AA - R0014 - InterviewVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0AA - R0015 - Deputy Principal**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0AA - R0016 - Deputy Principal**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0AA - R0017 - Movement**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0AA - R0018 - External Movement**

No Asbestos

B0AA - R0019 - Staff Room AnnexeVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0AA - R0020 - Staff Room**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0AA - R0021 - Staff Kitchen**

No Asbestos

B0AA - R0022 - Toilet - Lobby

No Asbestos

B0AA - R0023 - Toilet - Lobby

No Asbestos

B0AA - R0024 - Toilet - Lobby

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B0AA - R0025 - Staff Toilet

No Asbestos

B0AA - R0026 - Staff Toilet

No Asbestos

B0AA - R0027 - Staff Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0BB - Communal Facilities/Pupil Facilities - 2002 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B0BB - R0001 - Canteen**

No Asbestos

B0BB - R0002 - Canteen Office/Store

No Asbestos

B0BB - R0003 - Covered Outdoor Learning Area

No Asbestos

B0BB - R0005 - Itinerant Teachers Unit

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0BB - R0006 - Itinerant Teachers Unit

No Asbestos

B0BB - R0007 - Garden Store

No Asbestos

B0BB - R0008 - Hall Chair Store

No Asbestos

B0BB - R0010 - Movement

No Asbestos

B0BB - R0011 - Raised Platform

No Asbestos

B0BB - R0012 - Movement

No Asbestos

B0BB - R0014 - Communal/Performance Store

No Asbestos

B0BB - R0015 - Itinerant Teachers Unit

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0BB - R0016 - P.E. Store

No Asbestos

B0BB - R0017 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B0BB - R0018 - Cleaning Distributed Store

No Asbestos

B0BB - R0019 - Communications Cupboard

No Asbestos

B0BB - R0021 - Access Shower/Toilet

No Asbestos

B0BB - R0022 - Communal Space

No Asbestos

B0BB - R0023 - External Movement

No Asbestos

B0BB - R0024 - Toilets - Boys

No Asbestos

B0BB - R0025 - Toilet - Lobby

No Asbestos

B0BB - R0026 - Toilet - Lobby

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0BB - R0027 - Toilets - Girls

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B0CC - General Learning - 2002 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B0CC - R0001 - External Movement**

No Asbestos

B0CC - R0002 - Cleaning Distributed Store

No Asbestos

B0CC - R0003 - Home Base Store

No Asbestos

B0CC - R0004 - Practical Activities - 1hb

No Asbestos

B0CC - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0006 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0008 - Practical Activities - 1hb

No Asbestos

B0CC - R0009 - Home Base Store

No Asbestos

B0CC - R0010 - External Movement

No Asbestos

B0CC - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B0CC - R0012 - Home Base Store

No Asbestos

B0CC - R0013 - Practical Activities - 1hb

No Asbestos

B0CC - R0014 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0015 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0CC - R0017 - External Movement

No Asbestos

B0CC - R0018 - Home Base Store

No Asbestos

B0CC - R0019 - Practical Activities - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B0DD - General Learning/Pupil Facilities - 2002 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B0DD - R0001 - External Movement**

No Asbestos

B0DD - R0002 - Toilets - Boys

No Asbestos

B0DD - R0003 - Access Shower/Toilet

No Asbestos

B0DD - R0004 - Toilets - Girls

No Asbestos

B0DD - R0005 - Practical Activities - 1hb

No Asbestos

B0DD - R0006 - Home Base Store

No Asbestos

B0DD - R0007 - Home BaseVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0DD - R0008 - Withdrawal Space - 2hb**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0DD - R0009 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0DD - R0010 - Practical Activities - 1hb**

No Asbestos

B0DD - R0011 - Home Base Store

No Asbestos

B0DD - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B0DD - R0013 - Home Base Store

No Asbestos

B0DD - R0014 - Practical Activities - 1hb

No Asbestos

B0DD - R0015 - Home BaseVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0DD - R0016 - Withdrawal Space - 2hb**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0DD - R0017 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0DD - R0018 - External Movement**

No Asbestos

B0DD - R0019 - Home Base Store

No Asbestos

B0DD - R0020 - Practical Activities - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0EE - Library/General Learning - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0EE - R0001 - External Movement

No Asbestos

B0EE - R0002 - Staff Toilet

No Asbestos

B0EE - R0003 - Cleaning Distributed Store

No Asbestos

B0EE - R0004 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0005 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B0EE - R0007 - K.L.A. Store

No Asbestos

B0EE - R0008 - Communications Room

No Asbestos

B0EE - R0009 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0010 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0011 - Practical Activities - 1hb

No Asbestos

B0EE - R0012 - Home Base Store

No Asbestos

B0EE - R0013 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B0EE - R0014 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0015 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0EE - R0017 - External Movement

No Asbestos

B0EE - R0018 - Home Base Store

No Asbestos

B0EE - R0019 - Practical Activities - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0FF - General Learning/Pupil Facilities - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0FF - R0001 - Cleaning Distributed Store

No Asbestos

B0FF - R0002 - Home Base Store

No Asbestos

B0FF - R0003 - Practical Activities - 1hb

No Asbestos

B0FF - R0004 - External Movement

No Asbestos

B0FF - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0FF - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0FF - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0FF - R0008 - Practical Activities - 1hb

No Asbestos

B0FF - R0009 - Home Base Store

No Asbestos

B0FF - R0010 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B0FF - R0011 - Toilets - Girls

No Asbestos

B0FF - R0012 - Kiln Room

No Asbestos

B0FF - R0013 - Toilets - Boys

No Asbestos

B0FF - R0014 - Plant

No Asbestos

B0FF - R0015 - Access Shower/Toilet - Type 2

No Asbestos

B0FF - R0016 - Laundry - Type 2

No Asbestos

B0FF - R0017 - Practical Activities - 1hb

No Asbestos

B0FF - R0018 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0FF - R0019 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0FF - R0020 - Home Base Store

No Asbestos

B0FF - R0021 - Home Base Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0FF - R0022 - Practical Activities - 1hb						
No Asbestos						
B0FF - R0023 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B0FF - R0024 - Withdrawal Space - 2hb						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0FF - R0025 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0FF - R0026 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0FF - R0027 - Practical Activities - 1hb						
No Asbestos						
B0FF - R0028 - Home Base Store						
No Asbestos						
B0FF - R0029 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0GG - Other-After School Care - 2002 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0GG - R0001 - External Movement

No Asbestos

B0GG - R0002 - Out Of School Hours Care Centre

No Asbestos

B0GG - R0003 - Movement

No Asbestos

B0GG - R0004 - General Storeroom - Pre

No Asbestos

B0GG - R0005 - Toilets - Boys/Girls

No Asbestos

B0GG - R0006 - Out Of School Hours Care Centre

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B0HH - Pre-School Facilities - 2004 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B0HH - R0001 - External Movement**

No Asbestos

B0HH - R0002 - Entry Vestibule

No Asbestos

B0HH - R0003 - Security Store

No Asbestos

B0HH - R0004 - General Storeroom - Pre

No Asbestos

B0HH - R0005 - Home Base - PreVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0HH - R0006 - Practical Activities - Pre**

No Asbestos

B0HH - R0007 - Toilets - Boys/Girls - Pre

No Asbestos

B0HH - R0008 - Laundry - Pre

No Asbestos

B0HH - R0009 - Access Shower/Toilet

No Asbestos

B0HH - R0010 - Cleaning Distributed Store

No Asbestos

B0HH - R0011 - Kitchen - Pre

No Asbestos

B0HH - R0012 - Clerical Office - PreVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0HH - R0013 - Clerical Office - Pre**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B0HH - R0014 - General Storeroom - Pre**

No Asbestos

B0HH - R0015 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0II - General Learning - 2006 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0II - R0001 - External Movement

No Asbestos

B0II - R0002 - Practical Activities - 1hb

No Asbestos

B0II - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0II - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0II - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0II - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0II - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0II - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0JJ - Building Services - 2007 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B0JJ - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10583 - Learning Unit - Standard With P.A.A. : Placement Date - 17/02/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

NS 100 - D11253 - Learning Unit - Single Primary/PAA : Placement Date - 9/01/2014

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.

NS 100 - D11254 - Learning Unit - Single Primary/PAA : Placement Date - 1/10/2015

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.

OS 602 - D11845 - Learning Unit - Standard With P.A.A. : Placement Date - 5/01/2004

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
OS 602 - D12447 - Learning Unit - Standard With P.A.A. : Placement Date - 17/02/2016						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D14011 - Learning Unit - Standard With P.A.A. : Placement Date - 27/11/2012						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017