


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bega Valley Public School (1168)
Region : Illawarra and South East
State Electorate : Bega
Local Government Area : Bega Valley

Initial Survey : Noel Arnold & Associates : 08 - May - 2008
Reviewed By : AECOM : 18 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1892 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 1168/B00A/R0002/Ceiling Structures/Linings/S19					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00A - R0002 - External Movement (1.65 m2)**

Ceiling Structures/Linings	Flat AC Sheeting 1168/B00A/R0002/Ceiling Structures/Linings/S19					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00A - R0003 - Duplicating Workroom (16.92 m2)

No Asbestos

B00A - R0004 - Interview (14.78 m2)

No Asbestos

B00A - R0005 - Sick Bay (13.24 m2)

No Asbestos

B00A - R0016 - Staff Kitchen (5.44 m2)

No Asbestos

B00A - R0017 - Disabled Shower/Toilet (7.52 m2)

No Asbestos

B00A - R0018 - General Storeroom (8.73 m2)

No Asbestos

B00A - R0019 - Deputy Principal (11.62 m2)

No Asbestos

B00A - R0020 - Principal (19.22 m2)

No Asbestos

B00A - R0021 - Clerical Office (11.85 m2)

No Asbestos

B00A - R0022 - Clerical Office (29.39 m2)

No Asbestos

B00A - R0023 - Movement (4.5 m2)

No Asbestos

B00A - R0024 - Entry Vestibule (7.55 m2)

No Asbestos

B00A - R0025 - Movement (21.6 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - General Learning - 1985 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting 1168/B00B/R0026/Ceiling Structures/Linings/S12					No Asbestos Detected
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00B - R0002 - Home Base (63.11 m2)**

Wall Linings Internal	Exterior Door Infill 1168/B00B/R0013/Wall Linings Internal/S23					No Asbestos Detected
-----------------------	---	--	--	--	--	----------------------

B00B - R0003 - Practical Activities (40.33 m2)

No Asbestos

B00B - R0004 - Home Base (63.11 m2)

Wall Linings Internal	Exterior Door Infill 1168/B00B/R0013/Wall Linings Internal/S23					No Asbestos Detected
-----------------------	---	--	--	--	--	----------------------

B00B - R0005 - Covered Outdoor Learning Area (25.03 m2)

Ceiling Structures/Linings	Flat AC Sheeting 1168/B00B/R0026/Ceiling Structures/Linings/S12					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00B - R0006 - Home Base Store (3.96 m2)

No Asbestos

B00B - R0007 - Withdrawal Space - 1hb (10.03 m2)

No Asbestos

B00B - R0008 - Home Base Store (3.92 m2)

No Asbestos

B00B - R0009 - General Storeroom (4.21 m2)

No Asbestos

B00B - R0010 - General Storeroom (4.16 m2)

No Asbestos

B00B - R0011 - Practical Activities (40.43 m2)

No Asbestos

B00B - R0012 - Home Base Store (3.8 m2)

No Asbestos

B00B - R0013 - Home Base (62.86 m2)

Wall Linings Internal	Exterior Door Infill 1168/B00B/R0013/Wall Linings Internal/S23					No Asbestos Detected
-----------------------	---	--	--	--	--	----------------------

B00B - R0014 - Covered Outdoor Learning Area (18.2 m2)

Ceiling Structures/Linings	Flat AC Sheeting 1168/B00B/R0026/Ceiling Structures/Linings/S12					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00B - R0015 - Withdrawal Space - 1hb (10.11 m2)

No Asbestos

B00B - R0016 - Covered Outdoor Learning Area (18.21 m2)

Ceiling Structures/Linings	Flat AC Sheeting 1168/B00B/R0026/Ceiling Structures/Linings/S12					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00B - R0017 - Home Base (62.98 m2)

No Asbestos

B00B - R0021 - Distribution Board (0.92 m2)

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting		1168/B00B/R0021/Wall Linings Internal/S13			No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting		1168/B00B/R0021/Wall Linings Internal/S13			No Asbestos Detected
B00B - R0023 - Toilets - Boys (16.58 m2)						
No Asbestos						
B00B - R0024 - Toilets - Girls (18.62 m2)						
No Asbestos						
B00B - R0025 - Access Shower/Toilet - Type 2 (6.61 m2)						
No Asbestos						
B00B - R0026 - External Movement (120.44 m2)						
Wall Linings Internal	Flat AC Sheeting		1168/B00B/R0026/Wall Linings Internal/S11			No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting		1168/B00B/R0026/Ceiling Structures/Linings/S12			No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Communal Facilities/Music - 1883 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids	Non Accessible Area - Area inaccessible - limited access gained due to storage.

Interior

B00C - R0001 - Special Programs Room (23.99 m2)

No Asbestos

B00C - R0002 - Special Programs Store (6.56 m2)

No Asbestos

B00C - R0005 - P.E. Store (6.49 m2)

No Asbestos

B00C - R0007 - Movement (35.37 m2)

No Asbestos

B00C - R0008 - K.L.A. Store (17.59 m2)

No Asbestos

B00C - R0009 - Communications Room (5.8 m2)

No Asbestos

B00C - R0010 - Reading Area (148.97 m2)

No Asbestos

B00C - R0011 - Library Office/Workroom (28.37 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library - 1892 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00D - R0004 - Resource/Toy Space (10.73 m2)**

No Asbestos

B00D - R0006 - Clerical Office (18 m2)

No Asbestos

B00D - R0007 - Toilets - Boys (2.43 m2)

No Asbestos

B00D - R0008 - Toilets - Girls (2.44 m2)

No Asbestos

B00D - R0009 - General Storeroom (5.44 m2)

No Asbestos

B00D - R0010 - Movement (3.82 m2)

No Asbestos

B00D - R0011 - Distribution Board (0.66 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00D/R0011/Door lining/S4					Chrysotile (white asbestos)
Door Lining	Flat AC Sheeting	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00D/R0011/Door lining/S4					Chrysotile (white asbestos)

B00D - R0012 - External Movement (5.7 m2)

No Asbestos

B00D - R0013 - External Movement (6.78 m2)

No Asbestos

B00D - R0014 - Staff Room Annexe (17.51 m2)

No Asbestos

B00D - R0015 - Staff Room (42.77 m2)

No Asbestos

B00D - R0016 - Staff Kitchen (10.46 m2)

No Asbestos

B00D - R0017 - Home Base Store (5.4 m2)

No Asbestos

B00D - R0018 - Practical Activities - 1hb (15.74 m2)

No Asbestos

B00D - R0019 - Home Base (57.79 m2)

No Asbestos

B00D - R0020 - Withdrawal Space - 1hb (9.08 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1970 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00E/Gable Verge Lining/S17				Chrysotile (white asbestos) , Amosite (brown asbestos)	
In-fill-panel	Flat AC Sheeting				No Asbestos Detected	
	1168/B00F/R0001/In-fill-panel/S16					
Gable Verge Lining	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00E/Gable Verge Lining/S17				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00E - R0010 - External Movement (40.17 m2)**

In-fill-panel	Flat AC Sheeting				No Asbestos Detected	
	1168/B00F/R0001/In-fill-panel/S16					
Ceiling Structures/Linings	Flat AC Sheeting	41m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00F/R0001/Ceiling Structures/Linings/S15				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00E - R0011 - Home Base (56.91 m2)

Wall Linings Internal	Flat AC Sheeting				No Asbestos Detected	
	1168/B00F/R0001/In-fill-panel/S16					

B00E - R0012 - Home Base Store (6.08 m2)

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00E/R0012/Floor Coverings Res/Textile/S1				Chrysotile (white asbestos)	

B00E - R0013 - Personal Effects Storage (7.19 m2)

Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00E/R0012/Floor Coverings Res/Textile/S1				Chrysotile (white asbestos)	

B00E - R0018 - Practical Activities - 1hb (15.39 m2)

No Asbestos

B00E - R0019 - Home Base (58.33 m2)

No Asbestos

B00E - R0020 - Withdrawal Space - 2hb (15.12 m2)

No Asbestos

B00E - R0021 - Home Base Store (9.63 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
B00F - General Learning - 1970 - Brick/Veneer (Brick/Veneer)						
Exterior						
Eaves Linings	Flat AC Sheeting 1168/B00F/Gable Verge Lining/S14	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
In-fill-panel	Flat AC Sheeting 1168/B00F/R0001/In-fill-panel/S16					No Asbestos Detected
Gable Verge Lining	Flat AC Sheeting 1168/B00F/Gable Verge Lining/S14	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	No Asbestos Found					
Interior						
B00F - R0001 - External Movement (41.19 m2)						
In-fill-panel	Flat AC Sheeting 1168/B00F/R0001/In-fill-panel/S16					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 1168/B00F/R0001/Ceiling Structures/Linings/S15	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00F - R0002 - Staff Room (6.18 m2)						
Floor Coverings Res/Textile	Vinyl Tiles 1168/B00E/R0012/Floor Coverings Res/Textile/S1	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
B00F - R0003 - Home Base Store (3.09 m2)						
Floor Coverings Res/Textile	Vinyl Tiles 1168/B00E/R0012/Floor Coverings Res/Textile/S1	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
B00F - R0004 - Toilets-Unisex (3.68 m2)						
No Asbestos						
B00F - R0005 - Practical Activities (15.45 m2)						
No Asbestos						
B00F - R0008 - Home Base (56.98 m2)						
Wall Linings Internal	Flat AC Sheeting 1168/B00F/R0001/In-fill-panel/S16					No Asbestos Detected
B00F - R0009 - Home Base Store (6.12 m2)						
Floor Coverings Res/Textile	Vinyl Tiles 1168/B00E/R0012/Floor Coverings Res/Textile/S1	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
				<i>Asbestos removed, remediation work completed - 13/04/2016</i>		
B00F - R0010 - Distribution Board (0.51 m2)						
Electrical Backing Board	Resinous Board	1m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
				Assumed Asbestos - Electrical Hazard		
B00F - R0011 - Staff Room (6.42 m2)						
Floor Coverings Res/Textile	Vinyl Tiles 1168/B00E/R0012/Floor Coverings Res/Textile/S1	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		
				<i>Asbestos removed, remediation work completed - 13/04/2016</i>		
B00F - R0012 - Home Base (69.61 m2)						
Wall Linings Internal	Flat AC Sheeting 1168/B00F/R0001/In-fill-panel/S16					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning/Building Services - 1970 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	25m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						
In-fill-panel	Flat AC Sheeting 1168/B00F/R0001/In-fill-panel/S16					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00G - R0001 - General Storeroom (7.53 m2)**

No Asbestos

B00G - R0002 - General Storeroom (4.67 m2)

Wall Linings Internal	Flat AC Sheeting	3m2	West	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1168/B00G/R0002/Wall Linings Internal/S21						Chrysotile (white asbestos)

B00G - R0004 - Cleaning Distributed Store (4.52 m2)

Wall Linings Internal	Flat AC Sheeting	3m2	West	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1168/B00G/R0002/Wall Linings Internal/S21						Chrysotile (white asbestos)

B00G - R0005 - General Storeroom (7.25 m2)

No Asbestos

B00G - R0010 - Home Base (56.5 m2)

Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
1168/B00G/R0010/Ceiling Structures/Linings/S2						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00G - R0011 - Home Base Store (6.69 m2)

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1168/B00E/R0012/Floor Coverings Res/Textile/S1						Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
1168/B00G/R0010/Ceiling Structures/Linings/S2						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00G - R0012 - Distribution Board (0.68 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0013 - Movement (5.91 m2)

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1168/B00E/R0012/Floor Coverings Res/Textile/S1						Chrysotile (white asbestos)
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
1168/B00G/R0010/Ceiling Structures/Linings/S2						Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B00G - R0014 - Stairs (4.67 m2)

No Asbestos

B00G - R0015 - Stairs (4.52 m2)

No Asbestos

B00G - R0016 - Special Programs Room (32.4 m2)

No Asbestos

B00G - R0017 - Withdrawal Space - 1hb (11.29 m2)

No Asbestos

B00G - R0018 - Home Base Store (7.86 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00G - R0019 - Home Base (62.98 m2)						
No Asbestos						
B00G - R0020 - Practical Activities - 1hb (12.89 m2)						
No Asbestos						
B00G - R0021 - Practical Activities - 1hb (12.78 m2)						
No Asbestos						
B00G - R0022 - External Movement (79.38 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	80m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1168/B00G/R0022/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)	
B00G - R0023 - Cleaning Distributed Store (3.67 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
1168/B00G/R0024/Ceiling Structures/Linings/S20						
B00G - R0024 - General Storeroom (14.39 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
1168/B00G/R0024/Ceiling Structures/Linings/S20						
B00G - R0025 - Movement (5.05 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
1168/B00G/R0024/Ceiling Structures/Linings/S20						
B00G - R0026 - Toilets - Girls (38.04 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
1168/B00G/R0024/Ceiling Structures/Linings/S20						
B00G - R0027 - Toilets - Boys (32.93 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
1168/B00G/R0024/Ceiling Structures/Linings/S20						
B00G - R1004 - Home Base Store (6.59 m2)						
No Asbestos						
B00G - R1006 - Home Base (57.05 m2)						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R1007 - Home Base Store (6.61 m2)						
No Asbestos						
B00G - R1008 - Personal Effects Storage (13.8 m2)						
No Asbestos						
B00G - R1009 - Home Base Store (6.65 m2)						
No Asbestos						
B00G - R1010 - Home Base (56.91 m2)						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00G - R1011 - Stairs (12.9 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
1168/B00G/R0024/Ceiling Structures/Linings/S20						
B00G - R1012 - Stairs (12.33 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
1168/B00G/R0024/Ceiling Structures/Linings/S20						
B00G - R1013 - Home Base (56.38 m2)						
No Asbestos						
B00G - R1014 - Practical Activities - 1hb (17.08 m2)						
No Asbestos						
B00G - R1015 - Practical Activities - 1hb (10.27 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00G - R1016 - Home Base (61.46 m2)

No Asbestos

B00G - R1017 - Home Base Store (6.86 m2)

No Asbestos

B00G - R1018 - Withdrawal Space - 1hb (8.96 m2)

No Asbestos

B00G - R1019 - External Movement (75.01 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Other-Community Use - 1965 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	8m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00H/Eaves Linings/S10					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00H - R0001 - Other-Community Use (21.41 m2)

No Asbestos

B00H - R0002 - Other-Community Use (16.58 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Pupil Facilities - 1970 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00K/R0001/Ceiling Structures/Linings/S18					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00K - R0001 - Movement (22.81 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00K/R0001/Ceiling Structures/Linings/S18					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting	5m	Above servery	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00K/R0001/Ceiling Structures/Linings/S18					Chrysotile (white asbestos)

B00K - R0002 - Canteen (22.44 m2)

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00K/R0001/Ceiling Structures/Linings/S18					Chrysotile (white asbestos)
In-fill-panel	Flat AC Sheeting	5m	Above servery	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00K/R0001/Ceiling Structures/Linings/S18					Chrysotile (white asbestos)

B00K - R0003 - Canteen Office/Store (2.94 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00K/R0001/Ceiling Structures/Linings/S18					Chrysotile (white asbestos)

B00K - R0004 - Canteen Office/Store (3.47 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00K/R0001/Ceiling Structures/Linings/S18					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Storage - 1970 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	6m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00L/Gable Verge Lining/S8					Chrysotile (white asbestos)
Gable Verge Lining	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00L/Gable Verge Lining/S8					Chrysotile (white asbestos)
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids	No Asbestos Found					
Wall Cladding	Flat AC Sheeting	4m2	Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1168/B00L/Wall Cladding/S9					Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior

B00L - R0001 - Wheelchair Store-Special Ed (21.83 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - General Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

No Asbestos

Interior

B000 - R0001 - Practical Activities - 1hb (19.93 m2)

No Asbestos

B000 - R0002 - Home Base (60.5 m2)

No Asbestos

B000 - R0003 - Home Base Store (6.35 m2)

No Asbestos

B000 - R0004 - Withdrawal Space - 2hb (11.74 m2)

No Asbestos

B000 - R0005 - Home Base (60.24 m2)

No Asbestos

B000 - R0006 - Home Base Store (6.33 m2)

No Asbestos

B000 - R0007 - Practical Activities - 1hb (19.96 m2)

No Asbestos

B000 - R0008 - External Movement (43.16 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00P - Communal Facilities - 2011 - Brick/Veneer (Brick/Veneer)**Exterior**

No Asbestos

Interior**B00P - R0001 - Communal Space (143.46 m2)**

No Asbestos

B00P - R0002 - Raised Platform (58.9 m2)

No Asbestos

B00P - R0003 - Movement (6.14 m2)

No Asbestos

B00P - R0004 - Movement (6.84 m2)

No Asbestos

B00P - R0005 - Ramp (11.46 m2)

No Asbestos

B00P - R0006 - Movement (12.16 m2)

No Asbestos

B00P - R0007 - Hall Chair Store (9.52 m2)

No Asbestos

B00P - R0008 - Communal/Performance Store (9.54 m2)

No Asbestos

B00P - R0009 - P.E. Store (12.99 m2)

No Asbestos

B00P - R0010 - Toilet - Lobby (2.36 m2)

No Asbestos

B00P - R0011 - Toilets - Girls (7.31 m2)

No Asbestos

B00P - R0012 - Sound Cupboard (2.06 m2)

No Asbestos

B00P - R0013 - Toilet - Lobby (3.3 m2)

No Asbestos

B00P - R0014 - Toilets - Boys (5.7 m2)

No Asbestos

B00P - R0015 - Cleaning Distributed Store (3.5 m2)

No Asbestos

B00P - R0016 - Plant (1.6 m2)

No Asbestos

B00P - R0017 - Distribution Board (3.23 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00P - R0018 - Access Shower/Toilet (6.86 m2)

No Asbestos

B00P - R0019 - Covered Outdoor Learning Area (147.33 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Storage - 2013 - Metal Shed (Metal Shed)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00Q - R0001 - Sports Store (28.32 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00R - Storage - 2013 - Metal Shed (Metal Shed)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00R - R0001 - General Storeroom (21.37 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 971 - D12722 - Shed - Container (Garden/Sports/Bulk) : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Interior

R1 - Garden Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017