

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1938 - Brick/Veneer (Brick/Veneer)**Exterior**

No Asbestos

Underfloor Voids - Slab on Ground Non Accessible Area

- Area inaccessible

Ceiling Voids - Flat Roof Non Accessible Area
- Height Restriction**Interior****B00A - R0001 - External Movement**

No Asbestos

B00A - R0003 - Canteen

Ceiling Structures/Linings Flat AC Sheeting 24m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

1175/B00A/R0003/Ceiling Structures/Linings/S3

Chrysotile (white asbestos)**B00A - R0004 - Handwashing Facilities**

Ceiling Structures/Linings Flat AC Sheeting 24m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

1175/B00A/R0003/Ceiling Structures/Linings/S3

Chrysotile (white asbestos)**B00A - R0006 - General Storeroom**

No Asbestos

B00A - R0007 - External Stairs

Floor Coverings Res/Textile Compressed AC Sheet

1175/B00A/R0007/Floor Coverings Res/Textile/S4

No Asbestos Detected**B00A - R0008 - Clerical Office**

No Asbestos

B00A - R0009 - Principal

No Asbestos

B00A - R0010 - Clerical Office/Workroom

No Asbestos

B00A - R0011 - Cleaning Distributed Store

No Asbestos

B00A - R0012 - General Storeroom

Ceiling Structures/Linings Flat AC Sheeting 7.66m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

1175/B00A/R0003/Ceiling Structures/Linings/S3

Chrysotile (white asbestos)**B00A - R0013 - Reading Area**

No Asbestos

B00A - R0014 - K.L.A. Store

No Asbestos

B00A - R0015 - External Movement

No Asbestos

B00A - R1001 - External MovementWall Linings Internal Flat AC Sheeting
1175/B00A/R1001/Wall Linings Internal/S5**No Asbestos Detected**

Electrical Backing Board Resinous Board 1m2 South Good Condition (1) Low (1) Low Priority (2-3)

1175/B00A/R1001/Electrical Backing Board/S6

Chrysotile (white asbestos)**B00A - R1002 - Practical Activities - 1hb**Wall Linings Internal Flat AC Sheeting
1175/B00A/R1001/Wall Linings Internal/S5**No Asbestos Detected****B00A - R1003 - Staff Room Annexe**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R1004 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles					
	1175/B00A/R1004/Floor Coverings Res/Textile/S8					No Asbestos Detected
B00A - R1005 - Home Base						
No Asbestos						
B00A - R1006 - Home Base						
No Asbestos						
B00A - R1007 - Staff Room						
No Asbestos						
B00A - R1008 - External Stairs						
Floor Coverings Res/Textile	Compressed AC Sheet					
	1175/B00A/R0007/Floor Coverings Res/Textile/S4					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1938 - Timber (Timber)**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Height Restriction					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 1175/B00D/Eaves Linings/S2	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior**B00B - R0003 - Sports Store**

No Asbestos

B00B - R0004 - External Movement

No Asbestos

B00B - R0005 - External Movement

No Asbestos

B00B - R0006 - External Stairs

Floor Coverings Res/Textile	Compressed AC Sheet 1175/B00A/R0007/Floor Coverings Res/Textile/S4					No Asbestos Detected
-----------------------------	---	--	--	--	--	-----------------------------

B00B - R1001 - Home Base

Heater Surround	Flat AC Sheeting 1175/B00B/R1001/Pard Behind Heater/S7	3Unit(s)	South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00B - R1002 - Practical Activities - 1hb

Wall Linings Internal	Flat AC Sheeting 1175/B00A/R1001/Wall Linings Internal/S5					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 1175/B00A/R0003/Ceiling Structures/Linings/S3	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		

B00B - R1003 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 1175/B00A/R0003/Ceiling Structures/Linings/S3	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos)		

B00B - R1004 - External Stairs

Floor Coverings Res/Textile	Compressed AC Sheet 1175/B00A/R0007/Floor Coverings Res/Textile/S4					No Asbestos Detected
-----------------------------	---	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Communal Facilities - 1978 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00C - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1957 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 1175/B00D/Eaves Linings/S2	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior**B00D - R0003 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting 1175/B00D/R0003/Ceiling Structures/Linings/S1	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0004 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting 1175/B00D/R0003/Ceiling Structures/Linings/S1	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0005 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting 1175/B00D/R0003/Ceiling Structures/Linings/S1	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Other - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B00E - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017