

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Bellingen Public School (1181)  
**Region :** North Coast  
**State Electorate :** Oxley  
**Local Government Area :** Bellingen

**Initial Survey :** Noel Arnold & Associates : 20 - May - 2008  
**Reviewed By :** Parsons Brinckerhoff : 08 - Oct - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - General Learning - 1972 - Brick/Block (Brick/Block)****Exterior**

In-fill-panel	Flat AC Sheeting	21m2	Throughout, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B001/In-fill-panel/S2					<b>Chrysotile (white asbestos)</b>
Eaves Linings	Flat AC Sheeting	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B001/Eaves Linings/S7					<b>Chrysotile (white asbestos)</b>
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					

**Interior****B001 - R0001 - Home Base Store**

Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B001/R0002/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B001 - R0002 - Personal Effects Storage**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B001/R0002/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B001 - R0003 - Home Base**

Ceiling Structures/Linings	Flat AC Sheeting	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B001 - R0004 - Home Base**

Ceiling Structures/Linings	Flat AC Sheeting	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B001 - R0005 - Home Base Store**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B001/R0002/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B001 - R0006 - Personal Effects Storage**

Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B001/R0002/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B001 - R0007 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0010/Partition Walls (Cubicles)/S5					<b>Chrysotile (white asbestos)</b>

**B001 - R0008 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Partition Walls (Cubicles)	Compressed AC Sheet	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0010/Partition Walls (Cubicles)/S5					<b>Chrysotile (white asbestos)</b>	
<b>B001 - R0009 - Distribution Board</b>				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
<b>B001 - R0010 - Cleaning Supplies</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
<b>B001 - R0011 - Toilets - Boys/Girls</b>						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0010/Partition Walls (Cubicles)/S5					<b>Chrysotile (white asbestos)</b>	
<b>B001 - R0012 - Home Base</b>						
Ceiling Structures/Linings	Flat AC Sheeting	86m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
<b>B001 - R0013 - Practical Activities - 1hb</b>						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
<b>B001 - R0014 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	122m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B001/R0014/Ceiling Structures/Linings/S12					<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B002 - General Learning - 1972 - Brick/Block (Brick/Block)</b>						
<b>Exterior</b>						
In-fill-panel	Flat AC Sheeting	21m2	Throughout, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B001/In-fill-panel/S2					<b>Chrysotile (white asbestos)</b>
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B002/Eaves Linings/S8					<b>Chrysotile (white asbestos)</b>
<b>Interior</b>						
<b>B002 - R0001 - Home Base Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B001/R0002/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
<b>B002 - R0002 - Personal Effects Storage</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B001/R0002/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
<b>B002 - R0003 - Home Base</b>						
Ceiling Structures/Linings	Flat AC Sheeting	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
<b>B002 - R0004 - Home Base</b>						
Ceiling Structures/Linings	Flat AC Sheeting	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
<b>B002 - R0005 - Home Base Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B001/R0002/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
<b>B002 - R0006 - Personal Effects Storage</b>						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B001/R0002/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
<b>B002 - R0008 - Toilets - Boys</b>						
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0010/Partition Walls (Cubicles)/S5					<b>Chrysotile (white asbestos)</b>
<b>B002 - R0009 - Distribution Board</b>						
				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B002 - R0010 - Cleaning Supplies</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
<b>B002 - R0011 - Toilets - Boys/Girls</b>						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
Wall Linings Internal	Flat AC Sheeting	4m2	Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B002/R0011/Wall Linings Internal/S13					<b>Chrysotile (white asbestos)</b>	
<b>B002 - R0012 - Home Base</b>						
Ceiling Structures/Linings	Flat AC Sheeting	86m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
<b>B002 - R0013 - Practical Activities - 1hb</b>						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
<b>B002 - R0014 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	122m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
<b>B002 - R0015 - Disabled Toilet</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
<b>B002 - R0016 - Toilets - Girls</b>						
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0010/Partition Walls (Cubicles)/S5					<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B003 - General Learning/Pupil Facilities - 1972 - Brick/Block (Brick/Block)****Exterior**

In-fill-panel	Flat AC Sheeting	7m2	Throughout, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B001/In-fill-panel/S2					<b>Chrysotile (white asbestos)</b>
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/Eaves Linings/S9					<b>Chrysotile (white asbestos)</b>

**Interior****B003 - R0001 - Interview**

Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B003 - R0002 - Staff Toilet**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B003 - R0003 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B003 - R0004 - Staff Kitchen**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B003 - R0005 - Staff Room**

Ceiling Structures/Linings	Flat AC Sheeting	97m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B003 - R0006 - Staff Room Annexe**

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B003 - R0007 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0007/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B003 - R0008 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0007/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B003 - R0009 - Movement**

Floor Coverings Res/Textile	Vinyl Tiles	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0007/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B003 - R0010 - Staff Toilet**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0010/Partition Walls (Cubicles)/S5				Chrysotile (white asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)		
Floor Coverings Res/Textile	Vinyl Tiles	3m2	Entry Hall	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0007/Floor Coverings Res/Textile/S4				Chrysotile (white asbestos)		
<b>B003 - R0011 - Staff Toilet</b>						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)		
<b>B003 - R0012 - Withdrawal Space - 1hb</b>						
Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)		
<b>B003 - R0013 - General Storeroom</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)		
<b>B003 - R0014 - General Assistant/Bulk Store</b>						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)		
<b>B003 - R0015 - Garden Store</b>						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)		
<b>B003 - R0016 - P.E. Store</b>						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)		
<b>B003 - R0017 - Staff Toilet</b>						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)		
<b>B003 - R0018 - Uniform Shop</b>						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3				Chrysotile (white asbestos)		
<b>B003 - R0019 - General Storeroom</b>						
No Asbestos						
<b>B003 - R0020 - Canteen</b>						
No Asbestos						
<b>B003 - R0021 - Movement</b>						
No Asbestos						
<b>B003 - R0022 - Main Switch Board</b>						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Some Damage - Unsealed (3)	Medium (2)	Medium Priority (4-5)
1181/B003/R0022/Ceiling Structures/Linings/S14				Chrysotile (white asbestos)		
<b>B003 - R0023 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0023/Ceiling Structures/Linings/S15				Chrysotile (white asbestos)		
<b>B003 - R0025 - Movement</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
<b>B003 - R0026 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	71m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B004 - Administration/Library - 1972 - Brick/Block (Brick/Block)</b>						
<b>Exterior</b>						
In-fill-panel	Flat AC Sheeting	31m2	Throughout, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B001/In-fill-panel/S2					<b>Chrysotile (white asbestos)</b>
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	100m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B004/Eaves Linings/S10					<b>Chrysotile (white asbestos)</b>
<b>Interior</b>						
<b>B004 - R0001 - Seminar/Study</b>						
Ceiling Structures/Linings	Flat AC Sheeting	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
<b>B004 - R0002 - Library Office/Workroom</b>						
Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
<b>B004 - R0003 - Reading Area</b>						
Ceiling Structures/Linings	Flat AC Sheeting	93m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
<b>B004 - R0004 - Duplicating Workroom</b>						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0007/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
<b>B004 - R0006 - Sick Bay</b>						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0007/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
<b>B004 - R0007 - Clerical Office</b>						
Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
<b>B004 - R0008 - Entry Vestibule</b>						
Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
<b>B004 - R0009 - Interview</b>						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
<b>B004 - R0010 - Principal</b>						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
<b>B004 - R0011 - Staff Toilet</b>						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B004 - R0012 - General Storeroom</b>						
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0007/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
<b>B004 - R0013 - Deputy Principal</b>						
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
<b>B004 - R0014 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	69m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
<b>B004 - R0015 - General Storeroom</b>						
No Asbestos						
<b>B004 - R0016 - General Storeroom</b>						
Floor Coverings Res/Textile	Vinyl Tiles	2m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
1181/B004/R0016/Floor Coverings Res/Textile/S16					<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B005 - General Learning - 1972 - Brick/Block (Brick/Block)</b>						
<b>Exterior</b>						
In-fill-panel	Flat AC Sheeting	38m2	Throughout, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B001/In-fill-panel/S2					<b>Chrysotile (white asbestos)</b>
Ceiling Void	No Asbestos Found					
Underfloor Void	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	10m2	Upper Eaves (above main roof)	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B005/Eaves Linings/S11					<b>Chrysotile (white asbestos)</b>
<b>Interior</b>						
<b>B005 - R0001 - Home Base</b>						
No Asbestos						
<b>B005 - R0002 - Distribution Board</b>						
No Asbestos						
Note: No inspection of live electrical installation.						
<b>B005 - R0003 - Special Programs Room</b>						
Floor Coverings Res/Textile	Vinyl Tiles	79m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B001/R0002/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting	25m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B005/R0003/Ceiling Structures/Linings/S17					<b>Chrysotile (white asbestos)</b>
<b>B005 - R0004 - General Storeroom</b>						
No Asbestos						
<b>B005 - R0005 - Home Base</b>						
No Asbestos						
<b>B005 - R0006 - Home Base</b>						
No Asbestos						
<b>B005 - R0007 - Toilets - Boys</b>						
Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0010/Partition Walls (Cubicles)/S5					<b>Chrysotile (white asbestos)</b>
<b>B005 - R0008 - Toilets - Girls</b>						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0017/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1181/B003/R0010/Partition Walls (Cubicles)/S5					<b>Chrysotile (white asbestos)</b>
<b>B005 - R0009 - General Storeroom</b>						
No Asbestos						
<b>B005 - R0010 - Home Base</b>						
No Asbestos						
<b>B005 - R0011 - Home Base Store</b>						
No Asbestos						
<b>B005 - R0012 - Home Base Store</b>						
No Asbestos						
<b>B005 - R0013 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	1181/B005/R0013/Ceiling Structures/Linings/S18					<b>No Asbestos Detected</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B006 - General Learning - 1993 - Timber (Timber)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B006 - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 1181/B006/R0001/Ceiling Structures/Linings/S19	<b>No Asbestos Detected</b>
----------------------------	--	-----------------------------

**B006 - R0002 - Withdrawal Space - 1hb**

No Asbestos

**B006 - R0003 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 1181/B006/R0003/Ceiling Structures/Linings/S20	<b>No Asbestos Detected</b>
----------------------------	--	-----------------------------

**B006 - R0004 - Home Base**

No Asbestos

**B006 - R0005 - Practical Activities - 1hb**

No Asbestos

**B006 - R0006 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 1181/B006/R0006/Ceiling Structures/Linings/S21	<b>No Asbestos Detected</b>
----------------------------	--	-----------------------------

**B006 - R0007 - Home Base Store**

No Asbestos

**B006 - R0008 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B006 - R0009 - Home Base Store**

No Asbestos

**B006 - R0010 - Practical Activities - 1hb**

No Asbestos

**B006 - R0011 - Home Base**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B007 - General Learning - 1995 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B007 - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 1181/B007/R0001/Ceiling Structures/Linings/S22	<b>No Asbestos Detected</b>
----------------------------	--	-----------------------------

**B007 - R0002 - Withdrawal Space - 1hb**

No Asbestos

**B007 - R0003 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 1181/B007/R0003/Ceiling Structures/Linings/S23	<b>No Asbestos Detected</b>
----------------------------	--	-----------------------------

**B007 - R0004 - Home Base**

No Asbestos

**B007 - R0005 - Practical Activities - 1hb**

No Asbestos

**B007 - R0006 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 1181/B007/R0006/Ceiling Structures/Linings/S24	<b>No Asbestos Detected</b>
----------------------------	--	-----------------------------

**B007 - R0007 - Home Base Store**

No Asbestos

**B007 - R0008 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B007 - R0009 - Home Base Store**

No Asbestos

**B007 - R0010 - Practical Activities - 1hb**

No Asbestos

**B007 - R0011 - Home Base**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B008 - Special Purpose - 1972 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B008 - R0001 - Craft Store**

Ceiling Structures/Linings	Flat AC Sheeting	91m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B008/R0001/Ceiling Structures/Linings/S25					<b>Chrysotile (white asbestos)</b>	

**B008 - R0002 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	79m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1181/B008/R0002/Ceiling Structures/Linings/S26					<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B009 - Special Purpose - 1995 - Steel (Steel)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B009 - R0001 - Covered Outdoor Learning Area**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B010 - Storage - 2008 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B010 - R0001 - General Storeroom**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B011 - Electrical Services - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B011 - R0001 - Main Switch Board**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B012 - Communal Facilities - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B012 - R0001 - Communal Space**

No Asbestos

**B012 - R0002 - Raised Platform**

No Asbestos

**B012 - R0003 - Hall Chair Store**

No Asbestos

**B012 - R0004 - Communal/Performance Store**

No Asbestos

**B012 - R0005 - P.E. Store**

No Asbestos

**B012 - R0006 - Toilet - Lobby**

No Asbestos

**B012 - R0007 - Toilets - Girls**

No Asbestos

**B012 - R0008 - Sound Cupboard**

No Asbestos

**B012 - R0009 - Toilet - Lobby**

No Asbestos

**B012 - R0010 - Toilets - Boys**

No Asbestos

**B012 - R0011 - Cleaning Distributed Store**

No Asbestos

**B012 - R0012 - Plant**

No Asbestos

**B012 - R0013 - Main Switch Board**

No Asbestos

**B012 - R0014 - Access Shower/Toilet**

No Asbestos

**B012 - R0015 - Covered Outdoor Learning Area**

No Asbestos

**B012 - R0016 - Movement**

No Asbestos

**B012 - R0017 - Movement**

No Asbestos

**B012 - R0018 - Movement**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B013 - Music - 2015 - Steel (Steel)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B013 - R0001 - External Movement**

No Asbestos

**B013 - R0002 - Special Programs Room**

No Asbestos

**B013 - R0003 - Special Programs Room**

No Asbestos

**B013 - R0004 - Staff Kitchen**

No Asbestos

**B013 - R0005 - Movement**

No Asbestos

**B013 - R0006 - General Storeroom**

No Asbestos

**B013 - R0007 - General Storeroom**

No Asbestos

**B013 - R0008 - Special Programs Room - Type 2**

No Asbestos

**B013 - R0009 - Special Programs Room - Type 2**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Build+1 - Added Building**

**Exterior**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Build+2 - Added Building**

**Exterior**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 602 - D10383 - Learning Unit - Standard With P.A.A. : Placement Date - 21/06/2013**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D14182 - Learning Unit - Standard With P.A.A. : Placement Date - 27/03/2015**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017