



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Administration - 1912 - Timber (Timber)**

**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Height Restriction, 3.6m					
Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1182/B00A/Eaves Linings/S1					<b>Chrysotile (white asbestos)</b>
Underfloor Voids	AC Fragments/Debris 1182/B00A/Underfloor Voids/S5					
						<b>No Asbestos Detected</b>
Underfloor Voids - Packing to Floor Joists	Packing 1182/B00A/Underfloor Voids/S5					
						<b>No Asbestos Detected</b>

**Interior**

**B00A - M0001 - Withdrawal Space - 1hb**

No Asbestos

**B00A - R0001 - Practical Activities - 1hb**

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1182/B00A/R0001/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting	3m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1182/B00A/R0001/Wall Linings Internal/S4					<b>Chrysotile (white asbestos)</b>

**B00A - R0002 - Reading Area**

No Asbestos

**B00A - R0004 - Home Base**

No Asbestos

**B00A - R0005 - Principal**

No Asbestos

**B00A - R0006 - Home Base Store**

Floor Coverings Res/Textile	Vinyl Tiles 1182/B00A/R0006/Floor Coverings Res/Textile/S2					
						<b>No Asbestos Detected</b>

**B00A - R0007 - Movement**

No Asbestos

**B00A - R0008 - Home Base**

No Asbestos

**B00A - R0009 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Pupil Facilities - 1912 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area  
 - Area inaccessible, slab to ground / no access points.

Ceiling Voids - Raked Ceiling      No Asbestos Found

**Interior**

**B00B - R0001 - Staff Toilet**

No Asbestos

**B00B - R0002 - Toilets - Girls**

No Asbestos

**B00B - R0003 - Toilets - Boys**

No Asbestos

**B00B - R0004 - Handwashing Facilities**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Library/Administration - 2010 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00D - R0001 - External Movement**

No Asbestos

**B00D - R0002 - Reading Area**

No Asbestos

**B00D - R0003 - Principal**

No Asbestos

**B00D - R0004 - K.L.A. Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Storage - 2010 - Steel (Steel)**

**Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area  
 - Area inaccessible, slab to ground / no access points.

Ceiling Voids      No Asbestos Found

**Interior**

**B00E - R0001 - External Movement**

No Asbestos

**B00E - R0002 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017