


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bemboka Public School (1189)
Region : Illawarra and South East
State Electorate : Bega
Local Government Area : Bega Valley

Initial Survey : Noel Arnold & Associates : 14 - May - 2008
Reviewed By : Greencap-NAA : 17 - Jun - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1933 - Timber (Timber)**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting					
	1189/B00A/Eaves Linings/S7					No Asbestos Detected
Underfloor Voids	Flat AC Sheeting					
	1189/B00A/Underfloor Voids/S8					No Asbestos Detected

Interior**B00A - R0001 - General Storeroom**

No Asbestos

B00A - R0002 - Main Switch Board

Wall Linings Internal	Flat AC Sheeting					
	1189/B00B/R0003/Ceiling Structures/Linings/S3					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	1189/B00B/R0003/Ceiling Structures/Linings/S3					No Asbestos Detected

B00A - R0003 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	1189/B00A/R0003/Ceiling Structures/Linings/S2					No Asbestos Detected

B00A - R0004 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting					
	1189/B00A/R0004/Wall Linings Internal/S1					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting					
	1189/B00A/R0004/Wall Linings Internal/S1					No Asbestos Detected

B00A - R0005 - Entry Vestibule

No Asbestos

B00A - R0006 - Clerical Office

No Asbestos

B00A - R0011 - Home Base Store

No Asbestos

B00A - R0012 - Home Base Store

No Asbestos

B00A - R0013 - Handwashing Facilities

No Asbestos

B00A - R0014 - Staff Room

No Asbestos

B00A - R0015 - Reading Area

No Asbestos

B00A - R0016 - Principal

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - General Learning/Pupil Facilities - 1984 - Timber (Timber)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 1189/B00B/Eaves Linings/S9					No Asbestos Detected

Interior**B00B - R0001 - Handwashing Facilities**

No Asbestos

B00B - R0002 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting 1189/B00B/R0003/Ceiling Structures/Linings/S3					No Asbestos Detected
-----------------------	-------------------------------------------------------------------	--	--	--	--	-----------------------------

Ceiling Structures/Linings	Flat AC Sheeting 1189/B00B/R0003/Ceiling Structures/Linings/S3					No Asbestos Detected
----------------------------	-------------------------------------------------------------------	--	--	--	--	-----------------------------

B00B - R0003 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 1189/B00B/R0003/Ceiling Structures/Linings/S3					No Asbestos Detected
----------------------------	-------------------------------------------------------------------	--	--	--	--	-----------------------------

B00B - R0004 - Canteen

No Asbestos

B00B - R0005 - Practical Activities - 2hb

No Asbestos

B00B - R0006 - General Storeroom

No Asbestos

B00B - R0007 - General Storeroom

No Asbestos

B00B - R0008 - Home Base

No Asbestos

B00B - R0009 - General Assistant/Bulk Store

No Asbestos

B00B - R0010 - Home Base Store

No Asbestos

B00B - R0011 - Withdrawal Space - 2hb

No Asbestos

B00B - R0012 - Home Base

No Asbestos

B00B - R0013 - Home Base Store

No Asbestos

B00B - R0014 - Personal Effects Storage

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1984 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 1189/B00B/Eaves Linings/S9					No Asbestos Detected

Interior

B00C - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 1189/B00B/R0003/Ceiling Structures/Linings/S3					No Asbestos Detected
----------------------------	-------------------------------------------------------------------	--	--	--	--	-----------------------------

B00C - R0002 - Movement

No Asbestos

B00C - R0003 - Personal Effects Storage

No Asbestos

B00C - R0004 - Personal Effects Storage

No Asbestos

B00C - R0005 - Practical Activities - 1hb

No Asbestos

B00C - R0006 - Craft Store

No Asbestos

B00C - R0007 - Home Base

No Asbestos

B00C - R0008 - Withdrawal Space - 1hb

No Asbestos

B00C - R0009 - Home Base Store

No Asbestos

B00C - R0010 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting 1189/B00B/R0003/Ceiling Structures/Linings/S3					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 1189/B00B/R0003/Ceiling Structures/Linings/S3					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1955 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 1189/B00D/Eaves Linings/S10					No Asbestos Detected

Interior

B00D - R0001 - Toilets - Boys

Wall Linings Internal	Flat AC Sheeting 1189/B00D/R0001/Wall Linings Internal/S4					No Asbestos Detected
-----------------------	--------------------------------------------------------------	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1955 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 1189/B00D/Eaves Linings/S10					No Asbestos Detected
Ceiling Voids - Flat Roof	No Asbestos Found					

Interior

B00E - R0001 - Toilets - Girls

Wall Linings Internal	Flat AC Sheeting 1189/B00D/R0001/Wall Linings Internal/S4					No Asbestos Detected
-----------------------	--------------------------------------------------------------	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Shed - 1980 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00F - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Shed - 1955 - Timber Shed (Timber Shed)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found				
Underfloor Voids - Packing to Floor Joists	No Asbestos Found				
Eaves Linings	Flat AC Sheeting	1189/B00G/Eaves Linings/S5			No Asbestos Detected
Wall Cladding	Flat AC Sheeting	1189/B00G/Wall Cladding/S6			No Asbestos Detected

Interior

B00G - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00H - R0001 - Movement

No Asbestos

B00H - R0002 - Reading Area

No Asbestos

B00H - R0003 - Library Office/Workroom

No Asbestos

B00H - R0004 - Communications Room

No Asbestos

B00H - R0005 - K.L.A. Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Building Services - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B001 - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017