


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Ben Lomond Public School (1196)  
**Region :** New England  
**State Electorate :** Northern Tablelands  
**Local Government Area :** Guyra

**Initial Survey :** Noel Arnold & Associates : 20 - May - 2008  
**Register Issue Date :** 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning - 1960 - Timber (Timber)**

**Exterior**

Eaves Linings	Flat AC Sheeting 1196/B00A/Eaves Linings/S5					<b>No Asbestos Detected</b>
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

**Interior**

**B00A - R0001 - Home Base Store**

Ceiling Structures/Linings	Flat AC Sheeting 1196/B00A/R0009/Ceiling Structures/Linings/S6					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

**B00A - R0002 - Home Base**

Wall Linings Internal	Flat AC Sheeting 1196/B00A/R0002/Wall Linings Internal/S7	4m2	South and west Behind Piano	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
-----------------------	--	-----	-----------------------------	--------------------	---------	--

**B00A - R0003 - Home Base**

No Asbestos

**B00A - R0004 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 1196/B00A/R0009/Ceiling Structures/Linings/S6					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

**B00A - R0005 - Withdrawal Space - 1hb**

No Asbestos

**B00A - R0006 - Home Base Store**

No Asbestos

**B00A - R0007 - Sick Bay**

No Asbestos

**B00A - R0008 - Practical Activities - 1hb**

Ceiling Structures/Linings	Flat AC Sheeting 1196/B00A/R0009/Ceiling Structures/Linings/S6					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

**B00A - R0009 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 1196/B00A/R0009/Ceiling Structures/Linings/S6					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Pupil Facilities/Staff Facilities - 1975 - Brick/Block (Brick/Block)**

**Exterior**

Panel Above Door	Flat AC Sheeting 1196/B00B/R0003/Panel Above Door/S4					<b>No Asbestos Detected</b>
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

**Interior**

**B00B - R0001 - Movement**

No Asbestos

**B00B - R0002 - Toilets - Girls**

Cement Pipe Through Ceiling	Fibre Cement Pipe	1m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1196/B00B/R0002/Cement Pipe Through Ceiling/S2			<b>Chrysotile (white asbestos) , Amosite (brown Asbestos)</b>		

**B00B - R0003 - Disabled Toilet**

Panel Above Door	Flat AC Sheeting 1196/B00B/R0003/Panel Above Door/S4					<b>No Asbestos Detected</b>
------------------	---	--	--	--	--	-----------------------------

**B00B - R0004 - Toilets - Boys**

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1196/B00B/R0004/Partition Walls (Cubicles)/S1			<b>Chrysotile (white asbestos) , Amosite (brown Asbestos)</b>		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Administration/Library - 1990 - Timber (Timber)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00C - R0001 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0002 - Movement**

No Asbestos

**B00C - R0003 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0004 - Principal**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0005 - Security Store**

No Asbestos

**B00C - R0006 - Staff Room**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0007 - Clerical Office/Workroom**

No Asbestos

**B00C - R0008 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0009 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Communal Facilities/Building Services - 1950 - Timber (Timber)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B00D - R0001 - Garden Store**

No Asbestos

**B00D - R0002 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Pupil Facilities - 1950 - Timber (Timber)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B00E - R0001 - Canteen Covered Area**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Communal Facilities - 2010 - Steel (Steel)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00F - R0001 - Communal Space**

No Asbestos

**B00F - R0002 - Communal/Performance Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017