


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Ben Venue Public School (1198)  
**Region :** New England  
**State Electorate :** Northern Tablelands  
**Local Government Area :** Armidale Dumaresq

**Initial Survey :** Noel Arnold & Associates : 20 - May - 2008  
**Reviewed By :** Greencap-NAA : 01 - Apr - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00G - General Learning/Pupil Facilities - 1930 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	200m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1198/B00G/Underfloor Voids/S10			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	Debris	5m2	Variable positions	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	1198/B00G/Underfloor Voids/S10			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

**Interior****B00G - R0004 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1198/B00G/R0026/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		

**B00G - R0005 - Movement**

No Asbestos

**B00G - R0014 - Toilets - Boys**

No Asbestos

**B00G - R0015 - Toilets - Girls**

No Asbestos

**B00G - R0017 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	73m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1198/B00G/R0026/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		

**B00G - R0019 - Staff Toilet**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1198/B00G/R0026/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		

**B00G - R0020 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1198/B00G/R0026/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		

**B00G - R0024 - Practical Activities - 1hb**

No Asbestos

**B00G - R0025 - Home Base Store**

No Asbestos

**B00G - R0026 - Withdrawal Space - 1hb**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1198/B00G/R0026/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		

**B00G - R0027 - Practical Activities - 1hb**

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1198/B00G/R0026/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		

**B00G - R0028 - Home Base**

Ceiling Structures/Linings	Flat AC Sheeting	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1198/B00G/R0026/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
<b>B00G - R0029 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00G - R0030 - Home Base</b>						
Ceiling Structures/Linings	Flat AC Sheeting	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1198/B00G/R0026/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0031 - Practical Activities - 1hb</b>						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1198/B00G/R0026/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0032 - Practical Activities - 1hb</b>						
Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1198/B00G/R0026/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0033 - Home Base</b>						
Ceiling Structures/Linings	Flat AC Sheeting	44m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1198/B00G/R0026/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0034 - General Storeroom</b>						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1198/B00G/R0034/Ceiling Structures/Linings/S10				<b>Chrysotile (white asbestos)</b>		
<b>B00G - R0035 - Withdrawal Space - 1hb</b>						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1198/B00G/R0026/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0036 - General Storeroom</b>						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1198/B00G/R0026/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0037 - Withdrawal Space - 1hb</b>						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1198/B00G/R0026/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0038 - General Storeroom</b>						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1198/B00G/R0026/Ceiling Structures/Linings/S11				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
<b>B00G - R0039 - Distribution Board</b>						
No Asbestos						
<b>B00G - R0040 - Home Base</b>						
No Asbestos						
<b>B00G - R0041 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00G - R0042 - Home Base Store</b>						
No Asbestos						
<b>B00G - R0043 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00G - R0044 - Home Base Store</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00G - R0045 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00G - R0046 - Home Base</b>						
No Asbestos						
<b>B00G - R0047 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00G - R0048 - Movement</b>						
No Asbestos						
<b>B00G - R0049 - Movement</b>						
No Asbestos						
<b>B00G - R0050 - Home Base</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - General Learning - 1971 - Brick/Veneer (Brick/Veneer)**

**Exterior**

panels Under Windows	Flat AC Sheeting	20m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1198/B00H/panels Under Windows/S1					<b>Chrysotile (white asbestos)</b>
Gable Verge Lining	Flat AC Sheeting					<b>No Asbestos Detected</b>
	1198/B00H/Gable Verge Lining/S8					
Eaves Linings	Flat AC Sheeting	60m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1198/B00H/R0028/Ceiling Structures/Linings/S4					<b>Chrysotile (white asbestos) , Amosite (brown Asbestos)</b>
Wall Cladding	Flat AC Sheeting					<b>No Asbestos Detected</b>
	1198/B00H/R0028/Wall cladding/S3					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting					<b>No Asbestos Detected</b>
	1198/B00H/Underfloor Voids - Packing to Floor Joists/S7					
Ceiling Voids	No Asbestos Found					

**Interior**

**B00H - R0002 - Withdrawal Space - 1hb**

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1198/B00H/R0028/Ceiling Structures/Linings/S4					<b>Chrysotile (white asbestos) , Amosite (brown Asbestos)</b>
Wall Linings Internal	Flat AC Sheeting					<b>No Asbestos Detected</b>
	1198/B00H/R0002/Wall Linings Internal/S5					

**B00H - R0013 - Distribution Board**

Note: No inspection of live electrical installation.

Electrical Backing Board	Resinous Board	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Assumed Asbestos - Electrical Hazard</b>
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1198/B00H/R0028/Ceiling Structures/Linings/S4					<b>Chrysotile (white asbestos) , Amosite (brown Asbestos)</b>
Wall Linings Internal	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1198/B00H/R0013/Wall Linings Internal/S9					<b>Chrysotile (white asbestos)</b>

**B00H - R0017 - Home Base**

No Asbestos

**B00H - R0018 - Home Base Store**

No Asbestos

**B00H - R0019 - Withdrawal Space - 1hb**

No Asbestos

**B00H - R0020 - Home Base Store**

No Asbestos

**B00H - R0021 - Withdrawal Space - 1hb**

No Asbestos

**B00H - R0022 - Home Base**

No Asbestos

**B00H - R0023 - Practical Activities - 1hb**

No Asbestos

**B00H - R0024 - Practical Activities - 1hb**

No Asbestos

**B00H - R0025 - Home Base**

No Asbestos

**B00H - R0026 - Home Base Store**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00H - R0027 - Withdrawal Space - 1hb**

No Asbestos

**B00H - R0028 - Movement**

Panels Under Windows	Flat AC Sheeting	20m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1198/B00H/R0028/Panels Under Windows/S2				<b>Chrysotile (white asbestos)</b>	
Wall cladding	Flat AC Sheeting					<b>No Asbestos Detected</b>
	1198/B00H/R0028/Wall cladding/S3					
Ceiling Structures/Linings	Flat AC Sheeting	58m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1198/B00H/R0028/Ceiling Structures/Linings/S4				<b>Chrysotile (white asbestos) , Amosite (brown Asbestos)</b>	
Panels Above Windows	Flat AC Sheeting	3m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1198/B00H/R0028/Panels Under Windows/S2				<b>Chrysotile (white asbestos)</b>	

**B00H - R9001 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00I - Pupil Facilities - 1999 - Steel (Steel)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00I - R0001 - Canteen Covered Area**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - General Learning - 1997 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00J - R0001 - Practical Activities - 1hb**

No Asbestos

**B00J - R0002 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00J - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00J - R0004 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00J - R0005 - Practical Activities - 1hb**

No Asbestos

**B00J - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00J - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00J - R0008 - Practical Activities - 1hb**

No Asbestos

**B00J - R0009 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00J - R0010 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00J - R0011 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00J - R0012 - General Storeroom**

No Asbestos

**B00J - R0013 - General Storeroom**

No Asbestos

**B00J - R0014 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00J - R0015 - Movement**

No Asbestos

**B00J - R0016 - Movement**

No Asbestos

**B00J - R0017 - Stairs**

No Asbestos

**B00J - R1001 - Practical Activities - 1hb**

No Asbestos

**B00J - R1002 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00J - R1003 - Home Base Store**



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00J - R1004 - Withdrawal Space - 1hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00J - R1005 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00J - R1006 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00J - R1007 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00J - R1008 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00J - R1009 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00J - R1010 - Withdrawal Space - 1hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00J - R1011 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
<b>B00J - R1012 - Distribution Board</b>						Note: No inspection of live electrical installation.
No Asbestos						
<b>B00J - R1013 - Movement</b>						
No Asbestos						
<b>B00J - R1014 - Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - General Learning - 1997 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00K - R0001 - Practical Activities - 1hb**

No Asbestos

**B00K - R0002 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00K - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00K - R0004 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00K - R0005 - Practical Activities - 1hb**

No Asbestos

**B00K - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00K - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00K - R0008 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00K - R0009 - Practical Activities - 1hb**

No Asbestos

**B00K - R0010 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00K - R0011 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00K - R0012 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00K - R0013 - General Storeroom**

No Asbestos

**B00K - R0014 - Movement**

No Asbestos

**B00K - R0015 - Stairs**

No Asbestos

**B00K - R1001 - Practical Activities - 1hb**

No Asbestos

**B00K - R1002 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00K - R1003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00K - R1004 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00K - R1005 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00K - R1006 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00K - R1007 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00K - R1008 - Withdrawal Space - 1hb</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00K - R1009 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00K - R1010 - Home Base</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00K - R1011 - Home Base Store</b>						
Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found						
<b>B00K - R1012 - Distribution Board</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00K - R1013 - Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Pupil Facilities - 1997 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00L - R0001 - Toilets - Girls**

No Asbestos

**B00L - R0002 - Staff Toilet**

No Asbestos

**B00L - R0003 - Toilets - Boys**

No Asbestos

**B00L - R0004 - Cleaning Distributed Store**

No Asbestos

**B00L - R0005 - Kiln Room**

No Asbestos

**B00L - R0007 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - Administration - 1996 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior**

**B00M - R0001 - Staff Room**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00M - R0002 - Staff Room Annexe**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00M - R0003 - Staff Toilet**

No Asbestos
-------------

**B00M - R0004 - No Access**

No Asbestos
-------------

**B00M - R0005 - Staff Toilet**

No Asbestos
-------------

**B00M - R0006 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00M - R0007 - Security Store**

No Asbestos
-------------

**B00M - R0008 - Principal**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00M - R0009 - Clerical Office**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00M - R0010 - Movement**

No Asbestos
-------------

**B00M - R0011 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00M - R0012 - Duplicating Workroom**

No Asbestos
-------------

**B00M - R0013 - Sick Bay**

No Asbestos
-------------

**B00M - R0014 - Sick Bay - Shower/Toilet**

No Asbestos
-------------

**B00M - R0015 - Interview**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00M - R0016 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00M - R0017 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00M - R0018 - Cleaning Distributed Store**

No Asbestos
-------------

**B00M - R0019 - Main Switch Board**

No Asbestos
-------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00N - Library - 1996 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00N - R0001 - Disabled Toilet**

No Asbestos

**B00N - R0002 - Staff Toilet**

No Asbestos

**B00N - R0003 - Communications Room**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00N - R0004 - Library Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00N - R0005 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00N - R0006 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00N - R0007 - Plant**

No Asbestos

**B00N - R0008 - Plant**

No Asbestos

**B00N - R0009 - Cleaning Distributed Store**

No Asbestos

**B00N - R0010 - Special Programs Room**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00N - R0011 - Special Programs Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00P - Communal Facilities - 1996 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00P - R0001 - Movement**

No Asbestos

**B00P - R0002 - Canteen**

No Asbestos

**B00P - R0003 - Canteen Office/Store**

No Asbestos

**B00P - R0004 - Sports Store**

No Asbestos

**B00P - R0005 - Hall Chair Store**

No Asbestos

**B00P - R0006 - P.E. Store**

No Asbestos

**B00P - R0007 - Toilets - Boys**

No Asbestos

**B00P - R0008 - Shower/Change**

No Asbestos

**B00P - R0009 - Movement**

No Asbestos

**B00P - R0010 - Raised Platform**

No Asbestos

**B00P - R0011 - Movement**

No Asbestos

**B00P - R0012 - Toilets - Girls**

No Asbestos

**B00P - R0013 - Garden Store**

No Asbestos

**B00P - R0014 - General Assistant/Bulk Store**

No Asbestos

**B00P - R0015 - Cleaning Supplies**

No Asbestos

**B00P - R0016 - Plant**

No Asbestos

**B00P - R0017 - Disabled Toilet**

No Asbestos

**B00P - R0018 - Communal Space**

No Asbestos

**B00P - R0019 - Cleaning Distributed Store**

No Asbestos

**B00P - R0020 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00P - R0021 - Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00Q - Communal Facilities - 1999 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00Q - R0001 - Sports Store**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00R - General Learning - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior**

**B00R - R0001 - Special Programs Room - Type 1**

No Asbestos

**B00R - R0002 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00S - General Learning - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior**

**B00S - R0001 - External Movement**

No Asbestos

**B00S - R0002 - Practical Activities - 1hb**

No Asbestos

**B00S - R0003 - Home Base Store**

No Asbestos

**B00S - R0004 - Home Base**

No Asbestos

**B00S - R0005 - Withdrawal Space - 2hb**

No Asbestos

**B00S - R0006 - Home Base**

No Asbestos

**B00S - R0007 - Home Base Store**

No Asbestos

**B00S - R0008 - Practical Activities - 1hb**

No Asbestos

**B00S - R0009 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00T - Storage - 2011 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior**

**B00T - R0001 - General Storeroom**

No Asbestos

**B00T - R0002 - P.E. Store**

No Asbestos

**B00T - R0003 - General Assistant/Bulk Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00U - Music - 2011 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior**

**B00U - R0001 - Special Programs Room**

No Asbestos

**B00U - R0002 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Build+1 - Building Between N and P**

**Exterior**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 602 - D10051 - Learning Unit - Standard With P.A.A. : Placement Date - 30/04/2014**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D13429 - Learning Unit - Standard With P.A.A. : Placement Date - 14/03/2013**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017