


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Berkeley Vale Public School (1203)
Region : Hunter/Central Coast
State Electorate : The Entrance
Local Government Area : Wyong

Initial Survey : Noel Arnold & Associates : 28 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 17 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1981 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00A/R0018/Ceiling Structures/Linings/S12				Chrysotile (white asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00A - M0001 - Interview (15.08 m2)**

No Asbestos

B00A - R0001 - Staff Room (75.29 m2)

No Asbestos

B00A - R0002 - Security Store (10.73 m2)

Floor Coverings Res/Textile	Vinyl Tiles	1203/B00A/R0011/Floor Coverings Res/Textile/S13			No Asbestos Detected
-----------------------------	-------------	---	--	--	-----------------------------

B00A - R0003 - Interview (21.98 m2)

Floor Coverings Res/Textile	Vinyl Tiles	1203/B00A/R0011/Floor Coverings Res/Textile/S13			No Asbestos Detected
-----------------------------	-------------	---	--	--	-----------------------------

B00A - R0004 - Staff Toilet (2.76 m2)

No Asbestos

B00A - R0005 - Distribution Board (1.24 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0006 - Staff Toilet (3.72 m2)

No Asbestos

B00A - R0007 - Interview (12.14 m2)

No Asbestos

B00A - R0008 - Deputy Principal (14.07 m2)

No Asbestos

B00A - R0009 - Principal (21.26 m2)

No Asbestos

B00A - R0010 - Sick Bay (10.85 m2)

Floor Coverings Res/Textile	Vinyl Tiles	1203/B00A/R0011/Floor Coverings Res/Textile/S13			No Asbestos Detected
-----------------------------	-------------	---	--	--	-----------------------------

B00A - R0011 - Cleaning Distributed Store (2.03 m2)

Floor Coverings Res/Textile	Vinyl Tiles	1203/B00A/R0011/Floor Coverings Res/Textile/S13			No Asbestos Detected
-----------------------------	-------------	---	--	--	-----------------------------

B00A - R0012 - Interview (13.79 m2)

No Asbestos

B00A - R0013 - Clerical Office (13.91 m2)

No Asbestos

B00A - R0014 - Entry Vestibule (13.95 m2)

No Asbestos

B00A - R0015 - Duplicating Workroom (35.38 m2)

Floor Coverings Res/Textile	Vinyl Tiles	1203/B00A/R0011/Floor Coverings Res/Textile/S13			No Asbestos Detected
-----------------------------	-------------	---	--	--	-----------------------------

B00A - R0016 - Movement (21.41 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R0017 - Movement (31.41 m2)

No Asbestos

B00A - R0018 - Movement (125.08 m2)

Ceiling Structures/Linings	Flat AC Sheeting	126m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	-------	------------	--------------------	---------	--------------------

1203/B00A/R0018/Ceiling Structures/Linings/S12

Chrysotile (white asbestos)

B00A - R0019 - Toilets - Boys (3.61 m2)

No Asbestos

B00A - R0020 - Toilets - Girls (3.61 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library - 1981 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00B - M0002 - Stairs (1.21 m2)**

No Asbestos

B00B - M0003 - Reading Area (12.57 m2)

No Asbestos

B00B - M0004 - General Storeroom (19.06 m2)

Wall Linings Internal	Flat AC Sheeting					
	1203/B00B/M0004/Wall Linings Internal/S6					No Asbestos Detected

B00B - M0005 - Special Programs Room (9.35 m2)

No Asbestos

B00B - M0006 - General Storeroom (24.5 m2)

No Asbestos

B00B - M0007 - Stairs (3.12 m2)

No Asbestos

B00B - M0008 - Communal/Performance Store (30.98 m2)

No Asbestos

B00B - M0009 - Stairs (0.35 m2)

No Asbestos

B00B - R0001 - General Assistant/Bulk Store (8.09 m2)

No Asbestos

B00B - R0002 - Cleaning Supplies (8.13 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
	1203/B00B/R0002/Floor Coverings Res/Textile/S14					No Asbestos Detected

B00B - R0003 - Movement (91.92 m2)

Ceiling Structures/Linings	Flat AC Sheeting	92m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00B/R0003/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00B - R0004 - Seminar/Study (16.9 m2)

No Asbestos

B00B - R0005 - K.L.A. Store (16.9 m2)

No Asbestos

B00B - R0006 - Reading Area (248.27 m2)

No Asbestos

B00B - R0007 - K.L.A. Store (11.36 m2)

No Asbestos

B00B - R0008 - Library Office/Workroom (11.36 m2)

No Asbestos

B00B - R0009 - Library Office/Workroom (20.67 m2)

No Asbestos

B00B - R0010 - Cleaning Distributed Store (1.02 m2)

No Asbestos

B00B - R0011 - Distribution Board (1.86 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0012 - Movement (7.4 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00B - R0013 - Stairs (2.2 m2)

No Asbestos

B00B - R0014 - Stairs (3.7 m2)

No Asbestos

B00B - R0015 - Stairs (0.43 m2)

No Asbestos

B00B - R0016 - General Storeroom (3.02 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Communal Facilities - 1981 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	10m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00C/Eaves Linings/S3					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00C - M0001 - General Storeroom (18.9 m2)**

No Asbestos

B00C - R0001 - Garden Store (11.12 m2)

No Asbestos

B00C - R0002 - Toilets - Boys (9 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	5m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00C/R0004/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)

B00C - R0003 - External Movement (16.46 m2)

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00C/R0018/Ceiling Structures/Linings/S27					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00C - R0004 - Toilets - Girls (11.48 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00C/R0004/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)

B00C - R0005 - Main Switch Board (8 m2)

No Asbestos

B00C - R0006 - External Movement (27.15 m2)

Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00C/R0018/Ceiling Structures/Linings/S27					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00C - R0007 - Communal Space (227.08 m2)

No Asbestos

B00C - R0008 - Cleaning Distributed Store (10.9 m2)

No Asbestos

B00C - R0009 - Raised Platform (52.59 m2)

No Asbestos

B00C - R0010 - P.E. Store (10.2 m2)

No Asbestos

B00C - R0011 - General Storeroom (3.01 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1203/B00C/R0011/Floor Coverings Res/Textile/S2					No Asbestos Detected

B00C - R0012 - External Movement (9.48 m2)

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00C/R0018/Ceiling Structures/Linings/S27					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00C - R0013 - Canteen (42.96 m2)

No Asbestos

B00C - R0014 - Canteen Office/Store (6.08 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
B00C - R0015 - Staff Toilet (2.73 m2)						
No Asbestos						
B00C - R0016 - Canteen Office/Store (2.89 m2)						
No Asbestos						
B00C - R0017 - Disabled Toilet (3.19 m2)						
No Asbestos						
B00C - R0018 - External Movement (9.5 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1203/B00C/R0018/Ceiling Structures/Linings/S27				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00C - R0019 - External Movement (5.77 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1203/B00C/R0018/Ceiling Structures/Linings/S27				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1981 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00C/Eaves Linings/S3					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00D - R0001 - External Movement (70.33 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	71m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00D/R0001/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)

B00D - R0002 - Home Base (62.47 m2)

No Asbestos

B00D - R0003 - Home Base Store (2.2 m2)

No Asbestos

B00D - R0004 - Withdrawal Space - 1hb (12.04 m2)

No Asbestos

B00D - R0005 - Home Base Store (1.99 m2)

No Asbestos

B00D - R0006 - Practical Activities - 1hb (31 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
	1203/B00D/R0013/Floor Coverings Res/Textile/S11					No Asbestos Detected

B00D - R0007 - Home Base (61.4 m2)

No Asbestos

B00D - R0008 - Movement (11.3 m2)

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00D/R0001/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)

B00D - R0009 - Home Base (61.49 m2)

No Asbestos

B00D - R0010 - Movement (11.93 m2)

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00D/R0001/Ceiling Structures/Linings/S10					Chrysotile (white asbestos)

B00D - R0011 - Withdrawal Space - 1hb (12.04 m2)

No Asbestos

B00D - R0012 - Home Base Store (2.2 m2)

No Asbestos

B00D - R0013 - Practical Activities - 1hb (31 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
	1203/B00D/R0013/Floor Coverings Res/Textile/S11					No Asbestos Detected

B00D - R0014 - Home Base Store (1.99 m2)

No Asbestos

B00D - R0015 - Staff Room Annexe (11.69 m2)

No Asbestos

B00D - R0016 - Security Store (8.93 m2)

No Asbestos

B00D - R0017 - Distribution Board (0.95 m2)

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00D - R0018 - Cleaning Distributed Store (0.76 m2)

No Asbestos

B00D - R0019 - External Movement (11.76 m2)

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

1203/B00D/R0001/Ceiling Structures/Linings/S10

Chrysotile (white asbestos)

B00D - R0020 - Home Base (63.26 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1981 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00C/Eaves Linings/S3					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00E - R0001 - Home Base (62.38 m2)

No Asbestos

B00E - R0002 - Home Base Store (1.99 m2)

No Asbestos

B00E - R0003 - Practical Activities - 1hb (30.99 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
	1203/B00E/R0013/Floor Coverings Res/Textile/S9					No Asbestos Detected

B00E - R0004 - Home Base (61.49 m2)

No Asbestos

B00E - R0005 - Home Base Store (2.21 m2)

No Asbestos

B00E - R0006 - Withdrawal Space - 1hb (12.04 m2)

No Asbestos

B00E - R0007 - Movement (10.88 m2)

No Asbestos

B00E - R0008 - Security Store (9.03 m2)

No Asbestos

B00E - R0009 - Distribution Board (0.95 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0010 - Cleaning Distributed Store (0.76 m2)

No Asbestos

B00E - R0011 - Kiln Room (10.66 m2)

No Asbestos

B00E - R0012 - Communications Room (35.21 m2)

No Asbestos

B00E - R0013 - Practical Activities - 1hb (30.99 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
	1203/B00E/R0013/Floor Coverings Res/Textile/S9					No Asbestos Detected

B00E - R0014 - Home Base (61.49 m2)

No Asbestos

B00E - R0015 - Home Base Store (1.99 m2)

No Asbestos

B00E - R0016 - Home Base Store (2.21 m2)

No Asbestos

B00E - R0017 - Personal Effects Storage (12.08 m2)

No Asbestos

B00E - R0018 - Home Base (61.58 m2)

No Asbestos

B00E - R0019 - External Movement (17.74 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting					
	1203/B00E/R0019/Ceiling Structures/Linings/S7					No Asbestos Detected
B00E - R0020 - Sports Store (11.94 m2)						
No Asbestos						
B00E - R0021 - Toilets - Girls (9.15 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	6m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00E/R0022/Partition Walls (Cubicles)/S8					Chrysotile (white asbestos)
B00E - R0022 - Toilets - Boys (12.43 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00E/R0022/Partition Walls (Cubicles)/S8					Chrysotile (white asbestos)
B00E - R0023 - External Movement (17.87 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	1203/B00E/R0019/Ceiling Structures/Linings/S7					No Asbestos Detected
B00E - R0024 - External Movement (23.17 m2)						
Ceiling Structures/Linings	Flat AC Sheeting					
	1203/B00E/R0019/Ceiling Structures/Linings/S7					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1981 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 1203/B00F/Eaves Linings/S22					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00F - R0001 - Movement (8.6 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00F/R0003/Ceiling Structures/Linings/S28					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00F - R0002 - Home Base (62.39 m2)

No Asbestos

B00F - R0003 - External Movement (12.04 m2)

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00F/R0003/Ceiling Structures/Linings/S28					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00F - R0004 - Withdrawal Space - 1hb (12.01 m2)

No Asbestos

B00F - R0005 - Home Base Store (2.21 m2)

No Asbestos

B00F - R0006 - Home Base Store (1.99 m2)

No Asbestos

B00F - R0007 - Home Base (62.39 m2)

No Asbestos

B00F - R0008 - Practical Activities - 1hb (30.72 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
	1203/B00F/R1008/Floor Coverings Res/Textile/S21					No Asbestos Detected

B00F - R0009 - Communications Room (34.3 m2)

No Asbestos

B00F - R0010 - Security Store (11.02 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1203/B00F/R0010/Floor Coverings Res/Textile/S23					No Asbestos Detected

B00F - R0011 - Distribution Board (0.83 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00F/R0003/Ceiling Structures/Linings/S28					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00F - R0012 - Kiln Room (5.1 m2)

No Asbestos

B00F - R0013 - Cleaning Distributed Store (2.37 m2)

No Asbestos

B00F - R0014 - External Movement (19.32 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
	1203/B00F/R1008/Floor Coverings Res/Textile/S21					No Asbestos Detected

B00F - R0015 - General Storeroom (33.2 m2)

No Asbestos

B00F - R0016 - External Stairs (8.92 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1203/B00F/R0003/Ceiling Structures/Linings/S28					Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00F - R1001 - Movement (9.66 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1203/B00F/R0003/Ceiling Structures/Linings/S28					Chrysotile (white asbestos) , Amosite (brown asbestos)	
B00F - R1002 - Home Base (62.39 m2)						
No Asbestos						
B00F - R1003 - External Movement (11.25 m2)						
No Asbestos						
B00F - R1004 - Home Base Store (2.21 m2)						
No Asbestos						
B00F - R1005 - Home Base Store (1.99 m2)						
No Asbestos						
B00F - R1006 - Withdrawal Space - 1hb (12.01 m2)						
No Asbestos						
B00F - R1007 - Home Base (62.39 m2)						
No Asbestos						
B00F - R1008 - Practical Activities - 1hb (30.72 m2)						
Floor Coverings Res/Textile	Vinyl Sheet					
1203/B00F/R1008/Floor Coverings Res/Textile/S21					No Asbestos Detected	
B00F - R1009 - Garden Store (10.87 m2)						
No Asbestos						
B00F - R1010 - Garden Store (10.81 m2)						
No Asbestos						
B00F - R1011 - Stairs (3.63 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1203/B00F/R0003/Ceiling Structures/Linings/S28					Chrysotile (white asbestos) , Amosite (brown asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1979 - Brick/Block (Brick/Block)**Exterior**

Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00G/Gable Verge Lining/S25				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00G - R0001 - Home Base Store (5.36 m2)**

Floor Coverings Res/Textile	Vinyl Tiles	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00G/R0001/Floor Coverings Res/Textile/S15				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite	6m2	Throughout	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	1203/B00G/R0003/Ceiling Structures/Linings/S29				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00G - R0002 - Distribution Board (0.67 m2)

Note: No inspection of live electrical installation.

Floor Coverings Res/Textile	Vinyl Tiles	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00G/R0001/Floor Coverings Res/Textile/S15				Chrysotile (white asbestos)	

B00G - R0003 - Practical Activities - 1hb (8.22 m2)

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00G/R0001/Floor Coverings Res/Textile/S15				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite	9m2	Throughout	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	1203/B00G/R0003/Ceiling Structures/Linings/S29				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00G - R0004 - Toilets - Boys/Girls (3.55 m2)

Ceiling Structures/Linings	Vermiculite	4m2	Throughout	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	1203/B00G/R0003/Ceiling Structures/Linings/S29				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00G - R0005 - Toilets - Boys/Girls (3.55 m2)

Ceiling Structures/Linings	Vermiculite	4m2	Throughout	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	1203/B00G/R0003/Ceiling Structures/Linings/S29				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00G - R0006 - Practical Activities - 1hb (8.22 m2)

Floor Coverings Res/Textile	Vinyl Tiles	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00G/R0001/Floor Coverings Res/Textile/S15				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite	9m2	Throughout	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	1203/B00G/R0003/Ceiling Structures/Linings/S29				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00G - R0007 - Home Base Store (6.27 m2)

Floor Coverings Res/Textile	Vinyl Tiles	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00G/R0001/Floor Coverings Res/Textile/S15				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Vermiculite	7m2	Throughout	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	1203/B00G/R0003/Ceiling Structures/Linings/S29				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00G - R0008 - Home Base (91.76 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite	92m2	Throughout	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
1203/B00G/R0003/Ceiling Structures/Linings/S29				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00G - R0009 - Home Base (92.28 m2)						
Ceiling Structures/Linings	Vermiculite	93m2	Throughout	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
1203/B00G/R0003/Ceiling Structures/Linings/S29				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00G - R0010 - External Movement (76.48 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1979 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00H/Eaves Linings/S24					Chrysotile (white asbestos)
Panels Under Windows	Flat AC Sheeting	14m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00H/R0001/Panels Under windows/S16					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00H - R0001 - External Movement (68.63 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	69m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00H/R0001/Ceiling Structures/Linings/S18					Chrysotile (white asbestos)
Panels Under Windows	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00H/R0001/Panels Under windows/S16					Chrysotile (white asbestos)

B00H - R0002 - K.L.A. Store (4.75 m2)

Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00H/R0005/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)

B00H - R0003 - Cleaning Distributed Store (2.61 m2)

Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00H/R0005/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)

B00H - R0004 - Staff Toilet (2.42 m2)

No Asbestos

B00H - R0005 - Staff Room Annexe (13.1 m2)

Floor Coverings Res/Textile	Vinyl Tiles	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00H/R0005/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)

B00H - R0006 - Home Base (59.04 m2)

No Asbestos

B00H - R0007 - Home Base Store (4.45 m2)

Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00H/R0005/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)

B00H - R0008 - Distribution Board (2.39 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0009 - Practical Activities - 1hb (13.99 m2)

Floor Coverings Res/Textile	Vinyl Sheet					
	1203/B00H/R0009/Floor Coverings Res/Textile/S19					No Asbestos Detected

B00H - R0010 - Home Base Store (7.03 m2)

Floor Coverings Res/Textile	Vinyl Tiles	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00H/R0005/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)

B00H - R0011 - Home Base (59.04 m2)

No Asbestos

B00H - R0012 - Toilets - Boys (13.72 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1203/B00H/R0013/Partition Walls (Cubicles)/S20					Chrysotile (white asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00H - R0013 - Toilets - Girls (13.72 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
1203/B00H/R0013/Partition Walls (Cubicles)/S20					Chrysotile (white asbestos)	
B00H - R0014 - Movement (4.03 m2)						
No Asbestos						
B00H - R0015 - Movement (4.77 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1203/B00H/R0005/Floor Coverings Res/Textile/S17					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B001 - R0001 - External Movement (38.47 m2)

No Asbestos

B001 - R0002 - Practical Activities - 1hb (19.4 m2)

No Asbestos

B001 - R0003 - Home Base Store (6.02 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0004 - Home Base (59.19 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0005 - Withdrawal Space - 2hb (11.36 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0006 - Home Base (59.18 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0007 - Home Base Store (6.02 m2)

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0008 - Practical Activities - 1hb (19.4 m2)

No Asbestos

B001 - R0009 - External Movement (27.74 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 2006 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting					
	1203/B00J/Underfloor Voids - Packing to Floor Joists/S26					No Asbestos Detected

Interior

B00J - R0001 - Other-Community Use (16.85 m2)

No Asbestos

B00J - R0002 - Other-Community Use (10.51 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Special Purpose - 2006 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00K - R0001 - Garden Store (12.88 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Special Purpose - 2006 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00L - R0001 - Sports Store (26.47 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Other-Community Use/Music - 2008 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00M - R0001 - Schools As Community Centres Program (19.51 m2)

No Asbestos

B00M - R0002 - Kitchen - Pre (10.4 m2)

No Asbestos

B00M - R0003 - Communal Space (103.72 m2)

No Asbestos

B00M - R0004 - Schools As Community Centres Program (17.02 m2)

No Asbestos

B00M - R0005 - Movement (4.28 m2)

No Asbestos

B00M - R0006 - Toilets-Unisex (1.76 m2)

No Asbestos

B00M - R0007 - Toilets-Unisex (3.79 m2)

No Asbestos

B00M - R0008 - External Movement (48.85 m2)

No Asbestos

B00M - R0009 - External Movement (11.73 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00N - General Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00N - R0001 - External Movement (61.3 m2)

No Asbestos

B00N - R0002 - Practical Activities - 1hb (19.08 m2)

No Asbestos

B00N - R0003 - Home Base Store (6.13 m2)

No Asbestos

B00N - R0004 - Toilets - Boys (8.78 m2)

No Asbestos

B00N - R0005 - Toilets - Girls (11.68 m2)

No Asbestos

B00N - R0006 - Home Base (60.26 m2)

No Asbestos

B00N - R0007 - Withdrawal Space - 2hb (11.64 m2)

No Asbestos

B00N - R0008 - Home Base (60.26 m2)

No Asbestos

B00N - R0009 - Home Base Store (6.13 m2)

No Asbestos

B00N - R0010 - Practical Activities - 1hb (18.21 m2)

No Asbestos

B00N - R0011 - Distribution Board (0.57 m2)

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - General Learning - 2011 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B000 - R0001 - External Movement (53.02 m2)

No Asbestos

B000 - R0002 - Practical Activities - 1hb (19.62 m2)

No Asbestos

B000 - R0003 - Home Base Store (6.49 m2)

No Asbestos

B000 - R0004 - Home Base (58.95 m2)

No Asbestos

B000 - R0005 - Withdrawal Space - 2hb (10.93 m2)

No Asbestos

B000 - R0006 - Home Base (58.95 m2)

No Asbestos

B000 - R0007 - Home Base Store (6.49 m2)

No Asbestos

B000 - R0008 - Practical Activities - 1hb (19.62 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - General Learning - 2011 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Ceiling Voids No Asbestos Found

Underfloor Voids No Asbestos Found

Interior**B00P - R0001 - External Movement (58.36 m2)**

No Asbestos

B00P - R0002 - Practical Activities - 1hb (19.62 m2)

No Asbestos

B00P - R0003 - Home Base Store (6.49 m2)

No Asbestos

B00P - R0004 - Home Base (58.95 m2)

No Asbestos

B00P - R0005 - Withdrawal Space - 2hb (10.93 m2)

No Asbestos

B00P - R0006 - Home Base (58.95 m2)

No Asbestos

B00P - R0007 - Home Base Store (6.49 m2)

No Asbestos

B00P - R0008 - Practical Activities - 1hb (19.62 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10514 - Learning Unit - Standard With P.A.A. : Placement Date - 10/05/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 840 - D11011 - Girls Toilet : Placement Date - 28/10/1996

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	2.88 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - Toilets-Girls

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	4 m2
End wall panel	Flat AC Sheet	Assumed Asbestos	36 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	18 m2

OS 841 - D11086 - Boys Toilet : Placement Date - 30/06/1995

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	2.88 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - Toilets-Boys

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	6 m2
End wall panel	Flat AC Sheet	Assumed Asbestos	36 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	18 m2

OS 602 - D11860 - Learning Unit - Standard With P.A.A. : Placement Date - 24/07/2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 603 - D12054 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 14/01/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
NS 020 - D13148 - Staff Study/Store : Placement Date - 15/10/1997						
Exterior						
No Asbestos Found.						
Interior						
R1 - Staff Room						
No Asbestos Found.						
R2 - Store						
No Asbestos Found.						
R3 - Entry						
No Asbestos Found.						
OS 603 - D13595 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 5/01/2012						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 601 - D14861 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 601 - D14866 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995						
Exterior						
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
OS 601 - D15227 - Learning Unit - Standard/Withdrawal : Placement Date - 26/09/1995						
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017