

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Berrigan Public School (1207)
Region : Riverina
State Electorate : Murray
Local Government Area : Berrigan

Initial Survey : Noel Arnold & Associates : 09 - May - 2008
Reviewed By : Parsons Brinckerhoff : 15 - Feb - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1982 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Raked Ceiling No Asbestos Found

Interior

B00A - R0001 - Reading Area

No Asbestos

B00A - R0002 - Library Office/Workroom

Floor Coverings Res/Textile Vinyl Tiles
 1207/B00A/R0006/Floor Coverings Res/Textile/S7 **No Asbestos Detected**

B00A - R0003 - General Storeroom

No Asbestos

B00A - R0004 - External Movement

No Asbestos

B00A - R0005 - Principal

No Asbestos

B00A - R0006 - General Storeroom

Floor Coverings Res/Textile Vinyl Tiles
 1207/B00A/R0006/Floor Coverings Res/Textile/S7 **No Asbestos Detected**

B00A - R0007 - External Movement

No Asbestos

B00A - R0008 - Main Switch Board

Wall Linings Internal Flat AC Sheeting 8m2 South facing, East facing Minimal Damage (2) Low (1) Low Priority (2-3)
 1207/B00A/R0008/Wall Linings Internal/S8 **Chrysotile (white asbestos)**

B00A - R0009 - Movement

No Asbestos

B00A - R0010 - Clerical Office

No Asbestos

B00A - R0011 - Duplicating Workroom

No Asbestos

B00A - R0015 - Cleaning Distributed Store

Wall Linings Internal Flat AC Sheeting 18m2 All surfaces Good Condition (1) Low (1) Low Priority (2-3)
 1207/B00A/R0014/Wall Linings Internal/S9 **Chrysotile (white asbestos)**

Ceiling Structures/Linings Flat AC Sheeting 2m2 All surfaces Good Condition (1) Low (1) Low Priority (2-3)
 1207/B00A/R0014/Wall Linings Internal/S9 **Chrysotile (white asbestos)**

B00A - R0016 - Sick Bay

Floor Coverings Res/Textile Vinyl Tiles
 1207/B00A/R0006/Floor Coverings Res/Textile/S7 **No Asbestos Detected**

B00A - R0017 - Staff Toilet

No Asbestos

B00A - R0018 - Staff Toilet

No Asbestos

B00A - R0019 - Toilet - Lobby

No Asbestos

B00A - R0020 - Toilet - Lobby

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0021 - Staff Room						
No Asbestos						
B00A - R0022 - Staff Kitchen						
No Asbestos						
B00A - R0023 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1897 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Packing to Floor Joists	Non Accessible Area - The entry point to the under floor area was blocked by equipment.

Interior

B00B - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	20m2	West End	Good Condition (1)	Low (1)	Low Priority (2-3)
1207/B00B/R0001/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	

B00B - R0002 - Craft Store

No Asbestos

B00B - R0003 - Home Base Store

No Asbestos

B00B - R0004 - Home Base

No Asbestos

B00B - R0005 - Home Base

No Asbestos

B00B - R0006 - General Storeroom

No Asbestos

B00B - R0007 - Staff Room Annexe

No Asbestos

B00B - R0008 - General Storeroom

No Asbestos

B00B - R0009 - Cleaning Distributed Store

Floor Coverings Res/Textile	Vinyl Tiles					
1207/B00A/R0006/Floor Coverings Res/Textile/S7					No Asbestos Detected	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1950 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Eaves Linings	Non Accessible Area - Height Restriction
Underfloor Voids - Packing to Floor Joists	No Asbestos Found

Interior

B00C - R0001 - External Movement

Electrical Mounting Board	Resinous Board	1Unit	South facing	Minimal Damage (2)	Low (1)	Low Priority (2-3)
---------------------------	----------------	-------	--------------	--------------------	---------	--------------------

Assumed Asbestos - Electrical Hazard Not able to be

B00C - R0002 - Home Base

No Asbestos

B00C - R0003 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Pupil Facilities - 1968 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1207/B00D/Eaves Linings/S13			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Cladding	Flat AC Sheeting	20m2	North facing, South facing, Upper portion, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1207/B00D/Wall Cladding/S6			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Under floor void - No access point	Non Accessible Area - No Access point to unnder floor void					

Interior

B00D - R0001 - External Movement

Ceiling Structures/Linings	No Asbestos Found					
Ceiling Structures/Linings	Compressed AC Sheet	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1207/B00D/R0001/Ceiling Structures/Linings/S14			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00D - R0002 - Canteen

No Asbestos

B00D - R0003 - Home Base Store

No Asbestos

B00D - R0004 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1950 - Timber (Timber)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found				
Ceiling Voids - Raked Ceiling	No Asbestos Found				
Eaves Linings	Flat AC Sheeting			1207/B00E/R0001/Ceiling Structures/Linings/S2	No Asbestos Detected
Incinerator	No Asbestos Found				

Interior

B00E - R0001 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting			1207/B00E/R0001/Ceiling Structures/Linings/S2	No Asbestos Detected
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1) Low Priority (2-3)
	1207/B00E/R0001/Partition Walls (Cubicles)/S3				Chrysotile (white asbestos)

B00E - R0002 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting			1207/B00E/R0001/Ceiling Structures/Linings/S2	No Asbestos Detected
Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1) Low Priority (2-3)
	1207/B00E/R0001/Partition Walls (Cubicles)/S3				Chrysotile (white asbestos)

B00E - R0003 - Disabled Toilet

Ceiling Structures/Linings	Flat AC Sheeting			1207/B00E/R0001/Ceiling Structures/Linings/S2	No Asbestos Detected
----------------------------	------------------	--	--	---	----------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1983 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Interior

B00F - R0001 - Movement

Floor Coverings Res/Textile Compressed AC Sheet

1207/Build+1/Room+1/Floor Coverings Res/Textile/S12

No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Shed - 1960 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Raked Ceiling No Asbestos Found

Interior

B00G - R0002 - General Storeroom

No Asbestos

Ceiling Structures/Linings No Asbestos Found

B00G - R0003 - Kiln Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Shed - 1950 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior

B00H - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Communal Facilities - 2008 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids - Raked Ceiling	No Asbestos Found

Interior

B00I - R0001 - Sports Store

No Asbestos

B00I - R0002 - Sports Store

No Asbestos

B00I - R0003 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids - Flat Roof	No Asbestos Found

Interior

B00J - R0001 - P.E. Store

No Asbestos

B00J - R0002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0003 - Communications Cupboard

No Asbestos

B00J - R0004 - Communal Space

No Asbestos

B00J - R0005 - Covered Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017