


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Beverly Hills Public School (1215)
Region : Sydney
State Electorate : Kogarah
Local Government Area : Hurstville

Initial Survey : Noel Arnold & Associates : 12 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00A - R0001 - Disabled Toilet

Wall Linings Internal	Flat AC Sheeting 1215/B00A/R0001/Wall Linings Internal/S3	No Asbestos Detected
-----------------------	--	-----------------------------

B00A - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0009 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0010 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0011 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0012 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0013 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0014 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0015 - External Movement

No Asbestos

B00A - R0016 - Practical Activities - 1hb

No Asbestos

B00A - R0017 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0018 - Practical Activities - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0019 - Practical Activities - 1hb						
No Asbestos						
B00A - R0020 - Withdrawal Space - 2hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0021 - Practical Activities - 1hb						
No Asbestos						
B00A - R0022 - Laundry - Type 2						
Wall Linings Internal	Flat AC Sheeting		1215/B00A/R0001/Wall Linings Internal/S3			No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Wall Cladding	Compressed AC Sheet 1215/B00B/R0001/Wall Linings Internal/S4					No Asbestos Detected
Ceiling Voids	No Asbestos Found					
Underfloor Void	No Asbestos Found					

Interior

B00B - R0001 - External Movement

Wall Linings Internal	Compressed AC Sheet 1215/B00B/R0001/Wall Linings Internal/S4					No Asbestos Detected
-----------------------	---	--	--	--	--	----------------------

B00B - R0002 - Practical Activities - 1hb

No Asbestos

B00B - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

B00B - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

B00B - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

B00B - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

B00B - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

B00B - R0008 - Practical Activities - 1hb

No Asbestos

B00B - R0009 - Ramp

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Pupil Facilities - 1947 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	140m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1215/B00C/Eaves Linings/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00C - R0001 - General Storeroom

No Asbestos

B00C - R0002 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	43m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1215/B00C/R0003/Ceiling Structures/Linings/S6			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00C - R0003 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	39m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1215/B00C/R0003/Ceiling Structures/Linings/S6			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00C - R0004 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1215/B00C/R0003/Ceiling Structures/Linings/S6			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00C - R0007 - Practical Activities - 1hb

No Asbestos

B00C - R0033 - External Movement

No Asbestos

B00C - R0034 - External Movement

No Asbestos

B00C - R0035 - Movement

No Asbestos

B00C - R0036 - Cleaning Distributed Store

No Asbestos

B00C - R0037 - Home Base

No Asbestos

B00C - R0038 - Practical Activities - 1hb

No Asbestos

B00C - R0039 - Home Base Store

No Asbestos

B00C - R0040 - Practical Activities - 1hb

No Asbestos

B00C - R0041 - Home Base

No Asbestos

B00C - R0042 - Home Base Store

No Asbestos

B00C - R0043 - Home Base Store

No Asbestos

B00C - R0044 - Withdrawal Space - 1hb

No Asbestos

B00C - R0045 - Distribution Board

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B00C - R0046 - Practical Activities - 1hb					
	No Asbestos					
	B00C - R0047 - Home Base					
	No Asbestos					
	B00C - R0048 - Withdrawal Space - 2hb					
	No Asbestos					
	B00C - R0049 - Home Base					
	No Asbestos					
	B00C - R0050 - Practical Activities - 1hb					
	No Asbestos					
	B00C - R0051 - Home Base Store					
	No Asbestos					
	B00C - R0052 - External Movement					
	No Asbestos					
	B00C - R0053 - External Movement					
	No Asbestos					
	B00C - R0054 - Cleaning Distributed Store					
	No Asbestos					
	B00C - R0055 - Plant					
	No Asbestos					
	B00C - R0056 - Home Base Store					
	No Asbestos					
	B00C - R0057 - Withdrawal Space - 1hb					
	No Asbestos					
	B00C - R0058 - Home Base					
	No Asbestos					
	B00C - R0059 - Practical Activities - 1hb					
	No Asbestos					
	B00C - R0060 - Home Base					
	No Asbestos					
	B00C - R0061 - Home Base					
	No Asbestos					
	B00C - R0062 - Practical Activities - 1hb					
	No Asbestos					
	B00C - R0063 - Withdrawal Space - 1hb					
	No Asbestos					
	B00C - R0064 - Home Base Store					
	No Asbestos					
	B00C - R0065 - Distribution Board					Note: No inspection of live electrical installation.
	No Asbestos					
	B00C - R0066 - External Movement					
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00D - R0001 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0002 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0003 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0004 - K.L.A. Store

No Asbestos

B00D - R0005 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	
	1215/B00D/R0005/Wall Linings Internal/S2	No Asbestos Detected

B00D - R0006 - Movement

No Asbestos

B00D - R0007 - Cleaning Distributed Store

No Asbestos

B00D - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Administration/Staff Facilities - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00E - R0001 - External Movement

No Asbestos

B00E - R0002 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0003 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0004 - Sick Bay

No Asbestos

B00E - R0005 - Access Shower/Toilet

No Asbestos

B00E - R0006 - Duplicating Workroom

No Asbestos

B00E - R0007 - Security Store

No Asbestos

B00E - R0008 - Main Switch Board

No Asbestos

B00E - R0009 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	1215/B00E/R0009/Wall Linings Internal/S5	No Asbestos Detected
-----------------------	------------------	--	-----------------------------

B00E - R0010 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	1215/B00E/R0009/Wall Linings Internal/S5	No Asbestos Detected
-----------------------	------------------	--	-----------------------------

B00E - R0011 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting	1215/B00E/R0009/Wall Linings Internal/S5	No Asbestos Detected
-----------------------	------------------	--	-----------------------------

B00E - R0012 - Cleaning Distributed Store

No Asbestos

B00E - R0013 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0014 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0015 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0016 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0017 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0018 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00E - R0019 - Interview

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00F - Communal Facilities/Pupil Facilities - 2001 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00F - R0015 - Communal Space**

No Asbestos

B00F - R0016 - Plant

No Asbestos

B00F - R0017 - Communications Cupboard

No Asbestos

B00F - R0018 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0019 - External Movement

No Asbestos

B00F - R0020 - Hall Chair Store

No Asbestos

B00F - R0021 - Raised Platform

No Asbestos

B00F - R0022 - Movement

No Asbestos

B00F - R0023 - Kiln Room

No Asbestos

B00F - R0024 - P.E. Store

No Asbestos

B00F - R0025 - Canteen Office/Store

No Asbestos

B00F - R0026 - Canteen

No Asbestos

B00F - R0027 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0028 - Cleaning Distributed Store

No Asbestos

B00F - R0029 - Movement

No Asbestos

B00F - R0030 - Toilets - Boys

No Asbestos

B00F - R0031 - Disabled Toilet

No Asbestos

B00F - R0032 - Toilets - Girls

No Asbestos

B00F - R0033 - Covered Outdoor Learning Area

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00G - R0001 - Home Base

No Asbestos

B00G - R0002 - Home Base

No Asbestos

B00G - R0003 - Home Base

No Asbestos

B00G - R0004 - Withdrawal Space - 1hb

No Asbestos

B00G - R0005 - Practical Activities

No Asbestos

B00G - R0006 - Practical Activities

No Asbestos

B00G - R0007 - Practical Activities

No Asbestos

B00G - R0008 - Withdrawal Space - 1hb

No Asbestos

B00G - R0009 - Withdrawal Space - 2hb

No Asbestos

B00G - R0010 - Home Base Store

No Asbestos

B00G - R0011 - Home Base Store

No Asbestos

B00G - R0012 - Home Base Store

No Asbestos

B00G - R0013 - Special Programs Store

No Asbestos

B00G - R0014 - Special Programs Store

No Asbestos

B00G - R0015 - External Movement

No Asbestos

B00G - R0016 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00G - R0017 - External Stairs

No Asbestos

B00G - R0018 - External Stairs

No Asbestos

B00G - R1001 - Home Base

No Asbestos

B00G - R1002 - Home Base

No Asbestos

B00G - R1003 - Home Base

No Asbestos

B00G - R1004 - Practical Activities

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00G - R1005 - Practical Activities						
No Asbestos						
B00G - R1006 - Practical Activities						
No Asbestos						
B00G - R1007 - Withdrawal Space - 1hb						
No Asbestos						
B00G - R1008 - Withdrawal Space - 2hb						
No Asbestos						
B00G - R1009 - Home Base Store						
No Asbestos						
B00G - R1010 - Home Base Store						
No Asbestos						
B00G - R1011 - Home Base Store						
No Asbestos						
B00G - R1012 - Distribution Board				Note: No inspection of live electrical installation.		
No Asbestos						
B00G - R1013 - External Movement						
No Asbestos						
B00G - R1014 - External Stairs						
No Asbestos						
B00G - R1015 - External Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

NS 100 - D10629 - Learning Unit - Single Primary/PAA : Placement Date - 5/01/2001

Exterior

No Asbestos Found.

Interior

R1 - Home Base

No Asbestos Found.

R2 - Practical Activity Area

No Asbestos Found.

R3 - Home Base Store

No Asbestos Found.

R4 - Entry

No Asbestos Found.

OS 602 - D15434 - Learning Unit - Standard With P.A.A. : Placement Date - 20/01/2002

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 602 - D15977 - Learning Unit - Standard With P.A.A. : Placement Date - 11/02/2003

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017