

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Binya Public School (1238)
Region : Riverina
State Electorate : Cootamundra
Local Government Area : Narrandera

Initial Survey : Noel Arnold & Associates : 09 - May - 2008
Reviewed By : Grencap-NAA : 15 - Jun - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Library - 1919 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1238/B00A/Eaves Linings/S1					Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area - Height Restriction 4m height					
Underfloor Voids	No Asbestos Found					

Interior**B00A - R0004 - External Movement**

No Asbestos

B00A - R0007 - Movement

No Asbestos

B00A - R0008 - Principal

No Asbestos

B00A - R0010 - Entry Vestibule

No Asbestos

B00A - R0011 - General Storeroom

No Asbestos

B00A - R0012 - Clerical Office/Workroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Shed - 1966 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B00B - R0001 - Sports Store

No Asbestos

B00B - R0002 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Library/General Learning - 1962 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	30m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	1238/B00C/Eaves Linings/S3					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	Non Accessible Area - Height Restriction 4m height					
Underfloor Voids	No Asbestos Found					

Interior**B00C - R0001 - Clerical Office**

No Asbestos

B00C - R0002 - Practical Activities - 1hb

No Asbestos

B00C - R0003 - Home Base

Wall Linings Internal	Flat AC Sheeting	2m2	South-west corner	Good Condition (1)	Low (1)	Low Priority (2-3)
	1238/B00C/R0003/Wall Linings Internal/S2					Chrysotile (white asbestos)

B00C - R0004 - External Movement

No Asbestos

B00C - R0005 - Reading Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1975 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 1238/B00D/Eaves Linings/S4	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

Interior**B00D - R0001 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting 1238/B00D/Eaves Linings/S4	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	------	------------	--------------------	---------	--

B00D - R0002 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting 1238/B00D/Eaves Linings/S4	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	-----	------------	--------------------	---------	--

B00D - R0003 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting 1238/B00D/Eaves Linings/S4	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	------	------------	--------------------	---------	--

Incinerette	Encapsulated Insulation material within unit Assumed Asbestos - Item inaccessible	1Unit	South	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
-------------	---	-------	-------	----------------------	---------	--------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1962 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B00E - R0001 - Drinking Facilities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017