


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Black Hill Public School (1247)
Region : Hunter/Central Coast
State Electorate : Cessnock
Local Government Area : Cessnock

Initial Survey : Noel Arnold & Associates : 26 - May - 2008
Reviewed By : AECOM : 17 - Jun - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1924 - Timber (Timber)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling Voids - Raked Ceiling	Non Accessible Area - Height Restriction - 3.89m					
Eaves Linings	Flat AC Sheeting 1247/B00A/Eaves Linings/S1				No Asbestos Detected	
Eaves Linings	Flat AC Sheeting	6m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction - 3.89m						

Interior

B00A - R0001 - Withdrawal Space - 1hb						
No Asbestos						
B00A - R0002 - Home Base						
No Asbestos						
B00A - R0003 - Security Store						
Floor Coverings Res/Textile	Vinyl Sheet 1247/B00A/R0003/Floor Coverings Res/Textile/S3				No Asbestos Detected	
B00A - R0004 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting 1247/B00A/R0004/Ceiling Structures/Linings/S2				No Asbestos Detected	
B00A - R0005 - Practical Activities - 1hb						
Floor Coverings Res/Textile	Vinyl Sheet 1247/B00A/R0003/Floor Coverings Res/Textile/S3				No Asbestos Detected	
B00A - R0006 - Home Base						
No Asbestos						
B00A - R0007 - Withdrawal Space - 1hb						
No Asbestos						
B00A - R0008 - Clerical Office						
No Asbestos						
B00A - R0009 - Security Store						
No Asbestos						
B00A - R0010 - Sports Store						
No Asbestos						
B00A - R0011 - Covered Outdoor Learning Area						
No Asbestos						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Pupil Facilities - 1960 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible, slab to ground. No access points.					
Ceiling Voids - Raked Ceiling	Non Accessible Area					
	- Area inaccessible, no access point. Flat roof.					
Eaves Linings	Flat AC Sheeting	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1247/B00B/R0001/Ceiling Structures/Linings/S4			Chrysotile (white asbestos) , Crocidolite (blue asbestos)		

Interior**B00B - R0001 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1247/B00B/R0001/Ceiling Structures/Linings/S4			Chrysotile (white asbestos) , Crocidolite (blue asbestos)		

B00B - R0002 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1247/B00B/R0001/Ceiling Structures/Linings/S4			Chrysotile (white asbestos) , Crocidolite (blue asbestos)		

B00B - R0003 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1247/B00B/R0001/Ceiling Structures/Linings/S4			Chrysotile (white asbestos) , Crocidolite (blue asbestos)		

B00B - R0004 - Handwashing Facilities

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1247/B00B/R0001/Ceiling Structures/Linings/S4			Chrysotile (white asbestos) , Crocidolite (blue asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Building Services - 1924 - Timber Shed (Timber Shed)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 1247/B00D/Eaves Linings/S5					No Asbestos Detected

Interior

B00D - R0001 - Cleaning Distributed Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Communal Facilities - 2007 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00E - R0001 - Communal Space

No Asbestos

B00E - R0002 - Sports Store

No Asbestos

B00E - R0003 - Canteen Covered Area

No Asbestos

B00E - R0004 - Special Programs Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Slab to ground, no access points.
Ceiling Voids	No Asbestos Found

Interior

B00F - R0001 - External Movement

No Asbestos

B00F - R0002 - Toilets - Boys

No Asbestos

B00F - R0003 - Toilets - Girls

No Asbestos

B00F - R0004 - Staff Toilet

No Asbestos

B00F - R0005 - Cleaning Distributed Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Building Services - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00G - R0001 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, no access points. Slab to ground.
Ceiling Voids	No Asbestos Found

Interior

B00H - R0001 - External Movement

No Asbestos

B00H - R0002 - Practical Activities - 1hb

No Asbestos

B00H - R0003 - Home Base Store

No Asbestos

B00H - R0004 - Home Base

No Asbestos

B00H - R0005 - Withdrawal Space - 2hb

No Asbestos

B00H - R0006 - Home Base

No Asbestos

B00H - R0007 - Practical Activities - 1hb

No Asbestos

B00H - R0008 - Home Base Store

No Asbestos

B00H - R0009 - Home Base Store

No Asbestos

B00H - R0010 - Home Base

No Asbestos

B00H - R0011 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 532 - D14402 - Library : Placement Date - 17/06/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Reading Area

No Asbestos Found.

R2 - Library Office/Workroom

No Asbestos Found.

R3 - Communications Room

No Asbestos Found.

OS 500 - D18124 - Admin - Library : Placement Date - 22/05/2002

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	20.16 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	13 m2

R2 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos	18 m2
---------	---------------	------------------	-------

R3 - Staff Room/Kitchen

Ceiling	Flat AC Sheet	Assumed Asbestos	19 m2
---------	---------------	------------------	-------

R4 - Clerical Office

Ceiling	Flat AC Sheet	Assumed Asbestos	18 m2
---------	---------------	------------------	-------

R5 - Library

Ceiling	Flat AC Sheet	Assumed Asbestos	54 m2
---------	---------------	------------------	-------

R6 - Storeroom

Ceiling	Flat AC Sheet	Assumed Asbestos	0 m2
---------	---------------	------------------	------

R7 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	6 m2
End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	4 m2

R8 - Entry to toilet

Ceiling	Flat AC Sheet	Assumed Asbestos	0 m2
---------	---------------	------------------	------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017