

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Blakebrook Public School (1254)


Region : North Coast

State Electorate : Lismore

Local Government Area : Lismore

Initial Survey : Noel Arnold & Associates : 10 - Jun - 2008

Reviewed By : Parsons Brinckerhoff : 25 - Oct - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Library - 1895 - Timber (Timber)

Exterior

Ceiling Void	No Asbestos Found					
Underfloor Void	AC Fragments/Debris 1254/B00A/Underfloor Void/S3					No Asbestos Detected

Interior

B00A - R0003 - Reading Area

Ceiling Structures/Linings	Flat AC Sheeting	16m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
1254/B00A/R0003/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)	

B00A - R0004 - Library Office/Workroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1980 - Steel (Steel)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00C - R0001 - Canteen

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Building Services - 1950 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00D - R0001 - General Assistant/Bulk Store

Wall Linings Internal	Flat AC Sheeting	30m2	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
1254/B00D/R0001/Wall Linings Internal/S7				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1898 - Timber (Timber)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00E - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1254/B00E/R0001/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	

B00E - R0002 - Home Base Store

No Asbestos

B00E - R0003 - Practical Activities - 1hb

No Asbestos

B00E - R0004 - Home Base

No Asbestos

B00E - R0005 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1907 - Timber (Timber)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00F - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1254/B00F/R0002/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	

B00F - R0002 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1254/B00F/R0002/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)	

B00F - R0003 - Home Base Store

No Asbestos

B00F - R0004 - General Storeroom

No Asbestos

B00F - R0005 - Home Base

No Asbestos

B00F - R0006 - Cleaning Distributed Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1955 - Timber (Timber)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00G - R0001 - Canteen Covered Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Building Services - 1980 - Metal Shed (Metal Shed)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00H - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00I - R0001 - External Movement

No Asbestos

B00I - R0002 - Practical Activities - 1hb

No Asbestos

B00I - R0003 - Home Base Store

No Asbestos

B00I - R0004 - Home Base

No Asbestos

B00I - R0005 - Withdrawal Space - 2hb

No Asbestos

B00I - R0006 - Home Base

No Asbestos

B00I - R0007 - Home Base Store

No Asbestos

B00I - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Pupil Facilities - 2016 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00J - R0001 - Toilets - Boys

No Asbestos

B00J - R0002 - Toilets - Girls

No Asbestos

B00J - R0003 - Toilet - P

No Asbestos

B00J - R0004 - Cleaning Distributed Store

No Asbestos

B00J - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 500 - D18129 - Admin - Library : Placement Date - 6/12/2001

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		20.16 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		13 m2

R2 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos		18 m2
---------	---------------	------------------	--	-------

R3 - Staff Room/Kitchen

Ceiling	Flat AC Sheet	Assumed Asbestos		19 m2
---------	---------------	------------------	--	-------

R4 - Clerical Office

Ceiling	Flat AC Sheet	Assumed Asbestos		18 m2
---------	---------------	------------------	--	-------

R5 - Library

Ceiling	Flat AC Sheet	Assumed Asbestos		54 m2
---------	---------------	------------------	--	-------

R6 - Storeroom

Ceiling	Flat AC Sheet	Assumed Asbestos		0 m2
---------	---------------	------------------	--	------

R7 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos		6 m2
End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		4 m2

R8 - Entry to toilet

Ceiling	Flat AC Sheet	Assumed Asbestos		0 m2
---------	---------------	------------------	--	------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017