

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bobs Farm Public School (1271)
Region : Hunter/Central Coast
State Electorate : Port Stephens
Local Government Area : Port Stephens

Initial Survey : Noel Arnold & Associates : 20 - May - 2008
Register Issue Date : 22 - Mar - 2017



2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00A - Library/Administration - 1928 - Timber (Timber)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | Requires Inspection |
| Underfloor Voids | Requires Inspection |

Interior

B00A - R0001 - K.L.A. Store

No Asbestos

B00A - R0002 - Reading Area

No Asbestos

B00A - R0003 - General Storeroom

No Asbestos

B00A - R0004 - Staff Room

No Asbestos

B00A - R0005 - Clerical Office/Workroom

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00B - Pupil Facilities/Staff Facilities - 1968 - Brick/Block (Brick/Block)**Exterior**

| | |
|------------------|---------------------|
| Ceiling Voids | Requires Inspection |
| Underfloor Voids | Requires Inspection |

Interior**B00B - R0001 - Drinking Facilities**

| | | | | | | |
|---|------------------|-----|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 3m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 1271/B00B/R0002/Ceiling Structures/Linings/S1 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

B00B - R0002 - Toilets - Boys

| | | | | | | |
|---|------------------|------|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 13m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 1271/B00B/R0002/Ceiling Structures/Linings/S1 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

| | | | | | | |
|---|---------------------|-----|------------|---|---------|--------------------|
| Partition Walls (Cubicles) | Compressed AC Sheet | 4m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 1271/B00B/R0002/Partition Walls (Cubicles)/S2 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

B00B - R0003 - Toilets - Girls

| | | | | | | |
|---|------------------|------|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 10m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 1271/B00B/R0002/Ceiling Structures/Linings/S1 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

| | | | | | | |
|---|---------------------|------|------------|---|---------|--------------------|
| Partition Walls (Cubicles) | Compressed AC Sheet | 10m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 1271/B00B/R0002/Partition Walls (Cubicles)/S2 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

B00B - R0004 - Drinking Facilities

| | | | | | | |
|---|------------------|-----|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 4m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 1271/B00B/R0002/Ceiling Structures/Linings/S1 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

B00B - R0005 - Staff Toilet

| | | | | | | |
|---|------------------|-----|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 3m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 1271/B00B/R0002/Ceiling Structures/Linings/S1 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00C - Pupil Facilities/Building Services - 1955 - Timber (Timber)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | Requires Inspection |
| Underfloor Voids | Requires Inspection |

Interior

B00C - R0001 - Movement

No Asbestos

B00C - R0002 - Cleaning Distributed Store

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00D - Building Services - 1930 - Metal Shed (Metal Shed)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | Requires Inspection |
| Underfloor Voids | Requires Inspection |

Interior

B00D - R0001 - General Storeroom

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00E - Building Services - 1987 - Metal Shed (Metal Shed)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | Requires Inspection |
| Underfloor Voids | Requires Inspection |

Interior

B00E - R0001 - General Assistant/Bulk Store

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00F - Storage - 1955 - Timber Shed (Timber Shed)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | Requires Inspection |
| Underfloor Voids | Requires Inspection |

Interior

B00F - R0001 - P.E. Store

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00G - Storage - 2009 - Metal Shed (Metal Shed)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00G - R0001 - General Storeroom

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00J - Other - 2011 - Timber (Timber)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00J - R0001 - Canteen

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 505 - D10273 - Admin Staff/Principal/Secure Store : Placement Date - 20/08/2001

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - Principal

No Asbestos Found.

R3 - Staff Room

No Asbestos Found.

R4 - Security Store

No Asbestos Found.

R5 - Clerical Office

No Asbestos Found.

OS 602 - D12103 - Learning Unit - Standard With P.A.A. : Placement Date - 15/04/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15537 - Learning Unit - Standard With P.A.A. : Placement Date - 15/04/2010

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017