


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bodalla Public School (1272)
Region : Illawarra and South East
State Electorate : Bega
Local Government Area : Eurobodalla

Initial Survey : Noel Arnold & Associates : 26 - May - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00J - Administration/Staff Facilities - 1998 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00J - R0001 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0002 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0003 - Sick Bay

No Asbestos

B00J - R0004 - Disabled Toilet

No Asbestos

B00J - R0005 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0006 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0007 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0008 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0009 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0010 - Cleaning Distributed Store

No Asbestos

B00J - R0011 - Staff Toilet

No Asbestos

B00J - R0012 - Staff Toilet

No Asbestos

B00J - R0013 - Staff Toilet

No Asbestos

B00J - R0014 - Security Store

No Asbestos

B00J - R0015 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0016 - Duplicating Workroom

No Asbestos

B00J - R0017 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0018 - Movement

No Asbestos

B00J - R0019 - Movement

No Asbestos

B00J - R0020 - Main Switch Board

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00K - R0001 - Practical Activities - 1hb

No Asbestos

B00K - R0002 - Home Base Store

No Asbestos

B00K - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00K - R0004 - Personal Effects Storage

No Asbestos

B00K - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00K - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00K - R0007 - Home Base Store

No Asbestos

B00K - R0008 - Practical Activities - 1hb

No Asbestos

B00K - R0009 - Personal Effects Storage

No Asbestos

B00K - R0010 - Movement

No Asbestos

B00K - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00K - R0012 - Practical Activities - 1hb

No Asbestos

B00K - R0013 - Home Base Store

No Asbestos

B00K - R0014 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00K - R0015 - Personal Effects Storage

No Asbestos

B00K - R0016 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00K - R0017 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00K - R0018 - Home Base Store

No Asbestos

B00K - R0019 - Practical Activities - 1hb

No Asbestos

B00K - R0020 - Personal Effects Storage

No Asbestos

B00K - R0021 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00K - R0022 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning/Pupil Facilities - 1998 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00L - R0001 - Toilets - Boys**

No Asbestos

B00L - R0002 - Toilets - Girls

No Asbestos

B00L - R0003 - Cleaning Distributed Store

No Asbestos

B00L - R0004 - Practical Activities - 1hb

No Asbestos

B00L - R0005 - Home Base Store

No Asbestos

B00L - R0006 - Home BaseVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00L - R0007 - Personal Effects Storage**

No Asbestos

B00L - R0008 - Withdrawal Space - 1hbVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00L - R0009 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00L - R0010 - Home Base Store**

No Asbestos

B00L - R0011 - Practical Activities - 1hb

No Asbestos

B00L - R0012 - Personal Effects Storage

No Asbestos

B00L - R0013 - Movement

No Asbestos

B00L - R0014 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0015 - Practical Activities - 1hb

No Asbestos

B00L - R0016 - Home Base Store

No Asbestos

B00L - R0017 - Home BaseVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00L - R0018 - Personal Effects Storage**

No Asbestos

B00L - R0019 - Withdrawal Space - 1hbVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00L - R0020 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00L - R0021 - Home Base Store**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00L - R0022 - Practical Activities - 1hb

No Asbestos

B00L - R0023 - Personal Effects Storage

No Asbestos

B00L - R0024 - Movement

No Asbestos

B00L - R0025 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning/Library - 1998 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00M - R0001 - Toilets - Boys**

No Asbestos

B00M - R0002 - Kiln Room

No Asbestos

B00M - R0003 - Toilets - Girls

No Asbestos

B00M - R0004 - No Access

No Asbestos

B00M - R0005 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0006 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0007 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0008 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0009 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0010 - Practical Activities - 1hb

No Asbestos

B00M - R0011 - Home Base Store

No Asbestos

B00M - R0012 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0013 - Personal Effects Storage

No Asbestos

B00M - R0014 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0015 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0016 - Home Base Store

No Asbestos

B00M - R0017 - Practical Activities - 1hb

No Asbestos

B00M - R0018 - Personal Effects Storage

No Asbestos

B00M - R0019 - Movement

No Asbestos

B00M - R0020 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00M - R0021 - Movement						
No Asbestos						
B00M - R0022 - Cleaning Distributed Store						
No Asbestos						
B00M - R0023 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Communal Facilities - 1998 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00N - R0001 - Toilets - Girls**

No Asbestos

B00N - R0002 - Movement

No Asbestos

B00N - R0003 - Lift

No Asbestos

B00N - R0004 - Raised Platform

No Asbestos

B00N - R0005 - Movement

No Asbestos

B00N - R0006 - Toilets - Boys

No Asbestos

B00N - R0007 - Sports Store

No Asbestos

B00N - R0008 - P.E. Store

No Asbestos

B00N - R0009 - Hall Chair Store

No Asbestos

B00N - R0010 - Communal Space

No Asbestos

B00N - R0011 - Plant

No Asbestos

B00N - R0012 - Cleaning Distributed Store

No Asbestos

B00N - R0013 - Disabled Shower/Toilet

No Asbestos

B00N - R0014 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00N - R0015 - General Assistant/Bulk Store

No Asbestos

B00N - R0016 - Security Store

No Asbestos

B00N - R0017 - Cleaning Supplies

No Asbestos

B00N - R0018 - Garden Store

No Asbestos

B00N - R0019 - General Storeroom

No Asbestos

B00N - R0020 - Movement

No Asbestos

B00N - R0021 - Movement

No Asbestos

B00N - R0022 - Outdoor Learning Area

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Pupil Facilities - 1998 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B000 - R0001 - Canteen

No Asbestos

B000 - R0002 - Canteen Office/Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Building Services - 2007 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00P - R0001 - General Storeroom

No Asbestos

B00P - R0002 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - Pupil Facilities/Art - 2004 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00Q - R0001 - Special Programs Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00R - Building Services/Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00R - R0001 - General Storeroom

No Asbestos

B00R - R0002 - P.E. Store

No Asbestos

B00R - R0003 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017