

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bogan Gate Public School (1274)


Region : Western NSW

State Electorate : Orange

Local Government Area : Parkes

Initial Survey : Noel Arnold & Associates : 24 - Apr - 2008

Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1923 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	10m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1274/B00A/R0001/Ceiling Structures/Linings/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00A - R0001 - Cleaning Supplies

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1274/B00A/R0001/Ceiling Structures/Linings/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0002 - Home Base

No Asbestos

B00A - R0003 - Clerical Office

No Asbestos

B00A - R0004 - Principal

No Asbestos

B00A - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1274/B00A/R0001/Ceiling Structures/Linings/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library/General Learning - 1923 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1274/B00B/Eaves Linings/S4					Chrysotile (white asbestos)
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00B - R0001 - Staff Room

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1274/B00B/Eaves Linings/S4					Chrysotile (white asbestos)

B00B - R0002 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1274/B00B/Eaves Linings/S4					Chrysotile (white asbestos)

B00B - R0003 - Reading Area

No Asbestos

B00B - R0004 - Home Base

No Asbestos

B00B - R0005 - Home Base

No Asbestos

B00B - R0006 - Craft Store

No Asbestos

B00B - R0007 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1923 - Timber (Timber)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Garden Store

No Asbestos

B00C - R0002 - Canteen Covered Area

No Asbestos

B00C - R0003 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities/Staff Facilities - 1920 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting 1274/B00D/R0001/Ceiling Structures/Linings/S3					No Asbestos Detected
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior**B00D - R0001 - Staff Toilet**

Ceiling Structures/Linings	Flat AC Sheeting 1274/B00D/R0001/Ceiling Structures/Linings/S3					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 1274/B00D/R0001/Wall Linings Internal/S2					No Asbestos Detected

B00D - R0002 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting 1274/B00D/R0001/Ceiling Structures/Linings/S3					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 1274/B00D/R0001/Wall Linings Internal/S2					No Asbestos Detected

B00D - R0003 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting 1274/B00D/R0001/Ceiling Structures/Linings/S3					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 1274/B00D/R0001/Wall Linings Internal/S2					No Asbestos Detected

B00D - R0004 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting 1274/B00D/R0001/Ceiling Structures/Linings/S3					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 1274/B00D/R0001/Wall Linings Internal/S2					No Asbestos Detected

B00D - R0005 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting 1274/B00D/R0001/Ceiling Structures/Linings/S3					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 1274/B00D/R0001/Wall Linings Internal/S2					No Asbestos Detected

B00D - R0006 - Handwashing Facilities

Ceiling Structures/Linings	Flat AC Sheeting 1274/B00D/R0001/Ceiling Structures/Linings/S3					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 1274/B00D/R0001/Wall Linings Internal/S2					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Reading Area

No Asbestos

B00E - R0002 - K.L.A. Store

No Asbestos

B00E - R0003 - Practical Activities

No Asbestos

B00E - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017