


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Boggabri Public School (1276)
Region : New England
State Electorate : Barwon
Local Government Area : Narrabri

Initial Survey : Noel Arnold & Associates : 05 - Apr - 2008
Reviewed By : Greencap-NAA : 14 - Apr - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1953 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	1276/B00A/Underfloor Voids - Packing to Floor Joists/S4				Chrysotile (white asbestos)	
Eaves Linings	Flat AC Sheeting	200m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1276/B00A/Eaves Linings/S5				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Void, flat ceiling, pitched roof no access 5metres high	No Asbestos Found					

Interior**B00A - R0001 - Home Base**

No Asbestos

B00A - R0002 - Home Base

No Asbestos

B00A - R0003 - Special Programs Room

No Asbestos

B00A - R0004 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1276/B00A/Eaves Linings/S5				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

B00A - R0005 - Home Base

No Asbestos

B00A - R0006 - Home Base

No Asbestos

B00A - R0007 - Movement

No Asbestos

B00A - R0008 - Movement

No Asbestos

B00A - R0009 - Outdoor Learning Area

No Asbestos

B00A - R0010 - Reading Area

No Asbestos

B00A - R0011 - Communications Room

No Asbestos

B00A - R0012 - Library Office/Workroom

No Asbestos

B00A - R0013 - Interview

No Asbestos

B00A - R0014 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Inside storage cupboard	Good Condition (1)	Low (1)	Low Priority (2-3)
	1276/B00A/Eaves Linings/S5				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	

Electrical Box lining	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	------------------	-----	------------	--------------------	---------	--------------------

Assumed Asbestos - Former electrical box, now holds**B00A - R0015 - Entry Vestibule**

No Asbestos

B00A - R0016 - Clerical Office

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0017 - Sick Bay						
No Asbestos						
B00A - R0018 - Principal						
No Asbestos						
B00A - R0019 - Movement						
No Asbestos						
B00A - R0020 - Staff Room						
No Asbestos						
B00A - R0021 - Toilets - Girls						
No Asbestos						
B00A - R0022 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	37m2	Inside storage cupboard	Good Condition (1)	Low (1)	Low Priority (2-3)
	1276/B00A/Eaves Linings/S5				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
B00A - R0023 - Toilets - Boys						
No Asbestos						
B00A - R0024 - Staff Toilet						
Wall Linings Internal	Flat AC Sheeting	8m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	1276/B00A/R0024/Wall Linings Internal/S2				Chrysotile (white asbestos)	
B00A - R0025 - Staff Toilet						
Wall Linings Internal	Flat AC Sheeting	8m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1276/B00A/R0024/Wall Linings Internal/S2				Chrysotile (white asbestos)	
B00A - R0026 - Movement						
No Asbestos						
B00A - R0027 - General Storeroom						
No Asbestos						
B00A - R0028 - General Storeroom						
No Asbestos						
B00A - R0029 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1276/B00A/Eaves Linings/S5				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
B00A - R0030 - Personal Effects Storage						
No Asbestos						
B00A - R0031 - Cleaning Distributed Store						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Communal Facilities/General Learning - 1883 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Packing to Floor Joists	Non Accessible Area - No opening also low headspace.					
Electrical Backing Board	Resinous Board	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)

Assumed Asbestos - Live electrical hazard

Ceiling Void - Pitched roof, flat ceiling	Non Accessible Area - Height restricted approximately 4m					
---	---	--	--	--	--	--

Interior

- B00B - R0001 - Practical Activities - 1hb**
No Asbestos
- B00B - R0002 - Toilets - Boys/Girls**
No Asbestos
- B00B - R0003 - General Storeroom**
No Asbestos
- B00B - R0004 - Movement**
No Asbestos
- B00B - R0005 - Cleaning Distributed Store**
No Asbestos
- B00B - R0006 - Movement**
No Asbestos
- B00B - R0007 - Communal Space**
No Asbestos
- B00B - R0008 - Home Base**
No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1966 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1276/B00C/Eaves Linings/S6					Chrysotile (white asbestos)
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	Non Accessible Area - No manhole 3m ceiling.					

Interior**B00C - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting					
	1276/B00E/R0001/Ceiling Structures/Linings/S1					No Asbestos Detected

B00C - R0002 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting					
	1276/B00E/R0001/Ceiling Structures/Linings/S1					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Sheet					
	1276/B00C/R0002/Floor Coverings Res/Textile/S7					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	1276/B00C/R0002/Floor Coverings Res/Textile/S8					No Asbestos Detected

B00C - R0003 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting					
	1276/B00E/R0001/Ceiling Structures/Linings/S1					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Sheet					
	1276/B00C/R0002/Floor Coverings Res/Textile/S7					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	1276/B00C/R0002/Floor Coverings Res/Textile/S8					No Asbestos Detected

B00C - R0004 - Canteen

Ceiling Structures/Linings	Flat AC Sheeting					
	1276/B00E/R0001/Ceiling Structures/Linings/S1					No Asbestos Detected
Electrical Backing Board	Resinous Board	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					
Floor Coverings Res/Textile	Vinyl Sheet					
	1276/B00C/R0002/Floor Coverings Res/Textile/S7					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	1276/B00C/R0002/Floor Coverings Res/Textile/S8					No Asbestos Detected

B00C - R0005 - Covered Outdoor Learning Area

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Communal Facilities - 1953 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 1276/B00A/Eaves Linings/S5	5m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Gable Verge Lining	Flat AC Sheeting 1276/B00D/Gable Verge Lining/S9	5m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					

Interior**B00D - R0001 - Sports Store**

Ceiling Structures/Linings	Flat AC Sheeting 1276/B00E/R0001/Ceiling Structures/Linings/S1					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00D - R0002 - Sports Store

Ceiling Structures/Linings	Flat AC Sheeting 1276/B00E/R0001/Ceiling Structures/Linings/S1					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Administration - 1953 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1276/B00A/Eaves Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Gable Verge Lining	Flat AC Sheeting	20m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1276/B00D/Gable Verge Lining/S9			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Void - Flat ceiling, pitched roof	Non Accessible Area - No manhole, ceiling approx 3m					

Interior**B00E - R0001 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	1276/B00E/R0001/Ceiling Structures/Linings/S1					
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	1276/B00E/R0001/Ceiling Structures/Linings/S1					

B00E - R0002 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	1276/B00E/R0001/Ceiling Structures/Linings/S1					

B00E - R0003 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	1276/B00E/R0001/Ceiling Structures/Linings/S1					

B00E - R0004 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	1276/B00E/R0001/Ceiling Structures/Linings/S1					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1981 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	2m2	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1276/B00F/Eaves Linings/S10				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Gable Verge Lining	Flat AC Sheeting	5m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1276/B00F/Gable Verge Lining/S11				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					

Interior**B00F - R0001 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting					
	1276/B00E/R0001/Ceiling Structures/Linings/S1				No Asbestos Detected	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Building Services - 1996 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00G - R0001 - Garage/Carport

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Building Services - 1996 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00H - R0001 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Communal Facilities - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00I - R0001 - Covered Outdoor Learning Area

No Asbestos

B00I - R0002 - External Movement

No Asbestos

B00I - R0003 - Communal Space

No Asbestos

B00I - R0004 - Canteen

No Asbestos

B00I - R0005 - Toilet - Lobby

No Asbestos

B00I - R0006 - Access Shower/Toilet/Change

No Asbestos

B00I - R0007 - P.E. Store

No Asbestos

B00I - R0008 - Toilet - Lobby

No Asbestos

B00I - R0009 - Toilets - Girls

No Asbestos

B00I - R0010 - Toilets - Boys

No Asbestos

B00I - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017