


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Bolwarra Public School (1286)  
**Region :** Hunter/Central Coast  
**State Electorate :** Maitland  
**Local Government Area :** Maitland

**Initial Survey :** Noel Arnold & Associates : 26 - May - 2008  
**Reviewed By :** AECOM : 25 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/General Learning - 1986 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior****B00A - R0002 - Withdrawal Space - 1hb**

No Asbestos

**B00A - R0003 - Home Base Store**

No Asbestos

**B00A - R0004 - Security Store**

No Asbestos

**B00A - R0005 - Staff Room Annexe**

No Asbestos

**B00A - R0006 - Staff Room**

No Asbestos

**B00A - R0007 - Staff Room Annexe**

No Asbestos

**B00A - R0008 - Movement**

No Asbestos

**B00A - R0009 - Sick Bay**

No Asbestos

**B00A - R0010 - Entry Vestibule**

No Asbestos

**B00A - R0011 - Clerical Office**

No Asbestos

**B00A - R0012 - Interview**

No Asbestos

**B00A - R0013 - Principal**

No Asbestos

**B00A - R0014 - Duplicating Workroom**

No Asbestos

**B00A - R0015 - Security Store**

No Asbestos

**B00A - R0016 - Security Store**

No Asbestos

**B00A - R0017 - Staff Room**

No Asbestos

**B00A - R0018 - Movement**

No Asbestos

**B00A - R0019 - Staff Toilet**

Ceiling Structures/Linings Flat AC Sheeting  
1286/B00A/R0020/Ceiling Structures/Linings/S3

**No Asbestos Detected****B00A - R0020 - Staff Toilet**

Ceiling Structures/Linings Flat AC Sheeting  
1286/B00A/R0020/Ceiling Structures/Linings/S3

**No Asbestos Detected****B00A - R0021 - Cleaning Distributed Store**

No Asbestos

**B00A - R0022 - Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Ceiling Structures/Linings Flat AC Sheeting  
 1286/B00A/R0022/Ceiling Structures/Linings/S4 **No Asbestos Detected**

**B00A - R0023 - Main Switch Board**

No Asbestos

**B00A - R0024 - Movement**

No Asbestos

**B00A - R0025 - Movement**

No Asbestos

**B00A - R0026 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning/Pupil Facilities - 1986 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior****B00B - R0001 - Movement**

No Asbestos

**B00B - R0003 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00A/R0020/Ceiling Structures/Linings/S3	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

**B00B - R0005 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00A/R0020/Ceiling Structures/Linings/S3	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

**B00B - R0006 - Shower/Change**

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00A/R0020/Ceiling Structures/Linings/S3	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

**B00B - R0007 - Sports Store**

No Asbestos

**B00B - R0008 - Sports Store**

No Asbestos

**B00B - R0009 - Interview**

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00A/R0020/Ceiling Structures/Linings/S3	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

**B00B - R0010 - Distribution Board**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00A/R0020/Ceiling Structures/Linings/S3	<b>No Asbestos Detected</b>
Electrical Backing Board	Resinous Board	1m2 East Good Condition (1) Low (1) Low Priority (2-3)

**Assumed Asbestos - Electrical Hazard Area inaccessible****B00B - R0011 - General Assistant/Bulk Store**

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00A/R0020/Ceiling Structures/Linings/S3	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

**B00B - R0012 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00A/R0020/Ceiling Structures/Linings/S3	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

**B00B - R0015 - Disabled Toilet**

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00A/R0020/Ceiling Structures/Linings/S3	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00B/R0015/Ceiling Structures/Linings/S5	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

**B00B - R0016 - Home Base**

No Asbestos

**B00B - R0017 - Practical Activities**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00C - Library/Tiered Learning - 1986 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior****B00C - R0001 - Reading Area**

No Asbestos

**B00C - R0002 - Security Store**

No Asbestos

**B00C - R0003 - Library Office/Workroom**

No Asbestos

**B00C - R0004 - Special Programs Room**

No Asbestos

**B00C - R0005 - Special Programs Store**

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00C/R0005/Ceiling Structures/Linings/S6	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

**B00C - R0006 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00C/R0005/Ceiling Structures/Linings/S6	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

**B00C - R0007 - Plant**

No Asbestos

**B00C - R0008 - Distribution Board**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00A/R0022/Ceiling Structures/Linings/S4	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

**B00C - R0011 - Covered Outdoor Learning Area**

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00A/R0020/Ceiling Structures/Linings/S3	<b>No Asbestos Detected</b>
----------------------------	---	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning/Pupil Facilities - 1976 - Timber (Timber)****Exterior**

Eaves Linings	Flat AC Sheeting 1286/B00D/Eaves Linings/S7					<b>No Asbestos Detected</b>
Underfloor Voids	AC Fragments/Debris 1286/B00D/Underfloor Voids/S8	NA	Throughout	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5) <b>Chrysotile (white asbestos)</b>
Ceiling Voids	No Asbestos Found					

**Interior****B00D - R0001 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00D/R0003/Ceiling Structures/Linings/S10					<b>No Asbestos Detected</b>
Wall Linings Internal	Flat AC Sheeting 1286/B00D/R0001/Wall Linings Internal/S1					<b>No Asbestos Detected</b>
Partition Walls (Cubicles)	Compressed AC Sheet 1286/B00D/R0005/Partition Walls (Cubicles)/S9					<b>No Asbestos Detected</b>

**B00D - R0002 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00D/Eaves Linings/S7					<b>No Asbestos Detected</b>
----------------------------	--	--	--	--	--	-----------------------------

**B00D - R0003 - Cleaning Supplies**

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00D/R0003/Ceiling Structures/Linings/S10					<b>No Asbestos Detected</b>
Wall Linings Internal	Flat AC Sheeting 1286/B00D/R0003/Wall Linings Internal/S2					<b>No Asbestos Detected</b>

**B00D - R0004 - Cleaning Distributed Store**

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00D/R0003/Ceiling Structures/Linings/S10					<b>No Asbestos Detected</b>
Wall Linings Internal	Flat AC Sheeting 1286/B00D/R0003/Wall Linings Internal/S2					<b>No Asbestos Detected</b>

**B00D - R0005 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00D/R0003/Ceiling Structures/Linings/S10					<b>No Asbestos Detected</b>
Wall Linings Internal	Flat AC Sheeting 1286/B00D/R0001/Wall Linings Internal/S1					<b>No Asbestos Detected</b>
Partition Walls (Cubicles)	Compressed AC Sheet 1286/B00D/R0005/Partition Walls (Cubicles)/S9					<b>No Asbestos Detected</b>

**B00D - R0006 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00D/Eaves Linings/S7					<b>No Asbestos Detected</b>
----------------------------	--	--	--	--	--	-----------------------------

**B00D - R0007 - Withdrawal Space - 1hb**

No Asbestos

**B00D - R0008 - Home Base**

No Asbestos

**B00D - R0009 - Home Base Store**

Ceiling Structures/Linings	Flat AC Sheeting 1286/B00D/R0003/Ceiling Structures/Linings/S10					<b>No Asbestos Detected</b>
----------------------------	--	--	--	--	--	-----------------------------

**B00D - R0010 - Practical Activities - 1hb**

No Asbestos

**B00D - R0011 - Security Store**

No Asbestos

**B00D - R0012 - Home Base**

No Asbestos

**B00D - R0013 - Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Ceiling Structures/Linings	Flat AC Sheeting 1286/B00D/Eaves Linings/S7					No Asbestos Detected
<b>B00D - R0014 - Home Base Store</b>						
No Asbestos						
<b>B00D - R0015 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00D - R0016 - Home Base</b>						
No Asbestos						
<b>B00D - R0017 - Home Base Store</b>						
Ceiling Structures/Linings	Flat AC Sheeting	4.32m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Height Restriction</b>						
<b>B00D - R0018 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00D - R0019 - Security Store</b>						
No Asbestos						
<b>B00D - R0020 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting 1286/B00D/Eaves Linings/S7					No Asbestos Detected
<b>B00D - R0021 - Home Base</b>						
No Asbestos						
<b>B00D - R0022 - Home Base Store</b>						
No Asbestos						
<b>B00D - R0023 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00D - R0024 - Security Store</b>						
No Asbestos						
<b>B00D - R0025 - General Storeroom</b>						
No Asbestos						
<b>B00D - R0026 - Distribution Board</b>						
						Note: No inspection of live electrical installation.
Ceiling Structures/Linings	Flat AC Sheeting 1286/B00A/R0022/Ceiling Structures/Linings/S4					No Asbestos Detected
Electrical Backing Board	Resinous Board	1m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Area inaccessible Height Restriction</b>						
<b>B00D - R0027 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting 1286/B00D/Eaves Linings/S7					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning - 2004 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00E - R0001 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00E - R0002 - Practical Activities - 1hb**

No Asbestos

**B00E - R0003 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00E - R0004 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00E - R0005 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00E - R0006 - Practical Activities - 1hb**

No Asbestos

**B00E - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00E - R0008 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0009 - Movement**

No Asbestos

**B00E - R0010 - Ramp**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### B00F - Communal Facilities/Pupil Facilities - 2010 - Brick/Veneer (Brick/Veneer)

#### Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

#### Interior

##### B00F - R0001 - Covered Outdoor Learning Area

No Asbestos

##### B00F - R0002 - Communal Space

No Asbestos

##### B00F - R0003 - Movement

No Asbestos

##### B00F - R0004 - Raised Platform

No Asbestos

##### B00F - R0005 - Ramp

No Asbestos

##### B00F - R0006 - Movement

No Asbestos

##### B00F - R0007 - Hall Chair Store

No Asbestos

##### B00F - R0008 - Communal/Performance Store

No Asbestos

##### B00F - R0009 - P.E. Store

No Asbestos

##### B00F - R0010 - Toilet - Lobby

No Asbestos

##### B00F - R0011 - Toilets - Girls

No Asbestos

##### B00F - R0012 - Sound Cupboard

No Asbestos

##### B00F - R0013 - Toilet - Lobby

No Asbestos

##### B00F - R0014 - Toilets - Boys

No Asbestos

##### B00F - R0015 - Cleaning Distributed Store

No Asbestos

##### B00F - R0016 - General Storeroom

No Asbestos

##### B00F - R0017 - Main Switch Board

No Asbestos

##### B00F - R0018 - Access Shower/Toilet

No Asbestos

##### B00F - R0019 - Canteen

No Asbestos

##### B00F - R0020 - Canteen Office/Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Storage - 2011 - Metal Shed (Metal Shed)**

**Exterior**

No Asbestos

**Interior**

**B00G - R0001 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - General Learning - 2014 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

No Asbestos

**Interior**

**B00H - R0001 - External Movement**

No Asbestos

**B00H - R0002 - Practical Activities - 1hb**

No Asbestos

**B00H - R0003 - Home Base**

No Asbestos

**B00H - R0004 - Withdrawal Space - 2hb**

No Asbestos

**B00H - R0005 - Home Base Store**

No Asbestos

**B00H - R0006 - Practical Activities - 1hb**

No Asbestos

**B00H - R0007 - Home Base**

No Asbestos

**B00H - R0008 - Home Base Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

## Demountables

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 603 - D10063 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 2/03/2011**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

### Exterior

No Asbestos Found.

### Interior

#### R1 - Learning space/withdrawal/entry

No Asbestos Found.

#### R2 - Home Base Store

No Asbestos Found.

**OS 603 - D10660 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 21/03/2001**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

### Exterior

No Asbestos Found.

### Interior

#### R1 - Learning space/withdrawal/entry

No Asbestos Found.

#### R2 - Home Base Store

No Asbestos Found.

**OS 603 - D11286 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 14/01/2003**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

### Exterior

No Asbestos Found.

### Interior

#### R1 - Learning space/withdrawal/entry

No Asbestos Found.

#### R2 - Home Base Store

No Asbestos Found.

**OS 602 - D11463 - Learning Unit - Standard With P.A.A. : Placement Date - 8/03/1999**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

### Exterior

No Asbestos Found.

### Interior

#### R1 - Learning space/withdrawal/entry

No Asbestos Found.

#### R2 - Home Base Store

No Asbestos Found.

**OS 602 - D11510 - Learning Unit - Standard With P.A.A. : Placement Date - 15/04/2015**

### Exterior

No Asbestos Found.

### Interior

#### R1 - Learning space/withdrawal/entry

No Asbestos Found.

#### R2 - Home Base Store

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>OS 602 - D12324 - Learning Unit - Standard With P.A.A. : Placement Date - 7/08/2012</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D12568 - Learning Unit - Standard With P.A.A. : Placement Date - 21/01/2009</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 603 - D12848 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 2/05/2000</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 602 - D13514 - Learning Unit - Standard With P.A.A. : Placement Date - 5/01/2012</b>						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						
<b>OS 603 - D14782 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 14/02/2006</b>						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
<b>Exterior</b>						
No Asbestos Found.						
<b>Interior</b>						
<b>R1 - Learning space/withdrawal/entry</b>						
No Asbestos Found.						
<b>R2 - Home Base Store</b>						
No Asbestos Found.						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017