

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bomaderry Public School (1287)
Region : Illawarra and South East
State Electorate : Kiama
Local Government Area : Shoalhaven

Initial Survey : Noel Arnold & Associates : 06 - May - 2008
Reviewed By : AECOM : 18 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1967 - Brick/Block (Brick/Block)**Exterior**

In-fill-panel	Flat AC Sheeting	18m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00C/In-fill-panel/S8					Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	60m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00A/R0016/Ceiling Structures/Linings/S16					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00A - R0001 - Staff Room (86.97 m2)**

No Asbestos

B00A - R0002 - Principal (20.92 m2)

No Asbestos

B00A - R0003 - Entry Vestibule (14.27 m2)

No Asbestos

B00A - R0004 - Clerical Office (15.13 m2)

No Asbestos

B00A - R0005 - Clerical Office/Workroom (15.27 m2)

No Asbestos

B00A - R0006 - Deputy Principal (12.16 m2)

No Asbestos

B00A - R0007 - Cleaning Distributed Store (1.73 m2)

No Asbestos

B00A - R0008 - Staff Toilet (3.78 m2)

No Asbestos

B00A - R0009 - Interview (7.38 m2)

No Asbestos

B00A - R0010 - Sick Bay (6.8 m2)

No Asbestos

B00A - R0011 - Staff Toilet (3.09 m2)

No Asbestos

B00A - R0012 - Movement (20.35 m2)

No Asbestos

B00A - R0013 - Movement (6.39 m2)

No Asbestos

B00A - R0014 - General Storeroom (9.1 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00D/R0002/Floor Coverings Res/Textile/S5					No Asbestos Detected

B00A - R0015 - Main Switch Board (9.25 m2)

No Asbestos

B00A - R0016 - Movement (2.22 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00A/R0016/Ceiling Structures/Linings/S16					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00A - R0017 - Movement (10.53 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Support Unit - 1967 - Brick/Block (Brick/Block)**Exterior**

In-fill-panel	Flat AC Sheeting	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00C/In-fill-panel/S8					Chrysotile (white asbestos)
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00B/R0004/Ceiling Structures/Linings/S17					Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior**B00B - R0001 - Home Base (56.42 m2)**

No Asbestos

B00B - R0002 - Home Base Store (5.44 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00D/R0002/Floor Coverings Res/Textile/S5					No Asbestos Detected

B00B - R0003 - Personal Effects Storage (13.71 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00D/R0002/Floor Coverings Res/Textile/S5					No Asbestos Detected

B00B - R0004 - Movement (12.21 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00B/R0004/Ceiling Structures/Linings/S17					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00B - R0005 - Home Base (56.94 m2)

No Asbestos

B00B - R0006 - Home Base Store (5.47 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00D/R0002/Floor Coverings Res/Textile/S5					No Asbestos Detected

B00B - R0007 - Home Base (56.87 m2)

No Asbestos

B00B - R0008 - Home Base Store (5.1 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00D/R0002/Floor Coverings Res/Textile/S5					No Asbestos Detected

B00B - R0009 - Distribution Board (0.6 m2)

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Assumed Asbestos - Electrical Hazard

B00B - R0010 - Personal Effects Storage (13.87 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00D/R0002/Floor Coverings Res/Textile/S5					No Asbestos Detected

B00B - R0011 - Movement (5.84 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00B/R0004/Ceiling Structures/Linings/S17					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00B - R0012 - Home Base (56.94 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0013 - Home Base Store (5.06 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00D/R0002/Floor Coverings Res/Textile/S5					No Asbestos Detected
B00B - R0018 - Personal Effects Storage (9 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00D/R0002/Floor Coverings Res/Textile/S5					No Asbestos Detected
B00B - R0019 - Movement (5.91 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00B/R0004/Ceiling Structures/Linings/S17					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0021 - Home Base - E (56.8 m2)						
No Asbestos						
B00B - R0022 - Practical Activities - E (16.64 m2)						
No Asbestos						
B00B - R0023 - Home Base Store - E (5.36 m2)						
No Asbestos						
B00B - R0024 - Movement (24.1 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00B/R0004/Ceiling Structures/Linings/S17					Chrysotile (white asbestos) , Amosite (brown asbestos)
B00B - R0025 - Access Shower/Toilet/Change (16.09 m2)						
No Asbestos						
B00B - R0026 - Home Base (56.95 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1967 - Brick/Veneer (Brick/Veneer)**Exterior**

In-fill-panel	Flat AC Sheeting	16m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00C/In-fill-panel/S8					Chrysotile (white asbestos)
Eaves Linings	Flat AC Sheeting	60m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00C/Eaves Linings/S18					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00C - R0001 - Home Base (51.49 m2)**

No Asbestos

B00C - R0003 - Home Base (56.71 m2)

No Asbestos

B00C - R0004 - Home Base Store (5.11 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00D/R0002/Floor Coverings Res/Textile/S5					No Asbestos Detected

B00C - R0005 - Distribution Board (0.62 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0006 - Personal Effects Storage (13.68 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00D/R0002/Floor Coverings Res/Textile/S5					No Asbestos Detected

B00C - R0007 - Movement (5.73 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00C/Eaves Linings/S18					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00C - R0008 - Home Base (56.5 m2)

No Asbestos

B00C - R0009 - Home Base Store (5.08 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00D/R0002/Floor Coverings Res/Textile/S5					No Asbestos Detected

B00C - R0010 - Movement (4.61 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00C/Eaves Linings/S18					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00C - R0011 - Practical Activities (9.92 m2)

No Asbestos

B00C - R0012 - Disabled Toilet (9.6 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Support Unit - 1967 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling
Non Accessible Area
- Area inaccessible

Underfloor Voids - Slab on Ground
No Asbestos Found

Interior**B00D - R0001 - Home Base (60.53 m2)**

No Asbestos

B00D - R0002 - Practical Activities - 1hb (7.54 m2)

Floor Coverings Res/Textile
Vinyl Tiles
1287/B00D/R0002/Floor Coverings Res/Textile/S5
No Asbestos Detected

B00D - R0003 - General Storeroom (13.5 m2)

No Asbestos

B00D - R0004 - Home Base (64.52 m2)

No Asbestos

B00D - R0005 - Practical Activities - 1hb (7.52 m2)

Floor Coverings Res/Textile
Vinyl Tiles
1287/B00D/R0002/Floor Coverings Res/Textile/S5
No Asbestos Detected

B00D - R0006 - Staff Room Annexe (12.73 m2)

No Asbestos

B00D - R0007 - Distribution Board (0.58 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings
Flat AC Sheeting
1m2
Throughout
Good Condition (1)
Low (1) Low Priority (2-3)
1287/B00D/R0007/Ceiling Structures/Linings/S3
Chrysotile (white asbestos)

Electrical Backing Board
Resinous Board
1m2
East
Good Condition (1)
Low (1) Low Priority (2-3)
Assumed Asbestos - Electrical Hazard

B00D - R0008 - Cleaning Supplies (11.94 m2)

Floor Coverings Res/Textile
Vinyl Tiles
12m2
Throughout
Good Condition (1)
Low (1) Low Priority (2-3)
1287/B00D/R0013/Floor Coverings Res/Textile/S4
Chrysotile (white asbestos)

B00D - R0009 - Home Base (63.89 m2)

No Asbestos

B00D - R0010 - Withdrawal Space - 1hb (0.96 m2)

No Asbestos

B00D - R0011 - Home Base - M (63.27 m2)

No Asbestos

B00D - R0012 - Withdrawal - M (1.57 m2)

No Asbestos

B00D - R0013 - Canteen (31.57 m2)

Floor Coverings Res/Textile
Vinyl Tiles
32m2
Throughout
Good Condition (1)
Low (1) Low Priority (2-3)
1287/B00D/R0013/Floor Coverings Res/Textile/S4
Chrysotile (white asbestos)

B00D - R0014 - Canteen Office/Store (3.29 m2)

Floor Coverings Res/Textile
Vinyl Tiles
4m2
Throughout
Good Condition (1)
Low (1) Low Priority (2-3)
1287/B00D/R0013/Floor Coverings Res/Textile/S4
Chrysotile (white asbestos)

B00D - R0015 - Cleaning Distributed Store (2.12 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R0016 - Staff Toilet (2.12 m2)						
No Asbestos						
B00D - R0017 - Movement (19.81 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1287/B00D/R0007/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00D - R0018 - Movement (88.6 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	89m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1287/B00D/R0007/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Communal Facilities/Library - 1995 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior**B00E - R0001 - Communal Space (243.84 m2)**

Ceiling Structures/Linings	Vermiculite								
	1287/B00E/R0005/Ceiling Structures/Linings/S6								Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>									

B00E - R0002 - Music Store (10.28 m2)

Ceiling Structures/Linings	Vermiculite								
	1287/B00E/R0005/Ceiling Structures/Linings/S6								Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>									

B00E - R0003 - P.E. Store (10.15 m2)

Ceiling Structures/Linings	Vermiculite								
	1287/B00E/R0005/Ceiling Structures/Linings/S6								Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>									

B00E - R0004 - Raised Platform (49.89 m2)

Ceiling Structures/Linings	Vermiculite								
	1287/B00E/R0005/Ceiling Structures/Linings/S6								Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>									

B00E - R0005 - Toilets - Boys (7.99 m2)

Ceiling Structures/Linings	Vermiculite								
	1287/B00E/R0005/Ceiling Structures/Linings/S6								Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>									

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00F/R0002/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)

B00E - R0006 - Cleaning Distributed Store (1.27 m2)

Ceiling Structures/Linings	Vermiculite								
	1287/B00E/R0005/Ceiling Structures/Linings/S6								Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>									

B00E - R0007 - Distribution Board (1.28 m2)

No Asbestos	Note: No inspection of live electrical installation.								
-------------	--	--	--	--	--	--	--	--	--

B00E - R0008 - Toilets - Girls (8.04 m2)

Ceiling Structures/Linings	Vermiculite								
	1287/B00E/R0005/Ceiling Structures/Linings/S6								Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>									

B00E - R0011 - Movement (105.97 m2)

No Asbestos

B00E - R0012 - Stairs (6.52 m2)

No Asbestos

B00E - R0013 - Stairs (6.5 m2)

No Asbestos

B00E - R0014 - Movement (2.65 m2)

No Asbestos

B00E - R0015 - Lift (1.93 m2)

No Asbestos

B00E - R0016 - Plant (4.48 m2)

No Asbestos

B00E - R1001 - Movement (6.21 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1287/B00D/R0007/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00E - R1003 - Library Office/Workroom (26.12 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
1287/B00E/R0005/Ceiling Structures/Linings/S6					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00E - R1004 - K.L.A. Store (13.36 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
1287/B00E/R0005/Ceiling Structures/Linings/S6					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00E - R1005 - Staff Room Annexe (14.32 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
1287/B00E/R0005/Ceiling Structures/Linings/S6					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00E - R1006 - Staff Room Annexe (13.4 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
1287/B00E/R0005/Ceiling Structures/Linings/S6					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00E - R1007 - Cleaning Distributed Store (1.42 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
1287/B00E/R0005/Ceiling Structures/Linings/S6					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Wall Linings Internal	Flat AC Sheeting	3m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
1287/B00E/R1007/Wall Linings Internal/S7					Chrysotile (white asbestos)	
B00E - R1008 - Distribution Board (1.41 m2)						
					Note: No inspection of live electrical installation.	
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
1287/B00E/R0005/Ceiling Structures/Linings/S6					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
Wall Linings Internal	Flat AC Sheeting	3m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
1287/B00E/R1007/Wall Linings Internal/S7					Chrysotile (white asbestos)	
B00E - R1009 - Movement (7.72 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
1287/B00E/R0005/Ceiling Structures/Linings/S6					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00E - R1010 - Movement (6.4 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1287/B00D/R0007/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00E - R1011 - Reading Area (241.06 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
1287/B00E/R0005/Ceiling Structures/Linings/S6					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00E - R1012 - Seminar/Study (14.14 m2)						
Ceiling Structures/Linings	Vermiculite					Limited Samples Taken
1287/B00E/R0005/Ceiling Structures/Linings/S6					Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works	
B00E - R1013 - Stairs (6.12 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1287/B00D/R0007/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00E - R1014 - Stairs (6.12 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1287/B00D/R0007/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	

B00E - R1015 - Movement (6.2 m2)

No Asbestos

B00E - R1016 - Lift (1.93 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities/Building Services - 1950 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior**B00F - R0001 - Movement (151.34 m2)**

No Asbestos

B00F - R0002 - Toilets - Girls (42.75 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1287/B00F/R0002/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)	

Ceiling Structures/Linings	Flat AC Sheeting	43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1287/B00F/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)	

B00F - R0003 - No Access (1.35 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1287/B00F/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)	

B00F - R0004 - Sports Store (12.85 m2)

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1287/B00F/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)	

B00F - R0005 - Toilets - Boys (47.39 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1287/B00F/R0002/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)	

Ceiling Structures/Linings	Flat AC Sheeting	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1287/B00F/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)	

B00F - R0006 - No Access (1.35 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1287/B00F/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)	

B00F - R0007 - General Assistant/Bulk Store (16.67 m2)

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1287/B00F/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)	

B00F - R0008 - General Storeroom (28.08 m2)

Ceiling Structures/Linings	Flat AC Sheeting	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1287/B00F/R0002/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1981 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	80m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00G/Eaves Linings/S9					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00G - R0001 - Practical Activities - 1hb (13.86 m2)**

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00G/R0001/Floor Coverings Res/Textile/S11					No Asbestos Detected

B00G - R0002 - Home Base (59.08 m2)

No Asbestos

B00G - R0003 - Home Base (57.96 m2)

No Asbestos

B00G - R0004 - Practical Activities - 1hb (14.4 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00G/R0001/Floor Coverings Res/Textile/S11					No Asbestos Detected

B00G - R0005 - Cleaning Distributed Store (1.69 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00G/R0001/Floor Coverings Res/Textile/S11					No Asbestos Detected

B00G - R0006 - Movement (5.9 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00G/R0001/Floor Coverings Res/Textile/S11					No Asbestos Detected

B00G - R0007 - Craft Store (10.42 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00G/R0001/Floor Coverings Res/Textile/S11					No Asbestos Detected

B00G - R0008 - Uniform Shop (13.72 m2)

No Asbestos

B00G - R0009 - Practical Activities - 1hb (13.84 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00G/R0001/Floor Coverings Res/Textile/S11					No Asbestos Detected

B00G - R0010 - Home Base (57.73 m2)

No Asbestos

B00G - R0011 - Home Base (57.09 m2)

No Asbestos

B00G - R0012 - Practical Activities - 1hb (14.19 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00G/R0001/Floor Coverings Res/Textile/S11					No Asbestos Detected

B00G - R0013 - Movement (6.58 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00G/Eaves Linings/S9					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00G - R0015 - Movement (23.34 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00G/Eaves Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00G - R0016 - Distribution Board (0.73 m2)				Note: No inspection of live electrical installation.		
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00G/Eaves Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting	4m2	South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00G/R0016/Wall Linings Internal/S10			Chrysotile (white asbestos)		
B00G - R9001 - General Storeroom (26.15 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00H - General Learning/Support Unit - 1967 - Brick/Block (Brick/Block)						
Exterior						
Ceiling Voids - Raked Ceiling	Non Accessible Area	- Area inaccessible				
Underfloor Voids - Slab on Ground	No Asbestos Found					
Interior						
B00H - R0001 - Staff Room Annexe (14.01 m2)						
Ceiling Structures/Linings	Vermiculite	1287/B00E/R0005/Ceiling Structures/Linings/S6				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0003 - Distribution Board (1.19 m2)						
No Asbestos					Note: No inspection of live electrical installation.	
B00H - R0005 - Special Programs Room (22.9 m2)						
Ceiling Structures/Linings	Vermiculite	1287/B00E/R0005/Ceiling Structures/Linings/S6				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0006 - Staff Shower/Change (3 m2)						
Ceiling Structures/Linings	Vermiculite	1287/B00E/R0005/Ceiling Structures/Linings/S6				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0007 - Duplicating Workroom (12.89 m2)						
Ceiling Structures/Linings	Vermiculite	1287/B00E/R0005/Ceiling Structures/Linings/S6				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0008 - Cleaning Distributed Store (3.67 m2)						
Ceiling Structures/Linings	Vermiculite	1287/B00E/R0005/Ceiling Structures/Linings/S6				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0009 - Staff Toilet (3.52 m2)						
Ceiling Structures/Linings	Vermiculite	1287/B00E/R0005/Ceiling Structures/Linings/S6				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0010 - General Storeroom (13.03 m2)						
Ceiling Structures/Linings	Vermiculite	1287/B00E/R0005/Ceiling Structures/Linings/S6				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0011 - Home Base (71.34 m2)						
Ceiling Structures/Linings	Vermiculite	1287/B00E/R0005/Ceiling Structures/Linings/S6				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0012 - Practical Activities - 1hb (13.53 m2)						
Ceiling Structures/Linings	Vermiculite	1287/B00E/R0005/Ceiling Structures/Linings/S6				Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	1287/B00D/R0002/Floor Coverings Res/Textile/S5				No Asbestos Detected
B00H - R0013 - Toilets - Boys/Girls (3.03 m2)						
No Asbestos						
B00H - R0014 - Home Base (71.53 m2)						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	1287/B00E/R0005/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B00H - R0015 - Practical Activities - 1hb (13.56 m2)						
Ceiling Structures/Linings	Vermiculite					
	1287/B00E/R0005/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00D/R0002/Floor Coverings Res/Textile/S5					No Asbestos Detected
B00H - R0016 - Toilets - Boys/Girls (3.03 m2)						
No Asbestos						
B00H - R0017 - Movement (73.21 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	74m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00H/R0017/Ceiling Structures/Linings/S14					Chrysotile (white asbestos)
B00H - R0018 - Entry Vestibule (33.21 m2)						
Ceiling Structures/Linings	Vermiculite					
	1287/B00E/R0005/Ceiling Structures/Linings/S6					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Pupil Facilities/Support Unit - 1967 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00I/R0010/Ceiling Structures/Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B001 - R0001 - Toilets - Girls (39.9 m2)**

Partition Walls (Cubicles)	Compressed AC Sheet	24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00F/R0002/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)

Ceiling Structures/Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00I/R0010/Ceiling Structures/Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)

B001 - R0002 - Cleaning Distributed Store (1.05 m2)

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00I/R0010/Ceiling Structures/Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)

B001 - R0003 - Staff Toilet (2.71 m2)

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00I/R0010/Ceiling Structures/Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)

B001 - R0006 - Toilets - Boys (38.65 m2)

Ceiling Structures/Linings	Flat AC Sheeting	39m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00I/R0010/Ceiling Structures/Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)

Partition Walls (Cubicles)	Compressed AC Sheet	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00F/R0002/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos)

B001 - R0007 - Movement (57.35 m2)

Ceiling Structures/Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00I/R0010/Ceiling Structures/Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)

B001 - R0008 - General Storeroom (6.76 m2)

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00I/R0010/Ceiling Structures/Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)

B001 - R0009 - Disabled Shower/Toilet (10.26 m2)

No Asbestos

B001 - R0010 - General Storeroom (27.19 m2)

Ceiling Structures/Linings	Flat AC Sheeting	28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00I/R0010/Ceiling Structures/Linings/S15					Chrysotile (white asbestos) , Amosite (brown asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 1967 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00K/Eaves Linings/S13					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00J - R0001 - Movement (3.21 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00K/Eaves Linings/S13					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00J - R0002 - Home Base (82.25 m2)

No Asbestos

B00J - R0003 - Practical Activities - 1hb (13.3 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00G/R0001/Floor Coverings Res/Textile/S11					No Asbestos Detected

B00J - R0004 - Home Base Store (2.89 m2)

Wall Linings Internal	Flat AC Sheeting					
	1287/B00J/R0006/Wall Linings Internal/S12					No Asbestos Detected

B00J - R0005 - Home Base (82.16 m2)

No Asbestos

B00J - R0006 - Home Base Store (2.91 m2)

Wall Linings Internal	Flat AC Sheeting					
	1287/B00J/R0006/Wall Linings Internal/S12					No Asbestos Detected

B00J - R0007 - Practical Activities - 1hb (13.52 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
	1287/B00G/R0001/Floor Coverings Res/Textile/S11					No Asbestos Detected

B00J - R0008 - Movement (3.21 m2)

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00K/Eaves Linings/S13					Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 1967 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00K/Eaves Linings/S13					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00K - R0001 - Practical Activities - 1hb (12.39 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00K/Eaves Linings/S13					Chrysotile (white asbestos) , Amosite (brown asbestos)
Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	1287/B00D/R0002/Floor Coverings Res/Textile/S5					

B00K - R0002 - Home Base (63.92 m2)

Ceiling Structures/Linings	Flat AC Sheeting	64m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00K/Eaves Linings/S13					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00K - R0005 - Movement (50.33 m2)

Ceiling Structures/Linings	Flat AC Sheeting	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1287/B00K/Eaves Linings/S13					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00K - R0006 - Practical Activities - 1hb (32.89 m2)

No Asbestos

B00K - R0007 - Home Base (48.22 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Special Purpose (Craft Art Science Tas Etc) - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00N - R0001 - Sports Store (19.98 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 971 - D14399 - Shed - Container (Garden/Sports/Bulk) : Placement Date - 30/06/1995

Exterior

No Asbestos Found.

Interior

R1 - Garden Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017