


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Bongongo Public School (1293)  
**Region :** Riverina  
**State Electorate :** Cootamundra  
**Local Government Area :** Gundagai

**Initial Survey :** Noel Arnold & Associates : 09 - May - 2008  
**Reviewed By :** Greencap-NAA : 02 - Sep - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Communal Facilities - 1908 - Metal Shed (Metal Shed)**

**Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area  
 - Area inaccessible

Ceiling Voids      No Asbestos Found

**Interior**

**B00A - R0001 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Other-Community Use - 1991 - Steel (Steel)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00B - R0001 - Other-Community Use**

No Asbestos

**B00B - R0002 - External Movement**

No Asbestos

**B00B - R0003 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Library - 1952 - Timber (Timber)**

**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting	3m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	1293/B00D/Eaves Linings/S1				<b>Chrysotile (white asbestos)</b>	
Underfloor Voids	No Asbestos Found					

**Interior**

**B00C - R0001 - Communal Space**

Wall Linings Internal	Flat AC Sheeting					<b>No Asbestos Detected</b>
	1293/B00C/R0001/Wall Linings Internal/S3					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning - 1956 - Timber (Timber)**

**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1293/B00D/Eaves Linings/S1					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	Non Accessible Area - Height Restriction 4m height					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00D - R0001 - Library Office/Workroom**

Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	1293/B00D/R0002/Floor Coverings Res/Textile/S6					
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1293/B00D/R0002/Floor Coverings Res/Textile/S5					<b>Chrysotile (white asbestos)</b>

**B00D - R0002 - Reading Area**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	43m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1293/B00D/R0002/Floor Coverings Res/Textile/S5					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					<b>No Asbestos Detected</b>
	1293/B00D/R0002/Floor Coverings Res/Textile/S6					

**B00D - R0003 - Staff Kitchen**

No Asbestos

**B00D - R0004 - Movement**

No Asbestos

**B00D - R0005 - Principal**

No Asbestos

**B00D - R0006 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Pupil Facilities/Staff Facilities - 1956 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior**

**B00E - R0001 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1293/B00E/R0003/Ceiling Structures/Linings/S2					<b>Chrysotile (white asbestos)</b>	

**B00E - R0002 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1293/B00E/R0003/Ceiling Structures/Linings/S2					<b>Chrysotile (white asbestos)</b>	

**B00E - R0003 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1293/B00E/R0003/Ceiling Structures/Linings/S2					<b>Chrysotile (white asbestos)</b>	

**B00E - R0004 - Staff Toilet**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1293/B00E/R0003/Ceiling Structures/Linings/S2					<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00F - R0001 - Reading Area**

No Asbestos

**B00F - R0002 - K.L.A. Store**

No Asbestos

**B00F - R0003 - Practical Activities**

No Asbestos

**B00F - R0004 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

### Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

**OS 601 - D12363 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995**

#### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

#### Interior

##### R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

##### R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

##### R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

**OS 837 - D17107 - Hcap Shower/Change/Toilet : Placement Date - 25/08/2009**

#### Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	2.88 m2

#### Interior

##### R1 - Disabled Shower/Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	12 m2
End wall panel	Flat AC Sheet	Assumed Asbestos	36 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	18 m2

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017