

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Bossley Park Public School (1321)
Region : South Western Sydney
State Electorate : Prospect
Local Government Area : Fairfield

Initial Survey : Noel Arnold & Associates : 29 - May - 2008
Reviewed By : Parsons Brinckerhoff : 28 - Dec - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1987 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
In-fill-panel	Flat AC Sheeting 1321/B00A/In-fill-panel/S16					No Asbestos Detected
Ceiling Void	No Asbestos Found					
Gable Ends	Flat AC Sheeting 1321/B00A/Gable Ends/S15					No Asbestos Detected

Interior**B00A - R0001 - Deputy Principal**

No Asbestos

B00A - R0002 - Principal

No Asbestos

B00A - R0003 - Clerical Office

No Asbestos

B00A - R0004 - Entry Vestibule

No Asbestos

B00A - R0005 - Movement

Wall Linings Internal	Flat AC Sheeting 1321/B00M/R0004/Wall Linings Internal/S6					No Asbestos Detected
-----------------------	--------------------------------------------------------------	--	--	--	--	----------------------

B00A - R0006 - Security Store

No Asbestos

B00A - R0007 - Security Store

Wall Linings Internal	Flat AC Sheeting 1321/B00A/R0007/Wall Linings Internal/S8					No Asbestos Detected
-----------------------	--------------------------------------------------------------	--	--	--	--	----------------------

B00A - R0009 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting 1321/B00A/R0007/Wall Linings Internal/S8					No Asbestos Detected
-----------------------	--------------------------------------------------------------	--	--	--	--	----------------------

Ceiling Structures/Linings	Flat AC Sheeting 1321/B00A/R0007/Wall Linings Internal/S8					No Asbestos Detected
----------------------------	--------------------------------------------------------------	--	--	--	--	----------------------

B00A - R0010 - Cleaning Distributed Store

Wall Linings Internal	Flat AC Sheeting 1321/B00A/R0007/Wall Linings Internal/S8					No Asbestos Detected
-----------------------	--------------------------------------------------------------	--	--	--	--	----------------------

Ceiling Structures/Linings	Flat AC Sheeting 1321/B00A/R0007/Wall Linings Internal/S8					No Asbestos Detected
----------------------------	--------------------------------------------------------------	--	--	--	--	----------------------

B00A - R0011 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting 1321/B00A/R0007/Wall Linings Internal/S8					No Asbestos Detected
-----------------------	--------------------------------------------------------------	--	--	--	--	----------------------

Ceiling Structures/Linings	Flat AC Sheeting 1321/B00A/R0007/Wall Linings Internal/S8					No Asbestos Detected
----------------------------	--------------------------------------------------------------	--	--	--	--	----------------------

B00A - R0012 - Staff Room

No Asbestos

B00A - R0014 - Movement

No Asbestos

B00A - R0015 - Interview

No Asbestos

B00A - R0016 - Movement

No Asbestos

B00A - R0017 - Sick Bay

No Asbestos

B00A - R0018 - Distribution Board

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting		1321/B00A/R0007/Wall Linings Internal/S8			No Asbestos Detected
B00A - R0019 - Clerical Office						
No Asbestos						
B00A - R0020 - Duplicating Workroom						
No Asbestos						
B00A - R0021 - Movement						
In-fill-panel	Flat AC Sheeting		1321/B00A/R0021/In-fill-panel/S19			No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - General Learning/Pupil Facilities - 1987 - Brick/Veneer (Brick/Veneer)**Exterior**

In-fill-panel	Flat AC Sheeting 1321/B00B/In-fill-panel/S17					No Asbestos Detected
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior**B00B - R0001 - Practical Activities - 1hb**

No Asbestos

B00B - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0003 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0005 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0006 - Security Store

No Asbestos

B00B - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0008 - Movement

No Asbestos

B00B - R0009 - Movement

No Asbestos

B00B - R0011 - Toilets - Girls

No Asbestos

B00B - R0012 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00B - R0013 - Sports Store

No Asbestos

B00B - R0015 - Toilets - Boys

No Asbestos

B00B - R0016 - Stairs

No Asbestos

B00B - R1001 - Practical Activities - 1hb

No Asbestos

B00B - R1002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R1003 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R1004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R1005 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R1006 - Security Store

No Asbestos

B00B - R1007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R1008 - Movement

No Asbestos

B00B - R1009 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Pupil Facilities - 1987 - Brick/Veneer (Brick/Veneer)**Exterior**

Wall Cladding	Flat AC Sheeting 1321/B00A/Gable Ends/S15					No Asbestos Detected
Underfloor Voids	Non Accessible Area - No key on site					
Ceiling Void	No Asbestos Found					

Interior**B00C - R0001 - Practical Activities - 1hb**

No Asbestos

B00C - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0003 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0005 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0006 - Security Store

No Asbestos

B00C - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0008 - Movement

No Asbestos

B00C - R0010 - Toilets - Girls

No Asbestos

B00C - R0012 - Toilets - Boys

No Asbestos

B00C - R0013 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00C - R0014 - Cleaning Distributed Store

No Asbestos

B00C - R0015 - Movement

No Asbestos

B00C - R0016 - Kiln Room

No Asbestos

B00C - R0017 - Stairs

No Asbestos

B00C - R1001 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1002 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1003 - Practical Activities - 1hb

No Asbestos

B00C - R1004 - Home Base

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1005 - Movement

No Asbestos

B00C - R1006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1007 - Security Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R1009 - Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library/Tiered Learning - 1987 - Brick/Veneer (Brick/Veneer)**Exterior**

Wall Cladding	Flat AC Sheeting 1321/B00A/Gable Ends/S15					No Asbestos Detected
Underfloor Voids	Non Accessible Area - No access - No key on site					
Ceiling Void	No Asbestos Found					

Interior**B00D - R0001 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0004 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0005 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0006 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0007 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0008 - Plant

No Asbestos

B00D - R0009 - Distribution Board

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting 1321/B00M/R0006/Wall Linings Internal/S5					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 1321/B00F/R1004/Wall Linings Internal/S4	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
Electrical Backing Board	Resinous Board 1321/B00D/R0009/Electrical Backing Board/S21	1Unit	West, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)

Chrysotile (white asbestos)

Chrysotile (white asbestos)

B00D - R0010 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting 1321/B00M/R0006/Wall Linings Internal/S5					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 1321/B00F/R1004/Wall Linings Internal/S4	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)

Chrysotile (white asbestos)

B00D - R0011 - Movement

Wall Linings Internal	Cladding 1321/B00M/R0004/Wall Linings Internal/S6					No Asbestos Detected
-----------------------	------------------------------------------------------	--	--	--	--	-----------------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1955 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 1321/B00E/Eaves Linings/S12					No Asbestos Detected
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00E - R0001 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1321/B00E/R0001/Ceiling Structures/Linings/S11					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00E - R0002 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1321/B00E/R0001/Ceiling Structures/Linings/S11					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00E - R0003 - Interview

No Asbestos

B00E - R0004 - Movement

No Asbestos

B00E - R0005 - Interview

No Asbestos

B00E - R0006 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1968 - Brick/Block (Brick/Block)**Exterior**

Gable Verge Lining	Flat AC Sheeting	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------	------------------	------	------------	--------------------	---------	--------------------

Assumed Asbestos - No access - Unable to sample safely

In-fill-panel	Flat AC Sheeting 1321/B00E/Eaves Linings/S12					No Asbestos Detected
---------------	-------------------------------------------------	--	--	--	--	-----------------------------

Ceiling Void	No Asbestos Found					
--------------	-------------------	--	--	--	--	--

Underfloor Voids	No Asbestos Found					
------------------	-------------------	--	--	--	--	--

Eaves Linings	Flat AC Sheeting	12m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------	------------------	------	-------	--------------------	---------	--------------------

1321/B00F/Eaves Linings/S13						Chrysotile (white asbestos)
-----------------------------	--	--	--	--	--	------------------------------------

Interior**B00F - R0001 - Garden Store**

No Asbestos

B00F - R0002 - Cleaning Supplies

No Asbestos

B00F - R0003 - Movement

No Asbestos

B00F - R0004 - Security Store

Ceiling Structures/Linings	Flat AC Sheeting 1321/B00F/R0008/Ceiling Structures/Linings/S20					No Asbestos Detected
----------------------------	--------------------------------------------------------------------	--	--	--	--	-----------------------------

B00F - R0005 - Special Programs Room

No Asbestos

B00F - R0006 - Security Store

No Asbestos

B00F - R0007 - Hall Chair Store

No Asbestos

B00F - R0008 - Main Switch Board

Electrical Backing Board	Resinous Board	1Unit	East, Middle portion	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-------	----------------------	--------------------	---------	--------------------

1321/B00F/R0008/Electrical Backing Board/S22						Chrysotile (white asbestos)
----------------------------------------------	--	--	--	--	--	------------------------------------

Ceiling Structures/Linings	Flat AC Sheeting 1321/B00F/R0008/Ceiling Structures/Linings/S20					No Asbestos Detected
----------------------------	--------------------------------------------------------------------	--	--	--	--	-----------------------------

Electrical Mounting Board	AC Fragments/Debris	1m2	Upper portion	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
---------------------------	---------------------	-----	---------------	---------------------------------------	---------	-----------------------

1321/B00F/R0008/Electrical Mounting Board/S14						Chrysotile (white asbestos)
-----------------------------------------------	--	--	--	--	--	------------------------------------

B00F - R0009 - Hall Chair Store

In-fill-panel	Flat AC Sheeting 1321/B00F/R0009/In-fill-panel/S1					No Asbestos Detected
---------------	------------------------------------------------------	--	--	--	--	-----------------------------

Ceiling Structures/Linings	Flat AC Sheeting 1321/B00F/R0008/Ceiling Structures/Linings/S20					No Asbestos Detected
----------------------------	--------------------------------------------------------------------	--	--	--	--	-----------------------------

B00F - R1001 - Personal Effects Storage

No Asbestos

B00F - R1002 - General Storeroom

No Asbestos

B00F - R1003 - Home Base

No Asbestos

B00F - R1004 - Toilets - Boys/Girls

Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------	------------------	------	------------	--------------------	---------	--------------------

1321/B00F/R1004/Wall Linings Internal/S4						Chrysotile (white asbestos)
------------------------------------------	--	--	--	--	--	------------------------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R1005 - Personal Effects Storage						
No Asbestos						
B00F - R1006 - Home Base Store						
No Asbestos						
B00F - R1007 - Home Base						
No Asbestos						
B00F - R1008 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1321/B00F/R1008/Ceiling Structures/Linings/S2				Chrysotile (white asbestos)	
In-fill-panel	Flat AC Sheeting	10m	North, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1321/B00F/R1008/In-fill-panel/S3				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Communal Facilities/Pupil Facilities - 1987 - Brick/Veneer (Brick/Veneer)**Exterior**

Wall Cladding	Flat AC Sheeting 1321/B00G/Wall Cladding/S18					No Asbestos Detected
Underfloor Voids	Non Accessible Area - No access - No key on site					
Ceiling Void	No Asbestos Found					

Interior**B00G - R0001 - Sports Store**

Ceiling Structures/Linings	Flat AC Sheeting 1321/B00M/R0006/Wall Linings Internal/S5					No Asbestos Detected
----------------------------	--------------------------------------------------------------	--	--	--	--	----------------------

B00G - R0002 - Hall Chair Store

Ceiling Structures/Linings	Flat AC Sheeting 1321/B00M/R0006/Wall Linings Internal/S5					No Asbestos Detected
----------------------------	--------------------------------------------------------------	--	--	--	--	----------------------

B00G - R0003 - P.E. Store

Ceiling Structures/Linings	Flat AC Sheeting 1321/B00M/R0006/Wall Linings Internal/S5					No Asbestos Detected
----------------------------	--------------------------------------------------------------	--	--	--	--	----------------------

B00G - R0004 - Communal Space

No Asbestos

B00G - R0005 - Raised Platform

No Asbestos

B00G - R0009 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 1321/B00G/R0013/Partition Walls (Cubicles)/S7					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 1321/B00M/R0006/Wall Linings Internal/S5					No Asbestos Detected

B00G - R0013 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 1321/B00G/R0013/Partition Walls (Cubicles)/S7					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 1321/B00M/R0006/Wall Linings Internal/S5					No Asbestos Detected

B00G - R0014 - Movement

Wall Linings Internal	Cladding 1321/B00M/R0004/Wall Linings Internal/S6					No Asbestos Detected
-----------------------	------------------------------------------------------	--	--	--	--	----------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning/Administration - 1933 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 1321/B00E/Eaves Linings/S12					No Asbestos Detected
Ceiling Void	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00K - R0001 - General Assistant/Bulk Store

Floor Coverings Res/Textile	Vinyl Tiles 1321/B00K/R0001/Floor Coverings Res/Textile/S9					No Asbestos Detected
In-fill-panel	Flat AC Sheeting 1321/B00K/R0001/In-fill-panel/S10	3m	Behind Sink splashback	Good Condition (1)	Low (1) Low Priority (2-3)	Chrysotile (white asbestos)

B00K - R0002 - Movement

No Asbestos

B00K - R0003 - Movement

No Asbestos

B00K - R0004 - Movement

No Asbestos

B00K - R0005 - Home Base

No Asbestos

B00K - R0006 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Administration - 1913 - Timber (Timber)

Exterior

Ceiling Void	Non Accessible Area - No manhole in building
Underfloor Voids	No Asbestos Found

Interior

B00L - R0001 - Community Clinic

No Asbestos

B00L - R0002 - General Storeroom

No Asbestos

B00L - R0003 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Pupil Facilities - 1987 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Gable Ends	Flat AC Sheeting 1321/B00G/Wall Cladding/S18					No Asbestos Detected
Ceiling Void	No Asbestos Found					

Interior**B00M - R0001 - Canteen**

No Asbestos

B00M - R0002 - Canteen Office/Store

No Asbestos

B00M - R0003 - Uniform Shop

No Asbestos

B00M - R0004 - External Movement

Cladding	Flat AC Sheeting 1321/B00M/R0004/Wall Linings Internal/S6					No Asbestos Detected
----------	--------------------------------------------------------------	--	--	--	--	-----------------------------

B00M - R0005 - Cleaning Distributed Store

Wall Linings Internal	Flat AC Sheeting 1321/B00M/R0006/Wall Linings Internal/S5					No Asbestos Detected
-----------------------	--------------------------------------------------------------	--	--	--	--	-----------------------------

Ceiling Structures/Linings	Flat AC Sheeting 1321/B00M/R0006/Wall Linings Internal/S5					No Asbestos Detected
----------------------------	--------------------------------------------------------------	--	--	--	--	-----------------------------

B00M - R0006 - Disabled Toilet

Wall Linings Internal	Flat AC Sheeting 1321/B00M/R0006/Wall Linings Internal/S5					No Asbestos Detected
-----------------------	--------------------------------------------------------------	--	--	--	--	-----------------------------

Ceiling Structures/Linings	Flat AC Sheeting 1321/B00M/R0006/Wall Linings Internal/S5					No Asbestos Detected
----------------------------	--------------------------------------------------------------	--	--	--	--	-----------------------------

B00M - R0007 - Plant

Wall Linings Internal	Flat AC Sheeting 1321/B00M/R0006/Wall Linings Internal/S5					No Asbestos Detected
-----------------------	--------------------------------------------------------------	--	--	--	--	-----------------------------

Ceiling Structures/Linings	Flat AC Sheeting 1321/B00M/R0006/Wall Linings Internal/S5					No Asbestos Detected
----------------------------	--------------------------------------------------------------	--	--	--	--	-----------------------------

B00M - R0008 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting 1321/B00M/R0006/Wall Linings Internal/S5					No Asbestos Detected
-----------------------	--------------------------------------------------------------	--	--	--	--	-----------------------------

Ceiling Structures/Linings	Flat AC Sheeting 1321/B00M/R0006/Wall Linings Internal/S5					No Asbestos Detected
----------------------------	--------------------------------------------------------------	--	--	--	--	-----------------------------

B00M - R0009 - Movement

Wall Linings Internal	Cladding 1321/B00M/R0004/Wall Linings Internal/S6					No Asbestos Detected
-----------------------	------------------------------------------------------	--	--	--	--	-----------------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00N - General Learning/Pupil Facilities - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00N - R0001 - Practical Activities - 1hb**

No Asbestos

B00N - R0002 - Home Base

No Asbestos

B00N - R0003 - Home Base Store

No Asbestos

B00N - R0004 - Withdrawal Space - 1hb

No Asbestos

B00N - R0005 - Practical Activities - 1hb

No Asbestos

B00N - R0006 - Home Base

No Asbestos

B00N - R0007 - Home Base Store

No Asbestos

B00N - R0008 - Withdrawal Space - 2hb

No Asbestos

B00N - R0009 - Practical Activities - 1hb

No Asbestos

B00N - R0010 - Home Base

No Asbestos

B00N - R0011 - Home Base Store

No Asbestos

B00N - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00N - R0013 - External Movement

No Asbestos

B00N - R0014 - Sports Store

No Asbestos

B00N - R0015 - General Assistant/Bulk Store

No Asbestos

B00N - R0016 - Garden Store

No Asbestos

B00N - R0017 - Laundry - Type 3

No Asbestos

B00N - R0018 - Access Shower/Toilet/Change

No Asbestos

B00N - R0019 - Special Programs Store

No Asbestos

B00N - R0020 - Movement

No Asbestos

B00N - R0021 - Special Programs Room

No Asbestos

B00N - R0022 - Toilets - Girls/Disabled Cubicle

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10552 - Learning Unit - Standard With P.A.A. : Placement Date - 20/12/2012

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 601 - D10962 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

NS 250 - D11769 - Learning Unit - Single E.S.L./Store : Placement Date - 16/01/2014

Exterior

No Asbestos Found.

Interior

R1 - Esl

No Asbestos Found.

R2 - Store

No Asbestos Found.

R3 - Entry

No Asbestos Found.

OS 602 - D13840 - Learning Unit - Standard With P.A.A. : Placement Date - 26/03/2013

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 601 - D15967 - Learning Unit - Standard/Withdrawal : Placement Date - 5/02/1997

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Exterior						
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Interior						
R1 - Entry						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2
R2 - General Learning Space						
End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2
R3 - Store						
Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017