



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Communal Facilities - 1903 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Void	Non Accessible Area - No Access - Manhole > 5m high
Underfloor Voids	No Asbestos Found

**Interior**

**B00A - R0001 - Movement**

No Asbestos

**B00A - R0002 - General Storeroom**

No Asbestos

**B00A - R0003 - Movement**

No Asbestos

**B00A - R0004 - Cleaning Distributed Store**

No Asbestos

**B00A - R0005 - Movement**

No Asbestos

**B00A - R0006 - Practical Activities - 1hb**

Floor Coverings Res/Textile	Vinyl Tiles	20m2	North facing	Some Damage / Unsealed (3)	Low (1) Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>

**B00A - R0007 - Home Base**

No Asbestos

**B00A - R0008 - Movement**

No Asbestos

**B00A - R0009 - Practical Activities - 1hb**

Floor Coverings Res/Textile	Vinyl Tiles	21m2	North facing	Some Damage / Unsealed (3)	Low (1) Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>

**B00A - R0010 - Home Base**

No Asbestos

**B00A - R0011 - Home Base**

No Asbestos

**B00A - R0012 - Uniform Shop**

No Asbestos

**B00A - R0013 - Movement**

Floor Coverings Res/Textile	Vinyl Tiles	2m2	East facing	Some Damage / Unsealed (3)	Low (1) Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>

**B00A - R0014 - Movement**

No Asbestos

**B00A - R0015 - Cleaning Distributed Store**

No Asbestos

**B00A - R0016 - Security Store**

No Asbestos

**B00A - R0017 - Movement**

No Asbestos

**B00A - R0018 - Entry Vestibule**

No Asbestos

**B00A - R0019 - Movement**

No Asbestos

**B00A - R0020 - General Storeroom**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0021 - Home Base</b>						
Floor Coverings Res/Textile	Vinyl Tiles	20m2	North facing	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0022 - Principal</b>						
No Asbestos						
<b>B00A - R0023 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0024 - Distribution Board</b>						
					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00A - R0025 - Sick Bay</b>						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0026 - Interview</b>						
No Asbestos						
<b>B00A - R0027 - Clerical Office/Workroom</b>						
No Asbestos						
<b>B00A - R0028 - Duplicating Workroom</b>						
No Asbestos						
<b>B00A - R0029 - Movement</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0030 - Cleaning Distributed Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0031 - Canteen Office/Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0032 - Canteen Office/Store</b>						
No Asbestos						
<b>B00A - R0033 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0034 - Canteen Office/Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles	3m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0035 - Canteen</b>						
No Asbestos						
<b>B00A - R0036 - Communal Space</b>						
No Asbestos						
<b>B00A - R0037 - Movement</b>						
No Asbestos						
<b>B00A - R0038 - Movement</b>						
No Asbestos						
<b>B00A - R0039 - Movement</b>						
No Asbestos						
<b>B00A - R0040 - Toilets - Boys</b>						
No Asbestos						
<b>B00A - R0041 - P.E. Store</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0042 - Toilets - Girls</b>						
No Asbestos						
<b>B00A - R0043 - Staff Room</b>						
No Asbestos						
<b>B00A - R0044 - General Storeroom</b>						
Floor Coverings Res/Textile	Vinyl Tiles	22m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0045 - Movement</b>						
Floor Coverings Res/Textile	Vinyl Tiles	8m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0046 - General Storeroom</b>						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0047 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0048 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0049 - Distribution Board</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00A - R0050 - Cleaning Distributed Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles	1m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0051 - Movement</b>						
No Asbestos						
<b>B00A - R0052 - Movement</b>						
Floor Coverings Res/Textile	Vinyl Tiles	12m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1001 - General Storeroom</b>						
No Asbestos						
<b>B00A - R1002 - Movement</b>						
No Asbestos						
<b>B00A - R1003 - Practical Activities - 1hb</b>						
Floor Coverings Res/Textile	Vinyl Tiles	20m2	North facing	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1004 - Home Base</b>						
No Asbestos						
<b>B00A - R1005 - Movement</b>						
No Asbestos						
<b>B00A - R1006 - Home Base</b>						
Floor Coverings Res/Textile	Vinyl Tiles	15m2	East facing	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R1007 - Home Base</b>						
No Asbestos						
<b>B00A - R1008 - Toilets - Boys</b>						
Wall Linings Internal	Flat AC Sheeting	24m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1323/B00A/R1008/Wall Linings Internal/S5					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
<b>B00A - R1009 - Toilets - Girls</b>						
Wall Linings Internal	Flat AC Sheeting	24m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1323/B00A/R1008/Wall Linings Internal/S5					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B00A - R9001 - No Access</b>						
Non Accessible						
<b>B00A - R9002 - Movement</b>						
Floor Coverings Res/Textile	Vinyl Tiles	30m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>
<b>B00A - R9003 - Movement</b>						
Floor Coverings Res/Textile	Vinyl Tiles	12m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>
<b>B00A - R9004 - Security Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles	31m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>
<b>B00A - R9005 - Toilets - Boys</b>						
No Asbestos						
<b>B00A - R9006 - Toilets - Girls</b>						
No Asbestos						
<b>B00A - R9007 - General Storeroom</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>
<b>B00A - R9008 - Cleaning Supplies</b>						
Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
	1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>
<b>B00A - R9009 - Movement</b>						
No Asbestos						
<b>B00A - R9010 - Main Switch Board</b>						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	1323/B00A/R9016/Ceiling Structures/Linings/S2					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B00A - R9011 - General Assistant/Bulk Store</b>						
No Asbestos						
<b>B00A - R9012 - General Storeroom</b>						
No Asbestos						
<b>B00A - R9013 - Hall Chair Store</b>						
No Asbestos						
<b>B00A - R9014 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	1323/B00A/R9016/Ceiling Structures/Linings/S2					<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>
<b>B00A - R9015 - General Storeroom</b>						
Floor Coverings Res/Textile	Vinyl Tiles	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>
<b>B00A - R9016 - Craft Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
1323/B00A/R9016/Ceiling Structures/Linings/S2				Chrysotile (white asbestos) , Amosite (brown asbestos)		

**B00A - R9017 - Special Programs Room**

No Asbestos

**B00A - R9018 - Special Programs Room**

No Asbestos

**B00A - R9019 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning - 1976 - Timber (Timber)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

**Interior**

**B00B - R0001 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning/Communal Facilities - 1868 - Brick/Block (Brick/Block)****Exterior**

Gable Ends	Flat AC Sheeting	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1323/B00C/Gable Ends/S7					<b>Chrysotile (white asbestos)</b>
Ceiling Void	Non Accessible Area - No Access - Mnahole > 6m high					
Underfloor Voids	Non Accessible Area - No Manhole in Building					

**Interior****B00C - R0001 - Communal Space**

No Asbestos

**B00C - R0002 - Movement**

No Asbestos

**B00C - R0003 - Raised Platform**

No Asbestos

**B00C - R0004 - Movement**

No Asbestos

**B00C - R0005 - Withdrawal Space - 1hb**

No Asbestos

**B00C - R0006 - Withdrawal Space - 1hb**

No Asbestos

**B00C - R0007 - Toilets - Boys**

No Asbestos

**B00C - R0008 - Toilets - Girls**

No Asbestos

**B00C - R0009 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	1323/B00C/R0009/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>

**B00C - R0010 - Movement**

No Asbestos

**B00C - R0011 - Home Base**

No Asbestos

**B00C - R0012 - Practical Activities - 1hb**

No Asbestos

**B00C - R0013 - Staff Room Annexe**

No Asbestos

**B00C - R0014 - Movement**

Floor Coverings Res/Textile	Vinyl Tiles	12m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	1323/B00C/R0015/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>

**B00C - R0015 - Community Clinic**

Floor Coverings Res/Textile	Vinyl Tiles	16m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	1323/B00C/R0015/Floor Coverings Res/Textile/S4					<b>Chrysotile (white asbestos)</b>

**B00C - R0016 - Community Clinic**

No Asbestos

**B00C - R0017 - Movement**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Library - 1976 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 1323/B00D/Eaves Linings/S6					<b>No Asbestos Detected</b>
Ceiling Void	No Asbestos Found					

**Interior**

**B00D - R0001 - K.L.A. Store**

No Asbestos

**B00D - R0002 - K.L.A. Store**

No Asbestos

**B00D - R0003 - Library Office/Workroom**

No Asbestos

**B00D - R0004 - Library Office/Workroom**

No Asbestos

**B00D - R0005 - Cleaning Distributed Store**

No Asbestos

**B00D - R0006 - Library Office/Workroom**

No Asbestos

**B00D - R0007 - Reading Area**

No Asbestos

**B00D - R0008 - Toilets - Boys**

No Asbestos

**B00D - R0009 - Movement**

No Asbestos

**B00D - R0010 - Toilets - Girls**

No Asbestos

**B00D - R0011 - Movement**

No Asbestos

**B00D - R0012 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - General Learning - 1976 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

**Interior**

**B00E - R0001 - Practical Activities - 1hb**

Floor Coverings Res/Textile	Vinyl Tiles	21m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	

**B00E - R0002 - Home Base**

No Asbestos

**B00E - R0003 - Home Base Store**

Floor Coverings Res/Textile	Vinyl Tiles	7m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	

**B00E - R0004 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	35m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
1323/B00E/R0004/Ceiling Structures/Linings/S8					<b>Chrysotile (white asbestos)</b>	

**B00E - R0005 - Home Base**

No Asbestos

**B00E - R0006 - Practical Activities - 1hb**

Floor Coverings Res/Textile	Vinyl Tiles	18m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	

**B00E - R0007 - Home Base Store**

Floor Coverings Res/Textile	Vinyl Tiles	14m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	

**B00E - R0008 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0009 - Sports Store**

Floor Coverings Res/Textile	Vinyl Tiles	14m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning/Pupil Facilities - 1976 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Void No Asbestos Found

**Interior****B00F - R0001 - Toilets - Boys**

No Asbestos

**B00F - R0002 - Toilets - Girls**

No Asbestos

**B00F - R0003 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0004 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	52m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
1323/B00F/R0004/Ceiling Structures/Linings/S9					<b>Chrysotile (white asbestos)</b>	

Wall Linings Internal	Flat AC Sheeting	12m2	Upper Portion, North	Good Condition (1)	Low (1)	Low Priority (2-3)
1323/B00F/R0004/Wall Linings Internal/S10					<b>Chrysotile (white asbestos)</b>	

**B00F - R0005 - Home Base Store**

Floor Coverings Res/Textile	Vinyl Tiles	8m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	

**B00F - R0006 - Practical Activities - 1hb**

Floor Coverings Res/Textile	Vinyl Tiles	21m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	

**B00F - R0007 - Toilets - Boys/Girls**

No Asbestos

**B00F - R0008 - Home Base**

No Asbestos

**B00F - R0009 - Sports Store**

Floor Coverings Res/Textile	Vinyl Tiles	9m2	All surfaces	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
1323/B00A/R9015/Floor Coverings Res/Textile/S1					<b>Chrysotile (white asbestos)</b>	

**B00F - R0010 - Home Base**

No Asbestos

**B00F - R0011 - Practical Activities - 1hb**

No Asbestos

**B00F - R0012 - Toilets - Boys/Girls**

No Asbestos

**B00F - R0013 - Home Base Store**

No Asbestos

**B00F - R0014 - Movement**

No Asbestos

**B00F - R0015 - Movement**

No Asbestos

**B00F - R0016 - Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00G - Tiered Learning - 2010 - Brick/Veneer (Brick/Veneer)****Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

**Interior****B00G - R0001 - Communal Space**

No Asbestos

**B00G - R0002 - Raised Platform**

No Asbestos

**B00G - R0003 - Chair Storeroom**

No Asbestos

**B00G - R0004 - Communal/Performance Store**

No Asbestos

**B00G - R0005 - P.E. Store**

No Asbestos

**B00G - R0006 - Toilet - Lobby**

No Asbestos

**B00G - R0007 - Toilets - Girls**

No Asbestos

**B00G - R0008 - Sound Cupboard**

No Asbestos

**B00G - R0009 - Toilet - Lobby**

No Asbestos

**B00G - R0010 - Toilets - Boys**

No Asbestos

**B00G - R0011 - Cleaning Distributed Store**

No Asbestos

**B00G - R0012 - Plant**

No Asbestos

**B00G - R0013 - Plant**

No Asbestos

**B00G - R0014 - Main Switch Board**

No Asbestos

**B00G - R0015 - Access Shower/Toilet/Change**

No Asbestos

**B00G - R0016 - Covered Outdoor Learning Area**

No Asbestos

**B00G - R0017 - Movement**

No Asbestos

**B00G - R0018 - Movement**

No Asbestos

**B00G - R0019 - Ramp**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Listing of Electronic Attachments as of 22/03/2017***

**Available Asbestos Related Electronic Files**

1323\_ASB\_010313\_AMP.pdf

\* Note : Refer to AMS for details of the attachment(s).

2017