

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Staff Facilities - 1910 - Timber (Timber)**Exterior**

Ceiling void	No Asbestos Found					
Underfloor void	AC Fragments/Debris	1m2	West	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	1347/B00A/Underfloor void/S8			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Window	Putty					No Asbestos Detected
	1347/B00B/Window/S4					

Interior**B00A - R0003 - Movement**

No Asbestos

B00A - R0004 - Clerical Office/Workroom

No Asbestos

B00A - R0005 - Staff Room

Wall Linings Internal	Flat AC Sheeting	14m2	North, South, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	1347/B00A/R0005/Wall Linings Internal/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1347/B00A/R0005/Wall Linings Internal/S1			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Floor Coverings Res/Textile No Asbestos Found

B00A - R0006 - Sports Store

No Asbestos

B00A - R0007 - Drinking Facilities

No Asbestos

B00A - R0008 - Home Base Store

Floor Coverings Res/Textile No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library - 1956 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1347/B00B/Eaves Linings/S3					Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor void	No Asbestos Found					
Window	Putty					No Asbestos Detected
	1347/B00B/Window/S4					
Wall Cladding	Compressed AC Sheet					No Asbestos Detected
	1347/B00B/Wall Cladding/S5					
Ceiling void	No Asbestos Found					

Interior

B00B - R0001 - Movement

Floor Coverings Res/Textile	Vinyl Tiles					
	1347/B00B/R0001/Floor Coverings Res/Textile/S2					No Asbestos Detected

B00B - R0002 - Reading Area

No Asbestos

B00B - R0003 - Covered Outdoor Learning Area

Wall Linings Internal	Compressed AC Sheet					
	1347/B00B/Wall Cladding/S5					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1960 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 1347/B00C/Eaves Linings/S6	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)

Interior**B00C - R0001 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting 1347/B00C/Eaves Linings/S6	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Door Lining	Flat AC Sheeting 1347/B00A/R0005/Wall Linings Internal/S1	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

B00C - R0002 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting 1347/B00C/Eaves Linings/S6	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
----------------------------	--	-----	------------	--------------------	---------	--

B00C - R0006 - Toilets - Girls

Door lining	Flat AC Sheeting 1347/B00A/R0005/Wall Linings Internal/S1	2m2	North	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet 1347/B00C/R0006/Partition Walls (Cubicles)/S7					No Asbestos Detected

B00C - R0007 - Cleaning Distributed Store

Wall Linings Internal	Flat AC Sheeting 1347/B00C/R0007/Wall Linings Internal/S9					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00C - R0008 - Cleaning Distributed Store

No Asbestos		0.5m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
-------------	--	-------	------	--------------------	---------	--------------------

B00C - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Shed - 1960 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling void	No Asbestos Found

Interior

B00D - R0001 - General Assistant/Bulk Store

No Asbestos

B00D - R0002 - General Storeroom

No Asbestos

B00D - R0003 - Storage

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Underfloor void	Non Accessible Area - Area inaccessible - no manhole access
Wall Cladding	No Asbestos Found
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible

Interior**B00E - R0001 - External Movement**

Floor lining	No Asbestos Found
Wall Linings Internal	No Asbestos Found

B00E - R0002 - Practical Activities

Floor Coverings Res/Textile	No Asbestos Found
Wall Linings Internal	No Asbestos Found

B00E - R0003 - Reading Area

Wall Linings Internal	No Asbestos Found
-----------------------	-------------------

B00E - R0004 - K.L.A. Store

Wall Linings Internal	No Asbestos Found
Floor Coverings Res/Textile	No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 2004 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B00F - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 844 - D10206 - Country Toilet - Reltc - Boys/Girls : Placement Date - 28/04/2004

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	2.88 m2

Interior

R1 - Staff Toilet

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	9 m2

R2 - Staff Toilet

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	9 m2

OS 837 - D11920 - Hcap Shower/Change/Toilet : Placement Date - 10/04/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Disabled Shower/Toilet

No Asbestos Found.

OS 601 - D12204 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2
---------	---------------	------------------	-------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017