

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Broken Hill North Public School (1371)  
**Region :** Western NSW  
**State Electorate :** Barwon  
**Local Government Area :** Broken Hill

**Initial Survey :** Noel Arnold & Associates : 08 - May - 2008  
**Reviewed By :** : 03 - Mar - 2015



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00A - General Learning/Library - 1927 - Brick/Veneer (Brick/Veneer)****Exterior**Underfloor Voids - Slab  
on GroundCeiling Voids Non Accessible Area  
- Height Restriction**Interior****B00A - R0001 - Cleaning Distributed Store (4.85 m2)**

No Asbestos

**B00A - R0002 - Movement (2.66 m2)**

No Asbestos

**B00A - R0003 - Movement (12.26 m2)**

No Asbestos

**B00A - R0004 - Staff Kitchen (12.56 m2)**

No Asbestos

**B00A - R0005 - Movement (2.81 m2)**

No Asbestos

**B00A - R0006 - Staff Room (66.66 m2)**

No Asbestos

**B00A - R0007 - Reading Area (197.6 m2)**

No Asbestos

**B00A - R0008 - Movement (2.81 m2)**

No Asbestos

**B00A - R0009 - K.L.A. Store (12.5 m2)**

No Asbestos

**B00A - R0010 - Movement (2.7 m2)**

No Asbestos

**B00A - R0011 - General Storeroom (4.74 m2)**

No Asbestos

**B00A - R0012 - Movement (12.15 m2)**

No Asbestos

**B00A - R0013 - Library Office/Workroom (8.39 m2)**

No Asbestos

**B00A - R0014 - Movement (2.73 m2)**

No Asbestos

**B00A - R0015 - Library Office/Workroom (12.72 m2)**

No Asbestos

**B00A - R0016 - Staff Toilet (5.46 m2)**

No Asbestos

**B00A - R1001 - Movement (15.15 m2)**

No Asbestos

**B00A - R1002 - Handwashing Facilities (2.29 m2)**

No Asbestos

**B00A - R1003 - Movement (73.8 m2)**

No Asbestos

**B00A - R1004 - Home Base (48.63 m2)**

No Asbestos

**B00A - R1005 - Home Base (49.7 m2)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00A - R1006 - Home Base (49.69 m2)**

No Asbestos

**B00A - R1007 - Home Base (48.9 m2)**

No Asbestos

**B00A - R1008 - Movement (17.65 m2)**

No Asbestos

**B00A - R1009 - Staff Room Annexe (23.26 m2)**

Splashback lining	Flat AC Sheeting	1m2	North	Minimal Damage (2)	Low (1)	Low Priority (2-3)
-------------------	------------------	-----	-------	--------------------	---------	--------------------

1371/B00A/R1009/Splashback lining/S6

**Chrysotile (white asbestos) , Amosite (brown asbestos)**

**B00A - R1010 - General Storeroom (0.46 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning/Support Unit - 1910 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	Non Accessible Area - Extreme Access Issue - Height Restricted - Approx >6m
Eaves Linings	No Asbestos Found
Underfloor Voids	No Asbestos Found
Ceiling Voids	Non Accessible Area - Height Restriction - Extreme Access Issue - Height Restricted - Approx >6m

**Interior**

**B00B - R0001 - Movement (9.21 m2)**

No Asbestos

**B00B - R0002 - Movement (10.31 m2)**

No Asbestos

**B00B - R0003 - Home Base (46.77 m2)**

No Asbestos

**B00B - R0004 - Home Base - M (46.95 m2)**

No Asbestos

**B00B - R0005 - Home Base (46.88 m2)**

No Asbestos

**B00B - R0006 - Movement (24.29 m2)**

Electrical Mounting Board	Resinous Board	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
---------------------------	----------------	-------	------	--------------------	---------	--------------------

**Assumed Asbestos - Electrical Hazard**

**B00B - R0007 - Movement (4.15 m2)**

No Asbestos

**B00B - R0008 - Cleaning Distributed Store (5.25 m2)**

No Asbestos

**B00B - R0009 - General Storeroom (4.24 m2)**

No Asbestos

**B00B - R0010 - Staff Room Annexe (12.77 m2)**

No Asbestos

**B00B - R0011 - Staff Room Annexe (21.25 m2)**

No Asbestos

**B00B - R0012 - Laundry - S (5 m2)**

Wall Linings Internal	Flat AC Sheeting 1371/B00B/R0016/Wall Linings Internal/S3	<b>No Asbestos Detected</b>
-----------------------	--	-----------------------------

Ceiling Structures/Linings	Flat AC Sheeting 1371/B00B/R0016/Wall Linings Internal/S3	<b>No Asbestos Detected</b>
----------------------------	--	-----------------------------

**B00B - R0013 - Practical Activities - M - 1hb (25.2 m2)**

Wall Linings Internal	Flat AC Sheeting 1371/B00B/R0016/Wall Linings Internal/S3	<b>No Asbestos Detected</b>
-----------------------	--	-----------------------------

**B00B - R0014 - Security Store (18.11 m2)**

No Asbestos

**B00B - R0015 - Plant (2.18 m2)**

No Asbestos

**B00B - R0016 - Toilet - M (6.34 m2)**

Wall Linings Internal	Flat AC Sheeting 1371/B00B/R0016/Wall Linings Internal/S3	<b>No Asbestos Detected</b>
-----------------------	--	-----------------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	1371/B00B/R0016/Wall Linings Internal/S3					
<b>B00B - R0017 - Movement (2.23 m2)</b>						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	1371/B00B/R0016/Wall Linings Internal/S3					
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	1371/B00B/R0016/Wall Linings Internal/S3					
<b>B00B - R0018 - Staff Toilet (3.5 m2)</b>						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	1371/B00B/R0016/Wall Linings Internal/S3					
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	1371/B00B/R0016/Wall Linings Internal/S3					
<b>B00B - R0019 - Movement (54.14 m2)</b>						
No Asbestos						
<b>B00B - R1001 - Movement (6.73 m2)</b>						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	1371/B00B/R0016/Wall Linings Internal/S3					
<b>B00B - R1002 - Communal Space (127.99 m2)</b>						
No Asbestos						
<b>B00B - R1003 - Handwashing Facilities (1.43 m2)</b>						
No Asbestos						
<b>B00B - R1004 - Home Base (47.16 m2)</b>						
No Asbestos						
<b>B00B - R1005 - Home Base (46.67 m2)</b>						
No Asbestos						
<b>B00B - R1006 - Home Base (46.81 m2)</b>						
No Asbestos						
<b>B00B - R1007 - Movement (12.94 m2)</b>						
No Asbestos						
<b>B00B - R1008 - Movement (17.55 m2)</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

### B00C - General Learning/Communal Facilities - 1902 - Brick/Block (Brick/Block)

#### Exterior

Ceiling Voids	Non Accessible Area - Extreme Access Issue - Height Restricted - Approx >6m
Underfloor Voids	No Asbestos Found
Ceiling Voids	Non Accessible Area - Height Restriction - Extreme Access Issue - Height Restricted - Approx >6m

#### Interior

##### B00C - R0001 - Movement (2.52 m2)

No Asbestos

##### B00C - R0002 - Raised Platform (31.23 m2)

No Asbestos

##### B00C - R0003 - Communal Space (104.44 m2)

No Asbestos

##### B00C - R0004 - Staff Kitchen (11.63 m2)

No Asbestos

##### B00C - R0005 - Hall Chair Store (19.06 m2)

No Asbestos

##### B00C - R0006 - Movement (2.42 m2)

No Asbestos

##### B00C - R0007 - No Access (2.45 m2)

No Asbestos

##### B00C - R0008 - Movement (23.24 m2)

No Asbestos

##### B00C - R0009 - Movement (8.37 m2)

No Asbestos

##### B00C - R0010 - Movement (22.89 m2)

No Asbestos

##### B00C - R0011 - General Storeroom (2.45 m2)

No Asbestos

##### B00C - R0012 - Movement (2.3 m2)

No Asbestos

##### B00C - R1001 - Movement (44.15 m2)

No Asbestos

##### B00C - R1002 - Home Base (51.76 m2)

No Asbestos

##### B00C - R1003 - Home Base (67.46 m2)

No Asbestos

##### B00C - R1004 - Home Base (51.9 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Administration/General Learning - 1969 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids	No Asbestos Found
Ceiling Voids	Non Accessible Area - Height Restriction

**Interior****B00D - R0001 - Canteen (36 m2)**

No Asbestos

**B00D - R0002 - Canteen Office/Store (5.34 m2)**

No Asbestos

**B00D - R0003 - Movement (6.89 m2)**

No Asbestos

**B00D - R0004 - General Storeroom (30.86 m2)**

Ceiling Structures/Linings	Vermiculite					
	1371/B00D/R0007/Ceiling Structures/Linings/S1					Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00D - R0005 - Movement (16.34 m2)**

No Asbestos

**B00D - R0006 - Movement (2.75 m2)**

Ceiling Structures/Linings	Vermiculite					
	1371/B00D/R0007/Ceiling Structures/Linings/S1					Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00D/R0006/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)

**B00D - R0007 - Staff Toilet (3.35 m2)**

Ceiling Structures/Linings	Vermiculite					
	1371/B00D/R0007/Ceiling Structures/Linings/S1					Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Incinerator	Encapsulated Insulation material within unit	1Unit(s)	East	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Area inaccessible</b>						

**B00D - R0008 - Cleaning Distributed Store (2.27 m2)**

Ceiling Structures/Linings	Vermiculite					
	1371/B00D/R0007/Ceiling Structures/Linings/S1					Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Floor Coverings Res/Textile	Vinyl Tiles	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00D/R0006/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)

**B00D - R0009 - Entry Vestibule (24.73 m2)**

Ceiling Structures/Linings	Vermiculite					
	1371/B00D/R0007/Ceiling Structures/Linings/S1					Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00D - R0010 - Movement (2.08 m2)**

No Asbestos

**B00D - R0011 - General Storeroom (5.58 m2)**

Ceiling Structures/Linings	Vermiculite					
	1371/B00D/R0007/Ceiling Structures/Linings/S1					Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

**B00D - R0012 - Clerical Office/Workroom (15.53 m2)**

Ceiling Structures/Linings	Vermiculite					
	1371/B00D/R0007/Ceiling Structures/Linings/S1					Limited Samples Taken
<b>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00D - R0013 - Clerical Office (19.91 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	1371/B00D/R0007/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00D - R0014 - Principal (17.43 m2)</b>						
Ceiling Structures/Linings	Vermiculite					
	1371/B00D/R0007/Ceiling Structures/Linings/S1					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
<b>B00D - R1001 - Personal Effects Storage (13.01 m2)</b>						
No Asbestos						
<b>B00D - R1002 - Home Base (77.35 m2)</b>						
No Asbestos						
<b>B00D - R1003 - Home Base (51.74 m2)</b>						
No Asbestos						
<b>B00D - R1004 - Personal Effects Storage (13.08 m2)</b>						
No Asbestos						
<b>B00D - R1005 - Withdrawal Space - 1hb (20.8 m2)</b>						
No Asbestos						
<b>B00D - R1006 - General Storeroom (3.81 m2)</b>						
Floor Coverings Res/Textile	Vinyl Tiles	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00D/R0006/Floor Coverings Res/Textile/S2					Chrysotile (white asbestos)
<b>B00D - R1007 - Drinking Facilities (0.94 m2)</b>						
No Asbestos						
<b>B00D - R1008 - Toilets - Boys/Girls (3.44 m2)</b>						
No Asbestos						

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Administration - 1950 - Timber (Timber)**

**Exterior**

Underfloor Voids	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

**Interior**

**B00E - R0001 - Movement (35.31 m2)**

No Asbestos

**B00E - R0002 - Duplicating Workroom (52.33 m2)**

No Asbestos

**B00E - R0003 - General Storeroom (52.48 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning - 1917 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground

Ceiling Voids Non Accessible Area - Height Restriction

**Interior**

**B00F - R0001 - Movement (35.42 m2)**

No Asbestos

**B00F - R0002 - Staff Room Annexe (15.82 m2)**

No Asbestos

**B00F - R0003 - Home Base (52.31 m2)**

No Asbestos

**B00F - R0004 - Withdrawal Space - 1hb (7.67 m2)**

No Asbestos

**B00F - R0005 - General Storeroom (20.24 m2)**

No Asbestos

**B00F - R0006 - Movement (42 m2)**

No Asbestos

**B00F - R0007 - Home Base (106.43 m2)**

No Asbestos

**B00F - R0008 - Sports Store (7.77 m2)**

No Asbestos

**B00F - R0009 - Movement (20.33 m2)**

No Asbestos

**B00F - R0010 - General Storeroom (9.09 m2)**

No Asbestos

**B00F - R0011 - General Storeroom (6.65 m2)**

No Asbestos

**B00F - R0012 - Home Base (52.16 m2)**

No Asbestos

**B00F - R0013 - Movement (34.4 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Support Unit - 1950 - Timber (Timber)**

**Exterior**

Underfloor Voids - Slab on Ground

Ceiling Voids Non Accessible Area - Height Restriction

**Interior**

**B00G - R0001 - Toilet - E (8.05 m2)**

No Asbestos

**B00G - R0003 - Home Base - E (52.04 m2)**

No Asbestos

**B00G - R0005 - Kitchen - Pre (14.29 m2)**

No Asbestos

**B00G - R0006 - Home Base - M (38.48 m2)**

No Asbestos

**B00G - R0007 - Movement (27.65 m2)**

No Asbestos

**B00G - R0008 - Laundry - Pre (0.86 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

**B00H - Pupil Facilities/Communal Facilities - 1950 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	30m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00H/Eaves Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Underfloor Voids - Slab on Ground						
Ceiling Voids	Non Accessible Area - Height Restriction					

**Interior****B00H - R0001 - Sports Store (46.97 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00H/Eaves Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00H - R0002 - General Storeroom (21.01 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00H/Eaves Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00H - R0003 - Handwashing Facilities (20.93 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00H/Eaves Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00H - R0004 - Toilets - Boys (24.91 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00H/Eaves Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00H - R0005 - Toilets - Girls (19.32 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00H/Eaves Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00H - R0006 - Cleaning Distributed Store (2.23 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00H/Eaves Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - Building Services - 1975 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground

Ceiling Voids - Flat Roof

**Interior**

**B001 - R0001 - Garden Store (18.91 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Pupil Facilities - 1991 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	10m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00H/Eaves Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Underfloor Voids - Slab on Ground						
Ceiling Voids	Non Accessible Area - Height Restriction					

**Interior****B00J - R0001 - Cleaning Distributed Store (2.23 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00H/Eaves Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00J - R0002 - Toilets - Girls (49.54 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00H/Eaves Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

Incinerator	Encapsulated Insulation material within unit	1Unit(s)	North	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	<b>Assumed Asbestos - Area inaccessible</b>					

**B00J - R0003 - Handwashing Facilities (17.85 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00H/Eaves Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Pupil Facilities - 1950 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	10m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00H/Eaves Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Underfloor Voids - Slab on Ground						
Ceiling Voids	Non Accessible Area - Height Restriction					

**Interior****B00K - R0001 - Cleaning Distributed Store (2.28 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00H/Eaves Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00K - R0002 - Toilets - Boys (50.8 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	51m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00H/Eaves Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00K - R0003 - Handwashing Facilities (19.86 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00H/Eaves Linings/S4			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Communal Facilities - 1950 - Steel (Steel)**

**Exterior**

Underfloor Voids - Slab on Ground

Ceiling Voids - Flat Roof

**Interior**

**B00L - R0001 - No Access (16.37 m2)**

No Asbestos

**B00L - R0002 - Movement (79.51 m2)**

No Asbestos

**B00L - R0003 - General Storeroom (12.52 m2)**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - Pupil Facilities - 1975 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting	12m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00M/Eaves Linings/S5				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>	

Underfloor Voids - Slab on Ground

Ceiling Voids No Asbestos Found

**Interior****B00M - R0001 - Drinking Facilities (16.47 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00M/Eaves Linings/S5				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>	

**B00M - R0002 - Drinking Facilities (16.51 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00M/Eaves Linings/S5				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>	

**B00M - R0003 - Plant (1.4 m2)**

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1371/B00M/Eaves Linings/S5				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00N - Other - 2005 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00N - R0001 - General Storeroom - Pre (11.81 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00P - Storage - 2010 - Metal Shed (Metal Shed)**

**Exterior**

Underfloor Voids - Slab on Ground

Ceiling Voids - Flat Roof

**Interior**

**B00P - R0001 - Sports Store (43.66 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

### B00Q - Pupil Facilities/Multi Purpose Facilities - 2010 - Brick/Veneer (Brick/Veneer)

#### Exterior

Underfloor Voids - Slab  
on Ground

Ceiling Voids - Raked  
Ceiling

#### Interior

##### B00Q - R0001 - Covered Outdoor Learning Area (142.05 m2)

No Asbestos

##### B00Q - R0002 - Communal Space (147.16 m2)

No Asbestos

##### B00Q - R0003 - Movement (5.89 m2)

No Asbestos

##### B00Q - R0004 - Raised Platform (59.37 m2)

No Asbestos

##### B00Q - R0005 - Movement (11.38 m2)

No Asbestos

##### B00Q - R0006 - Plant (7.11 m2)

No Asbestos

##### B00Q - R0007 - Movement (11.2 m2)

No Asbestos

##### B00Q - R0008 - Hall Chair Store (9.59 m2)

No Asbestos

##### B00Q - R0009 - Communal/Performance Store (9.54 m2)

No Asbestos

##### B00Q - R0010 - P.E. Store (13.02 m2)

No Asbestos

##### B00Q - R0011 - Toilet - Lobby (2.35 m2)

No Asbestos

##### B00Q - R0012 - Toilets - Girls (7.45 m2)

No Asbestos

##### B00Q - R0013 - Sound Cupboard (2.05 m2)

No Asbestos

##### B00Q - R0014 - Toilets - Boys (5.75 m2)

No Asbestos

##### B00Q - R0015 - Toilet - Lobby (3.39 m2)

No Asbestos

##### B00Q - R0016 - Cleaning Distributed Store (3.55 m2)

No Asbestos

##### B00Q - R0017 - Plant (1.54 m2)

No Asbestos

##### B00Q - R0018 - Main Switch Board (2.95 m2)

No Asbestos

##### B00Q - R0019 - Access Shower/Toilet/Change (6.91 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00R - Pupil Facilities - 2016 - Fibre Cement Clad (Fibre Cement Clad)****Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior****B00R - R0001 - Covered Outdoor Learning Area (21.68 m2)**

No Asbestos

**B00R - R0002 - Movement (5.18 m2)**

No Asbestos

**B00R - R0003 - Movement (11.91 m2)**

No Asbestos

**B00R - R0004 - Staff Kitchen (2.82 m2)**

No Asbestos

**B00R - R0005 - Disabled Toilet (5.96 m2)**

No Asbestos

**B00R - R0006 - Clerical Office (12.76 m2)**

No Asbestos

**B00R - R0007 - External Movement (3.09 m2)**

No Asbestos

**B00R - R0008 - Distribution Board (0.24 m2)**

Note: No inspection of live electrical installation.

No Asbestos

**B00R - R0009 - Clerical Office (16.87 m2)**

No Asbestos

**B00R - R0010 - Community Clinic (26.28 m2)**

No Asbestos

**B00R - R0011 - Community Clinic (15.78 m2)**

No Asbestos

**B00R - R0012 - Handwashing Facilities (2.88 m2)**

No Asbestos

**B00R - R0013 - General Storeroom (2.04 m2)**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017