


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Brungle Public School (1387)  
**Region :** Riverina  
**State Electorate :** Wagga Wagga  
**Local Government Area :** Tumut

**Initial Survey :** Noel Arnold & Associates : 16 - May - 2008  
**Reviewed By :** Grencap-NAA : 02 - Sep - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning - 1868 - Timber (Timber)**

**Exterior**

Ceiling Voids	Non Accessible Area - Height Restriction 4m height
Underfloor Voids	No Asbestos Found

**Interior**

**B00A - R0001 - Movement**

Floor Coverings Res/Textile	Compressed AC Sheet					
	1387/B00A/R0001/Floor Coverings Res/Textile/S5					<b>No Asbestos Detected</b>
Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)

**Assumed Asbestos - Electrical Hazard**

**B00A - R0002 - Staff Room**

No Asbestos

**B00A - R0003 - Staff Kitchen**

No Asbestos

**B00A - R0004 - General Storeroom**

No Asbestos

**B00A - R0005 - Cleaning Supplies**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Library/Staff Facilities - 1960 - Timber (Timber)**

**Exterior**

Eaves Linings	Flat AC Sheeting	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1387/B00E/Eaves Linings/S2					<b>Chrysotile (white asbestos)</b>
Ceiling Voids	Non Accessible Area - Height Restriction 4m height					
Underfloor Voids	No Asbestos Found					

**Interior**

**B00B - R0001 - Home Base**

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1387/B00B/R0001/Floor Coverings Res/Textile/S6					<b>Chrysotile (white asbestos)</b>
Floor Coverings Res/Textile	Adhesive					
	1387/B00B/R0001/Floor Coverings Res/Textile/S7					<b>No Asbestos Detected</b>

**B00B - R0002 - Security Store**

No Asbestos

**B00B - R0003 - Interview/Meeting**

Floor Coverings Res/Textile	Adhesive					
	1387/B00B/R0001/Floor Coverings Res/Textile/S7					<b>No Asbestos Detected</b>
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1387/B00B/R0001/Floor Coverings Res/Textile/S6					<b>Chrysotile (white asbestos)</b>

**B00B - R0004 - Reading Area**

No Asbestos

**B00B - R0005 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Pupil Facilities - 1960 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

**Interior**

**B00C - R0001 - Toilets - Girls**

No Asbestos

**B00C - R0002 - Toilets - Boys**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Pupil Facilities - 1960 - Timber (Timber)**

**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting	4m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	1387/B00E/Eaves Linings/S2				<b>Chrysotile (white asbestos)</b>	
Underfloor Voids	No Asbestos Found					

**Interior**

**B00D - R0001 - Shelter**

Floor Coverings Res/Textile	Compressed AC Sheet					
	1387/B00A/R0001/Floor Coverings Res/Textile/S5				<b>No Asbestos Detected</b>	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Other-Community Use - 1937 - Timber (Timber)****Exterior**

Wall Cladding	Flat AC Sheeting 1387/B00E/Wall Cladding/S1	20m2	Adjacent Room ER0008	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Eaves Linings	Flat AC Sheeting 1387/B00E/Eaves Linings/S2	50m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Ceiling Voids	Non Accessible Area - Height Restriction 4m height					
Underfloor Voids	No Asbestos Found					

**Interior****B00E - R0001 - Aboriginal Resource Centre**

No Asbestos

**B00E - R0002 - Aboriginal Resource Centre**

Wall Linings Internal	Flat AC Sheeting 1387/B00E/R0011/Wall Linings Internal/S3	5m2	North facing, South facing, East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B00E - R0003 - Aboriginal Resource Centre**

Wall Linings Internal	Flat AC Sheeting 1387/B00E/R0011/Wall Linings Internal/S3	2m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B00E - R0004 - Aboriginal Resource Centre**

No Asbestos

**B00E - R0005 - Aboriginal Resource Centre**

No Asbestos

**B00E - R0006 - Aboriginal Resource Centre**

No Asbestos

**B00E - R0007 - Aboriginal Resource Centre**

Ceiling Structures/Linings	Flat AC Sheeting 1387/B00E/Eaves Linings/S2	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting 1387/B00E/R0011/Wall Linings Internal/S3	6m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B00E - R0008 - Aboriginal Resource Centre**

No Asbestos

**B00E - R0009 - Aboriginal Resource Centre**

No Asbestos

**B00E - R0010 - Aboriginal Resource Centre**

No Asbestos

**B00E - R0011 - Aboriginal Resource Centre**

Wall Linings Internal	Flat AC Sheeting 1387/B00E/R0011/Wall Linings Internal/S3	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Ceiling Structures/Linings	Flat AC Sheeting 1387/B00E/Eaves Linings/S2	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>

**B00E - R0012 - Aboriginal Resource Centre**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Communal Facilities - 1999 - Timber (Timber)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Wall Cladding	Fibre Cement Casting (Monocrete) 1387/B00F/Wall Cladding/S4	40m2	All surfaces	Minimal Damage (2)	Low (1)	Low Priority (2-3)
				<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		
Eaves Linings	Flat AC Sheeting 1387/B00E/Eaves Linings/S2	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						<b>Chrysotile (white asbestos)</b>
Ceiling Voids	No Asbestos Found					

**Interior**

**B00F - R0001 - Other-Community Use**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Pupil Facilities - 1999 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area  
 - Area inaccessible

Ceiling Voids      No Asbestos Found

**Interior**

**B00G - R0001 - Drinking Facilities**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Library - 2011 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00H - R0001 - Reading Area**

No Asbestos

**B00H - R0002 - Movement**

No Asbestos

**B00H - R0003 - K.L.A. Store**

No Asbestos

**B00H - R0004 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00J - Administration - 2011 - Steel (Steel)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00J - R0001 - Entry Vestibule**

No Asbestos

**B00J - R0002 - Movement**

No Asbestos

**B00J - R0003 - Principal**

No Asbestos

**B00J - R0004 - Clerical Office**

No Asbestos

**B00J - R0005 - Toilet - Lobby**

No Asbestos

**B00J - R0006 - Staff Toilet**

No Asbestos

**B00J - R0007 - Security Store**

No Asbestos

**B00J - R0008 - Staff Room**

No Asbestos

**B00J - R0009 - Clerical Office**

No Asbestos

**B00J - R0010 - Sick Bay**

No Asbestos

**B00J - R0011 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Pupil Facilities - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

**Interior**

**B00K - R0001 - General Storeroom**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Building Services - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area  
 - Area inaccessible

Ceiling Voids      No Asbestos Found

**Interior**

**B00L - R0001 - Garden Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - Building Services - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area  
 - Area inaccessible

Ceiling Voids      No Asbestos Found

**Interior**

**B00M - R0001 - General Assistant/Bulk Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 844 - D18137 - Country Toilet - Reltc - Boys/Girls : Placement Date - 12/12/2008**

**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		2.88 m2

**Interior**

**R1 - Staff Toilet**

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		9 m2

**R2 - Staff Toilet**

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		9 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017